

02-28-22 1

INVOICE

M07540

SOLD TO: SHIP TO:

ORDER# ORD DATE CUST# CONTACT CUSTOMER PO# G.S.T.# P.S.T.# LOCATION

S07255 01-25-22 00076 ANDREW CREDIT CARD 65 AB

50/255 01-25-22 000/6 ANDREW CREDIT CARD 65 AB

TE T750 TELE BOOM TRUCK CRANE

Serial# : 750174

Stock # :

001 WO TYPE: CRET - CUSTOMER OWNED MACHINE

COMPLAINT (CUSTOMER): OUTRIGGERS WILL ONLY SYNC, WILL NOT OPERATE INDEPENDENT. FRONT O/R WILL NOT EXTEND OR

RETRACT.

CAUSE (TECH):

CORRECTION (TECH):

BB 01/26/22 - 1.5HRS ST, 3.5HRS ST TRAVEL
TRAVEL FROM HOME TO DEAD MAN FLATS, MEET WITH CUSTOMER/
OPERATOR, DISCUSS O/R FAULTS, REMOVE SLIP RING COVER,
INSPECT ALL SEGMENTS/BRUSHES, MANUALLY BYPASS O/R CONTROL
VALVES, ALL OUTRIGGERS ENGAGE, CUSTOMER DOES NOT HAVE
ELECTRICAL/HYDRAULIC SCHEMATICS, WILL REQUIRE TO CONTINUE
T/S, DISCUSS RELOCATING UNIT TO OUR YARD, CUSTOMER WILL
DRIVE CRANE TO YARD ON MONDAY, TRAVEL FROM DEAD MAN FLATS
TO SHOP.

BB 02/07/22 - 2HRS ST CONTACT CUSTOMER AS PROVIDED SCHEMATICS ARE INCOMPLETE, CUSTOMER DOES NOT HAVE ANYTHING FURTHER, CONTACT TEREX USA, RETIREVE ELECTRICAL/HYDRAULIC SCHEMATICS, BEGIN

CONTINUED

Remit to: Leavitt Cranes Canada Inc. #102 - 19433 96th Ave. Surrey, BC V4N 4C4

1-844-662-7263 (1-844-66-CRANE)

Fax: 1-844-870-5670 www.leavittcranes.com

Payments Due:

Equipment Sales: upon delivery Equipment Rentals: upon receipt of invoice

Parts & Service: net 30 days

GST Registration Number: 811819366 PST Registration Number: 1055-1647 SST Registration Number: 2612513 MST Registration Number: 811819366

## INVOICE



02-28-22

INVOICE

M07540

2

SOLD TO: SHIP TO:

ORDER# ORD DATE CUST# CONTACT CUSTOMER PO# G.S.T.# P.S.T.# LOCATION S07255 01-25-22 00076 ANDREW CREDIT CARD 65 AB

TRACING CIRCUITS AND FOLLOWING VOLTAGE TO OR SOLENOIDS.

DV 02/07/22 - 2HRS ST GO THROUGH NEW ELECTRICAL AND HYDRAULIC SCHEMATICS. START TRACING WIRES AND IDENTIFYING SOLENOIDS, CHECK TO SEE IF POWER IS GOING TO THE RIGHT ONES.

BB 02/08/22 - 6.5HRS ST
REMOVE COVERS, REMOVE SLIP RING COVER, THOROUGHLY INSPECT
HARNESS TO PIN POINT FAULT, FOUND BREAK IN HARNESS WITH
CORROSION, MOVE AND PARK UNIT INSIDE BAY 1, LOCK
SWING AND RAISE BOOM, LOCK OUT UNIT, DISCONNECT BATTERY,
REMOVE ELECTRICAL TAPE AND LOOM ON HARNESS, CUT BACK TO
ABOUT 6" FROM HYDRAULIC SLIP RING, WIRING INSULATION
MELTED TOGETHER, CONTINUE TO CUT BACK LOOM, FOUND AT
ABOUT 4" FROM HYDRAULIC SLIP RING INSULATION IS OK,
WIRING SHOULD BE OK TO UTILIZE FROM HERE, CONTACT CUSTOMER
DISCUSS REPAIRS, CONTACT ADMIN RETRIEVE PO FOR BUTT
CONNECTORS AND SHRINK TUBE, CLEAN UP TOOLING, PREPARE FOR
REPAIR OF 25 WIRES AS CUSTOMER ONLY APPROVED A PATCH
REPAIR.

DV 02/08/22 - 6.5HRS ST CONITUE TROUBLESHOOTING CRANE. FOUND BURNT WIRES IN HARNESS DUE TO RUBBING ON DRIVESHAFT. TRACE WIRES, REMOVE SLIP RING COVER. BRING CRANE INTO SHOP. REMOVE DRIVE SHAFT. PICK UP BUTT CONNECTORS AND SHRINK TUBING.

CONTINUED

Remit to: Leavitt Cranes Canada Inc. #102 - 19433 96th Ave. Surrey, BC V4N 4C4

1-844-662-7263 (1-844-66-CRANE) Fax: 1-844-870-5670

www.leavittcranes.com

Payments Due:

Equipment Sales: upon delivery Equipment Rentals: upon receipt of invoice Parts & Service: net 30 days

GST Registration Number: 811819366 PST Registration Number: 1055-1647 SST Registration Number: 2612513 MST Registration Number: 811819366

## INVOICE



02-28-22 3

INVOICE

M07540

SOLD TO: CASH SALE

ALBERTA, AB

SHIP TO: GREYS INDUSTRIAL

BANFF MOUNTAIN RESORT

AB T1W2W4

ORDER# ORD DATE CUST# CONTACT CUSTOMER PO# G.S.T.# P.S.T.# LOCATION

S07255 01-25-22 00076 ANDREW CREDIT CARD

BB 02/09/22 - 5HRS ST CUT A REMOVE BURNT/MELTED SECTION OF SLIP HARNESS, PATCH 12 INCH SECTIONS OF WIRE, BUTT CONNECT AND SHRINK TUBE BOTH ENDS, REPAIR 23 WIRES, PLUG IN HARNESS, CONNECT BATTERY POST, TEST ALL FUNCTIONS, FOUND FRONT OUTRIGGER CONTINUES TO STROKE UPON PTO ENGAGEMENT, TRACE CIRCUITS BACK TO EXT/RET ROCKER SWITCH, FOUND ROCKER SWITCH HAS MELTED INTERNALLY CAUSING A SHORT TO EXTEND, REPLACE ROCKER SWITCH, TEST FUNCTION, ALL OK, DISCONNECT HARNESS, SORT WIRING AND WRAP IN ELECTRICAL TAPE, ROUTE HARNESS AWAY FROM DRIVESHAFT, TORQUE MOUNTING BOLTS TO 150FT/LBS AS PER MANUAL, TIE STRAP TO HYDRAULIC HARD LINES, INSTALL DRIVE SHAFT, INSTALL COVER PANELS, INSTALL SLIP RING COVER, LOWER BOOM.

DV 02/09/22 - 4HRS ST MAKE UP WIRE TAILS AND CRIMPS. CUT SHRINK TUBING. RE TERMINATE BATTERY. INSTALL DRIVESHAFT AND COVERS. TROUBLESHOOT AND REPLACE SWITCH FOR FRONT STABILIZER.

BB 02/10/22 - 1HR ST CUT 4INCH LENGTH OF HEATER HOSE, CUT OPEN, WRAP AROUND HARNESS, TIE DOWN WITH STRAPS. \*\*JOB COMPLETE\*\*

DV 02/10/22 - 1HR ST

CONTINUED

Remit to: Leavitt Cranes Canada Inc. #102 - 19433 96th Ave. Surrey, BC V4N 4C4

1-844-662-7263 (1-844-66-CRANE)

1-844-870-5670 Fax: www.leavittcranes.com Payments Due:

Equipment Sales: upon delivery Equipment Rentals: upon receipt of invoice

Parts & Service: net 30 days GST Registration Number: 811819366 PST Registration Number: 1055-1647

SST Registration Number: 2612513 MST Registration Number: 811819366





02-28-22

INVOICE

M07540

4

SOLD TO:

ORDER# ORD DATE CUST# CONTACT CUSTOMER PO# G.S.T.# P.S.T.# LOCATION

S07255 01-25-22 00076 ANDREW CREDIT CARD 65 AB

PULL CRANE OUT OF SHOP. TEST ALL OUTRIGGER FUNCTIONS.

SHIP TO:

BB 02/15/22 - 1HR ST ASSIST RIGGING CRANE FOR TRANSPORT.

NET QTY SHP PART NUMBER DESCRIPTION  ${ t TOTAL}$ 14AWG SHRINK TUBING 19.78 19.78 1 1 100 - 14AWG BUTT CONNECTO 39.91 39.91 1 ROCKER SWITCH 3 POSITION 69.17 69.17 4590.00 Labour 1 SERVICE TRUCK CHARGE 80KM 216.00 216.00

Segment 001 total: 4934.86

Total Labour : 4590.00
Total Parts : 344.86
Shop Supplies : 436.05

Shop Supplies : 436.05

 Sub Total
 :
 5370.91

 GST/HST
 :
 268.55

Invoice Total : 5639.46

**Payments Due:** 

Equipment Sales: upon delivery

Equipment Rentals: upon receipt of invoice

Parts & Service: net 30 days

GST Registration Number: 811819366 PST Registration Number: 1055-1647 SST Registration Number: 2612513 MST Registration Number: 811819366

Entered by: 1407

Remit to:

Leavitt Cranes Canada Inc. #102 - 19433 96th Ave.

Surrey, BC V4N 4C4 1-844-662-7263 (1-844-66-CRANE)

Fax: 1-844-870-5670 www.leavittcranes.com