



Atlas Industrial Holdings Pty Ltd
 Email: accounts@atlasholdings.com.au
 Phone: 1800 784 453
 ABN: 55 154 445 137
 Address: 526 Benetook Ave, Mildura Vic 3500

Service History

Date Generated: 18/03/2026 04:30 PM

Equipment Details

Equipment Number	YH229	Make:	Dynapac
Equipment Description	Dynapac CC1250 - 3.0 Ton Twin Drum Roller	Model:	CC1250
Serial Number	10300379VKE006213		

Date	Type	Description	Last Meter Reading
01/06/2020 01:35 PM	Work Order - Repair	1346 - complaint- roller cut out and won't start. Cause- faulty wire at starter motor. Correction- repaired faulty wire.	
09/06/2020 07:24 AM	Work Order - Repair	1310 - supply and install decals on roller	5.00
15/01/2021 12:25 PM	Work Order - Repair	2457 - found power at the lower plug on both sides of the plug but neither positive or negative at light found a pinched piece of insulation and cut open to expose wiring to find wiring had been cut, fixed wiring section and reconnected insulated section, tested at light all working correctly	47.00
06/05/2021 12:36 PM	Work Order - Repair	3037 - Roller loosing oil out of breather on front drum. Found blown front seal in front vibrating drum. Removed hydraulic pump. All seals in pump damaged. Sourced new pump under warranty. Replaced pump. Tested ok	
12/05/2021 03:25 PM	Work Order - Repair	3085 - remove and replaced rear vibrator motor (warranty) Repaired flashing ligh (Blown fuse).	71.00
03/12/2021 11:54 AM	Work Order - Repair	3700 - Travel to site, sign in locate unit found bolts fallen off scraper blade locate scraper blade blade requires repair travel back to workshop. Repaired and fitted scraper. tested ok	112.00
27/04/2022 07:10 AM	Work Order - Repair	BE5169 - Travel to site locate unit inspect issue found rotating light wiring has come apart inside rotating light dismantle and repair refit and test found no further fault	
27/04/2022 07:26 AM	Work Order - Repair	4300 - Fit work lights as new head lights (Replaced broken lights). Tested OK	125.00
28/07/2022 01:09 PM	Work Order - Repair	BE5674 - Customer lost keys. Sourced and replaced keys	141.00
08/08/2022 07:13 AM	Work Order - Repair	BE5753 - Travel to site inspect issue. check oil levels drive around found fault sear switch and operator Instruct operator on issue travel back to workshop	
07/11/2022 08:20 AM	Work Order - Repair	BE6263 - Travel to site locate unit inspect found estop in start machine travel back to w/spare	174.00
06/11/2023 01:45 PM	Work Order - Repair	BE8459 - Replace dead battery	243.00

Date	Type	Description	Last Meter Reading
13/06/2024 07:35 AM	Work Order - 250 Hour Service	BE8734 - 250 Hour Service, replace fuel lines	243.00
22/08/2024 04:50 PM	Work Order - Repair	BE10181 - complaint: beacon not working. Replaced wiring and fuses.	387.00
24/10/2025 03:05 PM	Work Order - 500 Hour Service	500 Hour Service	
20/01/2026 09:54 AM	Work Order - Repair	Replace Seat and Water tank cap	