



Atlas Industrial Holdings Pty Ltd  
 Email: [accounts@atlasholdings.com.au](mailto:accounts@atlasholdings.com.au)  
 Phone: 1800 784 453  
 ABN: 55 154 445 137  
 Address: 526 Benetook Ave, Mildura Vic 3500

# Service History

Date Generated: 18/03/2026 04:20 PM

## Equipment Details

<b>Equipment Number</b>	YH418	<b>Make:</b>	New Holland
<b>Equipment Description</b>	New Holland C327 - 75 Hp Track Skid Steer	<b>Model:</b>	C327
<b>Serial Number</b>	JAF0C327CPM426813		

Date	Type	Description	Last Meter Reading
20/09/2023 10:52 AM	Work Order - Repair	M7877 - contractor fitted reverse camera	4.00
13/10/2023 11:44 AM	Work Order - Repair	M8364 - Refit reverse camera and estop. Estop wired through a relay located behind ignition panel	38.00
06/11/2023 07:07 AM	Work Order - Repair	M8100 - Machine delivered to Roncomotors for repair as it is under warranty. Ronco first couldn't connect to the machine. After playing around they connected to the machine and found the joy sticks werent calibrated. After calibrating the joysticks more fault codes popped up. Ronco cleared the Fault codes only to have more pop up. After further diagnostics ronco found the ecu to be the proble and replaced it. After programing the ecu ronco tested the machine and found the fault to be resolved. *** Note due to the ecu being replaced the hours of the machine reset to zero***	38.00
28/11/2023 03:51 PM	Work Order - Repair	M8539 - Travel to site. Sit through induction. Attended machine. Checked over machine, retensioned tracks, replaced aerial, found hydraulic couplings leaking. Was old by ronco to rewire estop to fuel relay. Machine doesn't have a fuel relay. Contacted ballarat tractors and wa told to wire estop into ignition as I previosly had. Refitted fire extinguisher. Return to workshop.	
28/11/2023 04:23 PM	Work Order - Repair	M8701 - drove to site with new beacon. Fitted new beacon. Returned to workshop, Ray: beacon charged out on contract.	
30/11/2023 11:42 AM	Work Order - Repair	M8682 - inspected a/c. found a/c to have no gas. Took photos for ronco. Ronco found loose fitting. Vacced down and regassed machine	
10/01/2024 03:38 PM	Work Order - 500 Hour Service	M8786 - 500 Hour Service	
11/01/2024 02:01 PM	Work Order - Repair	M8972 - A/C bolts rattled loose. Replaced bolts	
17/01/2024 09:59 AM	Work Order - Repair	M9014 - Trave to site. Waited for escort. Found machine not cranking. Checked estop. Found wire came loose in estop. Resecured wire. Machine starts. Return travel to workshop	
07/06/2024 12:24 PM	Work Order - 1000 Hour Service	M9784 - 1000 Hour Service	

Date	Type	Description	Last Meter Reading
08/07/2024 08:18 AM	Work Order - Repair	M9130 - oil leak. Hydraulic.	
02/08/2024 08:11 AM	Work Order - Repair	M10030 - Complaint: reverse camera not working, headlight globe, missing grease nipple, using coolant, window seal leaking. Correction: travel to site. Replace globes, uhf aerial, repaired wiring for reverse cameras, greased, check coolant ok, check window seal, pressure washer caused leak. All ok.	
12/08/2024 09:46 AM	Work Order - Repair	M10091 - Complaint: low power. Rear door handle broken. Cause: blocked fuel filter. Damaged rear door handle Correction: removed and replaced door handle. Replaced fuel filter.	
27/08/2024 11:39 AM	Work Order - Repair	M10241 - Complaint: front access door damaged on site. Cause: Operation. Correction: Traveled to site. Inspected machine. Ordered parts. Returned to site. Removed and replaced damaged door and associated components. Reassembled and tested for correct operation.	
16/09/2024 10:52 AM	Work Order - Repair	M10391 - complaint: Hydraulic issue. Cause: unknown. Correction: traveled to site. Inspected machine and could not fault. Adjusted Arm rest safety switch to ensure wasn't causing intermittent fault.	
23/09/2024 07:58 AM	Work Order - Repair	M10411 - Complaint: a/c not working. Cause: schreader valve leaking causing loss of gas. Correction: serviced system and recharged. Replaced schreader valve.	1394.00
14/11/2024 11:05 AM	Work Order - Repair	M10686 - machine had a damaged fire extinguisher, delivered a new replacement 1.0kg fire extinguisher to site.	1394.00
12/12/2024 03:48 PM	Work Order - 1000 Hour Service	M10756 - 1000 Hour Service	1394.00
12/12/2024 03:51 PM	Work Order - Repair	M10768 - 4 in 1 bucket locating bolt has fallen out. Source new parts, travel to site, install	1394.00
08/01/2025 12:58 PM	Work Order - Repair	M10910 - Growers attended site, replaced two fuses for fan control and radio.,	1394.00
04/03/2025 02:37 PM	Work Order - Repair	M11196 - Replace tracks, replace light switch, replace solenoid	
20/03/2025 02:28 PM	Work Order - 250 Hour Service	M11479 - 250 Hour Service. Final Drive oil change only. Mobile mobilube hd multipurpose gear oil 80w-90 [or equivalent]	1677.00
05/06/2025 01:49 PM	Work Order - Repair	M11481 - travel to site identify faulty fitting go and get one from Force, return to site and fit. Tested and working.	
10/11/2025 01:35 PM	Work Order - Repair	Diagnose and repair A/C fault, YH418 - New Holland C327 Positrack, JAF0C327CPM426813. Works to be completed at Growers Workshop.	