



Atlas Industrial Holdings Pty Ltd
 Email: accounts@atlasholdings.com.au
 Phone: 1800 784 453
 ABN: 55 154 445 137
 Address: 526 Benetook Ave, Mildura Vic 3500

Service History

Date Generated: 18/03/2026 04:16 PM

Equipment Details

| | | | |
|------------------------------|---|---------------|-------------|
| Equipment Number | YH430 | Make: | New Holland |
| Equipment Description | New Holland C327 - 75 Hp Track Skid Steer | Model: | C327 |
| Serial Number | JAF0C327KPM426730 | | |

| Date | Type | Description | Last Meter Reading |
|---------------------|-------------------------------|--|--------------------|
| 18/09/2023 01:40 PM | Work Order - Repair | M8071 - machine build up | 9.00 |
| 20/09/2023 10:09 AM | Work Order - Repair | M8147 - Replaced hydraulic fitting | 15.00 |
| 09/11/2023 04:30 PM | Work Order - Repair | M8598 - travel to site. Checked over machine annd checked hours. | |
| 17/11/2023 03:50 PM | Work Order - Repair | M8554 - Travel to Ronco, strip alternator bracket of Broken down machine, Travel to customer site, remove and replace broken bolt and alternator bracket. Refit and test, take bracket and broken parts to Ronco for warranty claim to be processed. | |
| 28/11/2023 04:12 PM | Work Order - Repair | M8681 - Drove to site. Waited for escort. Got escorted to machine. Found f4 in1 ucket hoses rubbed through. Removed hydraulic hoses. Waited for escort. Got escorted off site. Took hoses to force hydraulics. Returned to site with new hoses. Waited for escort to machine. Got escorted to machine. Fitted new hoses and checked oil level. Ok. Waite for escort. Got escorted off site. Returned to workshop | |
| 07/12/2023 03:05 PM | Work Order - Repair | M8805 - Drive to site. Find blower fan failed. Drove to ronco motors to pinch blower fan off other machine. Remove fan from other machine. Return to site. Fit new blower fan. Fan not working correctly. Find wiring has a bad earth. Fix earth issue. Refit panels. Leave site to ronco motors. Drop off dodgy fan. Return to workshop. | |
| 10/01/2024 03:45 PM | Work Order - 50 Hour Service | M8797 - 50 Hour Service. New Purchase. | |
| 31/05/2024 07:50 AM | Work Order - Repair | M9289 - inspect a/c | |
| 08/07/2024 08:21 AM | Work Order - Repair | M9413 - repair oil leaks | 459.00 |
| 08/07/2024 08:49 AM | Work Order - 500 Hour Service | M9777 - 500 Hour Service | |
| 08/07/2024 09:31 AM | Work Order - Repair | M9798 - Complaint: reverse cameras not working. Cause: wiring to reverse cameras. Correction: traveled to site. Inspected wiring and repaired. Tested for correct operation. | |

| Date | Type | Description | Last Meter Reading |
|---------------------|--|--|--------------------|
| 15/07/2024 09:34 AM | Work Order - Repair | M9989 - Complaint: Low power. Cause: fuel blockage. Correction: mtraced fault and found fuel blockage at in line filter. Removed and replaced filter. Tested for correct oepration. | |
| 27/08/2024 11:40 AM | Work Order - Repair | M10267 - Complaint: uhf not working Cause: electrical connections. Correction: travel to site. Inspected and repaired power connections. Inspected fast mode not working. Lifted cab and cleaned out belly plates. Inspected wiring. Reseated wiring. Tested ok. | |
| 16/09/2024 10:38 AM | Work Order - Repair | M10311 - complaint: hi lo speed not working correctly. Camera not working | |
| 24/09/2024 02:19 PM | Work Order - Repair | M10447 - Complaint: track fell off machine. Cause: unknown. Correction: travel to site. Jacked up machine and reinstalled track. | |
| 16/04/2025 07:48 AM | Work Order - Repair | M11341 - Replace tracks due to wear, replace serpentine belt | 1273.00 |
| 24/04/2025 11:13 AM | Work Order - Miscellaneous Scheduled Service | M11115 - 1000hr service | 1273.00 |
| 29/07/2025 01:36 PM | Work Order - Repair | M12315 - REPLACE WIPER ARM | |
| 17/11/2025 10:15 AM | Work Order - Breakdown | Re-install track, check adjustment of both tracks. Attend site at 28 Jindalee Road, Coomealla, Site Contact Deep - 0469 330 190. MACHINE - YH430, NEW HOLLAND C327 POSITRACK, JAF0C327KPM426730 | |
| 17/11/2025 10:37 AM | Work Order - Breakdown | Tracks repeatedly dislodging : replace worn components - reinstall and test | |