

Search Work Orders - All History(All work types)

Assigned To	Scheduled Date	WO #	Entity Name	Problem Description	Location	Status Date	Type
Marcos Erivez	8/27/2026	21781	HT34	charged batteries, jumpstarted checked over for cleaning and inspection for sale	26-1014	8/24/2026	Non PM
John Kiley	7/12/2026	21513	HT34	lights on dash/ diff lock issues/ button got switched	26-1014	8/19/2026	Non PM
Anthony Magri	6/28/2026	21431	HT34	troubleshoot engine code ----- Ht34 down for like 3 weeks ECU code on Requested By: Francisco Moreno Requested Date: 5/19/2026 1:45:54 PM From: HCSS Field	26-1014	7/23/2026	Non PM
Anthony Magri	6/18/2026	21360	HT34	hyd leak	26-1014	6/25/2026	Non PM
John Kiley	6/15/2026	21332	HT34	bed upper pins not getting greased/manually use grease gun/zirks ? plugged and damage	26-1014	6/25/2026	Non PM
Michael McCarthy	5/7/2026	21055	HT34	jump start and get unit running for the afternoon	26-1014	6/15/2026	Non PM
John Kiley, Michael McCarthy	3/20/2026	20545	HT34	Replace new hydraulic line under cab. Re-installed drive shaft & get unit ready for transport. RR drive line. Got drop box, bolted up, U joint & bolts, installed. Also got one drive line bolt started, need to rotate to complete drive-line install & test unit. Drop box & U joint issues. Prep unit for new parts & set up for install. Still need parts. Worked on transmission and drive line issues. Inspect and get parts. Dove line &	26-1014	6/12/2026	Non PM
Anthony Magri	5/7/2026	21071	HT34	troubleshoot drop box/ drain oil troubleshoot air leak/ test run troubleshoot loss of power	26-1014	5/19/2026	Non PM
Marcos Erivez	4/26/2026	20960	HT34	get machine ready to top off fluid on brake cooling	26-1014	5/6/2026	Non PM
Oscar Alvarez	2/6/2026	19385	HT34	250 SVC	26-1014	2/12/2026	PM
Anthony Magri	11/24/2025	18944	HT34	RR tail gate cable	26-1014	12/4/2025	Non PM
Stormy Wetherington	5/22/2025	17900	HT34	Charge A/C From: Inspections Recorder: Emanuel Lecona Galvez Job: 24-1001 Reported: 4/23/2025 Form: Claystone Equipment Inspection (Espanol) Item: Acondiciona dor de airo	26-1014	6/13/2025	Non PM
Anthony Magri	5/2/2025	17671	HT34	Service	26-1014	5/22/2025	PM
Anthony Magri, Noel Pavon	12/26/2024	15493	HT34	Troubleshoot exhaust system From: Inspections Recorder: Tomas Sanchez Job: 24-1001 Reported: 12/5/2024 Form: Claystone Equipment Inspection Item: Exhaust System Note: broke hose	26-1014	5/15/2025	Non PM
Anthony Magri, Noel Pavon	11/1/2024	15106	HT34	Cooling	26-1014	3/11/2025	Non PM
Anthony Magri, Noel Pavon	11/1/2024	15101	HT34	Service	26-1014	3/11/2025	PM
Anthony Magri, Noel Pavon	8/22/2024	14400	HT34	Check exhaust.	26-1014	11/16/2024	Non PM

Noel Pavon, Pedro Suarez, Stormy Wetherington, Troy Wetherington	1/25/2024	11772	RHT VOLVO	1st A60H serial # is VCE0A60HK00340050 Claystone unit # should be RHT27 (current Rango unit # 12603 stenciled in red on truck) PS 2.0 FE 2nd A60H serial # is VCE0A60HK00340062 Claystone unit # should be RHT28 (current Rango unit # 12605 stenciled in red on truck) PS 2.0 FE TW/SW 4.8 Start 3rd A60H serial # is VCE0A60HE00340105 Claystone unit # should be RHT29 (current Rango unit # 12607 stenciled in red on truck) NP 5.0 PS 1.5 FE 4th A60H serial # is VCE0A60HE00340115 Claystone unit # should be RHT30 (current Rango unit # 12612 stenciled in red on truck) NP 2.5 PS 2.0 FE 5th A60H serial # is VCE0A60HK00340143 Claystone unit # should be RHT31 (current Rango unit # 12614 stenciled in red on truck) NP 1.5 PS 1.0 FE TW/SW 6.8 Start 6th A60H serial # is VCE0A60HJ00350009 Claystone unit # should be RHT32 (current Rango unit # 12618 stenciled in red on truck) PS 2.0 FE TW/SW 4.8 Start NP 1.0 tire PSI 7th A60H serial # is VCE0A60HA00350029 Claystone unit # should be RHT33 (current Rango unit # 12619 stenciled in red on truck) PS 2.5 FE SW 1.0 Mirror 8th A60H serial # is VCE0A60HA00350032 Claystone unit # should be RHT34 (current Rango unit # 12622 stenciled in red on truck) PS 2.0 FE TW/SW 4.8 Start 9th A60H serial # is VCE0A60HJ00350053 Claystone unit # should be RHT35 (current Rango unit # 12629 stenciled in red on truck) PS 2.0 FE 10th A60H serial # is VCE0A60HJ00350074 Claystone unit #		11/16/2024	Non PM
Anthony Magri, Noel Pavon	8/30/2024	14558	HT34	R&R Fuel filters, test run , top off fuel. Fuel issus , metal in fuel	26-1014	11/16/2024	Non PM
Anthony Magri, Noel Pavon	8/30/2024	14552	HT34	RR wiring	26-1014	11/16/2024	Non PM
Noel Pavon	4/25/2024	12434	HT34	Repair wipers.	26-1014	5/6/2024	Non PM

Noel Pavon	3/21/2024	12161	HT34	Troubleshoot low power. Regen. Repair exh leak. Ht34 has this code Requested By: Francisco Moreno Requested Date: 3/13/2024 12:22:06 PM From: HCSS Field ----- Ht34 exhaust is broke Requested By: Francisco Moreno Requested Date: 3/13/2024 1:23:47 PM From: HCSS Field	26-1014	4/1/2024	Non PM
Alfonso Rodriguez-Rodriguez	2/29/2024	11992	HT34	500 hour service.	26-1014	3/4/2024	PM
Noel Pavon	2/15/2024	11909	HT34	R&R fuel filter and start.	26-1014	2/26/2024	Non PM
Pedro Suarez	2/9/2024	11896	RHT34	Sticker. Air up 2 tires.	24-1001	2/26/2024	Non PM

Filter:
Wednesday, September 9, 2026