

Search Work Orders - All History(All work types)

Assigned To	Scheduled Date	WO #	Entity Name	Problem Description	Location	Status Date	Type
Anthony Magri	9/3/2026	21828	HT31	troubleshoot no start	26-1008	8/31/2026	Non PM
John Kiley, Anthony Magri, Michael M	4/16/2026	20763	HT31	Move to east yard Move to yard by shop Troubleshoot codes/ leaks/test run	26-1008	5/6/2026	Non PM
John Kiley	2/12/2026	20436	HT31	Broken mount on transmission, go to aurora, remove broken bolts for mounts & try to put back on . but nothing lining up. Stripped bolts for drive shaft try to remove drive shaft. Go to Aurora Job/Lorenzo. Hydraulic leak from hydraulic pump missing. Top mount bolt, find matching bolt tighten pump up to seal leak.	26-1008	3/19/2026	Non PM
Oscar Alvarez, Francisco Navejas	2/26/2026	20499	HT31	Changed fuel filters.	26-1008	3/10/2026	Non PM
Oscar Alvarez	2/6/2026	19384	HT31	250 SVC	26-1008	2/12/2026	PM
Jose Gallegos	12/18/2025	19082	HT31	Power washing haul truck. and cleaning windows.	26-1008	2/9/2026	Non PM
Anthony Magri	5/2/2025	17669	HT31	Service	26-1008	5/22/2025	Non PM
Anthony Magri	10/18/2024	14972	HT31	R&R wiring	26-1008	11/16/2024	Non PM
Noel Pavon, Pedro Suarez, Stormy Wetherington, Troy Wetherington	1/25/2024	11772	RHT VOLVO	1st A60H serial # is VCE0A60HK00340050 Claystone unit # should be RHT27 (current Rango unit # 12603 stenciled in red on truck) PS 2.0 FE 2nd A60H serial # is VCE0A60HK00340062 Claystone unit # should be RHT28 (current Rango unit # 12605 stenciled in red on truck) PS 2.0 FE TW/SW 4.8 Start 3rd A60H serial # is VCE0A60HE00340105 Claystone unit # should be RHT29 (current Rango unit # 12607 stenciled in red on truck) NP 5.0 PS 1.5 FE 4th A60H serial # is VCE0A60HE00340115 Claystone unit # should be RHT30 (current Rango unit # 12612 stenciled in red on truck) NP 2.5 PS 2.0 FE 5Th A60H serial # is VCE0A60HK00340143 Claystone unit # should be RHT31 (current Rango unit # 12614 stenciled in red on truck) NP 1.5 PS 1.0 FE TW/SW 6.8 Start 6th A60H serial # is VCE0A60HJ00350009 Claystone unit # should be RHT32 (current Rango unit # 12618 stenciled in red on truck) PS 2.0 FE		11/16/2024	Non PM

				TW/SW 4.8 Start NP 1.0 tire PSI 7th A60H serial # is VCE0A60HA00350029 Claystone unit # should be RHT33 (current Rango unit # 12619 stenciled in red on truck) PS 2.5 FE SW 1.0 Mirror 8th A60H serial # is VCE0A60HA00350032 Claystone unit # should be RHT34 (current Rango unit # 12622 stenciled in red on truck) PS 2.0 FE TW/SW 4.8 Start 9th A60H serial # is VCE0A60HJ00350053 Claystone unit # should be RHT35 (current Rango unit # 12629 stenciled in red on truck) PS 2.0 FE 10th A60H serial # is VCE0A60HJ00350074 Claystone unit # should be RHT36 (current Rango unit # 12640 stenciled in red on truck) PS 1.5 FE TW/SW 4.8 Start TW 1.0 Tailgate pin.			
Anthony Magri, Noel Pavon	10/11/2024	14909	HT31	RR mirror housing	26-1008	11/16/2024	Non PM
Anthony Magri, Noel Pavon	9/27/2024	14784	HT31	R&R coolant line Troubleshoot coolant leak	26-1008	11/16/2024	Non PM
Anthony Magri, Emanuel Munoz Alcala, Noel Pavon, Stormy Wetherington	10/3/2024	14145	HT31	Troubleshoot Trans overheat	26-1008	11/2/2024	Non PM
Anthony Magri, Noel Pavon	7/11/2024	14021	HT31	Tailgate mount broke. remove tailgate.	26-1008	11/2/2024	Non PM
Anthony Magri, Noel Pavon	7/11/2024	14013	HT31	Repair exhaust piping and clamps. R&R air cleaner from HT33	26-1008	11/2/2024	Non PM
Anthony Magri, Noel Pavon	6/27/2024	13962	HT31	Replace radiator and HYD fan from HT33. Ht31 transmission oil level high code on Requested By: Francisco Moreno Requested Date: 3/12/2024 11:27:14 AM From: HCSS Field	26-1008	8/15/2024	Non PM
Noel Pavon	5/2/2024	12502	HT31	No power. Hood stuck. Replace switch. ----- Ht31 wipers don't work Requested By: Francisco Moreno Requested Date: 4/19/2024 8:24:59 AM From: HCSS Field	26-1008	7/22/2024	Non PM
Noel Pavon	5/16/2024	12646	HT31	Repair coolant leak.	26-1008	6/3/2024	Non PM

		12650	HT31	Ht31 He came very close to the dozer from the rear and the dozer reversed and hit the truck on the left side fender. ETI Repaired. Requested By: Francisco Moreno Requested Date: 3/11/2024 6:31:07 AM From: HCSS Field.	26-1008	5/13/2024	Non PM
Alfonso Rodriguez-Rodriguez	5/9/2024	12559	HT31	250 hour service.	26-1008	5/13/2024	Non PM
Noel Pavon	4/18/2024	12404	HT31	Troubleshoot SCR DEF system.	26-1008	5/6/2024	Non PM
Pedro Suarez	2/22/2024	11961	HT31	Sticker.	26-1008	3/4/2024	Non PM
Pedro Suarez	2/9/2024	11895	RHT31	Sticker.	24-1001	2/26/2024	Non PM

Filter:

Wednesday, September 9, 2026