

Search Work Orders - All History(All work types)

Assigned To	Scheduled Date	WO #	Entity Name	Problem Description	Location	Status Date	Type
Pedro Suarez	8/27/2026	21770	HT28	jump start replace oring of engine oil hose	26-1008	8/24/2026	Non PM
John Kiley	6/25/2026	21417	HT28	leaking hyd for brakes , remove line and set new line, in stall new line test run blew another line, get from 33 remove and replace a second line test run and move to yard	26-1008	7/23/2026	Non PM
Benjaman Sands	5/8/2026	21109	HT28	high brake pressure ECU issues	26-1008	6/22/2026	Non PM
John Kiley	4/30/2026	21000	HT28	take cab floor out remove bad line go to 4 rivers to get made	26-1008	6/22/2026	Non PM
Sebastian Navejas, Alfonso Rodriguez-Rodriguez	5/7/2026	21095	HT28	fill hyd oil	26-1008	5/19/2026	Non PM
Anthony Magri	4/23/2026	20919	HT28	installed solenoid	26-1008	5/6/2026	Non PM
Anthony Magri	4/6/2026	20766	HT28	pick up parts RR wiring RR Brake pump wiring	26-1008	5/6/2026	Non PM
Anthony Magri, Michael McCarthy	3/20/2026	20582	HT28	RR harness, rear machine harness. Close all up, prep for transport, still needs harness repairs.	26-1008	5/5/2026	Non PM
Alfonso Rodriguez-Rodriguez	12/4/2025	19000	HT28	250 SVC	26-1008	1/8/2026	PM
Anthony Magri, Noel Pavon	11/1/2024	15107	HT28	Cooling	26-1008	3/11/2025	Non PM
Pedro Suarez	12/13/2024	15394	HT28	Replace 2 light bulbs From: Inspections Recorder: Carlos Quiroz Martinez Job: 24-1001 Reported: 12/9/2024 Form: Claystone Equipment Inspection (Espanol) Item: Luces Note: Tengo dos luces fundidas Recorder: Carlos Quiroz Martinez Job: 24-1001 Reported: 11/19/2024 Form: Claystone Equipment Inspection (Espanol) Item: Luces Note: Las luces altas no funcionan	26-1008	3/11/2025	Non PM

Noel Pavon, Pedro Suarez, Stormy Wetherington, Troy Wetherington	1/25/2024	11772	RHT VOLVO	1st A60H serial # is VCE0A60HK00340050 Claystone unit # should be RHT27 (current Rango unit # 12603 stenciled in red on truck) PS 2.0 FE 2nd A60H serial # is VCE0A60HK00340062 Claystone unit # should be RHT28 (current Rango unit # 12605 stenciled in red on truck) PS 2.0 FE TW/SW 4.8 Start 3rd A60H serial # is VCE0A60HE00340105 Claystone unit # should be RHT29 (current Rango unit # 12607 stenciled in red on truck) NP 5.0 PS 1.5 FE 4th A60H serial # is VCE0A60HE00340115 Claystone unit # should be RHT30 (current Rango unit # 12612 stenciled in red on truck) NP 2.5 PS 2.0 FE 5th A60H serial # is VCE0A60HK00340143 Claystone unit # should be RHT31 (current Rango unit # 12614 stenciled in red on truck) NP 1.5 PS 1.0 FE TW/SW 6.8 Start 6th A60H serial # is VCE0A60HJ00350009 Claystone unit # should be RHT32 (current Rango unit # 12618 stenciled in red on truck) PS 2.0 FE TW/SW 4.8 Start NP 1.0 tire PSI 7th A60H serial # is VCE0A60HA00350029 Claystone unit # should be RHT33 (current Rango unit # 12619 stenciled in red on truck) PS 2.5 FE SW 1.0 Mirror 8th A60H serial # is	11/16/2024	Non PM
--	-----------	-------	-----------	---	------------	--------

				out A60H serial # is VCE0A60HA00350032 Claystone unit # should be RHT34 (current Rango unit # 12622 stenciled in red on truck) PS 2.0 FE TW/SW 4.8 Start 9th A60H serial # is VCE0A60HJ00350053 Claystone unit # should be RHT35 (current Rango unit # 12629 stenciled in red on truck) PS 2.0 FE 10th A60H serial # is VCE0A60HJ00350074 Claystone unit # should be RHT36 (current Rango unit # 12640 stenciled in red on truck) PS 1.5 FE TW/SW 4.8 Start TW 1.0 Tailgate pin.			
Anthony Magri, Noel Pavon	10/4/2024	14827	HT28	Assess blown drive damage	26-1008	11/16/2024	Non PM
Noel Pavon	9/19/2024	14683	HT28	Repair hyd leak and line broke.	26-1008	11/16/2024	Non PM
Anthony Magri, Noel Pavon, Stormy Wetherington	9/19/2024	14650	HT28	Recharge A/C	26-1008	11/16/2024	Non PM
Anthony Magri, Noel Pavon	9/6/2024	14607	HT28	Clean out cab	26-1008	11/16/2024	Non PM
Anthony Magri, Noel Pavon	8/30/2024	14557	HT28	Trans lines RR coolant res	26-1008	11/16/2024	Non PM
Anthony Magri, Noel Pavon	8/30/2024	14556	HT28	Update drop box	26-1008	11/16/2024	Non PM
Noel Pavon	4/12/2024	12316	HT28	Water in fuel.	26-1008	4/29/2024	Non PM
Noel Pavon	4/12/2024	12312	HT28	Repair drop case mount bolts loose.	26-1008	4/29/2024	Non PM
Noel Pavon	3/21/2024	12153	HT28	Trouble shoot not going into gear. shut off all switches and test. Okay.	26-1008	4/1/2024	Non PM
Pedro Suarez	3/14/2024	12122	HT28	Replace fuse for radio.	26-1008	4/1/2024	Non PM
Noel Pavon	2/15/2024	11913	HT28	Repair horn.	26-1008	2/26/2024	Non PM
Noel Pavon	2/15/2024	11908	RHT28	Repair mirror. Weld handrail right side. From: Inspections Recorder: Ramiro Alvarez Cota Job: 24-1001 Reported: 2/1/2024 Form: Claystone Equipment Inspection (Espanol) Item: Otros Note:	24-1001	2/26/2024	Non PM
Pedro Suarez	2/9/2024	11897	RHT28	Sticker. Air up 3 tires.	24-1001	2/26/2024	Non PM