

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
9123	12359	Replace seat belt	30/12/1899	3691	
	12194	Radio not operating. Checked out radio, checked wires, removed radio had a rattle in it. Decided radio was u/s came back to G&G, got a new radio and went back to fit it.	15/07/2003	16	
	12195	Trans failure. Inspected oil and filter removed by Danny. Checked pump pressure found to be okay. Removed cutting edges for helped load machine onto float. Send back G&G Parramatta for trans removal.	28/07/2003	100	
	12196	Air line clamp broken. Removed side guards. Removed old clamp and fitted new clamp. Refitted guards.	12/08/2003	143	
	12197	Tranny filter light coming on. Changed tranny filter. Removed and cleaned filter switch. Operated machine found light to not come on.	13/08/2003	150	
	12198	250HR service.	23/08/2003	233	PM
	12199	500 service.	3/11/2003		
	12200	Straighten steps to cab take SOS for 500HR service.	5/11/2003	515	PM
	12201	Tighten frame to scraper bar from bolts front and rear as well as rear diff housing o-bolts.	7/11/2003	535	
	12202	Cut off a/c drain hoses, valves and adjust some scraper bars.	21/11/2003		
	12203	Oil leak under cab. Hose rubbing on tranny case. Inspected leak found to be coming from steering hose under cab. Removed hose t/ad ENZEC make new hose. Refitted and topped up oil. Tested found to be good.	9/12/2003		
	12205	Str pilot hose blown, repair.	9/12/2003	683	
	12206	Water pump leaking.	11/12/2003		
	12207	Water pump leaking. Drained coolant, changed water pump and refilled coolant. Tested machine, found to be okay.	17/12/2003	718	
	12208	250HR service.	19/12/2003	738	PM
	12209	Repair vandalism, rewire new cd, and install roof parts, reposition f/light.	30/01/2004	882	
	12210	1000HR service, straighten out left step to cab.	17/02/2004		PM
	12211	Tighten bolts on grill order others, check trans screen, debris.	19/02/2004	996	
	12212	Trans light coming on, inspect, and run. Check over repairs.	4/03/2004	1011	
	12213	Change trans filter, light now off. Run test paint light bracket. Trans light coming after returned from G&G.	5/03/2004	1019	

Asset History Report

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	12214	Install new fuel primary switch on engine.	8/03/2004	1032	
	12215	Shimmed and tightened l/h push arm bolts. Fitted bolt back into front diff.	20/03/2004	1110	
	12216	Adjust scraper bars.	23/03/2004	1124	
	12217	Replaced all four locks on engine bay doors and adjusted.	24/03/2004		
	12218	Refit loctite bolts for armrest and seat.	27/03/2004	1158	
	12219	Hard steering, turning more one-way than the other. checked steering system. Steering wheel adjustment not centered from when cab was rmved. Re-centered steering wheel & tested, OK. Found steering wheel height adjustment mechanism to have failed.	21/04/2004	1246	
	12220	Removed old steering column and fitted a new one due to steering wheel height adjustment not locking up. Removed seat cover found fitting to be leaking for air suspension. Replaced fitting and hoses.	28/04/2004		
	12221	Tighten rear wheel bearing; cover plates on scraper bar frame, leaking.	28/04/2004	1450	
	12222	500HR service on all S.O.S.	3/06/2004	1490	PM
	12223	Tighten scraper bar.	4/08/2004		
	12224	Fit scraper bars.	6/08/2004		
	12225	1000HR service.	5/09/2004		PM
	12226	250HR service.	9/10/2004	2268	PM
	12227	Fitted new hoses (blade tilt right hand side). Installed guards, test machine.	20/10/2004		
	12228	500HR service.	4/11/2004	2500	PM
	12229	Fit injector fuel, rail hose and bleed off valve.	16/11/2004		
	12230	Change cleaner bars.	10/12/2004		
	12231	Remove, refit and adjust all compactor wheel scraper bars.	12/12/2004		
	12232	Welded sheep feet on compactor wheels and adjusted and replaced scraper bars.	22/12/2004		
	12233	Change 6 cleaner bars.	2/02/2005	4801	
	12234	1000HR service	14/02/2005		PM
	12235	Repair seat, replace scraper bars.	18/02/2005		

Asset History Report

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	12236	250HR service.	2/03/2005		PM
	12237	Check 825 shutdown problems.	10/03/2005		
	12239	Investigate engine shut down electrical fault (clean and tighten emergency stop switches).	17/03/2005		
	12240	500HR service.	14/04/2005	3544	PM
	12241	Weld on new sheeps feet. Investigate electrical fault.	15/04/2005		
	12242	Weld on foot to position 4 wheel. Inspected intermittent shutdown fault (only did once).	16/04/2005		
	12243	Welded on pad on wheels, fitted 2 new wheel scraper edges.	22/04/2005		
	12244	Replace broken cab panels, refit 2 way console bearings. Valve set, fit new steps.	12/08/2005	4131	
	12245	Cut and fit rear cleaner bars.	18/08/2005	4131	
	12246	Move machine drop off point, unload machine, put cutting edges on. Service check machine and perform condition reports.	29/08/2005	4132	
	12247	250HR service.	14/09/2005		PM
	12248	Remove and install new grease line for blade lift so able to grease from ground.	16/09/2005	4244	
	12249	Accident, punched hole in bottom of trans drop box.	29/09/2005		
	12250	Damaged transmission transfer box . Release park brake and lift blade and move machine. Patch up hole in transfer box to load onto truck. To go to Westrac Grafton for transfer case replacement.	29/09/2005	4327	
	12252	500HR service.	31/10/2005	4501	PM
	12254	250HR service and new air cleaner.	13/12/2005	4771	PM
	12255	Right hand arm rest support failure. Remove blade control GP and remove seat. Raining at time of removing seat. Get backhoe to lift out of machine and into GTE. Disassemble seat to workshop to repair.	16/12/2005		
	12256	Assemble seat with new parts. Install sent into machine.	17/12/2005	4771	
	12258	New fuel line made by Pirtek, pin hole in hose allowed fuel to bleed back. Hole in fuel line, replace line with Pirtek.	3/01/2006	4771	
	12259	Look/inspect for oil leak from middle of machine. Unknown leak.	14/01/2006	4830	
	12260	Repair radio and uhf radio.	17/01/2006	4848	

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	12261	Weld axle housing assembly	19/01/2006		
	12262	Repair and replace rear work lights. Remove blade lift cylinder fit new bearings.	23/01/2006	4856	
	12264	Prepare for transport of site. rmve blade lift cylinder assembly. Failed support bearing. rmve & install starter motor, rmve blade lift cylinder, wash inside & out. rmve & install blade cylinder. Rebush. Clean machine. rmve cutting edges.	31/01/2006		
	70690	PS50918 Install New Valve Cover Ht.shield	15/05/2006		OEM Recall
	12265	500HR service	19/06/2006	5500	PM
	12266	R+R heater hoses	26/06/2006	5527	
	12267	R+R fuel line from filter to rear of cylinder head- NPR up	26/06/2006	5527	
	12268	Adjust scraper bars	8/07/2006	5612	
	12269	Beacon and flood lamp R+R	25/07/2006	5681	
	12270	Weld up mirror bracket where trimble aerial mounts	8/08/2006	5700	
	12271	Re-tension cab bolts replace missing 1s	1/09/2006	5909	
	12272	R+R door locks in the engine cabinet doors	2/09/2006	5912	
	12273	Replace hoses on trans oil cooler	12/10/2006	6129	
	12274	Tensioned bolts on belly guards	25/10/2006	6213	
	12275	Replace engine drive belt	31/10/2006	6247	
	12276	Replace broken flood lamp	3/11/2006	6266	
	12277	Valve adjustment	8/11/2006		
	12278	Weld on 1x new compactor tip	21/11/2006	6349	
	12279	R+R fuel cap	22/11/2006	6353	
	12280	R+R blade tilt hoses- genuine cat hoses	30/11/2006	6408	
	12281	Replace UHF aerial end	18/12/2006	6493	
	12282	2000HR service, c/o o-ring on suction for trans pump	7/02/2008		PM

Asset History Report

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	12283	Carry out valve adjustment	11/02/2008	8002	
	12284	Fit fuel sender, drain front and rear diff and final drives	11/02/2008	8002	
	12285	Diagnose oil leak, c/o cab roof insulation (head-liner)	1/03/2008	8107	
	12286	Inspector oil leak	19/03/2008	8191	
	12287	Repair oil leaks on compactor remove cabin remove hoses (rubbed thru)	25/03/2008		
	12288	Install new hoses onto compactor reseal pump compensation valve install cann wash and test - ok	27/03/2008		
	12289	Add 30L coolant/turn heater taps off - leak under cab	31/03/2008	8224	
	12290	250HR service	1/04/2008	8245	PM
	12291	Repair radio wiring - replace am/fm radio, repair horn wiring, repair implement control	7/04/2008	8029	
	12292	Broken blade stabilizer arm, remove clean up re-weld and replace on machine	8/05/2008		
	12293	Fit new bucket on front tilt ram, repair seat and control slide assy in cab, clean cab/windows, fix UHF cable	20/05/2008	8542	
	12294	Replace steering lock unit pins, replace seat cushion base	28/05/2008	8485	
	12295	500HR service	29/05/2008	8499	PM
	12296	Replace coolant hose elbow, top pipe to regulator housing	17/06/2008	8583	
	12297	Replace trans cooler hoses, replace fuel return hose on engine to filter return - upd hose, replace coolant hose to header tank	24/06/2008	8634	
	12298	Rear diff housing / axle housing has cracked on left hand side. Upd housing available on s / letter PS51006. remove all rear scraper bars, remove belly guard and side panels	17/07/2008	8278	
	12299	Removed wheels when crane arrived. Remove driveshaft and grease lines, unbolt trunnions from chassis. Remove rear axle after crane arrives.	18/07/2008		
	12300	Remove front and rear support trunnions, remove and store differential.	21/07/2008		
	12301	Install both final drive / wheel ends unto housing	24/07/2008		
	12302	Change out trunnion and joint bolts in rear axle as per service manual install diff centre. Replace pinion bolts	25/07/2008		
	12303	Install axle, attach front and rear trunnions. Grease lines, driveshaft, install cleaner bar brackets to axle housing. Prepare to fit wheels	28/07/2008		
	12304	Refit rear diff assembly machine fit wheels to compactor clean up all cleaner bar pins/nuts etc, remove all cotter pins drill out broken belly guard bolt	29/07/2008		

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	12305	Install and adjust all rear cleaner bars to rear check diff and final drive levels. All ok	30/07/2008		
	12306	Largo oil leak under cabin caused by steering hose on L/H cylinder had blown	2/09/2008	8850	
	12307	Carried out 250HR service	13/10/2008		PM
	12308	Carried out 1000HR service	17/10/2008		PM
	12309	Clean left right wheel and remove x4 scraper bars. Clean out dirt/mud. Refit and adjust scraper bars. Remove left hand steps to cabin and dismantle. Assemble and fit new steps onto machine	29/12/2008	1553	
	12310	Weld broken and yoke came loose. Air arc gauge weld and grind smooth. Heat and weld with 70TI electrode.	16/01/2009	9500	
	12312	Removed arm rest seat pan and fitted bolt into spare hole and tightened tied rear section of arm rest	30/01/2009	9597	
	12313	Remove push arms, tilt cylinder & stabilizer arm off the front, remove scraper support for hub, pack onto pallets	24/03/2009		
	12314	Remove belly guards & clean, remove panel & inspect diesel leak, was leaking from breather, R&R LH eng covers & tighten trans cooler hoses, remove RH covers & inspect oil leak from tell tale hole in pump, found missing fasteners on diff mounts	25/03/2009		
	12315	Remove bushes from blade, remove & fit new bushes in blade tilt ram, disassemble LH hub support found retaining plates bent & bolts loose, clean hub supports for assembly, helicoil hub carrier, remove bushes from blade link mounts	30/03/2009		
	12316	FIT NEW FIRE EXTINGUISHER	21/04/2009	9047	
	12317	250HR SERVICE	29/05/2009	9244	PM
	12318	REPLACE CYL HEAD RETURN FUEL HOSE ON FRONT OF ENGINE	30/05/2009	9254	
	12319	ENG RPM ERRATIC REPLACE TPS O.K	18/06/2009	9346	
	12320	REPLACE A/C SWITCH IN CAB	10/07/2009	9460	
	12321	500HR SERVICE	21/07/2009	9490	PM
	12322	TIGHTEN ALL HYD SUCTION HOSES AND RESEAL ORING AT PUMP	18/08/2009	9613	
	12323	Pins and bearings worn out in steering cylinders. Remover and replaced seals and bearing in cylinder and rod. Installed cylinder, re-seal and connected hoses.	30/09/2009		
	12324	Resealed combination valve on hydraulic pump.	30/09/2009		
	12326	BLADE TILT CYLINDER SNAPPED CYLINDER REMOVE MACHINE AND WELD OVERNIGHT TO RUN DOWNTIME 4hrs	4/11/2009	9696	
	12327	250HR service	10/11/2009		PM

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	12328	Replace, flash and program CMS monitor.	4/12/2009	9888	
	12329	FIT NEW EMS PANEL FLASH AND REALIGN hr METER AFTER MODULE FAILURE HASTINGS DOC 0B09254	7/12/2009	9888	
	12330	TRANS TEMP SWITCH FITTED TO REPAIR LIGHT ON DASH PROBLEM	15/12/2009	9916	
	12358	2000HR service + mech check	7/01/2010	9985	PM
	12331	BLOWN HOSE AT TRACTOR END OF BLADE BRACE FOR BLADE TILT CYLINDER REMOVE AND MAKE NEW 2hrS DOWNTIME	11/01/2010	9990	
	12348	Fit new seat belt	15/01/2010	2690	
	12349	250HR service with mech check	22/01/2010	2746	PM
	12332	Replace blade lift pipe under fuel tank	29/01/2010	10100	
	12333	Replace cab mounts	30/01/2010	10104	
	12356	Repair damaged RHS trans guard	5/02/2010	10112	
	12334	250HR Service and mech check	25/03/2010	10248	PM
	12346	1000HR service and full mech check	7/04/2010	3000	PM
	12335	REPLACE SMASHED TRANSPORT FLASHING LIGHT WITH HELLA DURARAY	14/04/2010	9010	
	12351	Fit new LHS seat bracket to repair broken backrest	28/04/2010	3096	
	12336	500HR service and mech check	18/05/2010	10500	PM
	12350	Repair broken belly guard bolts	27/05/2010	3230	
	12352	250HR service and mech check	28/05/2010	3245	PM
	12337	Engine blade miss find no 3 inject spring broken	23/06/2010	10671	
	12360	ENGINE MISS FIND NO3 INJECTOR SPRING BROKEN FIND ALL PIECES AND REPLACE WITH REMAN UNIT RESET HEIGHT TO RUN DOWNTIME 12hrs	23/06/2010	10671	
	12338	Replace no 3 injector with remain after failure	24/06/2010	10671	
	12354	250HR service and mech check	2/07/2010	10750	PM
	12345	Drill out broken bolt in belly guard and replace evac tranny fitting	3/07/2010	3433	
	12339	New lower LHS Door glass fitted	12/07/2010	10791	

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	12347	500HR service and mech check	14/07/2010	3500	PM
	12355	Leave 2C2 site for kcet	2/08/2010	10874	
	12357	Fit corner tips check over	6/08/2010	10874	
	12363	LEAVE C2C TO KOORAGANG 1196hrS WORKED C2C 20HRS DOWNTIME 98% AVAILABILITY	6/08/2010	10874	PM
	12340	Fit lower RH door glass	13/08/2010	10874	
	12341	Remove and fit new trans evac hose and fitting prepare for transport.	4/10/2010	3698	
	12342	Start compactor feet replacement	11/10/2010		
	12343	250HR Service	18/10/2010	11249	PM
	12344	250HR Service	21/01/2011	11758	PM
	33595	REMOVE GUARDS & CLEAN MACHINE, REMOVE CAB TO GAIN ACCESS TO THE PUMPS REMOVE THE THREE PUMPS, REPLACE THE TWO HYD PUMPS WITH NEW & REBUILD THE TRANS PUMP WITH NEW BEARINGS, SEALS & TWO NEW GEARS, REFIT PUMPS USING NRE WEALS FOR THE FITTINGS AND HOSES. REFIT CAB, FILL OLS AND TEST ALL GOOD NOW NO LEAKS.	28/04/2011		
	33169	FIT FRONT AXEL ASSEMBLY FIT ENGINE ASSEMBLY RE-CONNECT HOSES TENSION TO SPECIFICATION/ BLADE RE-BUSH	23/09/2011		
	33177	FITTING UP HYDRAULIC HOSES PIPING GREASE LINES E.C.T	26/09/2011		
	33681	MAJOR REBUILD SCOPE , HOSES ,PIPPING,HYDRULIC CONTROLS , AND COMPNETRY	5/10/2011		
	33746	ONGOING REBUILD 825G COMPACTOR CAB,STAIRWAYS,FILTERS,OILS	6/10/2011		
	33753	FIT CAB AND ELECTRICAL ASSEMBLIES	7/10/2011		
	36657	FIT BATERRIES PREPARE MACHINE FOR STARTING AND TESTING	10/10/2011		
	36658	ASSEMBLE FRAME WORK , ADD OILS WATER, PREPARE FOR INTIAL START UP	12/10/2011		
	33699	COMPLETE BLADE FIT AND HOSES TO SUITE /TEST AND INSPECT FOR LEAKS ADJUST ACCORDINGLY	24/10/2011		
	33761	COMPLETE PAINTING / RE-ASSEMBLE COVERS GAURDS HANDRAILS STEPS DOORS AND GRILLS	4/11/2011		
	36653	RE-FIT COVERS GAURDS LIGHTS CAB	7/11/2011	825	
	36654	PREPARE MACHINE FOR FINAL PRE-DELIVERY	8/11/2011	825	

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	36656	PREPARE MACHINE FOR DELIVERY	10/11/2011		
	36655	ELECTRICAL REPAIRS/ RADIO - WIPERS	11/11/2011	825	
	33869	Park brake engaging when machine articulated, dissassembled park brake found shoes fitted on the wrong sides refitted correctly and adjusted tested ok.	18/11/2011	12357	Break
	33930	Replace broken diagonal brace retaing bolt and re-shim.	23/11/2011	12386	Break
	36042	825G AXB 500HR SERVICE AND MECHANICAL CHECK	13/01/2012	12601	PM
	37438	Replace seat pan.Secure stereo.	18/01/2012	12650	Correct
	37556	Alt light coming on. Tighten loose earth on chassis.	31/01/2012	12715	Correct
	38706	Re-seal turbo drain tube.	2/03/2012	12915	Correct
	37706	825G AXB 250HR SERVICE AND MECHANICAL CHECK	7/03/2012	12930	PM
	38934	Fit missing cleaner bar to pos4 wheel.Tighten loose hyd fitting under cab.Re-orientate pump hose to prevent rubbing on a/c pipe.	8/03/2012	12938	Correct
	38947	Clean out ac evaporator.	14/03/2012	12967	Correct
	39386	825G AXB 1000HR SERVICE AND MECHANICAL CHECK	28/04/2012	13213	PM
	40721	250HR Service and mech check.	10/05/2012	13252	PM
	40726	Front diff overfull, found hydraulic oil bypassing into diff housing, suspect brake pack piston/s leaking. Removed blade, cleaner bars & both front wheels and brake packs, found missing o-rings on internal bleeder pipes at connection to brake pack both sides, replaced and re-assembled machine, tested ok.	15/05/2012		Break
	43160	Replaced rubbed through low side hose from a/c compressor. Replace dryer & recharge with new refrigerant test ok.	4/07/2012	13392	Correct
	43681	REPLACE FUEL BLEED VALVE	7/08/2012	13564	Correct
	43902	Carry out repairs as per task list.	30/08/2012		Correct
	44640	825G AXB 250HR SERVICE AND MECHANICAL CHECK	2/10/2012	13731	PM
	43250	SERVICE	8/10/2012		PM
	48252	remove corner cutters	14/11/2012		Correct
	48235	remove covers	21/11/2012		Correct

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	55212	CARRY OUT BLADE INSPECTION. Min 11mm, Max 12mm	3/05/2013		Blade Insp
	43510	Seized a/c comp, parts ordered	16/07/2013		
	35271	Steer control valve leaking- re-seal.	28/05/2014		Correct
	74856	Carry out off hire repairs and service.	25/06/2014		Correct
	80864	Inspect and repair for hire. 13846hrs. Replace front windscreen. Calibrate hydraulics. Reseal blade tilt ram and LHS steer cylinder. Replace throttle control switch.	11/04/2017	13846	
	80878	825G AXB 250HR SERVICE AND MECHANICAL CHECK 13846hrs	11/04/2017	13846	PM
	81050	Fit corner tips and check over ready for work	19/04/2017	13846	
	80965	Fit new transmission down shift button to joystick	21/04/2017	13852	
	81052	Fit trans down shift button on joystick	21/04/2017	13852	
	80969	Fit new belly plate bolts	27/04/2017	13861	
	81079	Belly plate nearly fell off, fitted new bolts and retensioned others	27/04/2017	13861	
	82716	9123 - fit new 2-way hand piece	22/05/2017	13974	
	84808	Inspect charging issue and install new 2-way handpiece	22/05/2017	13974	
	81639	Inspect charging issue and install new 2 Way handpiece	22/05/2017	13974	
	81587	Heater not working diagnosed fault in heater box	5/06/2017	14027	
	81592	Fitted new Two Way hand piece	6/06/2017	14033	
	81595	Check out oil leak on timing cover . All good	8/06/2017	14054	
	82092	825G AXB 2000HR SERVICE AND MECHANICAL CHECK Done at 14050hrs	14/06/2017	14050	PM
	81608	Adjust and replace scraper bars	15/06/2017	14071	
	81557	Adjust and fit new scraper bars	29/06/2017	14152	
	82093	825G AXB 250HR SERVICE AND MECHANICAL CHECK Done at 14247hrs	22/07/2017	14247	PM
	82004	9123 - scraper bars	29/07/2017	14296	
	82711	9123 - fit new scraper bars	30/07/2017	14320	

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	82700	9123 - hydraulic hose repairs	8/08/2017	14318	
	84611	Hydraulic pipe in chassis rub through	8/08/2017	14318	
	82695	9123 - replaced hydraulic pipe	10/08/2017	14318	
	84617	Fitted new hydraulic pipe along chassis	10/08/2017	14318	
	82645	9123 - adjust scraper bars	12/09/2017	14471	
	82657	9123 - 500hr service	16/09/2017	14487	
	82661	9123 - fit new fuel primer housing	19/09/2017	14487	
	82606	9123 - repair arm rest on seat	9/10/2017	14564	
	82094	825G AXB 250HR SERVICE AND MECHANICAL CHECK Done at 14742	10/11/2017	14742	PM
	82551	9123 - flip scraper bars	16/11/2017	14762	
	82503	9123 - replace hydraulic hose on blade lift cylinder.	4/12/2017	14854	
	82259	825G AXB 1000HR SERVICE AND MECHANICAL CHECK 1000hr 16-12-2017 14964hrs	16/12/2017	14964	PM
	82466	9123 - install new beacon switch	19/01/2018	15080	
	82460	9123 - lift cylinder fault	23/01/2018	15093	
	82459	9123 - Check out blade lift fault	24/01/2018	15093	
	82455	9123 - install lift cylinder	29/01/2018	15116	
	82453	9123 - relief valve inspection	30/01/2018	15116	
	82451	9123 - install new lift control valve	1/02/2018	15116	
	82449	9123 - refit repaired lift control valve	2/02/2018	15116	
	82415	9123 - adjust scraper bars	19/02/2018	15194	
	82405	9123 - check charge fault	22/02/2018	15214	
	82397	9123 - carry out 250hr service	27/02/2018	15228	
	82398	9123 - fit and adjust scraper bars	27/02/2018	15228	

Asset History Report

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	82646	fit new access step due to damage from recovery	19/03/2018	15301	
	83158	carry out exit inspection	27/04/2018	15380	
	83188	refit cutting edges after transport	6/06/2018	15385	
	85251	825G AXB 500HR SERVICE AND MECHANICAL CHECK	18/07/2018	15500	PM
	85927	825G AXB 250HR SERVICE AND MECHANICAL CHECK	24/11/2018	15773	PM
	86522	CAT dealer inspection - see documents	28/03/2019	16088	Planned
	86533	825G AXB 250HR SERVICE AND MECHANICAL CHECK	25/05/2019	16305	PM
	86978	Off hire inspection - NCP - see documents	5/07/2019		Mobe
	87029	825G AXB 500HR SERVICE AND MECHANICAL CHECK 10/10/2019 16438hrs See docs	10/10/2019	16438	PM
	87718	Operator complaint smoke coming from engine bay, Found engine overheated and stalled. Coolant temp sensor active code, Voltage below normal, Temp gauge in cab not working. Engine extremely hot, melting paint off block. Pull engine oil filter, white metal debris found. Potential main bearing failure? Turn over engine by hand no lock up, Pull rocker covers, all over head rocker gear looking ok. Engine not blowing any smoke. Drive onto Float. Send to MtK. []	24/03/2020	16480	Break
	90228	Engine Rebuild - as per Westrac Proforma SC49823 - see documents attached.	11/08/2020	16480	Overhaul
	90229	Replaced Seat Belt, Fire Extinguishers Restamped, Replaced Wiper Inserts, Replaced Rear Transmission Output Seal and Fitted 2 x New Uni Joints, Resealed RHS Steering Cylinder, 2 x New Door Latches Fitted, New Stickers Fitted, Site Paperwork Completed.	15/01/2021	16485	Planned
	92490	Adjust scraper bars.	17/02/2021	16616	Correct
	92497	Fix oil leak on right steering ram. Adjust scraper bars	20/02/2021	16646	Correct
	92467	Adjust scraper bars. fix coolant leak, tighten hose clamp on lower coolant hose.	2/03/2021	16691	Correct
	92469	refit pin in the steering column strut	4/03/2021	16710	Correct
	92474	replace weeping SOS sample valve on hydraulic tank	5/03/2021	16716	Correct
	92483	adjust scraper bars	9/03/2021	16898	Correct
	92485	Adjust scraper bars	11/03/2021	16909	Correct
	92466	825G AXB 250HR SERVICE AND MECHANICAL CHECK	15/03/2021	16780	PM

Asset History Report

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	92487	reseal blade tilt cylinder	15/03/2021	16780	Correct
	92501	re mount fire extinguisher in cab	25/03/2021	16802	Correct
	92479	replaced 6 missing wheel tips	7/04/2021	16888	Correct
	91373	825G AXB 1000HR SERVICE AND MECHANICAL CHECK 17015hrs Rookwood	6/05/2021	17015	PM
	93051	825G AXB 250HR SERVICE AND MECHANICAL CHECK	22/06/2021	17263	PM
	94432	825G AXB 500HR SERVICE AND MECHANICAL CHECK, 17532hrs - see documents	9/06/2022	17532	PM
	94334	Welded tamping feet x 3	21/06/2022	17552	Correct
	94890	Repair UHF wiring to UHF unit in cab	2/08/2022	17622	Correct
	94978	Investigate engine oil leak, leak at starter, (Order parts)	16/08/2022	17678	Correct
	95115	Purge grease in left steer cylinder	27/08/2022	17725	Correct
	95135	Replaced AM/FM aerial and cable, replace radiator cap and panel latch	28/08/2022	17732	Correct
	96443	825G AXB 250HR SERVICE AND MECHANICAL CHECK, 17754hr - see documents	29/08/2022	17754	PM
	95176	test A/C, replace boost hose, adjust scrapper bars, replace failed intake hose	30/08/2022	17754	Correct
	95259	No AM/FM found plug at rear of unit disconnected, reconnected, run and OK	6/09/2022	17776	Correct
	95307	Rplace failed A/C Compressor and drier, vac and gas A/C system. Test, OK	9/09/2022	17763	Correct
	95542	Replaced broken RHS access door latch rear of engine enclosure, replaced grease nipple RHS rear bank	25/09/2022	17881	Correct
	95660	Replace A/C fan switch	5/10/2022	17927	Correct
	95775	Fit LinkedSite module	10/10/2022	17952	Correct
	95921	Investigate faulty trans temp gauge, sensor OK - further diagnosis required	18/10/2022	17983	Correct
	95944	Replace air filter and checkover	19/10/2022	17986	Correct
	96161	A/C warm - found comp fitting cracked, replace - vac and gas and test	3/11/2022	12030	Correct
	96262	Investigate coolant - minor leak radiator cores require resealing. Parts in stock.	10/11/2022	18095	Correct
	96316	Repair blade stabilisers - weld broken shaft.	17/11/2022	18123	Correct

Asset History Report

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	96358	Not all fan speeds working - wiring fault to resistor & blocked air filters.	19/11/2022	18134	Correct
	96670	AM/FM no reception - found plug out of radio & antenna base loose.	22/11/2022	18159	Correct
	96801	Install repaired blade tilt linkage.	29/11/2022	8179	Correct
	98170	825G AXB 250HR SERVICE AND MECHANICAL CHECK, 18241hr - see documents	6/12/2022	18241	PM
	96909	A/C repairs - blocked evap - repair crack / leaking evap - clear out A/C. Carry out 250hr service, replace tamping feet x 20	7/12/2022	18241	Correct
	96923	Finish A/C repairs - pressure test, vac, gas C/O drier.	8/12/2022	18242	Correct
	96944	Replaced RHS radiator core seals x2 that were leaking, test after repair, OK.	11/12/2022	18241	Correct
	98171	825G AXB 500HR SERVICE AND MECHANICAL CHECK, 18484hr - see documents	2/02/2023	18484	PM
	97701	Replaced cab door seals and tightened loose stabiliser bar trunion bolts blade end. Run and Okay.	7/02/2023	18193	Correct
	98651	825G AXB 250HR SERVICE AND MECHANICAL CHECK, 18771hrs - see documents	30/03/2023	18771	PM
	98853	Bleed fuel and replace fuel and water separator.	4/04/2023	18772	Correct
	99125	Reseal blade lift cylinder hose, adjust shims on blade arm tunnions, replace missing bolts in engine house, blow out air filter	26/04/2023	18913	Correct
	98814	LH steering line blown - make 2x new hoses at workshop and fit - test and bleed steering - ok.	6/05/2023	18956	Correct
	98815	Replace missing tamping feet, LH light tower, weld cracks in crossbeam - blade lift, belly guard, troubleshoot and repair oil leak -	6/05/2023	18956	Correct
	98835	Troubleshoot oil leak - found blade lift hydraulic pipe cracked - removed panels and pipe - repaired pipe back at workshop.	7/05/2023		Correct
	99681	825G AXB 1000HR SERVICE AND MECHANICAL CHECK, 18999hrs - see documents	12/05/2023	18999	PM
	99569	Straighten bent belly guards - refit trans belly guard - unplumb and remove fuel tank.	28/06/2023		Correct
	99579	Cleaned fuel tank - carried out crack repairs - carry out machine inner chassis clean and crack inspections - carried out further crack repairs - refit fuel tank - refit control valve panel - replumb/seal - carried out multiple scraper bar sets. Clean up and adjust scraper bar - reassemble machine. Assist with hydraulic hoses.	29/06/2023		Correct
	99590	Change out hose under cab - segregate hoses - repair grease fittings - refit bonnet - top oils - run and check over for leaks - inspect machine - repair step. Tighten loose hardware - check over scraper bar tensions - remove machine from jack stands - test operation of machine - fabricate a door latch for isolator door. Scraper bars & reassemble machine.	30/06/2023	19180	Correct
	99600	Repair reverse camera faults.	1/07/2023	19179	Correct

Asset History Report

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	99624	C/O 2 way mircophone.	2/07/2023	19185	Correct
	99385	Replace rear cooler room door latches - carry out heater tap change out - test - ok.	8/07/2023	19199	Correct
	99690	825G AXB 250HR SERVICE AND MECHANICAL CHECK, 19247hrs - see documents	20/07/2023	19247	PM
	100087	825G AXB 500HR SERVICE AND MECHANICAL CHECK, 19476hrs - see documents	15/09/2023	19476	PM
	100341	Blow out cab, filters, radiators and cooler packs.	5/10/2023	19566	PM
	101171	Remove panels & guards for machine wash	2/04/2024	19634	Correct
	101172	Remove corner tips, fit belly guards and panels, detail cab	4/05/2024	19683	Correct