

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
22029	76480	Fabricate chute for end conveyor.	3/06/2006	367	
	76481	Move evac coupling point on engine.	26/07/2006	400	
	76482	Remove truck pusher and clean out re assemble with rubber cover over	8/09/2006	480	
	76483	Brace and weld up conveyor slew bracketry	13/09/2006	496	
	76484	Repair wiring at positrac solenoid	14/09/2006	490	
	76485	Replace worn bolts in hopper to conveyor shute	30/10/2006	630	
	76486	Fit grease lines to top conveyor rollers	14/11/2006	700	
	76487	Broken auger drive remove weld up and replace	17/11/2006	700	
	76488	Weld wear bars into hopper	18/11/2006	720	
	76489	Re route hyd hoses at hopper tie up hoses	14/12/2006	800	
	54063	Repair oil leak at filter housing	18/12/2006	820	
	76471	Check accident damage front rubber guards	25/01/2007		
	76472	Rectify faults - No emergency dash stop or slew alarm	1/02/2007		
	54066	1000HR service	3/02/2007	1000	
	76474	Repair rubber in front of hopper weld steel plate in to hold back away from tipper ect...	5/02/2007		
	76475	Walk around inspection. conveyor swing alarm not working	14/02/2007		
	54069	Straighten guard on hopper	5/04/2007		
	76476	Straighten guard on hopper	5/04/2007		
	76477	Remove, repair and refit guards on lhs of discharge conveyor	12/04/2007		
	76478	Repair oil leak at hydraulic control valve	17/04/2007		
	54072	Repair engine oil leak @ turbo drain pipe	24/04/2007		
	76479	Replace rear wheel seals	24/04/2007		

Asset History Report

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	76456	Repair front buffer rubber	26/06/2008		
	76457	Finish off repair on front rubber skirt and chain guard	27/06/2008		
	76458	Broken conveyor roller - remove and re position another roller	3/07/2008		
	76459	Check oil leak hub wheel drive	6/08/2008		
	76460	Fit new work light	25/08/2008		
	54079	Service	3/09/2008	12411	
	76461	Service	3/09/2008	12411	
	76462	Front roller conversion	1/10/2008		
	76463	Finish off front roller modification	2/10/2008		
	54082	Replace conveyor roller	7/11/2008		
	54083	Rectify conveyor jamming	10/11/2008		
	54084	Check over, top up final drive oils	24/11/2008		
	54085	Service	24/02/2009	1510	
	76467	Service	24/02/2009	1510	
	54086	Replace auger sections required	6/03/2009		
	76469	Replace upper conveyor spiral roller - check	19/05/2009		
	76470	Check & tighten wheel hub bolts, remove auger drive motor & re-seal	28/05/2009		
	54089	Replaced batteries and repaired hydraulic oil leak at return filter	14/12/2010		
	33527	Repaired oil leak on coveyor slew and lift circuit.	4/08/2011		
	48170	replace truck/hopper rubber	24/10/2012		Correct
	48098	Remove upper conveyor drive motor. Shaft broken	10/11/2012		Correct
	48259	fit belt drive morto, adjust belt tension, adjust conveyor for twist	12/11/2012	1847	Correct
	48924	Install hyd hose	8/12/2012		Correct

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	48847	MTP 2000HR SERVICE AND MECHANICAL CHECK	11/12/2012		PM
	48913	remove POS 2 final drive	12/12/2012		Correct
	48916	assemble final drive	14/12/2012		Correct
	48918	fit POS 2 final drive, top up all final drive oils	15/12/2012		Correct
	61920	FIT NEW UPPER CONVEYOR TENSION CABLES AND GREASE PULLEY BEARINGS	31/07/2013	2231	
	66621	Fit new larger drive and tail rollers to verge paver conveyor, new belt fitted down 3 days. Hopper modified to suit original MTP ground rollers.	16/08/2013	2245	
	66626	Tail end of verge conveyor walked out of bearing refit to run down .5 day.	19/08/2013	2248	
	66632	LHS wheel bearing failed remove and strip LHS and RHS down 2 days.	22/08/2013	2250	
	66595	New hour meter fitted old unit failed at 2357 hrs new at zero.	9/09/2013	2357	
	66646	LHS front wheel bearing failure remove to inspect BD 2 days.	19/09/2013	40	
	66656	Fit new pos 1 final drive remove water from ballast tank and counterweight down 1 day. Fit new urathane hopper rollers and re race pos 2 final drive.	23/09/2013	40	
	66469	POS 1 FINAL DRIVE U/S REMOVE AND RE RACE TO RUN D 1DAY	1/10/2013	50	Correct
	69705	Replace pos 2 final drive as metal showing on plug.	30/10/2013	116	Correct
	71013	Remove pos 1 final drive and replace with spare as wheel bearings u/s.	22/11/2013	124	Correct
	78326	22029 MTP Repairs April 2015 @ 170Hrs • FD's Pos 3 and 4• Repair cracks in Pos 1 and 2 spindles• Reset front steering preload• Replace failed upper conveyor rollers• Fit and modify upper conveyor guards• Fit new upper conveyor pump• Replace Auger pump servo coil• Replace lower conveyor skirts• Replace Pressure washer motor and water pump• Tidy up machine wiring• Fit new hopper elevation switches• hammered and cleaned hopper• Auger drive Bearings• Fit re lagged hopper rollers with new bearings• fitted one is bent (Expected 2 May)• New FD's for Pos 1 and 2• Overhaul FD first reductions• Replace front steering grease seals• Adjust rear steering preload• Replace upper conveyor skirts• Fit New upper conveyor drive motor• Replace lower conveyor pump servo Repair hole in upper conveyor belt• Fit new lower conveyor hang chains• Fit new water pump filter• Reconnect auger and upper conveyor dash wiring• Fit new air filter• Jack Refit Hopper gate cylinder hoses• Fit new Fit new Auger drive shafts• Fit new Auger drive gland packing• Order new Auger as Rebrand Machine	27/04/2015	170	
	78742	Install new adjustable scraper bar assembly to long conveyor.	11/06/2015	223	Correct

Asset History Report

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	79406	REPLACE ALL LONG CONVEYOR SKIRTING RUBBERS	23/05/2016	520	
	79460	500HR SERVICE AND MECH CHECK COMPLETE	24/05/2016	520	
	80030	MTP 250HR SERVICE AND MECHANICAL CHECK	4/08/2016	578	PM
	82262	Replace failed main ignition solenoid.	18/01/2017	587	Break
	80027	Repair travel pump oil leak.	17/05/2017	699	Correct
	82267	Strip machine and clean in preparation for painting.	9/10/2017	700	Planned
	82265	Strip and repair conveyor guards and panels	12/10/2017	701	Job Damage
	82266	Paint machine and guards	16/10/2017	703	Planned
	82271	Refit lights, Estops and repair wiring.	31/10/2017	704	Planned
	82268	Fit new upper belt using new red rollers and one new lower roller.	8/11/2017	704	Planned
	82264	Supply and Rhino coat new seat.	21/11/2017	700	Planned
	82261	Fabricate and assemble new Narrow hopper to suit NCX project. New Auger shafts, bearings and flights fitted. New wheels fitted. New Skirts fitted. Fit new truck pusher roller bearings.	27/11/2017	700	Request
	82269	Fit new skirts and belt scrapers to both belts, refit lower conveyor	9/12/2017	704	Planned
	82272	Fit new hopper and test.	11/12/2017	704	Commission
	82273	Carry out service, check all levels and test machine operation and safety systems.	12/12/2017	705	PM
	82270	Fit new Decals	18/01/2018	705	Planned
	82274	Fit Fog maker system at request of NCX project.	8/02/2018	706	Request
	82263	Fit new Muffler at request of NCX	21/02/2018	706	Request
	83684	Transport to Hornsby Quarry	5/03/2018	708	
	83685	Paving Trial and test	20/03/2018		Request
	83686	Machine inspection and safety checks	22/08/2018		PM
	86723	Replace failed upper conveyor rollers.	20/09/2018		Job Damage

Asset History Report

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	86720	replace failed upper conveyor rollers.	14/03/2019		Job Damage
	86713	Carry out 500 Hr service (NCX)	20/03/2019	1551	PM
	86668	Replace lower belt and all rollers	16/05/2019		Planned
	86716	Replace leaking steering orbital valve.	12/07/2019	1802	Correct
	94245	Repairs after NCX.Replace belt bearings, Rebuild Hopper, 2000 Hr Service. Prepare for WCX.	6/10/2020	2031	Planned
	94246	MTP 2000HR SERVICE AND MECHANICAL CHECK, 2031hrs	20/10/2020	2031	PM
	93951	New Lanyard Cables Fitted, New Front Fitted to Hopper, Tyres Pumped Up, New Conveyor Belts Fitted, New Skirting Rubbers Fitted, New Rollers Fitted, Rookwood Weir Site Paperwork Completed.	29/06/2022	2038	Planned
	95428	changed out u/s roller on rear conveyor. Replaced faulty E'stop	30/07/2022	2060	Correct
	95357	lost all hydraulic fuctions, found posi track valve coil failed	1/08/2022	2071	Correct
	95361	replaced failed conveyor rollers, replaced transfer conveyor scraper	4/08/2022	2094	Correct
	95381	adjust transfer conveyor	10/08/2022	2128	Correct
	95382	change out broken auger	13/08/2022	2160	Correct
	95399	replaced damaged auger flights	16/08/2022	2168	Correct
	95264	replace broken auger flights	7/09/2022	2258	Correct
	95303	Auger broken, replace roller on rear conveyor	9/09/2022	2258	Correct
	95305	removed auger for repairs. Refit	9/09/2022	2258	Correct
	95388	remove broken auger, remove auger drive shaft to remove flange and reweld back on straight	15/09/2022	2262	Correct
	95392	fix oil leak on the auger motor. Loose case drain hose.	16/09/2022	2262	Correct
	95393	auger welded back together, replaced 3 flights, refit auger.	17/09/2022	2262	Correct
	95415	change out brocken auger, weld drive flange back on straight.	24/09/2022	2205	Correct
	95434	replace centre shaft on auger and hard face	28/09/2022	2246	Correct
	95436	replaced centre shaft on auger and hard face.	29/09/2022	2246	Correct

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	95439	weld new skins in hopper	30/09/2022	2246	Correct
	95440	replaced the centre shaft on spare Auger.	1/10/2022	2246	Correct
	95764	replaced broken pressure washer lance.	13/10/2022	4535	Correct
	97019	removed radiator core	29/10/2022	2307	Correct
	97027	fit new radiator	14/12/2022	2307	Correct
	98383	replaced 2 auger flights	6/03/2023	2314	Correct
	98388	Replace failed vibrator switch	11/03/2023	2344	Correct
	98404	remove damaged sprocket and shaft for repairs.	16/03/2023	2356	Correct
	98458	replaced broken auger drive shaft.	23/04/2023	2367	Correct
	99250	replaced broken bolts in auger bearing carrier.	5/06/2023	2425	Correct
	99240	removed auger bearing carrier, removed broken bolts cleaned and reinstalled.	5/07/2023	2444	Correct
	99248	replaced rear conveyor scraper. Refit transfer conveyor guide	9/07/2023	2476	Correct
	99312	replaced worn flights	12/07/2023	2496	Correct
	99322	replaced worn flights	16/07/2023	2512	Correct
	99784	MTP 500HR SERVICE AND MECHANICAL CHECK, 2519hrs - see documents	18/07/2023	2519	PM
	99761	drive roller bearing on transfer conveyor failed	21/07/2023	2532	Correct
	99762	replaced left drive roller bearing and left tail drum bearing on transfer conveyor, repair skirt rubber on feed side and discharge side of transfer conveyor, replaced 2 damaged auger flights.	22/07/2023	2532	Correct
	99751	tighten loose flights	1/08/2023	2574	Correct
	99818	replaced rear roller on rear conveyor.	14/08/2023	2595	Correct
	99832	replaced two auger flights	20/08/2023	2605	Correct
	99980	replaced missing auger bolt	29/08/2023	2622	Correct
	101240	Reseal Tyre valves.	12/06/2024	2647	Planned
	101367	Repair Hopper: Replace lazy side end wall, shaft and bearing. Replace drive shaft and sprocket.	3/07/2024	2647	Planned

Asset History Report

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	101411	Replace Pos 3 wheel motor.	9/07/2024	2647	Correct
	101368	Replace rusted out exhaust from turbo to muffler.	11/07/2024	2647	Correct
	101410	Carry out full service. Change all gear boxes and compartments.	17/07/2024	2647	PM