

Detail

Date Printed: 05/30/2025



0000003471

Work Order #: 0000003471  
Title: Transmission / clutch issue  
Origin: Non-PM  
Cost Center: 4150  
Priority: High(1-3 days)  
Problem: Unknown  
Originated: 10/19/2021 06:17:00 AM  
Expected:

Source Type: Asset  
WO Status: Completed  
Originator: Andy Reddick  
  
Work Type: Corrective Maintenance (CM)  
Cause: Unknown  
Assigned: 10/19/2021 07:42:00 AM  
Completed: 12/13/2021 03:07:00 PM

Work requested:

Transmission / clutch issue  
  
Needs New Clutch

Action Taken:

Truck scheduled to go to hoyts monday the 25th.

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	46.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	7161.14		
WO Cost:	7207.14	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Cody Dick	Maintenance		cdick@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00538	Unit #163	HME, Inc.	Trucking Department	Peterbilt	379	HME_00538

Source Custom Fields

No	Name	Custom Field	Value
HME_00538	Unit #163	License Plate #	155212

Labor

None

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	Mufflers/bushings		1.00		Dispatched	Mufflers and exhaust mounting bushings
X007785	Donaldson Exhaust Clamp 5" (Stepped)	Maintenance Shop	4.00	each	Dispatched	
	A&M Truck Repair		1.00		Dispatched	Rebuilt trans New clutch

Detail

Date Printed: 05/30/2025



0000000373

Work Order #: 0000000373  
Title: Leaking 1 gallon of antifreeze per hourBlowing  
w  
Origin: Non-PM  
Cost Center: 4150  
Priority: High(1-3 days)  
Problem: Equipment Damage  
Originated: 03/27/2020 07:09:00 AM  
Expected: 04/30/2020 12:00:00 PM

Source Type: Asset  
WO Status: Completed  
Originator: Andy Reddick  
Work Type: Breakdown Maintenance  
Cause: Unknown  
Assigned: 03/27/2020 07:39:00 AM  
Completed: 05/06/2020 07:51:00 AM

Work requested:

Leaking 1 gallon of antifreeze per hour  
Blowing white smoke from exhaust pipe

Action Taken:

Truck was taken to Hoyt's for headgasket and ended up needing a complete overhaul. Ended up going with a longblock.

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	40578.04		
WO Cost:	40578.04	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Cody Dick	Maintenance		cdick@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00538	Unit #163	HME, Inc.	Trucking Department	Peterbilt	379	HME_00538

Source Custom Fields

No	Name	Custom Field	Value
HME_00538	Unit #163	License Plate #	155212

Labor

None

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	Hoyts Invoice #W 41142		1.00		Dispatched	Long block installed by Hoyt's