

NOTES

LOADER

EIN# PH8P69 T3

(L-653) 928HZ Caterpillar CXK01564 2011

ENG MODEL # / SER # / ARR # H.P FAMILY #
C6.6 C6E37507 150 BKPXL06.6PJ2

MISCELLANIOUS STANDARD PARTS

Forks Serial # A27602; Bucket Holt # H10836 GROUP # 231-1498;

EDGES End Bits (2) 4T8091; Centers (2) 8E4567; Bolts (10) 1J5607 1X2 ¾; Nuts (10) 2J3507

ALT. BELTS. STARTER. BATTERIES (2) TIRE SIZE

<u>ENGINE OIL FILTER</u> 462-1171 273-5711 Crank Case	<u>TRANSMISSION OIL FILTER</u> 341-6643	<u>HYDRAULIC OIL FILTER</u> 465-6506	<u>FUEL FILTERS</u> 2) 299-8229 326-1643 Sep	<u>AIR FILTERS*</u> (I) 222-9021 (O) 256-7902
---	--	---	--	---

OIL MAINTENANCE RECORDS

<u>ENGINE</u>	<u>TRANSMISSION</u>	<u>HYDRAULIC</u>	<u>DIFFERENTIAL</u>	<u>Random Hours</u>
462-1171	341-6643	465-6506	2) 299-8229	(I) 222-9021
273-5711 Crank Case			326-1643 Sep	(O) 256-7902
DONALDSON CROSS 10/14/25				
P550920	P177047	P764737	2-P502504	I) P780036
		Note: Has 9/16" thread port. P550900 is alternative with standard drain valve without sensor port for WIF sensor.		
			P551110	O) P782104
		NO SENSOR PORT		
			P550900	

NOTES

10/30/13 Bought from Holt bucket and forks;
8/5/14; Ordered Parts and service manual.
5/20/15; Engine front cover was leaking. Front cover was done under warranty before we bought it. Holt resealed front cover again and was agreed upon to split the bill 50%-50% by Holt and Lund. Lund's portion \$1,540.40
1/9/17 Mark Trask repaired belly pan
7/3/19; 6,597 hours; Replaced quick coupler lock hydraulic cylinder.
9/11/23 9,540 hours: Replaced steering column replaced exhaust manifold and turbo. Performed a 500 hour service.
8/5/24: 9,873 hours: Installed engine long block. New turbo, injectors and any miscellaneous items needed. Installed updated software.
7/19/25: 10,485 hours: replaced leaking transmission line to the oil cooler, replaced steering stops
9/9/25: 10,528 hours: Repaired lights, removed GPS, straighten step and driveline guard.
11/15/25: 10,602 hours: Top of radiator was leaking coolant. Replaced radiator and water pump.

