

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9469
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3689	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number: 3568111
 Invoice Date: 04/23/2026
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Authorization Number: [REDACTED]
 Page: [REDACTED]

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

Service Reminders:
JFCC JD ALL Retail

COMPLAINT:

02 FREE CLEANUP OF CAB

CORRECTION:

Friday, April 17, 2026 11:07 AM - Wiped down all interior surfaces with an all purpose cleaner wiped and cleaned all interior windows with glass cleaner, and finally swept out little floor debris and scrubbed floor with all purpose cleaner cab in complete. B.O

Thursday, April 23, 2026 2:12 PM - Checked and found the inside cab is clean already, i added a floor-mat plastic, so that at least it wont get dirtier until the customer can have it. just needing to clean the exterior and interior windshield window that i am going to do it tomorrow

Friday, April 24, 2026 6:11 AM - Performed cleaning on the outside and inside windshield window, and the rear view mirror. completed. SR.

Miscellaneous	Description	Quantity	Net Price	Extended Price	Tax and Ind
LABDIS	LAB DISC CUST	-1.00	172.50	-\$172.50	Y
Labor: \$172.50	Parts: \$0.00	OL&M: \$0.00	Misc: -\$172.50	Sub-Total: \$0.00	

EXPERT-1000000314900 Retail

COMPLAINT:

03 S-Series Combine ValueMax Inspection COMPLAINT
 S SERIES COMBINE VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION
 VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST

HEADER SERIAL # _____

ENGINE HOURS _____ 2244 _____

SEPERATOR HOURS _____ 1539 _____

DOES THIS UNIT GET A VALUEMAX STICKER __ YES __X__ NO

HAS THE STICKER BEEN INSTALLED __ YES __X__ NO

PATTISON AGRICULTURE LIMITED
 6100 Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number B18708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Præceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number:	[REDACTED]
Invoice Date:	04/29/2026
Location:	10
Work Order Number:	[REDACTED]
Payment Type:	[REDACTED]
Authorization Number:	4257.46
Page:	2 of 10

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

Service reminders:

THIS UNIT HAS HAD THE CAB CLEANED _____mm_____ (INITIAL)

THIS UNIT HAS HAD A FINAL CHECKOVER _____mm_____ (INITIAL)

THIS UNIT HAS HAD A COMPLETE GREASE JOB _____mm_____ (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:

CORRECTION:

- ValueLink Job Task
- Serial Number, Check
- Safety Shields, Remove
- Initial Training, Check
- Engine Hours, Check
- Separator Hours, Check
- Service Lights, Check
- Tracks or Tires, Check
- Machine Frame, Check
- Engine RPM, Check
- Multi-Function Control Lever, Check
- Backup Alarm, Check
- Transmission Speed Ranges, Check
- AutoTrac System, Check
- Service Brake, Check
- Feeder House Raise-Lower, Fore-Aft, and Lateral Tilt, Check
- Header Hydraulic Function, Check
- Check Operation of Folding Cover (if Equipped), Check
- Unloading Auger Engage, Check
- Unloading Auger Swing, Check
- Separator Engage Switch, Check
- Header Engage Switch, Check
- Header Reverser Engage Switch, Check
- Multi-Function Control Lever Quick Stop, Check
- Threshing Clearance Adjustment, Check [It won't raise to the zero position]
- Rotor Speed Adjustment, Check
- Cleaning Fan Speed Adjustment, Check [No response to fan speed adjustment.]
- Chaffer and Sieve Setting Adjustment, Check
- Variable Stream Vanes Operation, Check [Not adjustable.]
- Powercast Functionality, Check

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3689	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number: [REDACTED]
 Invoice Date: 04/29/11
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Authorization Number: [REDACTED]
 Page: 1

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

Service Reminders:

- Spreader Speed Adjust, Check [Not adjustable.]
- Stored Diagnostic Trouble Codes, Check [Need diagnostic codes]
- Active Diagnostic Trouble Codes, Check [Need diagnostic active codes]
- Software Update, Check [Need update all controllers]
- MTG/Modem Model, Check
- MTG/Remote Connection to Service Advisor, Check
- PIP's Available
- Take Fluid Test Sample
- Air Conditioning Drain Hoses, Check
- Feeder House Frame, Check
- Feeder House Inspection Doors, Check
- Feeder House Position Sensor and Wiring Harness, Check
- Lateral Tilt Frame Seal, Check
- Lateral Tilt Cylinder, Check
- Lateral Tilt Frame, Hoses, Sensor, and Wiring Harness, Check
- Feeder House Conveyor Chain and Eyebolts, Check [
- The conveyor needs to be replaced; the chain rollers are heavily worn.
- If the chain is not being replaced, the half-links need to be removed and adjusted.]
- Feeder House Conveyor Chain Slats, and Plastic Chain Guides, Check
- Feeder House Top Shaft Bearings, Sprockets, Plastic Wear Strips, and Stripper Plates [Need replace wear strips]
- Feeder House Backshaft Speed Sensor, Tone Wheel, and Wiring Harness, Check
- Feeder House Backshaft and Bearing, Check
- Feeder House Front Drum and Bearings, Check [The bearings on both sides need to be replaced, as they are making noise.]
- Feeder House Front Floor Plate, Check
- Stone Trap, Check
- Feeder House Floor Sheet and Seal, Check [The feeder house floor is worn through in several places and needs to be replaced.]
- Fore-Aft Tilt Cylinder, Check
- Rotor Bearing, Check
- Rotor Front Feed Flights, Check
- Feeder House Lift Cylinder Support, Pins, and Pivots, Check
- Multi-Coupler Hydraulic Hoses, Harness, and Connections, Check [Need replace two cartridges]
- Header Locking Pins and Latching Mechanisms, Check [Need install three bolts]
- Feeder House Fixed Speed Drive Belt, Pulleys, Tensioner, Idlers and Bushings, Check [Need replace belt]
- Feeder House Variable Drive Speed Belt, Sheaves, Idler, and Bearings, Check
- Feeder House Drive Chain, Slip Clutch, Sprockets, Bearings, and Guide Rails, Check
- Reverser Gear Case Hoses, Fittings, Mounting Hardware, and Drive Shaft Bearing, Check
- Feederhouse Reverser Cooler, Check
- Feeder House Lift Cylinder Safety Stop, Check
- Feederhouse Lift Cylinders, Check
- Lateral Tilt Wear Pads, Check [Need replace wear pads both sides]
- Feeder House Fore/Aft Position Sensor and Wiring, Check
- Feeder House Drum Adjustment, Check
- Feeder House Pivoting Mid-floor, Check
- Feeder House Pivots, Retainer and Bushing, Check [Need replace plastic bushings both sides]
- Hinged Curved Feed Plate, Check
- Shoe Auger Backlash, Check [Need adjustment]

PATTISON AGRICULTURE LIMITED
 6100 20th Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 E-mail: info@pattisonag.com
 GST # R123078372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 582-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number: [REDACTED]
 Invoice Date: 04/29/2026
 Location: 10
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Authorization Number: 4257.46
 Page: 4 of 10

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

Service reminders:

- Shock absorber Speed Sensor and Wiring
- Conveyor Auger Front Bearings and Bevel Gears, Check
- Clean Auger Conveyor Augers, Rear Bearings, and Auger Trough, Check
- Feed Accelerator Speed Sensor and Wiring Harness, Check
- Feed Accelerator Supports, Wings, and Wear Strips, Check [Need replace four wings]
- Right Side Feed Accelerator Bearings, Check
- Left Side Feed Accelerator Bearings, Check
- Feed House Top Door and Seal, Check
- Rotor Guard Dust Shroud, Check [Need replace plastic cover]
- Rotor Speed Sensor and Wiring Harness, Check
- Separate Feed Floor and Ramp, Check
- Feed Accelerator Drive Belt, Tensioner, and Idler, Check
- Transmission Leaks, Filter, Lines, and Hoses, Check
- Front Hydraulic Motor, Check
- Front PTO Shaft Splines and Collars, Check
- Final Drive Oil Level, Check [Need replace seal]
- Upper End Drive Belt, Tensioner, Spring, Idler and Bearing, Check [Need replace belt, tensioner pulley and arm bushing]
- Feed House Electric Clutch Drive Sheave and Brush Module, Check
- Primary Countershaft Bearings and Gear Case Oil, Check
- Feed House Multi-speed Gearbox or Countershaft Gearbox, Check
- Separate Driveshaft, Check
- Reel Pump and Bearings, Check
- Reel PTO Hoses and Fittings, Check
- Clean Fan Housing and Fan Blades, Check [The fan blades need to be replaced – four are broken, and the others show wear at the mounting points. Also, two blade mounting wheels need to be replaced.]
- Clean Fan Bearings, Speed Sensor and Wiring [Need replace bearings both sides]
- Left Side Chaffer and Sieve Pitman Arms and Bearings, Check [All linkage arms need to be replaced. The chaffer frame is misaligned, and the sieve frame is already rubbing against the combine housing. The bushings in the linkage arms have shifted out of their seats.]
- Clean Auger Auger Bearing, Speed Sensor, and Wiring Harness, Check
- Tailings Auger Bearing, Speed Sensor and Wiring Harness, Check
- Vertical Unloading Auger and Housing, Check
- Hydraulic Valve Stack and Accumulator, Check
- Main Hydraulic Pump Stack, Check
- Separate Frame, Check
- Filler Door, Check
- Feeding, Threshing, and Separating Top Covers, Check
- Threshing and Separating Plastic Covers Left Side, Check
- Separate Left Side Rails, Check
- Rotor Mid Plate, Check
- Remove and Install Concave, Check [Need replace first and second concave]
- Concave, Check
- Concave Bar, Check
- Concave Hangers and Hardware, Check
- Concave Adjusting Motor and Mechanism, Check
- Concave Position Sensor and Wiring Harness, Check
- Concave Isolation Hoses and Fittings, Check
- Concave Isolation Hydraulic Cylinders, Boots, Locks, and Pins, Check

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balfarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number: [REDACTED]
 Invoice Date: 04/29/11
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Authorization Number: [REDACTED]
 Page: 1

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

Service Reminders:

- Standard Concave Level and Calibration, Check
- Active Concave Level and Calibration, Check [Need factory calibration]
- Bulkhead Cracks, Check [Need replace two bolts]
- TriStream Rotor, Check
- Variable Stream Rotor, Check
- Threshing Elements, Check [Need replace three sets]
- Separator Grates, Check
- Separator Grate Cover, Check
- Separator Tines, Check [Need replace all separator tines (This component shows significant wear)]
- Rotor Rear Discharge Flights, Check
- Separator Loss Sensor, Check [Need diagnostic]
- Left Hand Grain Tank Drain Covers, Check
- Left Hand Grain Tank Unloading Cross Auger Bearing, Check
- Unloading Auger Sump Clean Out, Check
- Vertical Unloading Auger Bevel Drive Gears and Bearings, Check
- Unloading Auger Drive Chain, Sprockets, Tensioner and Shear Bolt, Check
- Unloading Auger Drive Belts, Tensioner, Guides, Speed Sensor and Bearings, Check
- Separator Variable Sheaves, Check
- Rotor Drive Belt, Check
- Rotor Gearbox Speed Selection Lever, Check
- Batteries, Cables, and Connections, Check [All terminals need to be cleaned, and some bolts need to be replaced.]
- Machine Fuse Center, Check
- Hydro Cable (Non-Prodrive)
- Debris Management Drive Belt and Tensioner, Check [Need replace tensioner and belt]
- Service Light Switch Panel, Check
- Left Side Discharge Beater Bearing, Check
- Overshot Beater Bearings, Check
- Discharge Beater Belt, Sheaves, Tensioner, and Idlers, Check
- Front Chaffer, Air Box and Extension, Check
- Sieve and Chaffer, Check [Need replace seven louvers]
- Shoe Loss Sensor, Check
- Sieve and Chaffer Frame, Check
- Sieve and Chaffer Seals, Check
- Dual Zone Adjust Rear Chaffer Louvers, Check
- Hillside Dividers and Flaps, Check
- Separator Shaker Pan, Check
- Rear Deflector, Check
- Overshot Beater Wear Strips, Check [All wear plates need to be replaced; they are worn and some are bent.]
- Discharge Beater Wear Strips, Check
- Discharge Beater Grate, Check
- Upper Chopper Jackshaft Belt, Tensioner, Idler Pulley, Check
- Chopper Jackshaft Pulleys and Bearings, Check
- Straw Chopper Drive Belt Tensioner and Idler Pulley, Check [Both idlers are noisy and need to be replaced.]
- Straw Chopper Drive Belt, Check [Need replace belt]
- Chopper Speed Adjustment Function, Check
- Chopper Raise and Lower Actuator, Check
- Chopper Support Arms, Check

PATTISON AGRICULTURE LIMITED
 1000 Avenue West, Box 1670
 Swift Current, SK S0N 2M0
 Phone: (306) 297-2039
 Fax: (306) 297-3827
 Email: info@pattisonag.com
 Toll Free: 1-877-372-3722

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
 Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
 Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
 Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
 Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
 Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
 North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
 Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639



JOHN DEERE

SERVICE INVOICE

Invoice Account No: [REDACTED]	Deliver To: [REDACTED]	Invoice Number: [REDACTED]
[REDACTED]	[REDACTED]	Invoice Date: 04/29/2026
[REDACTED]	[REDACTED]	Location: 10
[REDACTED]	[REDACTED]	Work Order Number: [REDACTED]
[REDACTED]	[REDACTED]	Payment Type: [REDACTED]
[REDACTED]	[REDACTED]	Authorization Number: 4257.46
[REDACTED]	[REDACTED]	Page: 6 of 10
Meter: [REDACTED]	Serial Number: [REDACTED]	EQ Id: [REDACTED]
Fleet No: [REDACTED]		
JOHN DEERE S790	2244	1H0S780SAJ0802072
		102072U

- Service reminders:
- Chopper Housing and Bearings, Check [The bolt is missing from the right-side bearing guard.]
 - Chopper Speed Sensor and Wiring Harness, Check
 - Chopper Stationary Knifebank and Housing, Check [Need flex]
 - Chopper Blades and Hammers, Check [Need replace all blades]
 - Chopper Windboard Vanes, Check [It is recommended to replace all chopper door vanes; they appear worn. Two are bent and worn down.]
 - Advanced Powercast Housing and Shrouds, Check
 - Advanced Powercast Wag Deflector, Bearings, and Linkage, Check [It is necessary to replace the left gas cylinder; it is not working. AXE 1000 (1pc)]
 - Advanced Powercast Bearings, Check
 - Chaffage Straw Spreader Safety Hoops or Rails, Check
 - Chaffage Straw Spreader Hydraulic Motor, Hoses, and Fittings, Check [There are oil leaks on the hydraulic motor.]
 - Spreader Disks and Rubber Flaps, Check
 - Collar Motor Door, Check
 - Chopper Chop Door, Linkage, and Straw Rakes, Check
 - Right Side Discharge Beater Bearing, Speed Sensor and Wiring Harness, Check
 - Vacuum Housing and Boot, Check
 - Tailings Elevator Housing and Boot, Check
 - Tailings Monitor Sensor and Wiring Harness, Check
 - Tailings Auger, Auger Trough, and Lower Bearings, Check
 - Tailings Elevator Conveyor Chain and Sprockets, Check [Need adjustment conveyor chain]
 - Tailings Elevator Drive Belt, Tensioner, Idler, and Sheaves, Check
 - Tailings Elevator Slip Clutch, Check
 - Upper Tailings Drive Chain, Sprocket and Tension Block, Check [Need replace chain and idlers]
 - Upper Tailings Delivery Auger Housing, Check
 - Upper Tailings Return Auger Flighting, Check
 - Active Tailings Auger Housing, Check
 - Active Tailings Wear Strips and Threshing Bars, Check [It is necessary to replace the wear strips; they are worn.]
 - Active Tailings Concave Adjustment, Check [Need clean]
 - Active Tailings Drive Chain, Check
 - Air Compressor Tank Drain, Check
 - Clean Grain Elevator Housing and Boot, Check
 - Lower Clean Grain Auger, Auger Trough, and Lower Bearings, Check
 - Clean Grain Elevator Chain and Sprockets, Check [Need adjustment chain]
 - Moisture Sensor, Active Clean Grain Camera, Active Tailings Camera, Check
 - Clean Grain Elevator Drive Belt, Idlers, and Tensioner, Check [Need replace belt and idler]
 - Separate Vane Actuator and Wiring Harness, Check
 - Right Side Chaffer and Sieve Pitman Arms and Bearings, Check
 - Cleaning Fan Drive Sheaves, Linkage, Bearing and Hardware, Check
 - Concave Right Hand Retaining Hardware, Check
 - Cleaning Fan Adjustment Motor, Speed Sensors, and Harness, Check [Need diagnostic]
 - Cleaning Fan and Cleaning Shoe Drive Belt, Check [Need replace belt (belt have a lot of cracks)]
 - Cleaning Fan, Shaft Bearings and Lock Collars, Check
 - Separate Grates, Check
 - Separate Right Side Rails, Check
 - Threshing and Separating Covers, Check
 - Feeding, Threshing, and Separating Top Covers, Check
 - Rear Countershaft Belt, Tensioner and Pulleys, Check

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preecaville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number: [REDACTED]
 Invoice Date: 04/28/11
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Authorization Number: [REDACTED]
 Page: 1

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

Service Reminders:

- Front Countershaft Belt, Tensioner and Pulley, Check
- Primary Countershaft and Bearings, Check
- Right Hand Grain Tank Unloading Cross Auger Bearing, Check
- Right Hand Grain Tank Drain Covers, Check
- Heater Hoses, Check
- Cab Wall Electrical Connectors, Check
- Left Hand Rear Wheel and Tire, Check
- Wheel Angle Sensor, Check
- Left Hand Steering Tie Rod, Check
- Left Hand Axle Spindle and Bushing Assembly, Check
- Left Hand Wheel Bearings and Seals, Check
- Tow Hook, Check
- Steering Cylinder and Hoses, Check
- Rear Axle Hardware, Check
- Rear Axle Pivot Bushing, Check
- Right Hand Rear Wheel and Tire, Check
- Right Hand Steering Tie Rod, Check
- Right Hand Spindle and Bushing Assembly, Check
- Right Hand Wheel Bearings and Seals, Check
- Four Wheel Drive Hoses and Fittings, Check
- Four Wheel Drive Motors and Seals, Check
- Engine Deck Access Ladder, Check
- Rotary Screen Propeller, Check [Need replace bearing and support]
- Rotary Screen, Tensioner, Idler and Belt, Check
- Rotary Screen Jackshaft, Bearings and Belt, Check [Need replace bearings both sides]
- Charge Air Cooler, Radiator and Fins, Check
- Fuel, Oil Cooler, A/C Condenser & Fins, Check
- Radiator Hoses, Lines, and Radiator Cap, Check
- Engine Coolant Level, Check
- Front Engine Bracket, Check
- Engine Fan Blades, Drive Belt, and Shroud, Check
- Air Conditioning Compressor and Alternator Drive Belt, Check
- Air Compressor Pump and Drive Belt, Check
- Vacuum Fan/Belt, Tensioner and Idler.
- Accessory Drive Mounting Hardware, Check
- Water Pump, Check
- Engine Front Seals and Crankshaft Damper, Check
- Rocker Arm Cover, Check
- Valve Lash Adjustment, Check
- ECU Connections and Seals, Check
- Open Crankcase Vent (OCV) System FT4, Check
- Ether Start Aid, Check
- Diesel Exhaust Fluid Tank, Check
- Fuel Tank, Cap, Sensor and Lines, Check
- DPF Exhaust System, Check
- Exhaust Manifold, Check
- Turbocharger, Check

PATTISON AGRICULTURE LIMITED
 5700 Maple West, Box 1670
 Swift Current, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Email: info@pattison-ag.com
 Toll Free: 1-877-837-2639

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosemin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Præceville, SK (306) 547-2007
Leader, SK (306) 528-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number:	[REDACTED]
Invoice Date	04/29/2026
Location:	10
Work Order Number:	[REDACTED]
Payment Type:	[REDACTED]
Authorization Number:	4257.46
Page:	8 of 10

Make/Model	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

- Service Includes:
- Two Wheel Rotor Drive Gear Case Oil, Check
 - Engine Oil Seal, Check
 - Main Drive Gear Case, Check
 - Hydraulic Motor and Hydraulic Pump, Check
 - Grain Saver Frame, Covers, Extensions, Linkage and Corner Flaps, Check
 - Grain Saver Cover Cylinders, Hoses, Fittings, and Pins, Check
 - Grain Saver Level Switches and Wiring Harness, Check
 - Active Head Sensors and Wiring Harnesses, Check
 - Grain Saver Loading Auger, Housing, Gear Case, Bearing, Brackets and Oil, Check
 - Clear Grain Elevator Hardware, Top Shaft, Sprocket and Bearings, Check
 - Clear Grain Elevator Mass Flow Sensor Impact Plate, Check
 - Grain Saver Trough, Check
 - Grain Saver Cross Augers, Troughs, and Covers, Check
 - Horizontal Auger 90° Gearcase, Check
 - Unloading Auger Swing Cylinder, Fittings, Hoses and Pins, Check
 - Horizontal Unloading Auger & Housing, Check
 - Unloading Auger Swing Bushing, and Pivot Point, Check
 - Unloading Auger Cradle, Pins and Hardware, Check
 - Unloading Auger Grain Saver Door and Boot, Check
 - Cab Filter, Check
 - Mirror, Check
 - Window Wash and Cab Glass, Check
 - Cab Seat, Check
 - GPS Receiver, Check
 - Seat Operation and Seat Belt, Check
 - Parking Brake, Check
 - Steering Column, Check
 - Multifunction Control Lever Neutral Safety Switch, Check
 - Wiper and Washer Operation, Check
 - Horn, Check
 - Lighting System, Check [The light on the unloading auger is not working.]
 - Air Conditioning System Operation, Check
 - Heat Operation, Check
 - Relief Valve, Check
 - Cab Lock, Check
 - Cab Warning Alarm, Check
 - Corner Post and Armrest Display, Check
 - Active Head Control Displayed on Corner Post, Check
 - Auxiliary Power Strip, Check
 - Panel Full Wings, Gull Wing Cylinders and Safety Shields, Check
 - Safety Labels and Signs, Check
 - Ladder Safety Chains, Check
 - Road Disconnect Switch, Check
 - Copy Operator Seat Presence Switch, Check
 - Fire Extinguisher, Check
 - Operator's Manual
 - Camera System, Check

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number: [REDACTED]
 Invoice Date: 01/23
 Location:
 Work Order Number:
 Payment Type:
 Authorization Number:
 Page:

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

- Service Reminders:
- Toolbox, Check
 - Static Drag Chain/Cable, Check
 - Remote Front Grease Lines, Check [There is no grease line to the final drive; it needs to be installed. Both sides]
 - Engine Air Filters, Check
 - Engine Oil and Filter, Check
 - Diesel Exhaust Fluid (DEF) System, Check
 - Fuel Filters, Check
 - Fuel Tank Breather, Check
 - Hydraulic Reservoir, Fluid and Filter, Check
 - Hydrostatic Charge Filter, Check
 - Overshot Beater Gearbox Oil, Drive Belt, Idler, and Tensioner, Check [Need replace overshot beater idler]
 - Feeder House Reverser Gear Case Oil, Check
 - Main Engine Gear Case Oil and Filter, Check
 - Cab Air Filters, Check
 - Wiper Fluid Level, Check [Need add]
 - Debris Management Primary and Secondary Filters, Check
 - Final Running, Check
 - Safety Shields, Install
 - Additional Jobs Required

PartNumber	Description	Quantity	Net Price	Extended Price	Unit
TY26860	INSPECTION+ 4 FLUID TEST KIT	1.00	0.00	\$0.00	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Unit
LABDIS	LAB DISC CUST	-1.00	1,208.00	-\$1,208.00	Y

Labor: \$4,515.00 Parts: \$0.00 OL&M: \$0.00 Misc: -\$1,208.00 Sub-Total: \$3,307.00

EXPERT-100000015278 Retail

COMPLAINT:

07 Concaves, Repair

CORRECTION:

1. Remove side covers.
2. Cover shoe augers with cardboard.
3. Set concave in open position.
4. Remove Z bar.
5. Remove retainers, hardware and concaves.
6. Remove feeder house.
7. Replace concaves.
8. Position Z bar over end of concaves and install cap screws, but do not tighten.
9. Tighten Z bar hardware in order of top row and then bottom row.
10. Reinstall side covers.

The job took a significant amount of time, as the cross bars on two concaves had to be heated and straightened. Six concave wires were

PATTISON AGRICULTURE LIMITED
 6700 Highway West, Box 1670
 Swift Current, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Email: pattisonag.com
 Cell: (306) 818703372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
 Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
 Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
 Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
 Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
 Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
 North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
 Humboldt, SK (306) 582-2572 Swan River, MB (204) 734-3466
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639



JOHN DEERE

SERVICE INVOICE

Invoice Account No: [REDACTED]	Deliver To: [REDACTED]	Invoice Number: [REDACTED]
[REDACTED]	[REDACTED]	Invoice Date: 04/29/2026
[REDACTED]	[REDACTED]	Location: 10
[REDACTED]	[REDACTED]	Work Order Number: [REDACTED]
[REDACTED]	[REDACTED]	Payment Type: [REDACTED]
[REDACTED]	[REDACTED]	Authorization Number: 4257.46
[REDACTED]	[REDACTED]	Page: 10 of 10
Meter: [REDACTED]	Serial Number: [REDACTED]	EQ Id: [REDACTED]
Fleet No: [REDACTED]		

See work order for details. The broken wires had to be removed in pieces due to severe damage. Additionally, welding was performed on six bars as they had broken. The concaves were reinstalled. Completed.

Part	Description	Quantity	Net Price	Extended Price	Taxed Ind
H12	NAIL Small Wire	6.00	12.12	\$72.72	Y

Miscellaneous Charges: \$150.00
 ACCESSORIES \$150.00

Label: \$0.00	Parts: \$72.72	OL&M: \$0.00	Misc: \$150.00	Sub-Total: \$747.72
---------------	----------------	--------------	----------------	---------------------

Credit Card Information		Labor:	\$5,212.50
Customer Name: Joanne Thronberg	Type: Credit Card	Parts:	\$72.72
Tax ID No:	Auth No: 4257.46	OL&M:	\$0.00
Address:	Amount: \$4,257.46	Misc:	-\$1,230.50
		GST:	\$202.74
		PST:	\$0.00
		Grand Total:	\$4,257.46

TERMS AND CONDITIONS
 I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purpose of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and any unpaid balance in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: Date:



PATTISON AGRICULTURE LIMITED
 6110 Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST # R12307872

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
 Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
 Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
 Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
 Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
 Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
 North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
 Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639



JOHN DEERE

Invoice Account No: [REDACTED]

Deliver To: ***** PROFORMA INVOICE *****

SERVICE INVOICE

[REDACTED]
 Business: [REDACTED]
 Private: [REDACTED]

[REDACTED]
 Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number:
 Invoice Date: 04/27/2026
 Location: 10
 Work Order Number: [REDACTED]
 Payment Type: Account
 Page: 12 of 12

Make/Model	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

Service reminders:

J081 1019 JD S780 Retail

COMMENTS:

11 REPLACEMENT FEEDERHOUSE CONVEYOR CHAIN

CORRECTION:

Replaced according to service advisor.
 Additional work was required to drill out four lower bolts on the feederhouse deflectors, as the internal heads were stripped.
 Done

Part Number	Description	Quantity	Net Price	Extended Price	Taxed Ind
21M1001	Screw M10x35 HexSocBttnHd 12.9T	4.00	3.66	\$14.64	Y
AH220501	CHAIN LINK-OFFSET COUPLER CA557-CHROME	4.00	19.16	\$76.64	Y
AXE21001	4-CHAIN FEEDER CHAIN S-SER 775001-	1.00	3,704.49	\$3,704.49	Y
H210001	Nylon Fin-Type Push Plug *see note	8.00	1.57	\$12.56	Y

Miscellaneous Charges:

SERVICE ACCESSORIES

\$150.00

Labor: \$546.00 Parts: \$3,808.33 OL&M: \$0.00 Misc: \$150.00 Sub-Total: \$4,504.33

Customer PO No:
 Tax Exempt No:
 Advisor: Joanne Thronberg

Labor: \$7,123.50
 Parts: \$5,672.00
 OL&M: \$0.00
 Misc: -\$1,230.50
 GST: \$578.25
 PST: \$0.00

Grand Total: \$12,143.25

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by:

Date:

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
 Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
 Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
 Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
 Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
 Unly, SK (306) 228-2696 Wynyard, SK (306) 554-2536
 North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
 Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: *** PROFORMA INVOICE ***

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number: [REDACTED]
 Invoice Date: 01/21/2010
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 11 of 11

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

- Service Reminders:
3. Remove belt from sheave.
 4. Remove cap screw and washer.
 5. Remove cap screws, nuts, springs, and spacers.
 6. Remove outer half of sheave using a puller.
 7. Remove key and inner half of sheave.
 8. Remove washer.
 9. Loosen set screw and remove locking collar.
 10. Remove nuts, round head bolts, and flange plate.
 11. Remove bearing and inner flange from shaft. Replace as necessary.
 12. Inspect shaft and remove any nicks or burrs using emery cloth or file.
 13. Install inner flange and bearing.
 14. Install outer flange, round head bolts, and nuts.
 15. Install lock collar and tighten set screw.
 16. Install washer.
 17. Install inner half of sheave and key.
 18. Install outer half of sheave.
 19. Tighten cap screw and washer to specification.
 20. Install cap screws, spacers, and springs.
 21. Install nuts and tighten until washer is seated against spacers inside of springs.
 22. Install belt to sheave.
 23. Left-hand side:
 24. Remove debris buildup and unplug cleaning fan speed sensor connector.
 25. Remove two screws and sensor.
 26. Loosen set screw and remove locking collar / tone wheel.
 27. Remove nuts, round head bolts, and flange plate.
 28. Remove bearing and inner flange from shaft. Replace as necessary.
 29. Inspect shaft and remove any nicks or burrs using emery cloth or file.
 30. Install inner flange and bearing.
 31. Install outer flange, round head bolts, and nuts.
 32. Install lock collar / tone wheel and tighten set screw.
 33. Install sensor using screws. Tighten to specification.
 34. Connect connector.
 35. Start machine and engage separator. Adjust cleaning fan to desired speed.

It took considerable time to remove the bearing on the right side. The sheave had to be heated to remove it without damaging the shaft. The bearing was also heated several times, but it did not move. Due to limited space, it had to be cut off in pieces using a small grinder. The bearings on both sides were then replaced according to the instructions.
 Done

PartNumber	Description	Quantity	Net Price	Extended Price	Unit
AH139297	BALL BEARING, BEARING-BALL, RELUBRI	1.00	71.38	\$71.38	Y
AH225510	BEARING, 25MM BORE, RELUBRICATABLE	1.00	47.02	\$47.02	Y
H113625	PRESSED FL	1.00	15.33	\$15.33	Y
H113626	PRESSED FL	1.00	22.30	\$22.30	Y

Labor: \$630.00 Parts: \$156.03 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$786.03

PATTISON AGRICULTURE LIMITED
 610 2nd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 819708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
 Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
 Kindersley, SK (306) 463-2583 Moosomin, SK (306) 435-3301
 Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
 Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
 Unity, SK (306) 228-2596 Wynyard, SK (306) 554-2536
 North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
 Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639



JOHN DEERE

SERVICE INVOICE

Invoice Account No: [REDACTED]

Deliver To: *** PROFORMA INVOICE ***

[REDACTED]
 Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]
 Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number:
 Invoice Date: 04/27/2026
 Location: 10
 Work Order Number: [REDACTED]
 Payment Type: Account
 Page: 10 of 12

Make/Model	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

Service Reminders:

Part Number	Description	Quantity	Net Price	Extended Price	Taxed Ind
H206345	Cleaning Fan Blade	12.00	128.90	\$1,546.80	Y
HXE167359	Insert	2.00	44.06	\$88.12	Y

Labor: \$735.00 Parts: \$1,634.92 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$2,369.92

EXPERT-1000000015278 Retail

COMPLAINT:

07 Concaves, Repair

CORRECTION:

1. Remove side covers.
2. Cover shoe augers with cardboard.
3. Set concave in open position.
4. Remove Z bar.
5. Remove retainers, hardware and concaves.
6. Remove feeder house.
7. Replace concaves.
8. Position Z bar over end of concaves and install cap screws, but do not tighten.
9. Tighten Z bar hardware in order of top row and then bottom row.
10. Reinstall side covers.

The job took a significant amount of time, as the cross bars on two concaves had to be heated and straightened. Six concave wires were also replaced. The broken wires had to be removed in pieces due to severe damage. Additionally, welding was performed on six bars as they had cracks. The concaves were reinstalled. Completed.

Part Number	Description	Quantity	Net Price	Extended Price	Taxed Ind
H156272	NAIL Small Wire	6.00	12.12	\$72.72	Y

Labor: \$525.00 Parts: \$72.72 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$597.72

EXPERT-1000000097723 Retail

COMPLAINT:

08 Cleaning Fan Bearings, Replace Both Sides. REPLACE CLEANING FAN BEARINGS. (BOTH SIDES)

CORRECTION:

1. Right hand side:
2. Relieve belt tension by operating the cleaning fan speed switch to the slow position. Loosen nuts and move to outer end of shaft if more slack is required to remove belt.

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
 Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
 Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
 Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
 Leader, SK (306) 628-3859 Russell, MB (204) 773-2149
 Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
 North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
 Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: *** PROFORMA INVOICE ***

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number: [REDACTED]
 Invoice Date: [REDACTED]
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 9 of 11

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

Service Reminders:

- Toolbox, Check
- Static Drag Chain/Cable, Check
- Remote Front Grease Lines, Check [There is no grease line to the final drive; it needs to be installed. Both sides]
- Engine Air Filters, Check
- Engine Oil and Filter, Check
- Diesel Exhaust Fluid (DEF) System, Check
- Fuel Filters, Check
- Fuel Tank Breather, Check
- Hydraulic Reservoir, Fluid and Filter, Check
- Hydrostatic Charge Filter, Check
- Overshot Beater Gearbox Oil, Drive Belt, Idler, and Tensioner, Check [Need replace overshot beater idler]
- Feeder House Reverser Gear Case Oil, Check
- Main Engine Gear Case Oil and Filter, Check
- Cab Air Filters, Check
- Wiper Fluid Level, Check [Need add]
- Debris Management Primary and Secondary Filters, Check
- Final Running, Check
- Safety Shields, Install
- Additional Jobs Required

PartNumber	Description	Quantity	Net Price	Extended Price	Tax/Inc
TY26860	INSPECTION+ 4 FLUID TEST KIT	1.00	0.00	\$0.00	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Tax/Inc
LABDIS	LAB DISC CUST	-1.00	1,208.00	-\$1,208.00	Y
Labor: \$4,515.00	Parts: \$0.00	OL&M: \$0.00	Misc: -\$1,208.00	Sub-Total: \$3,307.00	

EXPERT-1000000120187 Retail

COMPLAINT:

06 Cleaning Fan Blades and Inserts, Replace All Blades

CORRECTION:

1. Remove body shields.
2. Remove belt from sheave.
3. Rotate cleaning fan.
4. Remove vanes.
5. Remove and replace cleaning fan blade inserts.
6. Assemble in reverse order.
7. Run and test operation.

It took a bit longer because I had to drill out two rusted bolts and clean each blade lock individually. They were packed with dirt, so I had to clean each one out using a screwdriver. Replaced according to service advisor.
 Done

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number R18708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: *** PROFORMA INVOICE ***

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number:	
Invoice Date:	04/27/2026
Location:	10
Work Order Number:	[REDACTED]
Payment Type:	Account
Page:	8 of 12

Make/Model	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

Service Reminders:

- Two Speed Rotor Drive Gear Case Oil, Check
- Engine Rear Seals, Check
- Main Engine Gear Case, Check
- Hydrostatic Motor and Hydraulic Pump, Check
- Grain Tank Frame, Covers, Extensions, Linkage and Corner Flaps, Check
- Grain Tank Cover Cylinders, Hoses, Fittings, and Pins, Check
- Grain Tank Level Switches and Wiring Harness, Check
- Active Yield Sensors and Wiring Harnesses, Check
- Grain Tank Loading Auger, Housing, Gear Case, Bearing, Brackets and Oil, Check
- Clean Grain Elevator Hardware, Top Shaft, Sprocket and Bearings, Check
- Clean Grain Elevator Mass Flow Sensor Impact Plate, Check
- Grain Sample Trough, Check
- Grain Tank Cross Augers, Troughs, and Covers, Check
- Horizontal Auger 90° Gearcase, Check
- Unloading Auger Swing Cylinder, Fittings, Hoses and Pins, Check
- Horizontal Unloading Auger & Housing, Check
- Unloading Auger Swing Bushing, and Pivot Point, Check
- Unloading Auger Cradle, Pins and Hardware, Check
- Unloading Auger Grain Saver Door and Boot, Check
- Cab Ladder, Check
- Mirrors, Check
- Windshield and Cab Glass, Check
- Cab Roof, Check
- GPS Receiver, Check
- Seat Operation and Seat Belt, Check
- Park Brake, Check
- Steering Column, Check
- Multi-Function Control Lever Neutral Safety Switch, Check
- Wiper and Washer Operation, Check
- Horn, Check
- Lighting System, Check [The light on the unloading auger is not working.]
- Air Conditioning System Operation, Check
- Heater Operation, Check
- Refrigerator, Check
- Cab Radio, Check
- Cab Warning Alarm, Check
- Corner Post and Armrest Display, Check
- Active Header Control Displayed on Corner Post, Check
- Auxiliary Power Strip, Check
- Panels, Gull Wings, Gull Wing Cylinders and Safety Shields, Check
- Safety Decals and Signs, Check
- Ladder Safety Chains, Check
- Road Disconnect Switch, Check
- copy of Operator Seat Presence Switch, Check
- Fire Extinguisher, Check
- Operators Manual
- Camera System, Check



PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
 Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
 Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
 Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
 Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
 Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
 North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
 Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: ***** PROFORMA INVOICE *****

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number:
Invoice Date: 04/27/2025
Location:
Work Order Number: [REDACTED]
Payment Type:
Page: 7 of 17

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

- Service Reminders:
- Front Countershaft Belt, Tensioner and Pulley, Check
 - Primary Countershaft and Bearings, Check
 - Right Hand Grain Tank Unloading Cross Auger Bearing, Check
 - Right Hand Grain Tank Drain Covers, Check
 - Heater Hoses, Check
 - Cab Wall Electrical Connectors, Check
 - Left Hand Rear Wheel and Tire, Check
 - Wheel Angle Sensor, Check
 - Left Hand Steering Tie Rod, Check
 - Left Hand Axle Spindle and Bushing Assembly, Check
 - Left Hand Wheel Bearings and Seals, Check
 - Tow Hook, Check
 - Steering Cylinder and Hoses, Check
 - Rear Axle Hardware, Check
 - Rear Axle Pivot Bushing, Check
 - Right Hand Rear Wheel and Tire, Check
 - Right Hand Steering Tie Rod, Check
 - Right Hand Spindle and Bushing Assembly, Check
 - Right Hand Wheel Bearings and Seals, Check
 - Four Wheel Drive Hoses and Fittings, Check
 - Four Wheel Drive Motors and Seals, Check
 - Engine Deck Access Ladder, Check
 - Rotary Screen Propeller, Check [Need replace bearing and support]
 - Rotary Screen, Tensioner, Idler and Belt, Check
 - Rotary Screen Jackshaft, Bearings and Belt, Check [Need replace bearings both sides]
 - Charge Air Cooler, Radiator and Fins, Check
 - Fuel, Oil Cooler, A/C Condenser & Fins, Check
 - Radiator Hoses, Lines, and Radiator Cap, Check
 - Engine Coolant Level, Check
 - Front Engine Bracket, Check
 - Engine Fan Blades, Drive Belt, and Shroud, Check
 - Air Conditioning Compressor and Alternator Drive Belt, Check
 - Air Compressor Pump and Drive Belt, Check
 - Vacuum Fan/Belt, Tensioner and Idler.
 - Accessory Drive Mounting Hardware, Check
 - Water Pump, Check
 - Engine Front Seals and Crankshaft Damper, Check
 - Rocker Arm Cover, Check
 - Valve Lash Adjustment, Check
 - ECU Connections and Seals, Check
 - Open Crankcase Vent (OCV) System FT4, Check
 - Ether Start Aid, Check
 - Diesel Exhaust Fluid Tank, Check
 - Fuel Tank, Cap, Sensor and Lines, Check
 - DPF Exhaust System, Check
 - Exhaust Manifold, Check
 - Turbocharger, Check

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number R18708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9469
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: ***** PROFORMA INVOICE *****

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number: [REDACTED]
 Invoice Date: 04/27/2026
 Location: 10
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 6 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

Service Reminders:

- Chopper Housing and Bearings, Check [The bolt is missing from the right-side bearing guard.]
- Chopper Speed Sensor and Wiring Harness, Check
- Chopper Stationary Knifebank and Housing, Check [Need flex]
- Chopper Blades and Hammers, Check [Need replace all blades]
- Chopper Tailboard Vanes, Check [It is recommended to replace all chopper door vanes; they appear worn. Two are bent and worn down.]
- Advanced Powercast Housing and Shrouds, Check
- Advanced Powercast Wag Deflector, Bearings, and Linkage, Check [It is necessary to replace the left gas cylinder; it is not working. AXE10131-1pc]
- Advanced Powercast Bearings, Check
- Chaff and Straw Spreader Safety Hoops or Rails, Check
- Chaff and Straw Spreader Hydraulic Motor, Hoses, and Fittings, Check [There are oil leaks on the hydraulic motor.]
- Spreader Disks and Rubber Flaps, Check
- Cob Deflector Door, Check
- Chop-to-Drop Door, Linkage, and Straw Rakes, Check
- Right Side Discharge Beater Bearing, Speed Sensor and Wiring Harness, Check
- Vac Fan Housing and Boot, Check
- Tailings Elevator Housing and Boot, Check
- Tailings Monitor Sensor and Wiring Harness, Check
- Tailings Auger, Auger Trough, and Lower Bearings, Check
- Tailings Elevator Conveyor Chain and Sprockets, Check [Need adjustment conveyor chain]
- Tailings Elevator Drive Belt, Tensioner, Idler, and Sheaves, Check
- Tailings Elevator Slip Clutch, Check
- Upper Tailings Drive Chain, Sprocket and Tension Block, Check [Need replace chain and idlers]
- Upper Tailings Delivery Auger Housing, Check
- Upper Tailings Return Auger Flighting, Check
- Active Tailings Auger Housing, Check
- Active Tailings Wear Strips and Threshing Bars, Check [It is necessary to replace the wear strips; they are worn.]
- Active Tailings Concave Adjustment, Check [Need clean]
- Active Tailings Drive Chain, Check
- Air Compressor Tank Drain, Check
- Clean Grain Elevator Housing and Boot, Check
- Lower Clean Grain Auger, Auger Trough, and Lower Bearings, Check
- Clean Grain Elevator Chain and Sprockets, Check [Need adjustment chain]
- Moisture Sensor, Active Clean Grain Camera, Active Tailings Camera, Check
- Clean Grain Elevator Drive Belt, Idlers, and Tensioner, Check [Need replace belt and idler]
- Separator Vane Actuator and Wiring Harness, Check
- Right Side Chaffer and Sieve Pitman Arms and Bearings, Check
- Cleaning Fan Drive Sheaves, Linkage, Bearing and Hardware, Check
- Concave Right Hand Retaining Hardware, Check
- Cleaning Fan Adjustment Motor, Speed Sensors, and Harness, Check [Need diagnostic]
- Cleaning Fan and Cleaning Shoe Drive Belt, Check [Need replace belt (belt have a lot of cracks)]
- Cleaning Fan, Shaft Bearings and Lock Collars, Check
- Separator Grates, Check
- Separator Right Side Rails, Check
- Threshing and Separating Covers, Check
- Feeding, Threshing, and Separating Top Covers, Check
- Rear Countershaft Belt, Tensioner and Pulleys, Check

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: ***** PROFORMA INVOICE *****

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number:
Invoice Date: 0-1/27/2026
Location: 10
Work Order Number: [REDACTED]
Payment Type: [REDACTED]

Page: 5 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

Service Reminders:

- Standard Concave Level and Calibration, Check
- Active Concave Level and Calibration, Check [Need factory calibration]
- Bulkhead Cracks, Check [Need replace two bolts]
- TriStream Rotor, Check
- Variable Stream Rotor, Check
- Threshing Elements, Check [Need replace three sets]
- Separator Grates, Check
- Separator Grate Cover, Check
- Separator Tines, Check [Need replace all separator tines (This component shows significant wear)]
- Rotor Rear Discharge Flights, Check
- Separator Loss Sensor, Check [Need diagnostic]
- Left Hand Grain Tank Drain Covers, Check
- Left Hand Grain Tank Unloading Cross Auger Bearing, Check
- Unloading Auger Sump Clean Out, Check
- Vertical Unloading Auger Bevel Drive Gears and Bearings, Check
- Unloading Auger Drive Chain, Sprockets, Tensioner and Shear Bolt, Check
- Unloading Auger Drive Belts, Tensioner, Guides, Speed Sensor and Bearings, Check
- Separator Variable Sheaves, Check
- Rotor Drive Belt, Check
- Rotor Gearbox Speed Selection Lever, Check
- Batteries, Cables, and Connections, Check [All terminals need to be cleaned, and some bolts need to be replaced.]
- Machine Fuse Center, Check
- Hydro Cable (Non-Prodrive)
- Debris Management Drive Belt and Tensioner, Check [Need replace tensioner and belt]
- Service Light Switch Panel, Check
- Left Side Discharge Beater Bearing, Check
- Overshot Beater Bearings, Check
- Discharge Beater Belt, Sheaves, Tensioner, and Idlers, Check
- Front Chaffer, Air Box and Extension, Check
- Sieve and Chaffer, Check [Need replace seven louvers]
- Shoe Loss Sensor, Check
- Sieve and Chaffer Frame, Check
- Sieve and Chaffer Seals, Check
- Dual Zone Adjust Rear Chaffer Louvers, Check
- Hillside Dividers and Flaps, Check
- Separator Shaker Pan, Check
- Rear Deflector, Check
- Overshot Beater Wear Strips, Check [All wear plates need to be replaced; they are worn and some are bent.]
- Discharge Beater Wear Strips, Check
- Discharge Beater Grate, Check
- Upper Chopper Jackshaft Belt, Tensioner, Idler Pulley, Check
- Chopper Jackshaft Pulleys and Bearings, Check
- Straw Chopper Drive Belt Tensioner and Idler Pulley, Check [Both idlers are noisy and need to be replaced.]
- Straw Chopper Drive Belt, Check [Need replace belt]
- Chopper Speed Adjustment Function, Check
- Chopper Raise and Lower Actuator, Check
- Chopper Support Arms, Check

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 618708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: ***** PROFORMA INVOICE *****

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number:
Invoice Date: 04/27/2026
Location: 10
Work Order Number: [REDACTED]
Payment Type: Account
Page: 4 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

Service Reminders:

- Shoe Auger Speed Sensor and Wiring
- Conveyor Auger Front Bearings and Bevel Gears, Check
- Cleaning Shoe Conveyor Augers, Rear Bearings, and Auger Trough, Check
- Feed Accelerator Speed Sensor and Wiring Harness, Check
- Feed Accelerator Supports, Wings, and Wear Strips, Check [Need replace four wings]
- Right Side Feed Accelerator Bearings, Check
- Left Side Feed Accelerator Bearings, Check
- Feeder House Top Door and Seal, Check
- Rotor Plastic Dust Shroud, Check [Need replace plastic cover]
- Rotor Speed Sensor and Wiring Harness, Check
- Separator Feed Floor and Ramp, Check
- Feed Accelerator Drive Belt, Tensioner, and Idler, Check
- Transmission Leaks, Filter, Lines, and Hoses, Check
- Front Hydrostatic Motor, Check
- Front Drive Shaft Splines and Collars, Check
- Final Drives Oil Level, Check [Need replace seal]
- Upper Front End Drive Belt, Tensioner, Spring, Idler and Bearing, Check [Need replace belt, tensioner pulley and arm bushing]
- Feeder House Electric Clutch Drive Sheave and Brush Module, Check
- Primary Countershaft Bearings and Gear Case Oil, Check
- Feeder House Multi-speed Gearbox or Countershaft Gearbox, Check
- Separator Driveshaft, Check
- Reel Drive Pump and Bearings, Check
- Reel Pump Hoses and Fittings, Check
- Cleaning Fan Housing and Fan Blades, Check [The fan blades need to be replaced – four are broken, and the others show wear at the mounting points. Also, two blade mounting wheels need to be replaced.]
- Cleaning Fan Bearings, Speed Sensor and Wiring [Need replace bearings both sides]
- Left Side Chaffer and Sieve Pitman Arms and Bearings, Check [All linkage arms need to be replaced. The chaffer frame is misaligned, and the sieve frame is already rubbing against the combine housing. The bushings in the linkage arms have shifted out of their seats.]
- Clean Grain Auger Bearing, Speed Sensor, and Wiring Harness, Check
- Tailings Auger Bearing, Speed Sensor and Wiring Harness, Check
- Vertical Unloading Auger and Housing, Check
- Hydraulic Valve Stack and Accumulator, Check
- Main Hydraulic Pump Stack, Check
- Separator Frame, Check
- Filler Plates, Check
- Feeding, Threshing, and Separating Top Covers, Check
- Threshing and Separating Plastic Covers Left Side, Check
- Separator Left Side Rails, Check
- Rotor Mid Plate, Check
- Remove & Install Concave, Check [Need replace first and second concave]
- Concave, Check
- Concave Z-Bar, Check
- Concave Hangers and Hardware, Check
- Concave Adjusting Motor and Mechanism, Check
- Concave Position Sensor and Wiring Harness, Check
- Concave Isolation Hoses and Fittings, Check
- Concave Isolation Hydraulic Cylinders, Boots, Locks, and Pins, Check

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: *** PROFORMA INVOICE ***

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number: [REDACTED]
 Invoice Date: 04/27/2026
 Location: 10
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 3 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

- Service Reminders:
- Spreader Speed Adjust, Check [Not adjustable.]
 - Stored Diagnostic Trouble Codes, Check [Need diagnostic codes]
 - Active Diagnostic Trouble Codes, Check [Need diagnostic active codes]
 - Software Update, Check [Need update all controllers]
 - MTG/Modem Model, Check
 - MTG/Remote Connection to Service Advisor, Check
 - PIP's Available
 - Take Fluid Test Sample
 - Air Conditioning Drain Hoses, Check
 - Feeder House Frame, Check
 - Feeder House Inspection Doors, Check
 - Feeder House Position Sensor and Wiring Harness, Check
 - Lateral Tilt Frame Seal, Check
 - Lateral Tilt Cylinder, Check
 - Lateral Tilt Frame, Hoses, Sensor, and Wiring Harness, Check
 - Feeder House Conveyor Chain and Eyebolts, Check [

The conveyor needs to be replaced; the chain rollers are heavily worn.
 If the chain is not being replaced, the half-links need to be removed and adjusted.]
 Feeder House Conveyor Chain Slats, and Plastic Chain Guides, Check
 Feeder House Top Shaft Bearings, Sprockets, Plastic Wear Strips, and Stripper Plates [Need replace wear strips]
 Feeder House Backshaft Speed Sensor, Tone Wheel, and Wiring Harness, Check
 Feeder House Backshaft and Bearing, Check
 Feeder House Front Drum and Bearings, Check [The bearings on both sides need to be replaced, as they are making noise.]
 Feeder House Front Floor Plate, Check
 Stone Trap, Check
 Feeder House Floor Sheet and Seal, Check [The feeder house floor is worn through in several places and needs to be replaced.]
 Fore-Aft Tilt Cylinder, Check
 Rotor Bearing, Check
 Rotor Front Feed Flights, Check
 Feeder House Lift Cylinder Support, Pins, and Pivots, Check
 Multi-Coupler Hydraulic Hoses, Harness, and Connections, Check [Need replace two cartridges]
 Header Locking Pins and Latching Mechanisms, Check [Need install three bolts]
 Feeder House Fixed Speed Drive Belt, Pulleys, Tensioner, Idlers and Bushings, Check [Need replace belt]
 Feeder House Variable Drive Speed Belt, Sheaves, Idler, and Bearings, Check
 Feeder House Drive Chain, Slip Clutch, Sprockets, Bearings, and Guide Rails, Check
 Reverser Gear Case Hoses, Fittings, Mounting Hardware, and Drive Shaft Bearing, Check
 Feederhouse Reverser Cooler, Check
 Feeder House Lift Cylinder Safety Stop, Check
 Feederhouse Lift Cylinders, Check
 Lateral Tilt Wear Pads, Check [Need replace wear pads both sides]
 Feeder House Fore/Aft Position Sensor and Wiring, Check
 Feeder House Drum Adjustment, Check
 Feeder House Pivoting Mid-floor, Check
 Feeder House Pivots, Retainer and Bushing, Check [Need replace plastic bushings both sides]
 Hinged Curved Feed Plate, Check
 Shoe Auger Backlash, Check [Need adjustment]

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preecaville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: ***** PROFORMA INVOICE *****

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number: [REDACTED]
 Invoice Date: 04/27/2026
 Location: 10
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 2 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

Service Reminders:

THIS UNIT HAS HAD THE CAB CLEANED _____mm_____ (INITIAL)

THIS UNIT HAS HAD A FINAL CHECKOVER _____mm_____ (INITIAL)

THIS UNIT HAS HAD A COMPLETE GREASE JOB _____mm_____ (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:

CORRECTION:

- ValueMax Job Task
- Serial Number, Check
- Safety Shields, Remove
- Initial Running, Check
- Engine Hours, Check
- Separator Hours, Check
- Service Lights, Check
- Tracks or Tires, Check
- Machine Frame, Check
- Engine RPM, Check
- Multi-Function Control Lever, Check
- Backup Alarm, Check
- Transmission Speed Ranges, Check
- AutoTrac System, Check
- Service Brake, Check
- Feeder House Raise-Lower, Fore-Aft, and Lateral Tilt, Check
- Header Hydraulic Function, Check
- Check Operation of Folding Cover (if Equipped), Check
- Unloading Auger Engage, Check
- Unloading Auger Swing, Check
- Separator Engage Switch, Check
- Header Engage Switch, Check
- Header Reverser Engage Switch, Check
- Multi-Function Control Lever Quick Stop, Check
- Threshing Clearance Adjustment, Check [It won't raise to the zero position]
- Rotor Speed Adjustment, Check
- Cleaning Fan Speed Adjustment, Check [No response to fan speed adjustment.]
- Chaffer and Sieve Setting Adjustment, Check
- Variable Stream Vanes Operation, Check [Not adjustable.]
- Powercast Functionality, Check

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
 Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
 Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
 Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
 Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
 Unlty, SK (306) 228-2696 Wynyard, SK (306) 554-2536
 North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
 Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: ***** PROFORMA INVOICE *****

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

[REDACTED]

Bus Phone: [REDACTED]
 Prv Phone: [REDACTED]

Invoice Number:
Invoice Date: 04/27/2026
Location: 10
Work Order Number: [REDACTED]
Payment Type: [REDACTED]

Page: 1 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2244	1H0S780SAJ0802072	102072U	

Service Reminders:
JFCC JD ALL Retail

COMPLAINT:
 02 FREE CLEANUP OF CAB

CORRECTION:
 Friday, April 17, 2026 11:07 AM - Wiped down all interior surfaces with an all purpose cleaner wiped and cleaned all interior windows with glass cleaner, and finally swept out little floor debris and scrubbed floor with all purpose cleaner cab in complete. B.O
 Thursday, April 23, 2026 2:12 PM - Checked and found the inside cab is clean already, i added a floor-mat plastic, so that at least it can't get dirtier until the customer can have it. just needing to clean the exterior and interior windshield window that i am going to do it tomorrow.
 Friday, April 24, 2026 6:11 AM - Performed cleaning on the outside and inside windshield window, and the rear view mirror. competed. SR.

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
LABDIS	LAB DISC CUST	-1.00	172.50	-\$172.50	Y
Labor: \$172.50	Parts: \$0.00	OL&M: \$0.00	Misc: -\$172.50	Sub-Total: \$0.00	

EXPERT-1000000314900 Retail

COMPLAINT:
 03 S-Series Combine ValueMax Inspection COMPLAINT
 S SERIES COMBINE VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION
 VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST

HEADER SERIAL # _____

ENGINE HOURS _____ 2244 _____

SEPERATOR HOURS _____ 1539 _____

DOES THIS UNIT GET A VALUEMAX STICKER __ YES __X__ NO

HAS THE STICKER BEEN INSTALLED __ YES __X__ NO



PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yerkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2636
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Workshop Sundry Invoice

Bus Phone:
Prv Phone:

[Redacted]

Bus Phone: [Redacted]
Prv Phone: [Redacted]

Invoice Number: **3435093**
 Invoice Date: 08/13/2025
 Location: 10
 Work Order Number: [Redacted]
 Payment Type: [Redacted]

Page: 1 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	1881	1H0S780SAJ0802072	102072U	

Service Reminders:

JSC RADIUS C Misc

COMPLAINT:

01 SERVICE CALL TO AND FROM MACHINE LOCATED IN RADIUS C.

CORRECTION:

Job Total: \$692.00

J06230003 JD S780 Misc

COMPLAINT:

02 REPLACE UNLOADING AUGER DRIVE CHAIN

CORRECTION:

Tuesday, August 12, 2025 10:11 PM - Installed the new chain and checked proper operation of unloading auger,

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE79735	80@199links UnloadAuger	1.00	597.81	\$597.81	N

Miscellaneous Charges:

SERVICE ACCESSORIES

\$65.00

Labor: \$210.00 Parts: \$597.81 OL&M: \$0.00 Misc: \$65.00 Sub-Total: \$872.81

Customer PO No:
 Tax Exempt No:
 Advisor: Joe Cadieux

Labor: \$650.00
 Parts: \$597.81
 OL&M: \$0.00
 Misc: \$317.00
 GST: \$0.00
 PST: \$0.00

Grand Total: \$1,564.81

Sundry G/L Entries

Br	Dpt	Acct	Sub	Ref	Description	Value
10	00	266	5	102072U	Warranty	\$1,564.81

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kinderley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Workshop Sundry Invoice

Bus Phone:

Prv Phone:

[Redacted]

Bus Phone: [Redacted]

Prv Phone:

Invoice Number:	3435093
Invoice Date	08/13/2025
Location:	10
Work Order Number:	[Redacted]
Payment Type:	[Redacted]
Page:	2 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	1881	1H0S780SAJ0802072	102072U	

Service Reminders:

TERMS AND CONDITIONS

Received by:

Date:



PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Mooseomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 306562733

Deliver To:

Internal Used Stock No. 245616 (Sold)

Bus Phone:
Prv Phone:

[Redacted]

Bus Phone:
Prv Phone:

Invoice Number: [Redacted]
 Invoice Date: 08/28/2025
 Location: 10
 Work Order Number:
 Payment Type: Account
 Page: 1 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S780	1867	1H0S780SAJ0802072	102072U	

Service Reminders:
JGEN01- Internal

COMPLAINT:

01 MIRROR BROKEN

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE63554	Rear View Mirror	1.00	109.94	\$109.94	N
Labor: \$122.00	Parts: \$109.94	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$231.94	

J06230060 JD S780 Internal

COMPLAINT:

02 REPLACE UNLOADING AUGER DRIVE BELTS

CAUSE:

CORRECTION:

REMOVED UNLOADING AUGER DRIVE CHAIN.
 REMOVED DRIVE PULLEY AND DRIVEN PULLEY SHIELDS.
 REPLACED DRIVE BELTS.
 REINSTALLED AND ADJUSTED DRIVE CHAIN.
 RAN AND TESTED OPERATION.

Wednesday, August 27, 2025 8:30 PM - We changed the belts and then once he tried it again the belts slipped so we pulled some grain out of the vertical auger and tightened the chain a bit more then he tried it again and we could hear whatever was plugging go through then it ran smoothly after that. TP/ KB

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH233198	Unloading Auger Drv Belt Set	2.00	354.25	\$708.50	N
Labor: \$674.00	Parts: \$708.50	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,382.50	

JSC RADIUS D Internal

COMPLAINT:

03 SERVICE CALL TO AND FROM MACHINE LOCATED IN RADIUS D.

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 306562733

Deliver To:

Internal Used [Redacted]

Bus Phone:
Prv Phone:

[Redacted]

Bus Phone:
Prv Phone:

Invoice Number: [Redacted]
 Invoice Date: 08/28/2025
 Location: 10
 Work Order Number: [Redacted]
 Payment Type: Account
 Page: 2 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S780	1867	1H0S780SAJ0802072	102072U	

Service Reminders:

CAUSE:

CORRECTION:

Job Total: \$1,064.60

Customer PO No:
 Tax Exempt No:
 Advisor: Joe Cadieux

Labor:	\$1,386.00
Parts:	\$818.44
OL&M:	\$0.00
Misc:	\$474.60
GST:	\$0.00
PST:	\$0.00
Grand Total:	\$2,679.04

TERMS AND CONDITIONS

Received by:

Date:



PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3381
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

[Redacted]

Bus Phone:
Prv Phone:

[Redacted]

Bus Phone:
Prv Phone:

Invoice Number: [Redacted]
 Invoice Date: 07/31/2025
 Location: 10
 Work Order Number: [Redacted]
 Payment Type: Account
 Page: 1 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	1874	1H0S780SAJ0802072	102072U	

Service Reminders:

JSC RADIUS D Misc

COMPLAINT:

01 SERVICE CALL TO AND FROM MACHINE LOCATED IN RADIUS D.

CORRECTION:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
ST MILE D	SERV TRK CHR G D	1.00	336.00	\$336.00	N
Labor: \$590.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$336.00	Sub-Total: \$926.00	

JENGD1AG1 JD ALL Misc

COMPLAINT:

02 PERFORM ENGINE DIAGNOSTICS- ENGINE OIL LEAKING FROM BREATHER

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS:_____

Thursday, July 31, 2025 12:27 PM - removed ocv housing and cleaned and freed up bearing that was stuck causing internals not to function as intended, reinstalled everything cleaned up oil mess and verified its working as intended. KB

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY22467	CLAMP	1.00	2.54	\$2.54	N
TY22468	Hose CLAMP	1.00	2.54	\$2.54	N
TY26675	15W-40 PLUS-50 II 9.46L	2.00	89.73	\$179.46	N
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF150	ENVIRO FEE	2.00	1.50	\$3.00	N

Miscellaneous Charges:

SERVICE ACCESSORIES \$90.50

Labor: \$315.00	Parts: \$184.54	OL&M: \$0.00	Misc: \$93.50	Sub-Total: \$593.04
------------------------	------------------------	-------------------------	----------------------	----------------------------

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 436-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 654-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Snaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Workshop Sundry Invoice

Bus Phone:
Prv Phone:

[Redacted]

Bus Phone: [Redacted]
Prv Phone: [Redacted]

Invoice Number: [Redacted]
 Invoice Date: 07/31/2025
 Location: 10
 Work Order Number: [Redacted]
 Payment Type: Account
 Page: 2 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	1874	1H0S780SAJ0802072	102072U	

Service Reminders:

Customer PO No:
 Tax Exempt No:
 Advisor: Joe Cadieux

Labor: \$905.00
 Parts: \$184.54
 OL&M: \$0.00
 Misc: \$429.50
 GST: \$0.00
 PST: \$0.00

Grand Total: \$1,519.04

Sundry G/L Entries

Br	Dpt	Acct	Sub	Ref	Description	Value
10	00	266	5	102072U	Warranty	\$1,519.04

TERMS AND CONDITIONS

Received by:

Date:

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 816708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Workshop Sundry Invoice

Bus Phone:
Prv Phone:

[Redacted]

Bus Phone: [Redacted]
Prv Phone:

Invoice Number: [Redacted]
 Invoice Date: 09/17/2025
 Location: 10
 Work Order Number: [Redacted]
 Payment Type: Account
 Page: 1 of 3

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2032	1H0S780SAJ0802072	102072U	

Service Reminders:

EXPERT-1000000177223 Misc

COMPLAINT:

02 Discharge Beater Bearings, Remove and Replace Replace discharger beater bearings. Both Sides

CORRECTION:

Wednesday, September 3, 2025 10:45 AM - kas kcs

- look up parts while in shop
- dont have all the parts, will take what we have and order the rest on emergency to hopefully have for tomorrow
- took out broken bolt for overshot gearbox bushing, tapped hole and made sure bolt went in
- took off vacuum fan tube and shielding around overshot drive area
- took off overshot pulley and belt
- took off lock collar and took off nuts on bearing flanges
- took off bearing outer flange but inner flange worn in on frame
- cut inner flange off, tapped bolts and spun nuts on, cut inner bearing race off and cleaned shaft.
- took off lock collar, flanges and bearing off on left side and cleaned shaft
- installed flanges and bearing on right side, installed flanges and bearing on left side, centered overshot beater, tightened lock collars, put pulley on right side, installed bushing, installed new belt, ran combine-good, put shields and covers on, put vacuum fan tube on. kas kcs customer could hear a squeaking sound coming from combine, rode with customer for several passes and squeak went away, customer happy. kas kcs
- Isolator borrowed from Floberg S7 800 that is in for engine- need to reinstall when it arrives
- installed isolator back on floberg's combine. kas

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
14M7296	M10x1.5 FlangeNut	5.00	2.16	\$10.80	N
26M4228	Woodruff Key M8x28 steel	1.00	9.17	\$9.17	N
AH129420	Pressed Flange TG72MSA	1.00	15.52	\$15.52	N
AH133191	Eccentric Locking Collar 35mm	1.00	24.41	\$24.41	N
AH139296	BALL BEARING	2.00	62.24	\$124.48	N
AH202007	PULLEY	1.00	537.31	\$537.31	N
GX21790	Bolt	1.00	27.75	\$27.75	N
H135410	Pressed Flange TG72MSB	2.00	8.60	\$17.20	N
H240895	Rethresher/Overshot V-belt	1.00	168.83	\$168.83	N
H81462	Spring	1.00	10.82	\$10.82	N
T41770	ISOLATOR	1.00	72.43	\$72.43	N
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
frt	FREIGHT	1.00	135.00	\$135.00	N

Labor: \$3,150.00 Parts: \$1,018.72 OL&M: \$0.00 Misc: \$135.00 Sub-Total: \$4,303.72

JSC RADIUS C Misc

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2535
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Workshop Sundry Invoice

Bus Phone:
Prv Phone:

STAYNOR FARMS LTD.
 PO BOX 211
 CHAD NELSON
 FRONTIER SK S0N 0W0

Bus Phone: (306)296-5151
 Prv Phone:

Invoice Number: **3469951**
 Invoice Date: 09/17/2025
 Location: 10
 Work Order Number: 508508
 Payment Type: Account

Page: 2 of 3

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2032	1H0S780SAJ0802072	102072U	

Service Reminders:

COMPLAINT:

01 SERVICE CALL TO AND FROM MACHINE LOCATED IN RADIUS C.

02 Discharge Beater Bearings, Remove and Replace Replace discharger beater bearings. Both Sides
 Wednesday, September 3, 2025 10:45 AM - kas kcs

- look up parts while in shop
- dont have all the parts, will take what we have and order the rest on emergency to hopefully have for tomorrow
- took out broken bolt for overshot gearbox bushing, tapped hole and made sure bolt went in
- took off vacuum fan tube and shielding around overshot drive area
- took off overshot pulley and belt
- took off lock collar and took off nuts on bearing flanges
- took off bearing outer flange but inner flange worn in on frame
- cut inner flange off, tapped bolts and spun nuts on, cut inner bearing race off and cleaned shaft.
- took off lock collar, flanges and bearing off on left side and cleaned shaft
- installed flanges and bearing on right side, installed flanges and bearing on left side, centered overshot beater, tightened lock collars, put pulley on right side, installed bushing, installed new belt, ran combine-good, put shields and covers on, put vacuum fan tube on. kas kcs customer could hear a squeaking sound coming from combine, rode with customer for several passes and squeak went away, customer happy. kas kcs
- isolator borrowed from Floberg S7 800 that is in for engine- need to reinstall when it arrives
- installed isolator back on floberg's combine. kas

CORRECTION:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
ST MILE C	SERV TRK CHR G	1.00	252.00	\$252.00	N
Labor: \$440.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$252.00	Sub-Total: \$692.00	

Customer PO No:
 Tax Exempt No:
 Advisor: Joanne Thronberg

Labor: \$3,590.00
 Parts: \$1,018.72
 OL&M: \$0.00
 Misc: \$387.00
 GST: \$0.00
 PST: \$0.00

Sundry G/L Entries

Br	Dpt	Acct	Sub	Ref	Description	Value
10	00	266	5	102072U	Warranty	\$4,995.72

Grand Total: \$4,995.72

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balfarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Mocsomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2097
Leader, SK (306) 629-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2535
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Workshop Sundry Invoice

Bus Phone:

Prv Phone:

[Redacted]

Bus Phone: [Redacted]

Prv Phone: [Redacted]

Invoice Number: [Redacted]

Invoice Date: 09/17/2025

Location: 10

Work Order Number: [Redacted]

Payment Type: Account

Page: 3 of 3

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2032	1H0S780SAJ0802072	102072U	

Service Reminders:

TERMS AND CONDITIONS

Received by:

Date:

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Workshop Sundry Invoice

Bus Phone:
Prv Phone:

[Redacted]

Bus Phone: [Redacted]
Prv Phone: [Redacted]

Invoice Number: [Redacted]
 Invoice Date: 11/19/2025
 Location: 10
 Work Order Number: [Redacted]
 Payment Type: Account
 Page: 1 of 5

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2238	1H0S780SAJ0802072	102072U	

Service Reminders:
JENGDIA3 JD ALL Misc

COMPLAINT:

01 PERFORM ENGINE DIAGNOSTICS- bad vibration and burning oil

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS: _____

Tuesday, November 4, 2025 11:54 AM - Before starting work, I inspected the engine and checked the oil level in the engine and the main engine gear case.
 Started the engine and warmed it up to operating temperature – vibration is noticeable.
 Searched for possible solutions regarding this issue.
 Performed cylinder electronic compression test, cylinder misfire test, and cylinder cutout test – all values are within specification.
 During a visual inspection of the running engine, detected oscillation of the cooling fan and strong vibration of the vacuum fan.
 Removed all belts from the engine and inspected all auxiliary components.
 Attempted to move the front damper as described in Service Advisor – the damper has play and needs to be replaced.SK.

Labor: \$1,050.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$1,050.00

JTRUCKING Misc

COMPLAINT:

02 TRUCKING CHARGES FOR PICK UP AND OR DELIVERY WITH SEMI.

CORRECTION:

Truck S780 (Duals) from Chad Nelson, Claydon area to PAG SH
 (LD# 32479 / Radius C)

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
PILOT14	PILOT 14	1.00	221.00	\$221.00	N
SEMIS7	SALES SEMI 7	1.00	578.00	\$578.00	N

Labor: \$0.29 Parts: \$0.00 OL&M: \$0.00 Misc: \$799.00 Sub-Total: \$799.29

J06020210 JD S780 Misc

COMPLAINT:

04 FRONT CRANKSHAFT DAMPENER R&R

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2655	Wynyard, SK (306) 554-2535
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 662-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Workshop Sundry Invoice

Bus Phone:
Prv Phone:

[Redacted]

Bus Phone: [Redacted]
Prv Phone: [Redacted]

Invoice Number: [Redacted]
 Invoice Date: 11/19/2025
 Location: 10
 Work Order Number: [Redacted]
 Payment Type: Account
 Page: 2 of 5

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2238	1H0S780SAJ0802072	102072U	

Service Reminders:

CORRECTION:

- If necessary, disconnect oil pressure sensor and crankshaft position sensor.
- Perform Fan Drive Belt - Removal
- Perform Accessory Belt - Removal
- Install JDG10996 - Flywheel Locking Tool through rear cylinder block flange and engage with flywheel ring gear.
- Perform Crankshaft Pulley - Removal
- Loosen and remove six hex head cap screws with washer from the damper hub.
- Install two guide pins through damper hub into crankshaft face to help hold damper hub.
- Loosen and remove flange head cap screw from the center of damper hub.
- Install JDG11315A - Thread Protector through damper hub center hole into threaded hole in crankshaft nose.
- Install JDG10543 - Forcing Screw through damper hub center until it bottoms on JDG11315A – Thread Protector in crankshaft nose.
- Turn forcing screw clockwise to remove damper hub.
- Remove JDG11315A - Thread Protector from crankshaft nose.
- Remove JDG10996 - Flywheel Locking Tool.
- Rotate engine flywheel with JDG820 - Flywheel Turning Tool until one button head cap screw is at 12 o'clock position.
- Install two cap screws into threaded holes of damper to aide in handling of damper.
- Loosen and remove 12 o'clock position button head cap screw from the damper to the crankshaft hub and insert a guide pin to support the balancer.
- Loosen and remove remaining button head cap screw from the damper to the crankshaft hub.
- Remove damper from the crankshaft hub.
- Select new Damper for the Installation.
- Install JDG10996 - Flywheel Locking Tool in rear flange of cylinder block to prevent crankshaft rotation when tightening damper hub cap screw.
- Perform Crankshaft Position Sensor - Installation
- Install one guide pin on the crankshaft hub for aide in locating damper assembly.
- Install two bolts into threaded holes of vibration damper to aide in handling of viscous damper, slide damper over guide pin to crankshaft hub.
- Install one button head cap screw through crankshaft balancer to hold the damper in position.
- Remove guide pin and install one button head cap screw through the damper to the crankshaft hub.
- Tighten crankshaft damper button head cap screws to specification of 25Nm(19 lb.-ft.)
- Install two guide pins to the crankshaft nose.
- Install the damper hub over guide pins and locate to damper bore.
- Secure damper hub using two cap screws with washer finger tight. Remove guide pins.
- Install remaining four cap screws finger tight through damper hub into crankshaft nose.
- Tighten six damper hub cap screws to specification(Torque-70 N·m (52 lb.-ft.)) as per sequence.
- Individually loosen the six damper hub cap screws to no load and retighten to specification(Torque Turn - 40 N·m (30 lb.-ft.) + 90° additional turn) in sequence.
- Install finger tight one flange head cap screw into the center hole of damper hub.
- Tighten cap screw to specification(30 N·m (23 lb.-ft.)).
- Perform Crankshaft Pulley - Installation.

Tuesday, November 4, 2025 5:06 PM - Removed the protective shields around the engine, removed the fan, and removed the fan and alternator belts – these need to be replaced. Removed the fan hub; the bearing has excessive play and needs replacement. The alternator belt idler pulley also has excessive play and needs replacement. The vacuum fan shaft, pulley housing, and bearings also need to be replaced (they have significant play). Removed the crankshaft pulley – it is worn and needs replacement. Removed the front damper (the bolts were barely holding it). Replaced the bearings and shaft with the pulley for the vacuum fan, and replaced the fan hub bearing. Reassembled everything in reverse



PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unly, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Workshop Sundry Invoice

Bus Phone:
Prv Phone:

[Redacted]

Bus Phone:
Prv Phone:

Invoice Number: [Redacted]
 Invoice Date: 11/19/2025
 Location: 10
 Work Order Number: [Redacted]
 Payment Type: Account
 Page: 3 of 5

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2238	1H0S780SAJ0802072	102072U	

Service Reminders:

order according to Service Advisor instructions. Installed a new front damper, crankshaft pulley, alternator idler, and new alternator, fan, and vacuum belts. Warmed the engine to operating temperature and checked under all operating conditions – engine vibration is absent.
 Done

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
19M7792	Screw M16x30 Flg 10.9	1.00	5.54	\$5.54	N
19M8088	CAP SCREW	6.00	7.48	\$44.88	N
26M6731	Shaft Key	2.00	9.02	\$18.04	N
AXE11655	BEARING	2.00	63.82	\$127.64	N
AXE21096	PULLEY	1.00	225.57	\$225.57	N
AXE46428	Pulley	1.00	286.86	\$286.86	N
GC00110	BOLT	2.00	2.19	\$4.38	N
H238831	Serpentine Belt	1.00	92.82	\$92.82	N
HXE21982	Housing	1.00	1,290.15	\$1,290.15	N
HXE32548	Eng Fan Serpentine Belt	1.00	97.07	\$97.07	N
HXE38073	Vacuum Fan Drive V-belt	1.00	40.23	\$40.23	N
HXE80992	Shaft	1.00	557.69	\$557.69	N
R524422	Hub	1.00	580.47	\$580.47	N
R529115	GASKET	1.00	237.42	\$237.42	N
R536126	Pulley	1.00	1,714.24	\$1,714.24	N
RE539805	Torsional Damper	1.00	5,504.95	\$5,504.95	N
RE567062	Roller Bearing NTN ET-CRI-0846	1.00	248.95	\$248.95	N
T20168	WASHER	6.00	1.00	\$6.00	N
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
frt	FREIGHT	1.00	135.00	\$135.00	N

Labor: \$1,155.00 Parts: \$11,082.90 OL&M: \$0.00 Misc: \$135.00 Sub-Total: \$12,372.90

JGEN04- Misc

COMPLAINT:

05 customer states it uses/loosing a litre of engine oil a day

CORRECTION:

Thursday, November 13, 2025 6:36 PM - Removed the pipes from both turbochargers—cold and hot sides. Visually, everything looks good. Removed the air filters; they were extremely clogged with dust. Replaced both sets of air filters. Performed several additional electronic engine compression tests and injector performance tests. Everything looks good. Completed a regeneration; it took four hours.

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 816708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2695	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Workshop Sundry Invoice

Bus Phone:
Prv Phone:

[Redacted]

Bus Phone:
Prv Phone:

Invoice Number: [Redacted]
 Invoice Date: 11/19/2025
 Location: 10
 Work Order Number: [Redacted]
 Payment Type: Account
 Page: 4 of 5

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2238	1H0S780SAJ0802072	102072U	

Service Reminders:

Inspected the engine—there is valve noise.
 The valves need adjustment.
 Inspected the engine breather—it was filled with condensation. Drained the water and blew it out with compressed air; the breather was excessively noisy when rotating. Replaced the breather with a new one

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE42065	DMS Secondary Air Filter	1.00	155.14	\$155.14	N
AXE42066	DMS Primary Air Filter	1.00	242.92	\$242.92	N
HXE11090	Primary EngAir Filter	1.00	461.37	\$461.37	N
HXE11091	Secondary EngAir Filter	1.00	325.55	\$325.55	N
RE550022	13.5L OCV unit	1.00	2,346.55	\$2,346.55	N

Labor: \$1,470.00 Parts: \$3,531.53 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$5,001.53

J06020110 JD S780 Misc

COMPLAINT:

06 ADJUST ENGINE VALVE CLEARANCE.

CORRECTION:

REMOVED APPLICABLE ENGINE SHIELDS AND SUPPORTS TO GAIN ACCESS TO VALVE COVER, (ALONG WITH TURBO AIR CROSS OVER TUBE, AND AIR FILTER HOUSING).
 REMOVED VALVE COVER FROM ENGINE.
 FOLLOWED SERVICE ADVISOR PROCEDURE FOR SETTING VALVES AND INJECTOR PRE-LOADS.
 REMOVED SEAL FROM VALVE COVER, REPLACED WITH NEW.
 RE-INSTALLED VALVE COVER TO MACHINE.
 RE-INSTALLED ALL REMOVED COMPONENTS AND SHIELDS.
 RAN UNIT, FUNCTION AND LEAK CHECKED.
 Done

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
R531581	GASKET	1.00	90.48	\$90.48	N
R531582	GASKET	1.00	91.30	\$91.30	N

Miscellaneous Charges:

SERVICE ACCESSORIES \$150.00

Labor: \$2,100.00 Parts: \$181.78 OL&M: \$0.00 Misc: \$150.00 Sub-Total: \$2,431.78

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2636
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Workshop Sundry Invoice

Bus Phone:
Prv Phone:

[Redacted]

Bus Phone: [Redacted]
Prv Phone: [Redacted]

Invoice Number: [Redacted]
 Invoice Date: 11/19/2025
 Location: 10
 Work Order Number: [Redacted]
 Payment Type: Account
 Page: 5 of 5

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S780	2238	1H0S780SAJ0802072	102072U	

Service Reminders:

Customer PO No:
 Tax Exempt No:
 Advisor: Joanne Thronberg

Labor: \$5,775.29
 Parts: \$14,796.21
 OL&M: \$0.00
 Misc: \$1,084.00
 GST: \$0.00
 PST: \$0.00

Grand Total: \$21,655.50

Sundry G/L Entries

Br	Dpt	Acct	Sub	Ref	Description	Value
10	00	266	5	102072U	Warranty	\$21,655.50

TERMS AND CONDITIONS

Received by:

Date:

