



TO

Work Order Invoice

REPRINT

Date: 02-04-25

Visit us at our website: www.brandt.ca

Remit to: Brandt Tractor Ltd. - 1 Brandt Way PO Box 3856 - Regina, SK S4P 3R8

Billing Inquiries: Please email us at transportar@brandt.ca

Sold To:

Ship To:

CUSTOMER
INVOICE

Year	Make / Model		VIN	License	Mileage	Unit/Stock
2017	Peterbilt / 579		1XPBDP9X3HD447916		995374	
Delivery Mileage	Delivery Date	Engine Hours	Engine Model / Serial #		Transmission Model/Serial #	
	12-16-16		MX13-13 Y125636 / Y125636		FULLER RTLO1818B 18 SPEED / P1008297	
Memo		P.O. Number	Open Date / Time		Complete	Service Writer
			01-20-25 / 09:18AM		01-20-25	

Tax ID Date: 02-24-99

Tax ID:

1 Peterbilt Platinum Courtesy Inspection

TOTAL LABOR

0.00

2 CEL

CAUSE:

Check DPF and see if cleanable first, look for any signs of over fueling.

P0275 - Cylinder 5, torque contribution low

p0305 - Cylinder 5, contribution too low or misfire

P1305 - Cylinder 5, intermittent misfire

P3797 - DPF soot level

P3798 - DPF soot level

P3880 - Hydrocarbon storage

P3896 - DPF filtration efficiency, too much soot detected

CORRECTION:

Brought truck in and read codes. Removed and inspected DPF first as requested by customer. DPF Filter media has shifted rearward into the EGT probes causing a breach, it is also soot loaded. Evidence of exhaust leaks from around the DOC heat shield noted. EGT probes damaged by the shifted DPF filter media. Referred to RMI for P0305 troubleshooting. RMI first refers you to E290 injector cleaning procedure. Checked stock, 1 injector available on hand. Not a warranty case. Unable to meet conditions to perform a Cylinder performance test. Unable to complete a compression test, batteries weak. Next step is to visually inspect rockers and jake assemblies. Engine covered in bird feces, moved to wash bay and cleaned under hood. Moved truck back

SERVING SASKATCHEWAN	SERVING ONTARIO				
	Ayr (519) 622-7799	Barrie (705) 431-7175	Belleville (343) 453-0348	Cardinal (613) 657-1300	Hagersville (905) 768-1300
	London (519) 686-1000	Mississauga (905) 268-2000	North Bay (705) 472-4000	Ottawa (613) 831-2940	Stoney Creek (905) 643-1214
	Sudbury (705) 222-1144	Vittoria (519) 426-9001	Whitby (905) 665-8888	Windsor (519) 737-6999	
-11					

Work Order Invoice

Date: 02-04-25

Year	Make / Model	VIN	License	Mileage	Unit/Stock
2017	Peterbilt / 579	1XPBDP9X3HD447916		995374	
Delivery Mileage	Delivery Date	Engine Hours	Engine Model / Serial #	Transmission Model/Serial #	
	12-16-16		MX13-13 Y125636 / Y125636	FULLER RTLO18918B 18 SPEED / P1008297	

Memo	P.O. Number	Open Date / Time	Complete	Service Writer
		01-20-25 / 09:18AM	01-20-25	AJE*AJE

Tax ID Date: 02-24-99 Tax ID:

into bay, allowed batteries to charge. Performed comparative compression test, cylinder 5 is 23% low compared to others.

TOTAL LABOR	3,075.00
TOTAL PACCAR	12,409.10

Qty	Part Number	Description	Unit	Extended
1	2274611PE	DPF KIT, W/ CLAMPS, GASKE	5,624.84	5,624.84
1	2129818PE	SENSOR, TEMPERATURE	537.63	537.63
2	90-0013	CLAMP-V BAND 5"	19.86	39.72
2	1844253PE	GASKET-EXHAUST CIRCULAR 5	24.66	49.32
1	1978266PE	DOC (INLET MODULE)	6,157.59	6,157.59

3 diagnose low compression cylinder 5 - approved for repair
 CAUSE:

CORRECTION:

Removed intake assembly, removed valve cover. Discovered bent intake pushrod on cyl 5 and the valve bridge laying in the head. All valves are far out of adjustment loose. Inspected lifter from above with an inspection camera. Removed oil filters and inspected for contamination, none found. Drained and removed oil pan, inspected cam and lifters, no damage found.

TOTAL LABOR	1,435.00
TOTAL PACCAR	737.42
TOTAL GAS/OIL	257.14
TOTAL ENVIRONMENT CHG	3.80

Qty	Part Number	Description	Unit	Extended
1	1924761PE	GASKET-VALVE COVER	177.53	177.53
1	2111441PE	GASKET, OIL PAN	321.83	321.83
1	2014634PE	ROD-TAPPET, INLET VALVE	36.66	36.66
1	1673526PE	ADJUSTING SCREW	18.09	18.09
1	1673527PE	NUT-HEX METRIC F	7.45	7.45
1	1313120PE	BOLT-FLANGE M8X55	0.89	0.89
1	1922496PE	PACCAR OIL ELEMENT-CENTRI	91.56	91.56
1	1948921PE	PACCAR OIL ELEMENT	83.41	83.41
46	257000-990C	CHV DELO400XLE SYNBLN10W30	5.59	257.14

SERVING SASKATCHEWAN		SERVING ONTARIO				
		Ayr (866)-539-7383	Barrie (888)-221-2191	Belleville (343)-453-0348	Cardinal (877)-657-1300	Hagersville (800)-544-9874

London (800)-561-7383	Mississauga (877)-268-0020	North Bay (800)-734-9876	Ottawa (888)-220-2642	Stoney Creek (844)-643-1214
Sudbury (866)-220-6099	Vittoria (877)-426-9001	Whitby (888)-471-8888	Windsor (844)-737-6999	

Work Order Invoice

RS124706

Date: 02-04-25

Year	Make / Model	VIN	License	Mileage	Unit/Stock
2017	Peterbilt / 579	1XPBDP9X3HD447916		995374	
Delivery Mileage	Delivery Date	Engine Hours	Engine Model / Serial #	Transmission Model/Serial #	
	12-16-16		MX13-13 Y125636 / Y125636	FULLER RTLO18918B 18 SPEED / P1008297	

Memo	P.O. Number	Open Date / Time	Complete	Service Writer
		01-20-25 / 09:18AM	01-20-25	

Tax ID Date: 02-24-99 Tax ID:

1 1922496PE&	ENV CHG	0.50	0.50
1 1948921PE&	ENV CHG	1.00	1.00
46 257000-990C&	ENV CHG	0.05	2.30

4 approved for 1 push rod - labor only - parts on condition 3

TOTAL LABOR 1,435.00

CARBON TAX SURCHARGE	118.90
SHOP SUPPLIES	535.05

G.S.T. - REG. NO. 899544779 5.00 % OF 20,006.41 = 1,000.32

PPD ENVIRON. TAX REG	3.80
SLS SERV RETAIL	5,945.00
SLS SHOP SUPP REG SV	535.05
SLS PAC PTS RO REG	13,146.52
ENVIRONMENTAL FEE	118.90
SLS G O G REG	257.14
G.S.T. 899544779	1,000.32
K0000 CASH SALE	21,006.73

CCCCCC	000000	DDDDDDDD
CCC CCC	00000000	DDDDDDDDDD
CCC	000 000	DDD DDD
CCC	000 000	DDD DDD
CCC CCC	00000000	DDDDDDDD
CCCCCC	000000	DDDDDDDD

SERVING SASKATCHEWAN

SERVING ONTARIO

Ayr	Barrie	Cardinal	Hagersville	London
(366)-539-7383	(888)-221-2191	(877)-657-1300	(800)-544-9874	(800)-561-7383
Mississauga	North Bay	Ottawa	Stoney Creek	Sudbury
(877)-268-0020	(800)-734-9876	(888)-220-2642	(844)-643-1214	(866)-220-6099
Vittoria	Whitby	Windsor	Woodstock	
(877)-426-9001	(888)-471-8888	(844)-737-6999	(800)-287-9878	

Work Order Invoice

Date: 02-04-25

Year	Make / Model	VIN	License	Mileage	Unit/Stock
2017	Peterbilt / 579	1XPBDP9X3HD447916		995374	
Delivery Mileage	Delivery Date	Engine Hours	Engine Model / Serial #	Transmission Model/Serial #	
	12-16-16		MX13-13 Y125636 / Y125636	FULLER RTLO18918B 18 SPEED / P1008297	

Memo	P.O. Number	Open Date / Time	Complete	Service Writer
L&K Bumphrey Trucking bumphrey_ryan@hotmail.com		01-20-25 / 09:18AM	01-20-25	

Tax ID Date: 02-24-99

Tax ID:

I/WE HEREBY ACKNOWLEDGE MY/OUR INDEBTEDNESS TO BRANDT TRACTOR LTD. IN RESPECT OF THIS INVOICE. I/WE AGREE TO THE TERMS OF THE SALE LISTED BELOW.

PAYMENT TERMS: DUE AND PAYABLE NET 30 FOLLOWING THE INVOICE DATE. IT IS UNDERSTOOD AND I AGREE TO PAY CARRYING CHARGES OF 2% ON OVERDUE ACCOUNTS.

1. LIMITED WARRANTY:

1. When does the warranty apply?
 - a) ONLY WHEN THE CUSTOMER INFORMS THE SERVICE MANAGER OF BRANDT TRACTOR LTD. WITHIN 30 DAYS OR 6,500 KM OF DISCOVERY OF THE ALLEGED DEFECT, WHICH EVER HAPPENS FIRST.
2. What is the effect of the warranty?
 - a) THE CUSTOMER IN CONSIDERATION OF THIS WARRANTY WAIVES ANY CLAIM AGAINST BRANDT TRACTOR LTD., ITS AGENT OR EMPLOYEES.
3. Who is covered by Warranty?
 - a) ONLY THE ORIGINAL CUSTOMER.
4. What is covered by Warranty?
 - a) MATERIAL AND WORKMANSHIP WHICH TOGETHER DO NOT EXCEED THE AMOUNT ORIGINALLY CHARGED TO THE CUSTOMER.
5. What is NOT covered by Warranty?
 - a) DAMAGE CAUSED BY MISUSE, ACCIDENT, ROAD HAZARDS, NEGLECT, PAYMENT OF LOSS OF TIME BY REASON OF THE ALLEGED DEFECT AND WARRANTY, REPAIRS, PAYMENT FOR LOSS OF USE OF VEHICLE BY REASON OF ALLEGED DEFECT AND WARRANTY REPAIRS, INCONVENIENCE, CONSEQUENTIAL DAMAGE.
6. Where are warranty repairs to be done?
 - a) AT A LOCATION AUTHORIZED BY BRANDT TRACTOR LTD.

2. RESPONSIBILITY FOR EQUIPMENT: BRANDT TRACTOR LTD. WILL NOT BE HELD RESPONSIBLE FOR LOSS TO VEHICLES, OR ARTICLES LEFT IN VEHICLES, IN CASE OF FIRE, THEFT, ACCIDENT, OR ANY OTHER CAUSE BEYOND THE CONTROL OF BRANDT TRACTOR LTD.

3. ALL OLD PARTS REMOVED WILL BE DISPOSED OF, UNLESS OTHERWISE SPECIFIED BEFORE REPAIRS STARTED.

4. THE SIGNATURE OF THE OWNER DULY AUTHORIZED REPRESENTATIVE ON THE ORIGINAL WORK ORDER REQUEST, AUTHORIZED THE REPAIR AND SERVICE WORK LISTED ON THIS REPAIR ORDER, ALONG WITH THE NECESSARY MATERIAL.

5. THE DEALER'S RIGHT TO REGISTER AN EXPRESS MECHANICS LIEN TO SECURE THE AMOUNT OF THE REPAIRS AND OTHER APPLICABLE CHARGES THERETO IS ACKNOWLEDGED.

Customer: X

Date: _____

SERVING SASKATCHEWAN		SERVING ONTARIO				
		Ayr	Barnie	Belleville	Cardinal	Hagersville
		(366)-539-7383	(888)-221-2191	(343)-453-0348	(877)-657-1300	(800)-544-9874
		London	Mississauga	North Bay	Ottawa	Stoney Creek
		(300)-561-7383	(877)-268-0020	(800)-734-9876	(888)-220-2642	(844)-643-1214
		Sedbury	Victoria	Whitby	Windsor	
		(866)-220-6099	(877)-426-9001	(888)-471-8888	(844)-737-6999	