



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 9/9/2024 <b>Location:</b> 05 <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> Account  <b>Page:</b> 1 of 14
--------------------------	--------------------------	---

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2020 JD S780 COMBINE	1343	1H0S780SLLT810823	1H0S780SLLT810823	#6

**/SPS780 Internal**  
 COMPLAINT:  
 02 GREENLIGHT SERVICE INSPECTION COMBINE

CORRECTION:

<b>Labor:</b> \$1,899.00	<b>Parts:</b> \$0.00	<b>OL&amp;M:</b> \$0.00	<b>Misc:</b> \$0.00	<b>Sub-Total:</b> \$1,899.00
--------------------------	----------------------	-------------------------	---------------------	------------------------------

**/GLOPCLEANS780 Internal**  
 COMPLAINT:  
 03 GREENLIGHT/RECONDITION CLEANING CHECKLIST - REMOVE #3 DECALS

CORRECTION:  
 CLEANED COMBINE

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
19M7783	Flange Head Cap Screw M10 X 16 GR10.9	6.00	2.20	2.20	\$13.20	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	75.60	75.60	\$75.60	N

<b>Labor:</b> \$1,260.00	<b>Parts:</b> \$13.20	<b>OL&amp;M:</b> \$0.00	<b>Misc:</b> \$75.60	<b>Sub-Total:</b> \$1,348.80
--------------------------	-----------------------	-------------------------	----------------------	------------------------------

**/150505S780 Internal**  
 COMPLAINT:  
 04 CALIBRATE FEEDER HOUSE FORE/AFT

CORRECTION:  
 CALIBRATED WHEN RUNNING UNIT.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

<b>Invoice Number:</b> [REDACTED]	<b>Invoice Date:</b> 9/9/2024	<b>Location:</b> 05	<b>Work Order Number:</b> [REDACTED]
<b>Bus Phone:</b>	<b>Bus Phone:</b>	<b>Payment Type:</b> Account	<b>Page:</b> 2 of 14
<b>Prv Phone:</b>	<b>Prv Phone:</b>		

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2020 JD S780 COMBINE	1343	1H0S780SLLT810823	1H0S780SLLT810823	#6

<b>/150505S780 Internal</b>						
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N
<b>Labor: \$53.10</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$3.19</b>	<b>Sub-Total: \$56.29</b>		

**/10160050S780 Internal**  
 COMPLAINT:  
 05 UPDATE ALL AMS COMPONENTS SOFTWARE - GEN 4 DISPLAY

CORRECTION:  
 DOWNLOADED AND UPDATED GEN 4.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
<b>Labor: \$177.00</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$10.62</b>	<b>Sub-Total: \$187.62</b>		

**Gen6- Internal**  
 COMPLAINT:  
 06 UPDATE SOFTWARE - PTP

CORRECTION:  
 DOWNLOADED PAYLOAD. PUSHED SOFTWARE.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
<b>Labor: \$88.50</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$5.31</b>	<b>Sub-Total: \$93.81</b>		

**/150428S780 Internal**  
 COMPLAINT:  
 07 REPLACE OR RECHARGE FIRE EXTINGUISHER ON CAB LADDER -



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

<b>Invoice Number:</b> [REDACTED]	<b>Invoice Date:</b> 9/9/2024	<b>Location:</b> 05	<b>Work Order Number:</b> [REDACTED]
<b>Bus Phone:</b>	<b>Bus Phone:</b>	<b>Payment Type:</b> Account	<b>Page:</b> 3 of 14
<b>Prv Phone:</b>	<b>Prv Phone:</b>		

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2020 JD S780 COMBINE	1343	1H0S780SLLT810823	1H0S780SLLT810823	#6

**/150428S780 Internal**  
 CORRECTION:  
 REMOVED AND REPLACED

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AT184159	10LB ABC FIRE EXTINGUISHER	1.00	214.85	214.85	\$214.85	N
<b>Miscellaneous</b>	<b>DESCRIPTION</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>
SERVACCESS	SERVICE ACCESSORIES	1.00	1.06	1.06	\$1.06	N
<b>Labor: \$17.70</b>		<b>Parts: \$214.85</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$1.06</b>
						<b>Sub-Total: \$233.61</b>

**GEN8- Internal**  
 COMPLAINT:  
 08 INSTALL WATER CANNON ON REAR LADDER LANDING - PREVIOUS CUSTOMER SUPPLYING

CORRECTION:

<b>Labor: \$0.00</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$0.00</b>	<b>Sub-Total: \$0.00</b>
----------------------	----------------------	-------------------------	---------------------	--------------------------

**/150365S780 Internal**  
 COMPLAINT:  
 11 REPLACE HEADER CLUTCH WIRING STRAP

CORRECTION:  
 REMOVED BROKE STRAP AND INSTALLED NEW ONE.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
H134773	STRAP	1.00	8.46	8.46	\$8.46	N
<b>Miscellaneous</b>	<b>DESCRIPTION</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 9/9/2024 <b>Location:</b> 05 <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> Account  <b>Page:</b> 4 of 14
--------------------------	--------------------------	---

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2020 JD S780 COMBINE	1343	1H0S780SLLT810823	1H0S780SLLT810823	#6

<b>/150365S780 Internal</b>						
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N
<b>Labor: \$53.10</b>		<b>Parts: \$8.46</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$3.19</b>	<b>Sub-Total: \$64.75</b>	

**GEN12- Internal**  
 COMPLAINT:  
 12 REPAIR SHOE SUPPLY AUGERS #1, #3 & #4 - GEARS LOOSE ON SHAFTS

CORRECTION:  
 LOOSENED SHOE DRIVE BELT. REMOVED SHOE AUGER 1,3,4. REMOVED BEVEL GEARS. INSTALLED NEW BEVEL GEARS AND ROLL PINS. AUGER SHAFTS LOOKED GOOD. GEARS ARE TIGHT ON SHAFT NOW. RE-INSTALLED AUGER IN AUGER BED. ADJUSTED #1 AND 4 TO 1/32" GAP AS PER SPEC. TENSIONED SHOE DRIVE BELT.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
E63018	SPRING PIN	3.00	5.32	5.32	\$15.96	N
H137215	Bevel Gear 13 Tooth	3.00	70.39	70.39	\$211.17	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	63.72	63.72	\$63.72	N
<b>Labor: \$1,062.00</b>		<b>Parts: \$227.13</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$63.72</b>	<b>Sub-Total: \$1,352.85</b>	

**/1415190S780 Internal**  
 COMPLAINT:  
 13 REPLACE FILLER PLATES IN CONCAVE - MISSING \*\*GET FROM PREVIOUS CUSTOMER

CORRECTION:

<b>Labor: \$0.00</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$0.00</b>	<b>Sub-Total: \$0.00</b>
----------------------	----------------------	-------------------------	---------------------	--------------------------



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

<b>Invoice Number:</b> [REDACTED]	<b>Invoice Date:</b> 9/9/2024	<b>Location:</b> 05	<b>Work Order Number:</b> [REDACTED]
<b>Bus Phone:</b>	<b>Bus Phone:</b>	<b>Payment Type:</b> Account	<b>Page:</b> 5 of 14
<b>Prv Phone:</b>	<b>Prv Phone:</b>		

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2020 JD S780 COMBINE	1343	1H0S780SLLT810823	1H0S780SLLT810823	#6

**/10180250AS780 Internal**

**COMPLAINT:**

14 CONCAVE LEVEL, ADJUST AND CALIBRATE (WITH ACI)

**CORRECTION:**

STARTED COMBINE AND SET CONCAVES TO 0. REMOVED LEVELING SCREWS FROM Z BAR BRACKET AND INSTALLED IN Z BAR RAIL. REMOVED SEPARATOR GRATES TO SPIN ROTOR OVER. REMOVE BOTH CYLINDER LOCKS. HAND TIGHTENED LEVELING SCREW AND LEVELING SCREW NUTS TO Z BAR RAIL. LOOSENED JAM NUT AND CYLINDER STOP ON BOTH CYLINDERS. UNPLUGGED CYLINDER SENSORS. ENTERED CONCAVE LEVELING CALIBRATION IN CAB DISPLAY. SHIFTED ROTOR TO NEUTRAL. SPUN ROTOR AND TIGHTENED REAR LEVELING CAP SCREW TILL ROTOR TICKED ON THE SPINNING CONCAVE. BACKED OFF LEVELING CAP SCREW 3 TURNS. DID THE SAME FOR FRONT LEVELING CAP SCREW. TIGHTENED REAR LEVELING CAP SCREW AGAIN TILL ROTOR TICKED, BACKED OFF 1.5 TURNS. DID THE SAME FOR FRONT LEVELING CAP SCREW. TIGHTENED BOTH LEVELING SCREWS SO THEY COULDN'T MOVE. TURNED BOTH CYLINDER STOPS UNTIL THEY WERE TIGHT AGAINST CYLINDER BARREL. TIGHTENED JAM NUT AGAINST CYLINDER STOP ON BOTH CYLINDERS. PLUGGED SENSORS BACK IN. FINISHED CONCAVE LEVELING CALIBRATION. STORED LEVELING CAP SCREWS IN BRACKET. DID THRESHING CLEARANCE CALIBRATION, CALIBRATION WAS SUCCESSFUL. RE-INSTALLED ROTOR GRATES AND TORQUED TO 54 FT-LBS (HEAVY DUTY TYPE). SHIFTED ROTOR INTO GEAR.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	23.90	23.90	\$23.90	N
<b>Labor: \$398.25</b>		<b>Parts: \$0.00</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$23.90</b>
						<b>Sub-Total: \$422.15</b>

**/110057S780 Internal**

**COMPLAINT:**

15 REPLACE CONNECTOR LINK FROM TAILINGS PADDLE CHAIN AND ADJUST - NOT HOOKED UP AND BENT

**CORRECTION:**

LOOSENED BELT TO SPIN CHAIN OVER. REMOVED BENT LINK. INSTALLED NEW LINK. TIGHTENED BELT.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH166638	#CA550 Connector Link	1.00	22.30	22.30	\$22.30	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 9/9/2024 <b>Location:</b> 05 <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> Account  <b>Page:</b> 6 of 14
--------------------------	--------------------------	---

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2020 JD S780 COMBINE	1343	1H0S780SLLT810823	1H0S780SLLT810823	#6

<b>/110057S780 Internal</b>							
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N	
<b>Labor: \$88.50</b>		<b>Parts: \$22.30</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$5.31</b>	
				<b>Sub-Total: \$116.11</b>			

**GEN16- Internal**  
 COMPLAINT:  
 16 REPLACE TOP TAILINGS RETHRESHER DRIVE CHAIN IDLER AND HEX BUSHING

CORRECTION:  
 REMOVED OLD IDLER AND BUSHING AND INSTALLED NEW ONE.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
AXE23133	Idler Sprocket 15 Teeth	1.00	87.73	87.73	\$87.73	N	
H216427	Spacer	1.00	20.01	20.01	\$20.01	N	
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N	
<b>Labor: \$88.50</b>		<b>Parts: \$107.74</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$5.31</b>	
				<b>Sub-Total: \$201.55</b>			

**/170452S780 Internal**  
 COMPLAINT:  
 17 REPLACE LOADING AUGER GEARCASE DIPSTICK - MISSING, HAS PLUG INSTALLED

CORRECTION:  
 REMOVED AND REPLACED DIPSTICK

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH166047	Dipstick	1.00	41.54	41.54	\$41.54	N
R26375	O-Ring	1.00	4.04	4.04	\$4.04	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 9/9/2024 <b>Location:</b> 05 <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> Account  <b>Page:</b> 7 of 14
--------------------------	--------------------------	---

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2020 JD S780 COMBINE	1343	1H0S780SLLT810823	1H0S780SLLT810823	#6

<b>/170452S780 Internal</b>						
SERVACCESS	SERVICE ACCESSORIES	1.00	1.06	1.06	\$1.06	N
<b>Labor: \$17.70</b>		<b>Parts: \$45.58</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$1.06</b>	<b>Sub-Total: \$64.34</b>	

**/10190090S780 Internal**  
 COMPLAINT:  
 18 REPLACE UPPER CLEAN GRAIN SHAFT BEARING AND SPROCKET - OUTER FAILED

CORRECTION:  
 REMOVED SHIELDS, REMOVED BELT AND PULLEY, REMOVED SHAFT/BEARINGS/SPROCKET, REPLACED BEARINGS AND SPROCKET, PUT EVERYTHING BACK TOGETHER.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH133191	Eccentric Locking Collar	2.00	25.89	25.89	\$51.78	N
H153308	Pressed Flanged Housing	4.00	14.65	14.65	\$58.60	N
H228385	Chain Sprocket	1.00	118.64	118.64	\$118.64	N
H84026	J Hook	2.00	0.93	0.93	\$1.86	N
JD39104	Ball Bearing	2.00	62.12	62.12	\$124.24	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	53.10	53.10	\$53.10	N
<b>Labor: \$885.00</b>		<b>Parts: \$355.12</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$53.10</b>	<b>Sub-Total: \$1,293.22</b>	

**/10040060S780 Internal**  
 COMPLAINT:  
 19 REPLACE VISIONTRAK SENSOR - REAR RIGHT HAND NOT WORKING

CORRECTION:  
 REMOVED OLD SENSOR AND INSTALLED NEW. TESTED AND WORKING PROPERLY NOW.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

<b>Invoice Number:</b> [REDACTED]	<b>Invoice Date:</b> 9/9/2024	<b>Location:</b> 05	<b>Work Order Number:</b> [REDACTED]
<b>Bus Phone:</b>	<b>Bus Phone:</b>	<b>Payment Type:</b> Account	<b>Page:</b> 8 of 14
<b>Prv Phone:</b>	<b>Prv Phone:</b>		

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2020 JD S780 COMBINE	1343	1H0S780SLLT810823	1H0S780SLLT810823	#6

<b>/10040060S780 Internal</b>						
AXE55969	Grain Loss Monitoring System Sensor	1.00	290.67	290.67	\$290.67	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	13.28	13.28	\$13.28	N
<b>Labor: \$221.25</b>		<b>Parts: \$290.67</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$13.28</b>
				<b>Sub-Total: \$525.20</b>		

**GEN20- Internal**  
 COMPLAINT:  
 20 REMOVE BROKEN LOUVER ON LEFT SECTION ADJUSTABLE PRECLEANER AND REPAIR - CHECK SALES SHELF FOR PARTS

CORRECTION:  
 REMOVED LEFT SECTION OF PRE-CLEANER. REMOVED BROKEN LOUVER. USED 2 LOUVERS FROM SALES SHELF. INSTALLED IN PRE-CLEANER SECTION. RE-INSTALLED SECTION BACK IN PRE-CLEANER.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
<b>Labor: \$177.00</b>		<b>Parts: \$0.00</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$10.62</b>
				<b>Sub-Total: \$187.62</b>		

**/1705081S780 Internal**  
 COMPLAINT:  
 22 REVERSE OVERSHOT BEATER WEAR STRIPS AND STRAIGHTEN

CORRECTION:  
 REMOVED WEAR STRIPS, STRAIGHTENED IN PRESS. RE-INSTALLED WEAR STRIPS, TORQUED TO 58 FT-LBS AS PER SPEC.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> Invoice Date: 9/9/2024 Location: 05 Work Order Number: Payment Type: Account Page: 9 of 14
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2020 JD S780 COMBINE	1343	1H0S780SLLT810823	1H0S780SLLT810823	#6

<b>/1705081S780 Internal</b>						
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N
<b>Labor: \$354.00</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$21.24</b>	<b>Sub-Total: \$375.24</b>		

**/10172010S780 Internal**  
 COMPLAINT:  
 23 R&R STRAW CHOPPER HAMMERS - 1 SET - CHECK SALES SHELF BEFORE GETTING FROM PARTS

CORRECTION:  
 REMOVED BROKEN SET OF BLADES. FOUND A SET OF BLADES ON SALES SHELF. INSTALLED NEW BLADES, BUSHINGS WERE STILL IN GOOD SHAPE. TORQUED NEW HARDWARE TO 52 FT-LBS AS PER SPEC.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE118760	Lock Nut M10	6.00	2.67	2.67	\$16.02	N
HXE119246	Hex Head Bolt M10 X 55	6.00	5.49	5.49	\$32.94	N
HXE15909	Flanged Spacer	2.00	20.68	20.68	\$41.36	N
HXE59496	Flanged Bushing	2.00	17.75	17.75	\$35.50	N
<b>Miscellaneous</b>	<b>Description</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>
SERVACCESS	SERVICE ACCESSORIES	1.00	31.86	31.86	\$31.86	N
<b>Labor: \$531.00</b>	<b>Parts: \$125.82</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$31.86</b>	<b>Sub-Total: \$688.68</b>		

**/10172050S780 Internal**  
 COMPLAINT:  
 24 REPLACE STRAW CHOPPER STATIONARY KNIVES

CORRECTION:  
 REMOVED KNIFE BANK, REMOVED OLD KNIVES. INSTALLED NEW KNIVES AND RE-INSTALLED KNIFE BANK.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 9/9/2024 <b>Location:</b> 05 <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> Account  <b>Page:</b> 10 of 14
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2020 JD S780 COMBINE	1343	1H0S780SLLT810823	1H0S780SLLT810823	#6

<b>/10172050S780 Internal</b>								
H215004	Stationary Chopper Blade	39.00	16.31	16.31	\$636.09	N		
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>		
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N		
<b>Labor: \$132.75</b>	<b>Parts: \$636.09</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$7.97</b>	<b>Sub-Total: \$776.81</b>				

**GEN25- Internal**  
 COMPLAINT:  
 25 REPLACE MISSING BLADE ON CENTER CHOPPER FLOOR

CORRECTION:  
 REPLACED MISSING CENTER BLADE.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
19M7867	Flange Head Cap Screw M8 X 25 GR10.9	1.00	1.69	1.69	\$1.69	N	
H137328	Flange Lock Nut M8	1.00	2.04	2.04	\$2.04	N	
HXE21494	Extra Fine Cut Stationary Blade	1.00	127.47	127.47	\$127.47	N	
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N	
<b>Labor: \$177.00</b>	<b>Parts: \$131.20</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$10.62</b>	<b>Sub-Total: \$318.82</b>			

**GEN26- Internal**  
 COMPLAINT:  
 26 REMOVE RIGHT PREMIUM SPREADER SHROUD AND STRAIGHTEN - SPREADER HITTING SHROUD

CORRECTION:  
 REMOVED SPREADER WHEELS HOUSING WITH SPREADERS, REMOVED RIGHT SPREADER SHROUD, STRAIGHTENED UP SPREADER SHROUD, PAINTED. REMOVED SPREADER WHEELS, REMOVED FINGERS WITH PLATES FROM SPREADER WHEELS, INSTALLED SPREADER WHEELS WITH NEW KEYS, LINED UP AND INSTALLED SPREADER WHEELS HOUSING. PUT EVERYTHING BACK TOGETHER TORQUED, TESTED AND CALIBRATED.



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 9/9/2024 <b>Location:</b> 05 <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> Account  <b>Page:</b> 11 of 14
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2020 JD S780 COMBINE	1343	1H0S780SLLT810823	1H0S780SLLT810823	#6

**GEN26- Internal**

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
03M7185	Carriage Bolt M8 X 25	6.00	0.65	0.65	\$3.90	N
03M7187	Carriage Bolt M8 X 35	4.00	1.69	1.69	\$6.76	N
14M7298	Flange Nut M8	6.00	1.45	1.45	\$8.70	N
19M7865	Flange Head Cap Screw M8 X 16 GR10.9	4.00	1.60	1.60	\$6.40	N
40M1821	Snap Ring	1.00	3.11	3.11	\$3.11	N
49M7061	Shaft Key Round Ends M8 X 7 X 32	1.00	1.33	1.33	\$1.33	N
H137328	Flange Lock Nut M8	4.00	2.04	2.04	\$8.16	N
<b>Miscellaneous</b>	<b>Description</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>
SERVACCESS	SERVICE ACCESSORIES	1.00	63.72	63.72	\$63.72	N
<b>Labor: \$1,062.00</b>		<b>Parts: \$38.36</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$63.72</b>	<b>Sub-Total: \$1,164.08</b>	

**/142804S780 Internal**

COMPLAINT:  
 27 REPLACE HOPPER CANVAS, LEFT FRONT CORNER

CORRECTION:  
 REMOVED OLD CANVAS AND INSTALLED NEW ONE.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE85635	Canvas	1.00	607.45	607.45	\$607.45	N
<b>Miscellaneous</b>	<b>Description</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N
<b>Labor: \$265.50</b>		<b>Parts: \$607.45</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$15.93</b>	<b>Sub-Total: \$888.88</b>	



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

<b>Invoice Number:</b> [REDACTED]	<b>Invoice Date:</b> 9/9/2024	<b>Location:</b> 05	<b>Work Order Number:</b> [REDACTED]
<b>Bus Phone:</b>	<b>Bus Phone:</b>	<b>Payment Type:</b> Account	<b>Page:</b> 12 of 14
<b>Prv Phone:</b>	<b>Prv Phone:</b>		

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2020 JD S780 COMBINE	1343	1H0S780SLLT810823	1H0S780SLLT810823	#6

**/150366S780 Internal**  
 COMPLAINT:  
 28 REPLACE FUEL TANK GRIP

CORRECTION:  
 HEATED AND REMOVED OLD GRIP. INSTALLED NEW FUEL TANK GRIP.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE153291	Mat	1.00	133.82	133.82	\$133.82	N
<b>Miscellaneous</b>	<b>DESCRIPTION</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
<b>Labor: \$132.75</b>		<b>Parts: \$133.82</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$7.97</b>	<b>Sub-Total: \$274.54</b>	

**/110101S780 Internal**  
 COMPLAINT:  
 29 TOP UP OIL IN PRIMARY COUNTERSHAFT GEARCASE

CORRECTION:  
 TOPPED UP OIL.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N
<b>Labor: \$53.10</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$3.19</b>	<b>Sub-Total: \$56.29</b>	

**/170268S780 Internal**  
 COMPLAINT:  
 30 TOP UP ENGINE OIL

CORRECTION:  
 TOPPED UP ENGINE OIL.



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

<b>Invoice Number:</b> [REDACTED]	<b>Invoice Date:</b> 9/9/2024	<b>Location:</b> 05	<b>Work Order Number:</b> [REDACTED]
<b>Bus Phone:</b>	<b>Bus Phone:</b>	<b>Payment Type:</b> Account	<b>Page:</b> 13 of 14
<b>Prv Phone:</b>	<b>Prv Phone:</b>		

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2020 JD S780 COMBINE	1343	1H0S780SLLT810823	1H0S780SLLT810823	#6

**/170268S780 Internal**

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N
<b>Labor: \$53.10</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$3.19</b>	<b>Sub-Total: \$56.29</b>	

**/170538S780 Internal**

COMPLAINT:  
 31 ADJUST ALL BELTS AND CHAINS AS PER IS DEPT GUIDELINES

CORRECTION:  
 BELTS AND CHAINS ADJUSTED

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
<b>Labor: \$177.00</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$10.62</b>	<b>Sub-Total: \$187.62</b>	

**/120014S780 Internal**

COMPLAINT:  
 32 GREASE COMBINE

CORRECTION:  
 COMBINE GREASED



<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY6341	SD POLYUREA GREASE	1.00	10.31	10.31	\$10.31	N
<b>Labor: \$177.00</b>	<b>Parts: \$10.31</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$10.62</b>	<b>Sub-Total: \$197.93</b>		



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 9/9/2024 <b>Location:</b> 05 <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> Account  <b>Page:</b> 14 of 14
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2020 JD S780 COMBINE	1343	1H0S780SLLT810823	1H0S780SLLT810823	#6

**/110312S780 Internal**  
 COMPLAINT:  
 33 REMOVE CUSTOMER SOFTWARE , DATA

CORRECTION:  
 REMOVED CUSTOMER DATA.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N
<b>Labor: \$44.25</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$2.66</b>	<b>Sub-Total: \$46.91</b>		

<b>Customer PO No:</b>	[REDACTED]
<b>Tax Exempt No:</b>	[REDACTED]
<b>Advisor:</b>	[REDACTED]

<b>Labor:</b>	\$9,646.05
<b>Parts:</b>	\$2,968.10
<b>OL&amp;M:</b>	\$0.00
<b>Misc:</b>	\$464.86
<b>Grand Total:</b>	<b>\$13,079.01</b>

\*\*\* DOCUMENT COPY \*\*\*

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
	00	00	160	1	147646	USED AG EQUIPMENT
	05	40	382	1	780902	INTERNAL LABOR-AG
	00	00	178	15	780902	WORK IN PROCESS PARTS -MJ
	05	40	482	1	780902	COS INTERNAL LABOR-AG
	05	40	544	1	780902	SUPPLIES EXPENSE
	05	30	366	2	780902	JD PARTS-COUNTER
	00	00	166	5	780902	JD PARTS-MOOSE JAW
	05	30	466	2	780902	JD PARTS-COUNTER

**TERMS AND CONDITIONS**

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.  
 I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by: .....Date: .....