



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/22/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 1 of 11
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9620RX 620HP TRACTOR	2489	1RW9620RTMP811376	1RW9620RTMP811376	

/4WDOP9620RX Internal

COMPLAINT:
 01 RECONDITIONING INSPECTION 4WD TRACTOR

CORRECTION:

Labor: \$1,399.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,399.00
--------------------------	----------------------	-------------------------	---------------------	------------------------------

/GLOPCLEAN9620RX Internal

COMPLAINT:
 02 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST

CORRECTION:



<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	57.60	57.60	\$57.60	N

Labor: \$960.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$57.60	Sub-Total: \$1,017.60
------------------------	----------------------	-------------------------	----------------------	------------------------------



/1103129620 Internal

COMPLAINT:
 03 REMOVE CUSTOMER SOFTWARE

CORRECTION:
 PERFORMED FACTORY RESET ON DISPLAY.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N

Labor: \$44.25	Parts: \$0.00	OL&M: \$0.00	Misc: \$2.66	Sub-Total: \$46.91
-----------------------	----------------------	-------------------------	---------------------	---------------------------



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Invoice Number: [REDACTED]	Invoice Date: 11/22/2024	Location: [REDACTED]	Work Order Number: [REDACTED]
Bus Phone:	Bus Phone:	Payment Type: [REDACTED]	Page: 2 of 11
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9620RX 620HP TRACTOR	2489	1RW9620RTMP811376	1RW9620RTMP811376	

Gen4- Internal

COMPLAINT:

04 DIAGNOSE CODE ECU 101.04. CRANKCASE PRESSURE SENSOR IS BROKEN OFF. REPLACE SENSOR AND TEST

CORRECTION:

CLEANED AROUND WHERE SENSOR GOES IN. INSTALLED NEW SENSOR. INSTALLED NEW BOLT FOR SENSOR. PLUGGED IN SENSOR AND TESTED. FOUND NO ACTIVE CODES TO COME UP.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
L115292	BOLT	1.00	3.63	3.63	\$3.63	N
REC5462277NX	Pressure Sensor	1.00	257.99	257.99	\$257.99	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00	Parts: \$261.62	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$449.24		

Gen5- Internal

COMPLAINT:

05 DIAGNOSE WIRING ISSUE WITH SEAT. CUTS OUT RPM AND TRANS WHEN SEAT IS TURNED OR LIFTED

CORRECTION:

MOVED THE SEAT ALL THE WAY FORWARD. REMOVED THE FRIDGE AND FLOOR MAT FROM BEHIND THE SEAT. INSPECTED WIRING HARNESS COMING FROM ARM REST DOWN BEHIND THE SEAT TO THE CONTROLLER. FOUND THAT THERE WAS A COUPLE OF ZIP TIES THAT ARE REALLY TIGHT AROUND THE HARNESS. REMOVED ALL THE ZIP TIES AND CLAMPS FOR THE WIRING HARNESS. REMOVED THE LOOM FROM THE HARNESS. INSPECTED THE WIRES AND FOUND NO SIGNS OF WIRES THAT ARE PINCHED. STARTED TRACTOR AND SET RPM UP AROUND 1500. WIGGLED THE HARNESS AND FOUND NO CHANGE IN THE RPM. WILL LEAVE FOR NOW AND TEST OUTSIDE ONCE THE REPAIRS ARE DONE. ONCE TRACTOR WAS OUTSIDE. DROVE AROUND THE YARD WITH THE HARNESS LOOSE. DROVE AROUND THE YARD AND WIGGLED THE HARNESS ALL ALONG THE HARNESS. FOUND THAT WITH THE HARNESS LOOSE THE ISSUE DID NOT COME UP. TIED UP HARNESS LOOSELY AND INSTALLED THE FLOOR MAT AND THE FRIDGE BACK INTO PLACE. TESTED TRACTOR ONE MORE TIME AROUND THE YARD. FOUND THAT ISSUE DOES NOT HAPPEN ANYMORE. ALSO FOUND THAT THERE WAS A THICK PIECE OF CARDBOARD ON THE FLOOR THAT THE PREVIOUS DEALERSHIP PUT DOWN WAS CONTACTING THE DECELERATION PEDAL ON THE FLOOR. REMOVED THE CARDBOARD AND TESTED, THIS IS WHAT WAS CAUSING THE PROBLEM WHEN TAKING PRESSURE OFF OF THE SEAT. WIRING HARNESS WAS CAUSING THE ISSUE WHEN THE SEAT WAS TURNED.



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 11/22/2024 Location: Work Order Number: Payment Type: Page: 3 of 11
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9620RX 620HP TRACTOR	2489	1RW9620RTMP811376	1RW9620RTMP811376	

Gen5- Internal

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N
Labor: \$354.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$21.24	Sub-Total: \$375.24	

Gen6- Internal

COMPLAINT:
 06 DIAGNOSE NOISE AT REAR OF ENGINE WHEN IDLING

CORRECTION:
 WITH TRACTOR OUTSIDE, OPENED HOOD AND LET RUN AT IDLE. ENGINE IS UP TO OPERATING TEMP. COULD NOT HEAR ANY NOISE THAT WAS NOT NORMAL. LET TRACTOR SIT OVER NIGHT. STARTED TRACTOR WHEN IT WAS COLD. COULD NOT HEAR ANY NOISE. LET TRACTOR WARM UP TO OPERATING TEMP AND LISTEN FOR A NOISE. COULD NOT HEAR ANYTHING. DROVE TRACTOR AROUND THE YARD AND FOUND EVERYTHING IS WORKING AND SOUNDING JUST LIKE IT SHOULD. PARKED TRACTOR IN THE DONE LINE UP.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	16.46	16.46	\$16.46	N
Labor: \$274.35		Parts: \$0.00	OL&M: \$0.00	Misc: \$16.46	Sub-Total: \$290.81	

/1100189620RX F Internal

COMPLAINT:
 07 REPLACE ENGINE AIR FILTERS

CORRECTION:
 REMOVED ALL FOUR ENGINE AIR FILTERS AND REPLACED WITH NEW ONES. WROTE ENGINE HOURS ON ALL FILTERS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE594852	Primary Air Filter	2.00	337.74	337.74	\$675.48	N



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/22/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 4 of 11
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9620RX 620HP TRACTOR	2489	1RW9620RTMP811376	1RW9620RTMP811376	

/1100189620RX F Internal

RE594853	Secondary Air Filter	2.00	104.36	104.36	\$208.72	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N
Labor: \$53.10		Parts: \$884.20		OL&M: \$0.00		Misc: \$3.19
				Sub-Total: \$940.49		

/1416039620RX Internal

COMPLAINT:
 08 REPLACE CRANKCASE BREATHER / VENT FILTER

CORRECTION:
 REMOVED COVER FOR CRANK CASE BREATHER FILTER AND REMOVED FILTER. REPLACED WITH A NEW ONE AND INSTALLED COVER BACK ON. WROTE ENGINE HOURS ON COVER.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RECCV5063400	Crankcase Vent Filter	1.00	86.46	86.46	\$86.46	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N
Labor: \$44.25		Parts: \$86.46		OL&M: \$0.00		Misc: \$2.66
				Sub-Total: \$133.37		

/1201799620RX Internal

COMPLAINT:
 09 REPLACE CAB AIR FILTERS

CORRECTION:
 REMOVED BOTH CAB AIR FILTERS AND REPLACED WITH NEW ONES. WROTE ENGINE HOURS ON FILTERS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE284091	Cab Fresh Air Filter	1.00	115.62	115.62	\$115.62	N



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/22/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 5 of 11
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9620RX 620HP TRACTOR	2489	1RW9620RTMP811376	1RW9620RTMP811376	

/1201799620RX Internal

RE291412	Recirculating Cab Air Filter	1.00	128.04	128.04	\$128.04	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$243.66		OL&M: \$0.00		Misc: \$5.31
						Sub-Total: \$337.47

/1100689620RX Internal
 COMPLAINT:
 10 CHANGE FUEL FILTERS

CORRECTION:
 REMOVED BOTH FUEL FILTERS AND REPLACED WITH NEW ONES. PRIMED FUEL SYSTEM AND STARTED ENGINE TO CHECK FOR LEAKS. FOUND NO LEAKS, WROTE ENGINE HOURS ON BOTH FILTERS.

RE561968	Primary Fuel Filter	1.00	177.25	177.25	\$177.25	N
RE574467	Secondary Fuel Filter	1.00	345.24	345.24	\$345.24	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	2.00	1.00	1.00	\$2.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$522.49		OL&M: \$0.00		Misc: \$7.31
						Sub-Total: \$618.30

/1426089620RX Internal
 COMPLAINT:
 11 REPLACE FUEL TANK BREATHERS. PLUGGED WITH DIRT

CORRECTION:
 REMOVED THE BREATHERS AND FITTINGS FROM THE FUEL TANK. CLEANED OUT THE DIRT FROM THE FITTINGS. INSTALLED THE FITTINGS AND BREATHERS BACK INTO THE FUEL TANK.



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/22/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 6 of 11
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9620RX 620HP TRACTOR	2489	1RW9620RTMP811376	1RW9620RTMP811376	

/1426089620RX Internal

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	4.25	4.25	\$4.25	N
Labor: \$70.80		Parts: \$0.00		OL&M: \$0.00		Misc: \$4.25
Sub-Total: \$75.05						

/1200399620RX F Internal

COMPLAINT:
 12 CHANGE ENGINE OIL AND FILTER

CORRECTION:
 DRAINED ENGINE OIL AND REMOVED OLD OIL FILTER. REPLACED OIL FILTER AND FILLED ENGINE WITH NEW OIL.
 STARTED ENGINE AND CHECKED FOR LEAKS. FOUND NO LEAKS, TOPPED UP OIL LEVEL AND WROTE ENGINE HOURS ON FILTER.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
DZ121669	Engine Oil Filter	1.00	139.55	139.55	\$139.55	N
TY26673	3.78L 15W40 PLUS 50 II	2.00	37.78	37.78	\$75.56	N
TY26674	946ML 15W40 PLUS 50 II	2.00	9.92	9.92	\$19.84	N
TY26679	18.9L 15W40 PLUS 50 II	2.00	170.86	170.86	\$341.72	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	1.00	1.00	1.00	\$1.00	N
EF15	ENVIRO FEE	2.00	0.15	0.15	\$0.30	N
EF300	ENVIRO FEE	2.00	3.00	3.00	\$6.00	N
EF50	ENVIRO FEE	2.00	0.50	0.50	\$1.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$576.67		OL&M: \$0.00		Misc: \$16.27
Sub-Total: \$725.69						



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 11/22/2024 Location: Work Order Number: Payment Type: Page: 7 of 11
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9620RX 620HP TRACTOR	2489	1RW9620RTMP811376	1RW9620RTMP811376	

/1200869620RX F Internal

COMPLAINT:

13 REPLACE TRANSMISSION AND HYDRAULIC FILTERS, CLEAN SUMP SCREEN

CORRECTION:

REMOVED ALL HYDRAULIC AND TRANS OIL FILTERS AND SEALS. REPLACED WITH NEW SEALS AND FILTERS. STARTED UNIT AND CHECKED FOR LEAKS. FOUND NO LEAKS, MARKED ALL THE FILTERS WITH ENGINE HOURS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
R319585	Wear Ring	1.00	12.19	12.19	\$12.19	N
R564922	RING	4.00	15.47	15.47	\$61.88	N
RE577250	Hydraulic Oil Filter	1.00	148.45	148.45	\$148.45	N
RE577612	Hydraulic Filter	4.00	189.23	189.23	\$756.92	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	5.00	1.00	1.00	\$5.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N

Labor: \$177.00 Parts: \$979.44 OL&M: \$0.00 Misc: \$15.62 Sub-Total: \$1,172.06



/1406139620RX Internal

COMPLAINT:

14 REPLACE TRANSMISSION BREATHER

CORRECTION:

REMOVED COVER FROM THE SIDE OF THE CAB. REMOVED THE OLD BREATHER AND REPLACED WITH A NEW ONE. INSTALLED COVER BACK ONTO THE SIDE OF THE CAB.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
H216169	Fuel Tank Vent Filter	1.00	44.63	44.63	\$44.63	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/22/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 8 of 11
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9620RX 620HP TRACTOR	2489	1RW9620RTMP811376	1RW9620RTMP811376	

/1406139620RX Internal									
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N			
Labor: \$44.25		Parts: \$44.63		OL&M: \$0.00		Misc: \$2.66		Sub-Total: \$91.54	

/150292962RX Internal
 COMPLAINT:
 16 REPLACE IDLER/MID ROLLER OIL (ALL CORNERS)

CORRECTION:
 DRAINED OIL FROM ALL THE IDLERS AND MID ROLLERS. INSTALLED COVERS BACK ON. FILLED ALL IDLERS AND MID ROLLERS UP WITH NEW OIL. TOPPED UP OIL LEVEL TO BOTTOM OF PLUG.

FOUND THAT FRONT OUTER IDLER COVER ON THE LH REAR TRACK WAS LEAKING. REMOVED THE COVER AND FOUND THAT O-RING WAS PINCHED. REMOVED O-RING AND REPLACED WITH A NEW ONE. INSTALLED COVER BACK ON AND FILLED HUB BACK UP WITH OIL.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>			
R254441	O-Ring	1.00	32.14	32.14	\$32.14	N			
TY6354	3.78L HYGARD HYD/TRANS OIL J20C	4.00	35.64	35.64	\$142.56	N			
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>			
EF50	ENVIRO FEE	4.00	0.50	0.50	\$2.00	N			
SERVACCESS	SERVICE ACCESSORIES	1.00	42.48	42.48	\$42.48	N			
Labor: \$708.00		Parts: \$174.70		OL&M: \$0.00		Misc: \$44.48		Sub-Total: \$927.18	

/1145169620RX Internal
 COMPLAINT:
 17 ADJUST ENGINE VALVE CLEARANCE - RECOMMENDED AT 2000 HRS

CORRECTION:



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/22/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 9 of 11
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9620RX 620HP TRACTOR	2489	1RW9620RTMP811376	1RW9620RTMP811376	

/1145169620RX Internal

OPENED HOOD TO SERVICE POSITION. USED BLOW GUN AND CLEANED OFF THE TOP OF THE ENGINE. REMOVED THE VALVE COVER FROM THE ENGINE. CHECKED AND ADJUSTED VALVE CLEARANCE. INSTALLED VALVE COVER BACK INTO PLACE AND TORQUED HARDWARE. INSTALLED PLUG BACK INTO THE TIMING OVER FOR TURNING OVER ENGINE. STARTED ENGINE AND MADE SURE ENGINE IS RUNNING SMOOTH. FOUND ENGINE TO RUN JUST LIKE IT SHOULD. INSPECTED FOR LEAKS AND FOUND NONE. CLOSED HOOD BACK INTO NORMAL POSITION.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	87.62	87.62	\$87.62	N
Labor: \$1,460.25	Parts: \$0.00	OL&M: \$0.00	Misc: \$87.62	Sub-Total: \$1,547.87		

/1426069620RX Internal

COMPLAINT:
 18 REPLACE DEF PUMP AND TANK FILTERS

CORRECTION:
 REMOVED FILTER FROM THE PUMP AND REPLACED WITH A NEW ONE. INSTALLED COVER BACK INTO PLACE.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
DZ114640	DEF Injection Pump Filter Kit	1.00	246.07	246.07	\$246.07	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	1.00	1.00	1.00	\$1.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	23.90	23.90	\$23.90	N
Labor: \$398.25	Parts: \$246.07	OL&M: \$0.00	Misc: \$24.90	Sub-Total: \$669.22		

GEN19- Internal

COMPLAINT:
 19 RESEAL OIL LEAK ON #7 SCV STACK

CORRECTION:



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 11/22/2024 Location: Work Order Number: Payment Type: Page: 10 of 11
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9620RX 620HP TRACTOR	2489	1RW9620RTMP811376	1RW9620RTMP811376	

GEN19- Internal

REMOVED #7 AND 8 SCV COUPLER HOUSINGS FROM THE STACKS. REMOVED THE O-RINGS AND REPLACED WITH NEW ONES. INSTALLED HOUSINGS BACK INTO PLACE AND TIGHTENED HARDWARE TO SPEC. TESTED AND CHECKED FOR LEAKS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE281895	Seal Kit	2.00	100.01	100.01	\$200.02	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N
Labor: \$354.00		Parts: \$200.02	OL&M: \$0.00	Misc: \$21.24	Sub-Total: \$575.26	

/100700309570RX Internal

COMPLAINT:
20 BREAKAWAY COUPLER, R&R #7 EXTEND COUPLER

CORRECTION:
REMOVED #7 SCV COUPLER COVER. REMOVED THE BAD COUPLER AND REPLACED WITH A NEW ONE. INSTALLED COVER BACK INTO PLACE. TESTED COUPLER AND NOW HOLDING PRESSURE.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE577560	SCV Breakaway Quick Coupler	1.00	242.45	242.45	\$242.45	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	13.28	13.28	\$13.28	N
Labor: \$221.25		Parts: \$242.45	OL&M: \$0.00	Misc: \$13.28	Sub-Total: \$476.98	

/11000499620RX Internal

COMPLAINT:
21 GREASE MACHINE COMPLETE

CORRECTION:
GREASED COMPLETE UNIT.



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/22/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 11 of 11
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9620RX 620HP TRACTOR	2489	1RW9620RTMP811376	1RW9620RTMP811376	

/11000499620RX Internal

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind			
TY6341	SD POLYUREA GREASE	1.00	10.31	10.31	\$10.31	N			
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind			
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N			
Labor: \$177.00		Parts: \$10.31		OL&M: \$0.00		Misc: \$10.62		Sub-Total: \$197.93	

Customer PO No: [REDACTED]
Tax Exempt No: [REDACTED]
Advisor: [REDACTED]

Labor:	\$7,226.50
Parts:	\$4,472.72
OL&M:	\$0.00
Misc:	\$367.99
Grand Total:	<u>\$12,067.21</u>

*** DOCUMENT COPY ***

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
	00	00	160	1	147292	USED AG EQUIPMENT
	05	40	382	1	801783	INTERNAL LABOR-AG
	00	00	178	15	801783	WORK IN PROCESS PARTS -MJ
	05	40	482	1	801783	COS INTERNAL LABOR-AG
	05	40	544	1	801783	SUPPLIES EXPENSE
	05	30	366	2	801783	JD PARTS-COUNTER
	00	00	166	5	801783	JD PARTS-MOOSE JAW
	05	30	375	3	801783	PARTS SPECIAL HANDLING
	05	30	466	2	801783	JD PARTS-COUNTER

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.
 I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:Date: