



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

Internal Used Stock No. 148942	[REDACTED]	Invoice Number: [REDACTED]
Bus Phone:	Bus Phone:	Invoice Date: 3/26/2026
Prv Phone:	Prv Phone:	Location: [REDACTED]
		Work Order Number: [REDACTED]
		Payment Type: [REDACTED]
		Page: 1 of 19

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	[REDACTED]

/4WD9620RX F Internal

COMPLAINT:

01 GREENLIGHT SERVICE INSPECTION 4WD TRACTOR

INSPECTION BILLED OUT ON WORK ORDER [REDACTED]

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
----------------------	----------------------	-------------------------	---------------------	--------------------------

Gen2- Internal

COMPLAINT:

02 REPLACE DEF MODULE CONNECTOR AND PINS AS NECESSARY - RAN TRACTOR AND IT IDLE ONLY DERATED, FOUND ISSUE IS DEF CONNECTOR HOUSING IS BROKEN, PINS PULLING BACK, PUSHING WIRE INTO BACK OF CONNECTOR WITH CONNECTOR PLUGGED IN RESOLVED CODE

CORRECTION:

Swapped pins to new connector.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
57M10958	ELEC. CONN	1.00	36.55	36.55	\$36.55	N
57M11439	ELEC. CONN	1.00	15.09	15.09	\$15.09	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N

Labor: \$132.75	Parts: \$51.64	OL&M: \$0.00	Misc: \$7.97	Sub-Total: \$192.36
------------------------	-----------------------	-------------------------	---------------------	----------------------------

/1200019620RX Internal

COMPLAINT:

03 BLOW OUT RADIATOR AND AFTERCOOLER - CHARGE AIR COOLER PLUGGED

CORRECTION:



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/26/2026 Location: Work Order Number: Payment Type: Page: 2 of 19
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	

/1200019620RX Internal

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$187.62	

9620RF1146698 Internal

COMPLAINT:

04 REPLACE U-JOINTS ON FRONT DRIVESHAFT - FDH STOP CODE ACTIVE SAYS DRIVESHAFT DAMAGED - U-JOINTS LOOSE

CORRECTION:

Remove drive shaft upper gard. Remove 2 bolts for lower gard from transmission mounts. install studs for alignment during removal and installation. Remove lower gard. remove drive shaft from transmission and front axle. Remove and inspect U joints. Replace U joint on transmission side. Grease u joint and shaft. install in revers order.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE40113	Universal Joint Spider Cross Bearing	1.00	1,063.49	1,063.49	\$1,063.49	N
Miscellaneous	SERVICE ACCESSORIES	1.00	31.86	31.86	\$31.86	N
Labor: \$531.00		Parts: \$1,063.49	OL&M: \$0.00	Misc: \$31.86	Sub-Total: \$1,626.35	

Gen5- Internal

COMPLAINT:

05 REPAIR ENGINE TO TRANSMISSION U-JOINT - LOOSE, CAN FEEL CLUNK IN IT MOVING BY HAND

CORRECTION:

Remove 4 hydraulic hoses to gain access to shaft. Remove adjustable mount from gard and flywheel housing. Remove gard around drive shaft. Remove drive shaft. torsion dampner center plate bolts are broken. remove torsion dampner bolts to flywheel to remove center plate. remove center plate and drill out broken bolts. tap holes and install new bolts to secure center plate to dampner. assemble in revers order. Dampner is cracking and should be replaced. Advised on condition.



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/26/2026 Location: Work Order Number: Payment Type: Page: 3 of 19
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	

Gen5- Internal

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7806	Flange Head Cap Screw M10 X 50 GR10.9	2.00	3.99	3.99	\$7.98	N
24H1314	WASHER	2.00	3.89	3.89	\$7.78	N
24M7178	Washer 10.5 X 30 X 2.5mm	2.00	0.93	0.93	\$1.86	N
<u>Miscellaneous</u> SERVACCESS	<u>Description</u> SERVICE ACCESSORIES	<u>Quantity</u> 1.00	<u>List Price</u> 53.10	<u>Net Price</u> 53.10	<u>Extended Price</u> \$53.10	<u>Taxed Ind</u> N

Labor: \$885.00 Parts: \$17.62 OL&M: \$0.00 Misc: \$53.10 Sub-Total: \$955.72

Gen6- Internal

COMPLAINT:
 06 REPLACE HOSE FROM BOTTOM OF PTO DROP BOX TO TOP OF REAR DIFF - LEAKING

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R213663	Clamp	2.00	12.53	12.53	\$25.06	N
RE566900	Hydraulic Hose	1.00	148.67	148.67	\$148.67	N
<u>Miscellaneous</u> SERVACCESS	<u>Description</u> SERVICE ACCESSORIES	<u>Quantity</u> 1.00	<u>List Price</u> 15.93	<u>Net Price</u> 15.93	<u>Extended Price</u> \$15.93	<u>Taxed Ind</u> N

Labor: \$265.50 Parts: \$173.73 OL&M: \$0.00 Misc: \$15.93 Sub-Total: \$455.16

GEN7- Internal

COMPLAINT:
 07 BATTERY(IES), R&R OR REPLACE - ONE BATTERY 0 AMPS, 2ND FROM INSIDE IS MARKED, OTHER BATTERIES OKAY

CORRECTION:



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/26/2026 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 4 of 19
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	[REDACTED]

GEN7- Internal

Disconnect battery cables. Remove all batteries. Rear battery had hole in it so all batteries was replaced. Positive cable to the starter clamp is broken and was loose on the terminal. Remove positive cable from starter. Remove all P clamps that secure cable to chassis and under cab. Remove cable and install new cable. Install 4 new batteries.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
19M7866	Flange Head Cap Screw M8 X 20 GR10.9	1.00	1.72	1.72	\$1.72	N
RE581052	Battery Cable	1.00	1,187.05	1,187.05	\$1,187.05	N
TY25879A-PL	Wet Charged Battery,BCI 31,CCA 950	3.00	279.03	279.03	\$837.09	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	29.21	29.21	\$29.21	N
Labor: \$486.75		Parts: \$2,025.86		OL&M: \$0.00		Misc: \$29.21
						Sub-Total: \$2,541.82

/1200599620RX Internal

COMPLAINT:

08 CLEAN BATTERY CABLES AND POSTS & REPLACE BATTERY BOLTS

Labour with seg 7

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY25908	BATTERY BOLT AND NUT	2.00	1.49	1.49	\$2.98	N
TY25913	FELT	4.00	1.53	1.53	\$6.12	N
Labor: \$0.00		Parts: \$9.10		OL&M: \$0.00		Misc: \$0.00
						Sub-Total: \$9.10

GEN9- Internal

COMPLAINT:

09 REPLACE REAR WINDOW SEAL - TORN AND HANGING OFF ON BOTTOM



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/26/2026 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 5 of 19
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	[REDACTED]

GEN9- Internal

CORRECTION:

Replaced the seal

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE570092	Weatherstripping Seal	1.00	106.37	106.37	\$106.37	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$106.37	OL&M: \$0.00	Misc: \$7.97	Sub-Total: \$247.09	

/1500669620RX Internal

COMPLAINT:

10 REPLACE CAB DOOR SEAL - DEFORMED FROM BEING CLOSED WITH SEAL HANGING OFF

CORRECTION:

Replaced the seal

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE570092	Weatherstripping Seal	1.00	106.37	106.37	\$106.37	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.76	10.76	\$10.76	N
Labor: \$177.00		Parts: \$106.37	OL&M: \$0.00	Misc: \$10.76	Sub-Total: \$294.13	

GEN11- Internal

COMPLAINT:

11 REPLACE REAR WORK LIGHT AND TAIL LIGHT HARNESS - MISSING FROM TRACTOR, MATING ROUND CONNECTOR WRAPPED IN ELECTRICAL TAPE AND TAPED TO HYD LINE

RE574554

CORRECTION:



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/26/2026 Location: Work Order Number: Payment Type: Page: 6 of 19
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	

GEN11- Internal

Installed new light harness and verified all lights worked.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE574554	Wiring Harness	1.00	846.25	846.25	\$846.25	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00		Parts: \$846.25	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$1,033.87	

GEN12- Internal

COMPLAINT:

12 REPLACE SCV / TRAILER / ISO / TRACK TENSION HARNESS - BURNT

RE580841

CORRECTION:

Removed old harness, compared the harnesses and found I had the wrong harness that was meant for a rear 3pt hitch option. Checked parts and found this incorrect harness was cheaper than the proper harness, installed the new harness and just ziptied the extra connectors to the side.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
19M7865	Flange Head Cap Screw M8 X 16 GR10.9	2.00	1.57	1.57	\$3.14	N
H224073	TIE BAND	1.00	3.40	3.40	\$3.40	N
R213663	Clamp	1.00	12.53	12.53	\$12.53	N
R44302	TIE BAND 7"	10.00	0.45	0.45	\$4.50	N
RE580841	Chassis Wiring Harness	1.00	2,355.48	2,355.48	\$2,355.48	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	13.28	13.28	\$13.28	N
Labor: \$221.25		Parts: \$2,379.05	OL&M: \$0.00	Misc: \$13.28	Sub-Total: \$2,613.58	



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/26/2026 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 7 of 19
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	[REDACTED]

GEN13- Internal

COMPLAINT:

13 REPLACE SCV LEAK OFF TUBE - HOSE BURNT

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
R184956	Hose	2.00	57.92	57.92	\$115.84	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.12	2.12	\$2.12	N
Labor: \$35.40		Parts: \$115.84		OL&M: \$0.00	Misc: \$2.12	Sub-Total: \$153.36

GEN14- Internal

COMPLAINT:

14 REPAIR END OF MAIN CHASSIS HARNESS BEHIND SCV & REPLACE BURNT CONDUIT & INSPECT / REPAIR ANY WIRING DAMAGE

CORRECTION:

Repaired damaged loom and connectors.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
57M7542	ELEC. CONNE	2.00	4.02	4.02	\$8.04	N
57M9383	Elec. Connector Accessory	1.00	26.05	26.05	\$26.05	N
RE258807	TIE BAND	1.00	2.50	2.50	\$2.50	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	37.17	37.17	\$37.17	N
Labor: \$619.50		Parts: \$36.59		OL&M: \$0.00	Misc: \$37.17	Sub-Total: \$693.26

GEN16- Internal

COMPLAINT:



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/26/2026 Location: Work Order Number: Payment Type: Page: 8 of 19
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	

GEN16- Internal

16 REMOVE FRONT SECTION OF CHASSIS HARNESS FROM TRANSMISSION FORWARD AND PULL OUT TO PROPERLY REPAIR A FIELD FIRE REPAIR FROM 3 YEARS AGO - WAS DONE LATE AT NIGHT STARTING TO HAVE ELECTRICAL ISSUES RAN EXTERNAL WIRES TO KEEP THEM GOING PATCH MOST LIKELY STARTING TO FAIL

CORRECTION:

Disconnected batteries, removed operator platform shields, removed engine intake pipe, cleaned dirt around harness, removed chassis harness from the front to the middle. Disassembled harness, inspected wires and found all damage. Repaired all damage to the main harness, reinstalled harnesses. Reinstalled removed components, ran and tested machine.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
19M7866	Flange Head Cap Screw M8 X 20 GR10.9	2.00	1.72	1.72	\$3.44	N
19M7867	Flange Head Cap Screw M8 X 25 GR10.9	1.00	1.72	1.72	\$1.72	N
57M10492	Elec. Conne	1.00	1.37	1.37	\$1.37	N
57M8560	Electrical Terminal	4.00	1.29	1.29	\$5.16	N
57M8603	Electrical Terminal Seal	3.00	0.69	0.69	\$2.07	N
R44302	TIE BAND 7"	100.00	0.45	0.45	\$45.00	N
RE515416	Screw	1.00	2.69	2.69	\$2.69	N
RWA11056	Repair Wire Assembly	7.00	6.40	6.40	\$44.80	N
RWA11058	Repair Wire assembly	1.00	7.28	7.28	\$7.28	N
RWA11094	Repair Wire Assembly	8.00	7.06	7.06	\$56.48	N
RWA11137	Repair Wire Assembly	2.00	10.46	10.46	\$20.92	N
RWA11145	REPAIR WIR	2.00	7.64	7.64	\$15.28	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
FREIGHT	FREIGHT	1.00	45.00	45.00	\$45.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N

Labor: \$4,425.00 Parts: \$206.21 OL&M: \$0.00 Misc: \$141.00 Sub-Total: \$4,772.21



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/26/2026 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 9 of 19
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	[REDACTED]

GEN17- Internal

COMPLAINT:
 17 CLEAN OUT INSIDE FRAME BETWEEN ENGINE AND TRANS - BUILT UP DEBRIS

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N
Labor: \$354.00		Parts: \$0.00		OL&M: \$0.00		Misc: \$21.24
Sub-Total: \$375.24						

GEN18- Internal

COMPLAINT:
 18 INSTALL HELICOIL IN BATTERY COMPARTMENT DOOR / STEP DOOR

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
19M9327	Flange Head Cap Screw M10 X 30 GR10.9	3.00	3.49	3.49	\$10.47	N
24M7299	Washer	2.00	1.84	1.84	\$3.68	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
FREIGHT	FREIGHT	1.00	62.99	62.99	\$62.99	N
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$14.15		OL&M: \$0.00		Misc: \$70.96
Sub-Total: \$217.86						

GEN19- Internal

COMPLAINT:
 19 REPLACE 2 BOLTS, 2 WASHERS AND 1 CLIP NUT FROM RH STEP TO DPF COVER - MISSING

CORRECTION:



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

[Redacted] Bus Phone: Prv Phone:	[Redacted] Bus Phone: Prv Phone:	Invoice Number: [Redacted] Invoice Date: 3/26/2026 Location: [Redacted] Work Order Number: [Redacted] Payment Type: [Redacted] Page: 10 of 19
--	--	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	[Redacted]

GEN19- Internal

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
19M8327	Flange Head Cap Screw M8 X 25 GR10.9	2.00	2.09	2.09	\$4.18	N
24M7299	Washer	2.00	1.84	1.84	\$3.68	N
L55969	NUT	1.00	4.08	4.08	\$4.08	N
R552228	Shoulder Bolt M8 X 25 GR10.9	1.00	4.41	4.41	\$4.41	N
R552269	Washer	1.00	5.82	5.82	\$5.82	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	4.25	4.25	\$4.25	N
Labor: \$70.80		Parts: \$22.17	OL&M: \$0.00	Misc: \$4.25	Sub-Total: \$97.22	

/1416039620RX Internal
 COMPLAINT:
 28 REPLACE OCV FILTER

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RECCV5063400	Crankcase Vent Filter	1.00	90.05	90.05	\$90.05	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N
Labor: \$44.25		Parts: \$90.05	OL&M: \$0.00	Misc: \$2.66	Sub-Total: \$136.96	

GEN29- Internal
 COMPLAINT:
 29 REPLACE OCV FILTER GUARD BRACKET - BROKEN (LABOUR ON SEG 28)

CORRECTION:



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

[Redacted] Bus Phone: Prv Phone:	[Redacted] Bus Phone: Prv Phone:	Invoice Number: [Redacted] Invoice Date: 3/26/2026 Location: [Redacted] Work Order Number: [Redacted] Payment Type: [Redacted] Page: 11 of 19
--	--	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	[Redacted]

GEN29- Internal

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
R544907	Guard	1.00	242.62	242.62	\$242.62	N
Labor: \$0.00		Parts: \$242.62	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$242.62	

/1413189620RX Internal

COMPLAINT:
 30 FLUSH COOLING SYSTEM AND REPLACE THERMOSTATS

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
PMCC2610X	Restore Cooling System Flush	1.00	60.78	60.78	\$60.78	N
REC018678000	Seal	1.00	55.72	55.72	\$55.72	N
REC544046500	Thermostat	1.00	254.72	254.72	\$254.72	N
TY26576	9.46L COOL-GARD PREMIX	7.00	61.58	61.58	\$431.06	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF240	ENVIRO FEE	7.00	2.40	2.16	\$15.12	N
SERVACCESS	SERVICE ACCESSORIES	1.00	58.41	58.41	\$58.41	N
Labor: \$973.50		Parts: \$802.28	OL&M: \$0.00	Misc: \$73.53	Sub-Total: \$1,849.31	

GEN31- Internal

COMPLAINT:
 31 REPLACE RADIATOR CAPS (LABOUR WITH COOLANT FLUSH)

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/26/2026 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 12 of 19
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	[REDACTED]

GEN31- Internal							
RE312969	Filler Cap	2.00	76.56	76.56	\$153.12	N	
Labor: \$0.00		Parts: \$153.12		OL&M: \$0.00		Misc: \$0.00	
				Sub-Total: \$153.12			

/150292962RX Internal
 COMPLAINT:
 32 REPLACE MID ROLLER OIL (ALL CORNERS) - LOT OF SPARKLES IN A FEW OF THEM IDLERS LOOK FINE

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
AR69444	18.9L HYGARD HYD/TRANS OIL J20C	1.00	147.96	147.96	\$147.96	N	
TY6354	3.78L HYGARD HYD/TRANS OIL J20C	1.00	32.13	32.13	\$32.13	N	
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
EF300	ENVIRO FEE	1.00	3.00	2.70	\$2.70	N	
EF50	ENVIRO FEE	1.00	0.50	0.45	\$0.45	N	
SERVACCESS	SERVICE ACCESSORIES	1.00	42.48	42.48	\$42.48	N	
Labor: \$708.00		Parts: \$180.09		OL&M: \$0.00		Misc: \$45.63	
				Sub-Total: \$933.72			

/1409689620RX F Internal
 COMPLAINT:
 36 UPDATE ALL MACHINE CONTROLLERS SOFTWARE

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/26/2026 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 13 of 19
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	[REDACTED]

/1409689620RX F Internal						
SERVACCESS	SERVICE ACCESSORIES	Quantity	List Price	Net Price	Extended Price	Taxed Ind
		1.00	15.93	15.93	\$15.93	N
Labor: \$265.50		Parts: \$0.00	OL&M: \$0.00	Misc: \$15.93	Sub-Total: \$281.43	

GEN39- Internal
 COMPLAINT:
 39 REPAIR BOTH POWER MIRRORS - DONT ADJUST

CORRECTION:
 Repair wiring for fuse. pin not making contact with fuse.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	31.86	31.86	\$31.86	N
Labor: \$531.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$31.86	Sub-Total: \$562.86	

GEN44- Internal
 COMPLAINT:
 44 REPAIR SCV #4 EXTEND - CREEPS FAST

CORRECTION:
 Remove and replace SCV coupler

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE281895	Seal Kit	1.00	99.11	99.11	\$99.11	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$99.11	OL&M: \$0.00	Misc: \$5.31	Sub-Total: \$192.92	

/1200399620RX F Internal
 COMPLAINT:



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/26/2026 Location: Work Order Number: Payment Type: Page: 14 of 19
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	

/1200399620RX F Internal
 48 CHANGE ENGINE OIL AND FILTER

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
DZ121669	Engine Oil Filter	1.00	141.83	141.83	\$141.83	N
TY26675	9.46L 15W40 PLUS 50 II	1.00	89.65	89.65	\$89.65	N
TY26679	18.9L 15W40 PLUS 50 II	2.00	170.72	170.72	\$341.44	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	2.00	1.00	0.90	\$1.80	N
EF300	ENVIRO FEE	2.00	3.00	2.70	\$5.40	N
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N

Labor: \$132.75	Parts: \$572.92	OL&M: \$0.00	Misc: \$15.17	Sub-Total: \$720.84
------------------------	------------------------	-------------------------	----------------------	----------------------------

/1427869620RX Internal

COMPLAINT:
 50 REPLACE DEF TANK, INLINE AND DOSING FILTERS (1500HR SERVICE)

CORRECTION:

INCLUDES REMOVE DEF HEADER TO REPLACE DEF TANK FILTER

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
DZ114640	DEF Injection Pump Filter Kit	1.00	207.94	207.94	\$207.94	N
DZ124403	FILTER KIT, DEF INLINE SERVICE KIT	1.00	119.97	119.97	\$119.97	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	1.00	1.00	0.90	\$0.90	N



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/26/2026 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 15 of 19
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	[REDACTED]

/1427869620RX Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	31.86	31.86	\$31.86	N	
Labor:	\$531.00	Parts:	\$327.91	OL&M:	\$0.00	Misc:	\$32.76
					Sub-Total:	\$891.67	

GEN53- Internal

COMPLAINT:

53 REPLACE FULL SYSTEM HYDRAULIC OIL AND FILTERS

CORRECTION:

Drain all hydraulic oil from axles, PTO and reservoir. Drain transmission oil and remove all hydraulic and transmission filters. removed R side shield to access hydraulic tank screens. remove screens and inspected. Found excessive debris in the bottom of the hydraulic tank. Cut open all hydraulic and transmission filters to inspect and determine the origin of the of debris in the reservoir. Found that the ale filter has excessive metal shavings and clutch material in it. Use Bore scope to look into front and rear axle housings and final drive housings to find origin of failure. Used bore scope to look into PTO clutch housing to inspect. Made tool to suck out debris from hydraulic reservoir. Had oil from another tractor that was drained to use in this one to flush out hydraulic system. filled with oil and replaced filters. Run unit and test front and rear brake system. tested front and rear diff lock to determine cause of failure. suspect front diff lock or brake discs. drained all oil after running up to temp and test driving for about 4 hours. removed screens from tank again and inspected. found reservoir with more debris again. refilled and replaced the filters again.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AR69444	18.9L HYGARD HYD/TRANS OIL J20C	6.00	147.96	147.96	\$887.76	N
AR69445	208L HYGARD HYD/TRANS OIL J20C	1.00	1,586.79	1,520.44	\$1,520.44	N
R319585	Wear Ring	1.00	13.10	13.10	\$13.10	N
R564922	Ring	4.00	15.54	15.54	\$62.16	N
RE577250	Hydraulic Oil Filter	1.00	152.39	152.39	\$152.39	N
RE577612	Hydraulic Filter	4.00	201.95	201.95	\$807.80	N
U12331	O-Ring	3.00	10.71	10.71	\$32.13	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	5.00	1.00	0.90	\$4.50	N
EF1025	ENVIRO FEE	1.00	10.25	9.23	\$9.23	N



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/26/2026 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 16 of 19
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	[REDACTED]

GEN53- Internal

EF300	ENVIRO FEE	6.00	3.00	2.70	\$16.20	N
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N
Labor: \$2,655.00		Parts: \$3,475.78		OL&M: \$0.00	Misc: \$125.93	Sub-Total: \$6,256.71

GEN54- Internal

COMPLAINT:
 54 PULL RESERVOIR SCREENS AND CHECK OUT TRANS AND HYD - MAKE SURE WEREN'T RUNNING WITH CAPS OFF (DO WITH SEG 53)

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
----------------------	----------------------	-------------------------	---------------------	--------------------------

/1427859620RX Internal

COMPLAINT:
 55 REPLACE HYDRAULIC BREATHER FILTER

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
H216169	Fuel Tank Vent Filter	1.00	43.43	43.43	\$43.43	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	4.25	4.25	\$4.25	N
Labor: \$70.80		Parts: \$43.43		OL&M: \$0.00	Misc: \$4.25	Sub-Total: \$118.48

/1100189620RX F Internal

COMPLAINT:
 57 REPLACE ENGINE AIR FILTERS



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/26/2026 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 17 of 19
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	[REDACTED]

/1100189620RX F Internal

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE594852	Primary Air Filter	2.00	343.26	343.26	\$686.52	N
RE594853	Secondary Air Filter	2.00	111.37	111.37	\$222.74	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N
Labor: \$53.10		Parts: \$909.26		OL&M: \$0.00		Misc: \$3.19
						Sub-Total: \$965.55

/1201799620RX Internal

COMPLAINT:
 58 REPLACE CAB AIR FILTERS

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE291412	Recirculating Cab Air Filter	1.00	130.14	130.14	\$130.14	N
TA32591	Cab Fresh Air Filter	1.00	117.51	117.51	\$117.51	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$247.65		OL&M: \$0.00		Misc: \$5.31
						Sub-Total: \$341.46

/1403849620RX Internal

COMPLAINT:
 59 DRAIN FUEL TANK SUMP, 250 HOUR SERVICE

CORRECTION:



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Invoice Number: [REDACTED]	Invoice Date: 3/26/2026	Location: [REDACTED]	Work Order Number: [REDACTED]
Bus Phone:	Bus Phone:	Payment Type: [REDACTED]	Page: 18 of 19
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	[REDACTED]

/1403849620RX Internal

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N
Labor: \$44.25		Parts: \$0.00		OL&M: \$0.00		Misc: \$2.66
Sub-Total: \$46.91						

/100700309570RX Internal

COMPLAINT:
 62 REPAIR SCV #2 RETRACT PORT BLOWS OIL OUT WITH NO HOSE INSTALLED

CORRECTION:
 Replaced the breakaway

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE577560	SCV Breakaway Quick Coupler	1.00	228.40	228.40	\$228.40	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	13.28	13.28	\$13.28	N
Labor: \$221.25		Parts: \$228.40		OL&M: \$0.00		Misc: \$13.28
Sub-Total: \$462.93						

/GLOPCLEAN9620RX Internal

COMPLAINT:
 63 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST

CORRECTION:
 ___ WASH COMPLETE MACHINE(OPEN & WASH BEHIND ALL SHIELDS)___ WAX IF REQUIRED___ REMOVE ANY OTHER DEALER DECALS ___ INSTALL SCE DEALERSHIP DECALS___ ALL FACTORY SAFETY AND MODEL DECALS IN GOOD CONDITION___ REMOVE CAB FLOORMAT AND CLEAN MAT AND FLOOR___ CLEAN SEAT AND REMOVE STAINS IF NECESSARY___ VACUUM CAB THOROUGHLY___ CLEAN INSTRUMENT PANEL, OPERATOR CONTROLS, UPHOLSTERY, AND AIR DELIVERY LOUVERS___ CLEAN WINDOWS AND MOLDINGS(OPEN WINDOWS TO CLEAN EDGESWHERE APPLICABLE)___ ELIMINATE ANY CAB ODORS AND INSTALL AIR FRESHENER IFREQUIRED___ PAINT AREAS THAT ARE BADLY SCRATCHED/DAMAGED-INCLUDING BUCKETS, GRAPPLES, WHEELS, EXHAUST, PLATFORMAUGERS(COMplete AUGER), CHOPPER FINS, FEEDERHOUSE DRUMS,BALER PICKUPS



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:
 Invoice Date: 3/26/2026
 Location:
 Work Order Number:
 Payment Type:
 Page: 19 of 19

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 9620RX TRACTOR	4219	1RW9620RPHP804175	1RW9620RPHP804175	

/GLOPCLEAN9620RX Internal

Labor: \$1,236.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$1,236.00

INVOICE CONTAINS \$72.60 DISCOUNT

Customer PO No:
 Tax Exempt No:
 Advisor:

Labor: \$16,466.85
 Parts: \$14,547.06
 OL&M: \$0.00
 Misc: \$845.53
Grand Total: \$31,859.44

*** DOCUMENT COPY ***

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
	00	00	160	1	148942	USED AG EQUIPMENT
	01	40	382	1	7194	INTERNAL LABOR-AG
	00	00	178	11	7194	WORK IN PROCESS PARTS -MJ
	01	40	482	1	7194	COS INTERNAL LABOR-AG
	01	30	366	2	7194	JD PARTS-COUNTER
	00	00	166	1	7194	JD PARTS-MOOSE JAW
	01	40	544	1	7194	SUPPLIES EXPENSE
	01	30	375	1	7194	PARTS SPECIAL HANDLING
	01	30	375	3	7194	PARTS SPECIAL HANDLING
	01	30	466	2	7194	JD PARTS-COUNTER

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:Date: