

Invoice

Bill To

Date	Invoice No.	P.O. Number	Terms	Project
03/18/25			Due on receipt	

Item	Description	Quantity	Rate	Amount
ELE-800-002	BRASS FLOAT	1	477.80	477.80T
DRAIN ASSEMBLY	DRAIN ASSEMBLY	1	125.00	125.00T
RAD CAP	RAD CAP	1	15.00	15.00T
WPX-378-313	BEARING KIT	1	156.00	156.00T
WPX-350-516	CLUTCH	2	10.00	20.00T
WPX-412-244	O RING	1	21.65	21.65T
SHIPPING	SHIPPING	1	25.00	25.00
LABOR	LABOR	2	100.00	200.00
AQUA HOT SERVICE	AQUA HOT SERVICE	1	500.00	500.00
	FUEL FILTER 33583			
	NOZZLE			
	SERVICE CALL			
BY SIGNING YOU ARE AGREEING TO PAY FOR SERVICES RENDERED.				Subtotal \$1,540.45
				Sales Tax (8.7%) \$70.94
				Total \$1,611.39



WO #:

Customer Name:
Address:

Postal/Zip:
Phone#(res):
Phone#(bus):
Cell Phone:
Email: NONE

Invoice#: 206071
Date In: 14 AUG 24
Completed Date: 22 AUG 24
Promised Date: 22 AUG 24
Promised Time:
Purchased Date:
Delivery Date:

Author:
Stock #:
Year: 2004
Manufacturer:
Brand: BEAVER
Model:
Unit Type: MAD-CLASS A DIESEL
MOTORHOME
Exterior Color:
Serial#: 1
License#:
Key#:
Tow Year:
Tow Make:
Tow Model:
Tow Capacity:

Job #1 - External

COMPLAINT: INSTALL 2 A/C'S
MORGAN QUOTED:
\$2195.00 X 2 - A/C
\$289.00 X 2 - T STAT
\$945.00 - LABOUR

CAUSE: 1 - INSTALL 2 A/C'S
MORGAN QUOTED:
\$2195.00 X 2 - A

CORRECTION: R AND R BOTH A/C AND T-STATS TO THE 10 BUTTON T-STAT
HAD TO TURN THE DIP SWITCHES ON FOR FURNACE THEN SWITCH THE FURNACE OPTION ON T
STAT TO THE
AQUA ZONE 1 ON FRONT T STAT CONTROL THE FRONT 2 REGISTERS AND ZONE 1 ON REAR
T-STAT CONTROLS BACK 2

Labor

Job #	Description	Total
1	INSTALL 2 A/C'S	945.00

Parts

Part #	Description	Qty	Price	Total
651815HXX1C0-01	A/C UNITS	2.00	2,198.50	4,397.00
3314082.011	THERMOSTAT, PKGD CCC2-WHITE	2.00	289.00	578.00

Other Services

Code	Description	Qty	Price	Total
EC	ENVIRONMENTAL DISPOSAL FEE	1.00	6.00	6.00
SST	SHOP SUPPLIES - TAXABLE	1.00	30.00	30.00

Subtotal for Job #1: 5,956.00

Job #2 - External

COMPLAINT: REAR DRIVER SIDE HYDRAULIC JACK IS NOT WORKING.



DIAGNOSE QUOTED 189 PLEASE CALL FOR ADDITIONAL PARTS AND LABOUR

CAUSE: 2 - REAR DRIVER SIDE HYDRAULIC JACK IS NOT WORKING.
D

CORRECTION: tested the leveling jack system and the driver rear does not extend out at all
called rvajack and they sent paper work to diagnose
first step was to swap the left and right extend valves on pump to see if it will work
had to use wrench to remove both extend valves to swap over then once swapped
i started the coach and released the air then tested the jack out and the driver rear extended to the
ground
customer needs a new right extend valve for driver rear
swapped the extend valve back to original

Labor

Job #	Description	Total
2	MISC	189.00
Subtotal for Job #2:		189.00

Parts Total:	4,975.00
Labour Total:	1,134.00
Sublet Total:	0.00
Extras Total:	36.00
GOODS & SERVICES TAX:	307.26
PROVINCIAL SALES TAX:	368.35
WORK ORDER TOTAL:	6,820.61

GST # 105537781RT

Customer Signature : _____

Date: 22 Aug 2024



Sales and Service

Payment terms are 30 days from invoice date unless otherwise agreed upon in writing. REMIT TO:
CUMMINS CANADA ULC
PO BOX 2521 STN M,
CALGARY AB T2P 0T6

INVOICE NO

REMIT T

BILL TO

PAGE 1 OF 2

*** CASH ***

DATE	CUSTOMER ORDER NO.	DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE
07-OCT-2024		23-SEP-2024	HDKAJ		ONAN
CUSTOMER NO.	SHIP VIA	FAIL DATE	ENGINE SERIAL NO.	CPL NO.	EQUIPMENT MODEL
3221086		02-OCT-2024	G030518787	SPEC H	HDKAJ
REF. NO.	SALESPERSON	PARTS DISP.	MILEAGE/HOURS	PUMP CODE	UNIT NO.
123485	KX036		/ 580		MOTORHOME

QUANTITY ORDERED	BACK ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION	PRODUCT CODE	LIST PRICE	UNIT PRICE	AMOUNT
OSN/MSN/VIN		G030518787						
COMPLAINT		DIAGNOSE FOR SHUTTING DOWN ON HIGH COOLANT TEMP.						
CAUSE		UNIT WILL RUN FOR 30 MINUTES THEN SHUT DOWN, SUBSEQUENT ATTEMPTS LAST LESS TIME. CUSTOMER HAS ALREADY REPLACED THERMOSTAT AND COOLANT TEMPERATURE SENSOR.						
CORRECTION		RADIATOR PLUGED INTERNALLY BRING RV INTO SHOP. PERFORM JSA. LOCK OUT GENERATOR, DRAIN COOLANT. REMOVE TOP COVER, REMOVE ALL RADIATOR HOSES, DISCONNECT RADIATOR MOUNTING BOLTS AND REMOVE RAD. CLEAN OUT DEBRIS IN SIDE FAN HOUSING. INSTALL NEW RADIATOR. INSTALL ALL HOSES WITH NEW CLAMPS. FLUSH COOLING SYSTEM WITH WATER. DRAIN AND INSTALL COOLANT. RUN UNIT UNDER AIR CONDITIONING LOAD FOR 45 MINUTES. UNIT OPERATED AS DESIGNED. SHUT DOWN AND PARK UNIT OUTSIDE FOR CUSTOMER PICKUP. REPLACE RADIATOR						
COVERAGE REMARK		CUSTOMER BILLABLE THANK YOU						
1		1	130-6936	RADIATOR	ONAN	720.91	720.91	720.91
2		2	CC2825-X	ES COMP EG	FLG	28.52	25.67	51.34
2		2	ENVA4L	ENVIRONMENTAL CHARGE	EC-NONSTOCK	.80	.80	1.60
1		1	PFI-4	CLAMP	WC-OTHER	1.88	1.88	1.88
				PARTS:				775.73
				PARTS COVERAGE CREDIT:				0.00CR
				TOTAL PARTS:			775.73	
				SURCHARGE TOTAL:				0.00
				LABOR:				752.40
				LABOR COVERAGE CREDIT:				0.00CR

GST NUMBER - 88788 0904

APPENDIX A IS ATTACHED AND INCORPORATED HEREIN. IN APPENDIX A THERE ARE ADDITIONAL CONTRACT TERMS AND CONDITIONS, INCLUDING LIMITATION ON WARRANTIES AND LIABILITIES WHICH ARE EXPRESSIVELY INCORPORATED HEREIN AND WHICH PURCHASER ACKNOWLEDGES HAVE BEEN READ, FULLY UNDERSTOOD AND ACCEPTED.

AUTHORIZED BY (print name)

SIGNATURE

DATE



**Sales and
Service**

Payment terms are 30 days from invoice date unless otherwise
agreed upon in writing. REMIT TO:
CUMMINS CANADA ULC
PO BOX 2521 STN M,
CALGARY AB T2P 0T6

INVOICE NO

BILL TO

PAGE 2 OF 2

*** CASH ***

DATE	CUSTOMER ORDER NO.	DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE
07-OCT-2024		23-SEP-2024	HDKAJ		ONAN
CUSTOMER NO.	SHIP VIA	FAIL DATE	ENGINE SERIAL NO.	CPL NO.	EQUIPMENT MODEL
3221086		02-OCT-2024	G030518787	SPEC H	HDKAJ
REF. NO.	SALESPERSON	PARTS DISP.	MILEAGE/HOURS	PUMP CODE	UNIT NO.
123485	KX036		/ 580		MOTORHOME

QUANTITY ORDERED	BACK ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION	PRODUCT CODE	LIST PRICE	UNIT PRICE	AMOUNT
---------------------	-----------------	---------------------	----------------	-------------	-----------------	------------	------------	--------

OSN/MSN/VIN G030518787

TOTAL LABOR: 752.40
MISC.: 40.00
MISC. COVERAGE CREDIT: 0.00CR
TOTAL MISC.: 40.00
FREIGHT 40.00
GST 78.41
PST 94.09

You saved \$5.70 on your parts.

GST NUMBER - 88788 0904

APPENDIX A IS ATTACHED AND INCORPORATED HEREIN. IN APPENDIX A THERE ARE
ADDITIONAL CONTRACT TERMS AND CONDITIONS, INCLUDING LIMITATION ON
WARRANTIES AND LIABILITIES WHICH ARE EXPRESSLY INCORPORATED HEREIN AND
WHICH PURCHASER ACKNOWLEDGES HAVE BEEN READ, FULLY UNDERSTOOD AND
ACCEPTED.

SUB TOTAL: 1,568.13
TOTAL TAX: 172.50
TOTAL AMOUNT: CA \$ 1,740.63

AUTHORIZED BY (print name)

SIGNATURE

DATE