



# Sales and Service

Payment terms are 30 days from invoice date unless otherwise agreed upon in writing. REMIT TO:  
CUMMINS CANADA ULC  
PO BOX 2521 STN M,  
CALGARY AB T2P 0T6

INVOICE NO

REMIT TO: PO BOX 2521 STN M,  
CALGARY AB T2P 0T6

## BILL TO

F

PAGE 1 OF 2

\*\*\* CASH \*\*\*

| DATE         | CUSTOMER ORDER NO. | DATE IN SERVICE | ENGINE MODEL      | PUMP NO.  | EQUIPMENT MAKE  |
|--------------|--------------------|-----------------|-------------------|-----------|-----------------|
| 02-JUL-2025  |                    |                 | ISC CM554         |           | UNLISTED        |
| CUSTOMER NO. | SHIP VIA           | FAIL DATE       | ENGINE SERIAL NO. | CPL NO.   | EQUIPMENT MODEL |
| 3219482      |                    | 02-JUL-2025     | 46296836          | 2695      | ALL             |
| REF. NO.     | SALESPERSON        | PARTS DISP.     | MILEAGE/HOURS     | PUMP CODE | UNIT NO.        |
| 126260       | UP426              |                 | 117042            |           | 00              |

| QUANTITY ORDERED | BACK ORDERED | QUANTITY SHIPPED | PART NUMBER | DESCRIPTION | PRODUCT CODE | LIST PRICE | UNIT PRICE | AMOUNT |
|------------------|--------------|------------------|-------------|-------------|--------------|------------|------------|--------|
|------------------|--------------|------------------|-------------|-------------|--------------|------------|------------|--------|

OSN/MSN/VIN 46296836

### COMPLAINT

CUSTOMER STATES UNIT HAS A CHECK ENGINE LIGHT ON.

### CAUSE

FAULT CODE 539 OPEN CIRCUIT DETECTED AT THE TRANSIENT SUPPRESSOR IN THE INJECTION CONTROL VALVE CIRCUIT IN THE ENGINE HARNESS. SUPPRESSOR,TRANSIENT

### CORRECTION

PERFORM JSA. CONNECT INSITE. CREATE IMAGE. CHECK CODES. CODE 539 ACTIVE. TROUBLESHOOT 539 PER CSS. DISCONNECT INJECTOR CONTROL VALVE FORM ENGINE HARNESS. DISCONNECT ENGINE HARNESS FROM ECM. CHECK INJECTOR CONTROL VALVE CIRCUIT FOR OPEN CIRCUIT, PIN TO PIN SHORT CIRCUIT AND SHORT CIRCUIT TO GROUND, ALL OK. DISCONNECT TRANSIENT SUPPRESSOR FORM ENGINE HARNESS. TEST TRANSIENT SUPPRESSOR HARNESS FOR OPEN CIRCUIT, OK. TRANSIENT SUPPRESSOR REQUIRES REPLACEMENT.REPLACE AND WIRE IN NEW TRANSIENT SUPPRESSOR. SECURE WIRING. INSTALL ENGINE HARNESS ECM CONNECTOR. CONNECT INSITE. RUN ENGINE. CODE 539 WENT INACTIVE. CLEAR CODE. PERFORM COURTESY INSPECTION. FOUND COOLANT LEVEL LOW.

### COVERAGE

### REMARK

CUSTOMER BILLABLE

THANK YOU

CUSTOMER WILL TOP UP COOLANT LEVEL

1

COURTESY INSPECTION

COURTESY INSPECTION

0.00

1

1 3944110

SUPPRESSOR,TRANSIENT

CECO

388.92

368.80

368.80

### CUSTOMER DECLINED COURTESY INSPECTION ESTIMATE

#### Courtesy Inspection :

Oil and coolant FAIL

PARTS:

368.80

PARTS COVERAGE CREDIT:

0.00CR

TOTAL PARTS:

368.80

SURCHARGE TOTAL:

0.00

GST NUMBER - 88788 0904

APPENDIX A IS ATTACHED AND INCORPORATED HEREIN. IN APPENDIX A THERE ARE ADDITIONAL CONTRACT TERMS AND CONDITIONS, INCLUDING LIMITATION ON WARRANTIES AND LIABILITIES WHICH ARE EXPRESSIVELY INCORPORATED HEREIN AND WHICH PURCHASER ACKNOWLEDGES HAVE BEEN READ, FULLY UNDERSTOOD AND ACCEPTED.

AUTHORIZED BY (print name)

SIGNATURE

DATE



# Sales and Service

Payment terms are 30 days from invoice date unless otherwise agreed upon in writing. REMIT TO:  
CUMMINS CANADA ULC  
PO BOX 2521 STN M,  
CALGARY AB T2P 0T6

INVOICE NO

**BILL TO**

PAGE 2 OF 2

\*\*\* CASH \*\*\*

| DATE             |              |                  |             | CUSTOMER ORDER NO. |             | DATE IN SERVICE |              | ENGINE MODEL      |            | PUMP NO.  |            | EQUIPMENT MAKE  |        |
|------------------|--------------|------------------|-------------|--------------------|-------------|-----------------|--------------|-------------------|------------|-----------|------------|-----------------|--------|
| 02-JUL-2025      |              |                  |             |                    |             |                 |              | ISC CM554         |            |           |            | UNLISTED        |        |
| CUSTOMER NO.     |              |                  |             | SHIP VIA           |             | FAIL DATE       |              | ENGINE SERIAL NO. |            | CPL NO.   |            | EQUIPMENT MODEL |        |
| 3219482          |              |                  |             |                    |             | 02-JUL-2025     |              | 46296836          |            | 2695      |            | ALL             |        |
| REF. NO.         |              |                  |             | SALESPERSON        |             | PARTS DISP.     |              | MILEAGE/HOURS     |            | PUMP CODE |            | UNIT NO.        |        |
| 126260           |              |                  |             | UP426              |             |                 |              | 117042            |            |           |            | 00              |        |
| QUANTITY ORDERED | BACK ORDERED | QUANTITY SHIPPED | PART NUMBER |                    | DESCRIPTION |                 | PRODUCT CODE |                   | LIST PRICE |           | UNIT PRICE |                 | AMOUNT |
| OSN/MSN/VIN      |              |                  |             | 46296836           |             |                 |              |                   |            |           |            |                 |        |

LABOR: 891.00  
LABOR COVERAGE CREDIT: 0.00CR  
TOTAL LABOR: 891.00  
MISC.: 0.00  
MISC. COVERAGE CREDIT: 0.00CR  
TOTAL MISC.: 0.00  
GST 62.99  
PST 75.59

You saved \$20.12 on your parts.

GST NUMBER - 88788 0904

APPENDIX A IS ATTACHED AND INCORPORATED HEREIN. IN APPENDIX A THERE ARE ADDITIONAL CONTRACT TERMS AND CONDITIONS, INCLUDING LIMITATION ON WARRANTIES AND LIABILITIES WHICH ARE EXPRESSLY INCORPORATED HEREIN AND WHICH PURCHASER ACKNOWLEDGES HAVE BEEN READ, FULLY UNDERSTOOD AND ACCEPTED.

SUB TOTAL: 1,259.80  
TOTAL TAX: 138.58  
TOTAL AMOUNT: CA \$ 1,398.38

AUTHORIZED BY (print name)

SIGNATURE

DATE



Promised Date:  
20 AUG 25



WO:

Customer Name:  
Address:

Postal/Zip:  
Phone#(res):  
Phone#(bus):  
Cell Phone:  
Email: NONE

Date In:  
Completed Date:  
Promised Date:  
Promised Time:  
Purchased Date:  
Delivery Date:

Author: ACOLLES  
Stock No:  
Year: 2004  
Manufacturer:  
Brand: BEAVER  
Model:  
Unit Type: MAD-CLASS A DIESEL  
MOTORHOME  
Exterior Color:  
Serial#: 1  
License#:  
Key#:  
Tow Year:  
Tow Make:  
Tow Model:  
Tow Capacity:

#### Job #1 - External

COMPLAINT: FRONT AND DRIVER SIDE REAR HYDRAULIC JACKS ARE LEAKING

QUOTED 189 DIAGNOSE - CUSTOMER AWARE WE WILL CALL AND QUOTE FOR ADDITIONAL PARTS AND LABOUR

CAUSE: 1 - FRONT AND DRIVER SIDE REAR HYDRAULIC JACKS ARE LEAKING

CORRECTION: THERE ARE 3 HYDRAULIC JACKS  
ONE UP FRONT AND TWO AT THE BACK  
THE FRONT AND DRIVER REAR ARE LEAKING OUT OF THE BOOT  
THE SEAL AT THE BOTTOM IS SHOT AND WOULD NEED BOTH JACKS REPLACED  
PARTS HAS SOP

#### Labor

| Job # | Description | Total  |
|-------|-------------|--------|
| 1     | DIAGNOSE    | 189.00 |

#### Other Services

| Code | Description                | Qty  | Price | Total |
|------|----------------------------|------|-------|-------|
| EC   | ENVIRONMENTAL DISPOSAL FEE | 1.00 | 5.67  | 5.67  |
| SST  | SHOP SUPPLIES - TAXABLE    | 1.00 | 28.35 | 28.35 |

Subtotal for Job #1: 223.02

|                          |               |
|--------------------------|---------------|
| Parts Total:             | 0.00          |
| Labour Total:            | 189.00        |
| Sublet Total:            | 0.00          |
| Extras Total:            | 34.02         |
| GOODS & SERVICES TAX:    | 11.15         |
| PROVINCIAL SALES TAX:    | 13.04         |
| <b>WORK ORDER TOTAL:</b> | <b>247.21</b> |



GST # 105537781RT

Customer Signature : \_\_\_\_\_

Date: 20 Aug 2025

