




W/O: 47587
Promised Date: 11 SEP 24



WO # [REDACTED]

Customer Name: [REDACTED]

Address: [REDACTED]

Postal/Zip: [REDACTED]

Phone#: [REDACTED]

Phone#(bus): [REDACTED]

Cell Phone: [REDACTED]

Email: NONE

Invoice#: [REDACTED]

Date In: 27 AUG 24

Completed Date: 06 SEP 24

Promised Date: [REDACTED]

Promised Time: [REDACTED]

Purchased Date: [REDACTED]

Delivery Date: [REDACTED]

Author: R [REDACTED]

Stock No: [REDACTED]

Year: 2004

Manufacturer: [REDACTED]

Brand: BEAVER

Model: [REDACTED]

Unit Type: MAD-CLASS A DIESEL

MOTORHOME

Exterior Color: [REDACTED]

Serial#: 1

License#: [REDACTED]

Key#: [REDACTED]

Tow Year: [REDACTED]

Tow Make: [REDACTED]

Tow Model: [REDACTED]

Tow Capacity: [REDACTED]

Job #1 - External

COMPLAINT: CUSTOMER NEEDS NEW SOLENOID COIL

PART IN

QUOTED \$283.50 FOR INSTALL

CAUSE: 1 - CUSTOMER NEEDS NEW SOLENOID COIL

PART IN

QUO

CORRECTION: r and r solonoid for left rear jack so it can extend
used heat shrink but connectors to reconnect the new solonoid
tested out the jack to make sure it works

Labor

Job #	Description	Total
1	MISC	283.50

Parts

Part #	Description	Qty	Price	Total
RVA-SC-01	SOLENOID COIL	1.00	69.95	69.95

Other Services

Code	Description	Qty	Price	Total
EC	ENVIRONMENTAL DISPOSAL FEE	1.00	6.00	6.00
SST	SHOP SUPPLIES - TAXABLE	1.00	30.00	30.00
FRT	RVA94159 SOLENOID COIL	1.00	40.00	40.00
BKGT	RVA SOLENOID COIL	1.00	20.00	20.00

Subtotal for Job #1: 449.45



Parts Total:	69.95
Labour Total:	283.50
Sublet Total:	0.00
Extras Total:	96.00
GOODS & SERVICES TAX:	22.48
PROVINCIAL SALES TAX:	26.97
WORK ORDER TOTAL:	498.90

GST # 105537761RT

Customer Signature : _____

Date: 06 Sep 2024



SaskBattery

PH (306) 791-9844 FAX (306) 525-0282
1444-A Lorne St.
Regina, Saskatchewan S4R 2K4
Canada

SaskBattery MJ

PH:(306) 692-9844
461-D Athabasca St E. Moose Jaw
Saskatchewan S6H 0L9 Canada



INVOICE

Invoice No.:
Date: 16/11/2024
Ship Date:
Page: 1
Re: Order No.

Sold to:

Ship to:

Regina, Saskatchewan
Canada

Canada

Business No.:

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
HC31S	Each	2	HIGH CYCLE GROUP 31 STU	EP	99.50	199.00
G2200	Each	4	FARM/IND BATTERY	EP	149.50	598.00
		2	2200 GOLF CART BATTERY	EP	20.00	40.00
		4	31 Core	EP	25.00	100.00
FARM PST EXEMPTION	Each	1	GC Core	GP		
			Certification (farmer must provide legal land location, date, and sign)			
			EP - GST 5%, no PST GST			46.85
Shipped By: Tracking Number:						Total Amount 983.85
Comment: 2004 Kenworth, Speedrite Electric Fence						Amount Paid 983.85
Sold By:						Amount Owing 0.00

WARRANTY DOES NOT INCLUDE BATTERIES THAT ARE FROZEN, DAMAGED, MERELY DISCHARGED OR IMPROPERLY TESTED

Sterling

TRUCK & TRAILER
SALES LTD.

...SINCE 1972

REGINA

762 McDonald Street
Regina, Sask. S4N 7M7
Bus: (306) 525-0466
Fax: (306) 352-7011

Parts Direct (306) 352-8600

Toll Free Parts 1-888-922-2322

REGINA - GTH

2059 Fleming Road
Regina, Sask. S4M 0A1
Bus: (306) 565-0466
Fax: (306) 543-7011

Toll Free Parts 1-888-922-2322

LLOYDMINSTER

5202 - 63rd Avenue
Lloydminster, Alberta T9V 3T8
Bus: (780) 875-2021
Fax: (780) 875-2586

Toll Free 1-844-875-2021

SASKATOON

2326 Northridge Drive
Saskatoon, Sask. S7L 1B9
Bus: (306) 242-7988
Fax: (306) 242-0389

Parts Direct (306) 242-7932

Toll Free Parts 1-866-562-0418

Website: www.sterlingtruckandtrailer.ca

GST # 710551500

DATE ENTERED 28 NOV 24	YOUR ORDER NO.	DATE SHIPPED 29 NOV 24	INVOICE DATE 29 NOV 24	INVOICE NUMBER	14:12
---------------------------	----------------	---------------------------	---------------------------	-------------------	-------

S
O
L
D

T
O

S
H
I
P

T
O

PAGE 1 OF 1

SHIP VIA			SLSM.	B/L NO.	TERMS	F.O.B. POINT	
CALL WHEN ARR							
ORD	QUANTITY		PART NO.	DESCRIPTION	LIST	NET	AMOUNT
	SHIP	B.O.					
1	1	0	170-955205	999 WABCO SS12		175.89	175.89
1	1	0	FRT	FRT FREIGHT		30.00	30.00
			G.S.T. 10501 7685				10.29
			P.S.T. 0871285				12.35

- INTEREST AT 2% PER MONTH (24% PER ANNUM) CHARGED ON OVERDUE ACCOUNTS.
- RETURNED GOODS SUBJECT TO 20% RESTOCKING CHARGE.
- NO RETURNS ON ELECTRICAL OR SPECIAL ORDER GOODS.
- NO ALLOWANCE FOR GOODS RETURNED UNLESS ACCOMPANIED BY THIS INVOICE WITHIN 5 DAYS FROM PURCHASE DATE.
- ALL GOODS MUST BE RETURNED IN ORIGINAL PACKAGING IN UNCHANGED AND USABLE CONDITION.

- ALL CORES MUST BE RETURNED WITHIN 15 DAYS AND WILL BE SUBJECT TO CORE INSPECTION.
- GOODS WILL NOT BE RETURNED TO STERLING TRUCK & TRAILER SALES WITHOUT PRIOR AUTHORIZATION.
- PRICES, TERMS AND CONDITIONS OF SALE ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE OR OBLIGATION.



WO #: 1

Customer Name: 4

Address: 11111

Postal/Zip

Phone#(r)

Phone#(bus):

Cell Phone:

Email: NONE

Invoice#:

Date In:

Completed Date: 11/05

Promised Date:

Promised Time:

Purchased Date:

Delivery Date:

Author:

Stock No:

Year:

Manufacturer:

Brand: BEAVER

Model:

Unit Type: MAD-CLASS A DIESEL

MOTORHOME

Exterior Color:

Serial#: 1

License#:

Key#:

Tow Year:

Tow Make:

Tow Model:

Tow Capacity:

Job #1 - External

COMPLAINT: APPROVED BY CUSTOMER ON AUGUST 20, 2025:

REPLACE FRONT AND REAR HYDRAULIC JACKS

QUOTED:

FRONT JACK - \$1795.00 (1-2 WEEKS SHIPPING FROM RVA)

BACK JACK - \$1795.00 (BACK ORDERED UNTIL END OF OCTOBER)

SHIPPING - \$50 - \$85 (BRKG), \$300 - \$400 (FRT)

LABOUR (AS PER KARL) - \$850.50

NOTE:

FITTINGS ON HOSES COULD BE OLD/RUSTY. WE ARE UNSURE OF THEIR CONDITION UNTIL WE GET EVERYTHING OPEN DURING THE INSTALATION PROCESS. THE CUSTOMER IS 100% AWARE THAT THIS WOULD BE AN ADDITIONAL COST TO FIX. PLEASE CONTACT HIM IF ADDITIONAL LABOUR IS NEEDED!

CAUSE: 1 - APPROVED BY CUSTOMER ON AUGUST 20, 2025:

REPLACE

CORRECTION: HAD TO UNBOLT THE REAR FENDER AROUND THE L/H WHEELS

REMOVED MUD FLAP

REMOVED REAR JACK LINE

REMOVED JACK

INSTALLED NEW JACK

REINSTALLED LINE

REINSTALLED FENDER

REINSTALLED MUD FLAP

HAD TO PULL GENERATOR OUT TO GAIN ACCESS TO THE FRONT

ONCE ACCESS WAS GRANTED CRAKLE DUNDER UNIT AND UNTHREADED LINE

REMOVED JACK

CLEANED JACK FOOT

Printed On: 2025-11-07 1:12:30PM

© 2025 Integrated Dealer Systems



INSTALLED NEW JACK
INSTALLED FOOT AND SPRINGS
THIS LINE FOR REAR JACK DID THE SAME THING BACK THERE)
TORQUED ALL JHARDWARE
TESTED JACKS
NO LEAKS
ALL CAME UP AND WENT DOWN
PUT GENERATOR BACK IN (ITS ON ROLLERS AND A SWITCH)
CLEANED UP
TESTED JACKS DURING INSPECTION, ALL WORKS NO LEAKS.

Labor

Job #	Description	Total
1	REPLACE JACKS	850.50

Parts

Part #	Description	Qty	Price	Total
J0916-15-01	22.5A - 32" REAR JACK CYLINDER ONLY	1.00	1,795.00	1,795.00
J0916-16-01	22.5A - 32" FRONT JACK CYLINDER ONLY	1.00	1,795.00	1,795.00

Sublet

Description	Total
ADAPTORS	22.75

Other Services

Code	Description	Qty	Price	Total
EC	ENVIRONMENTAL DISPOSAL FEE	1.00	6.00	6.00
SST	SHOP SUPPLIES - TAXABLE	1.00	30.00	30.00
FRT	RVA COMPANY 107588 / 107589	1.00	387.72	387.72
BKGT	PERCY 00088375 / FEDEX 17525980968940	1.00	73.50	73.50

Subtotal for Job #1: 4,960.47

Parts Total: 3,590.00
Labour Total: 850.50
Sublet Total: 22.75
Extras Total: 497.22
GOODS & SERVICES TAX: 248.04
PROVINCIAL SALES TAX: 292.86
WORK ORDER TOTAL: 5,501.37

GST # 105537781RT

Customer Signature : _____

Date: 07 Nov 2025

