



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                    |                      |                                 |
|--------------------|----------------------|---------------------------------|
| Branch<br>MOOSOMIN |                      |                                 |
| Date<br>08/24/22   | Time<br>08:44:29 (O) | Page<br>03                      |
| Account No.        | Phone No.            | Reference No.<br>W37537         |
| Ship Via           |                      | Purchase Order                  |
| SE31-15-31W1       |                      | G.S.T. No.<br>79759 4660 RT0001 |
| Credit Card No.    |                      | Salesperson<br>H40              |

### Description of Work and Parts

| STK#/FLEET# | HRS  | PIN/EIN         | WARRANTY DATE    | HRS       | Fold -- |
|-------------|------|-----------------|------------------|-----------|---------|
| 052881      | 2588 | COMBINE         | 1580             | H4J304834 |         |
|             | 2588 | X               |                  |           |         |
| FREIGHT     |      | FREIGHT         | 1                | 20.00     | 20.00   |
| Q3959       |      | GIB KEY 3/8X4.5 | 2 N              | 22.40     | 44.80   |
| 1500-30     |      | PIN COT 5/16X2- | 4                | .95       | 3.80    |
| 286909      |      | BEARING, BALL   | 4 O              | 62.54     | 250.16  |
|             |      |                 |                  | PARTS     | 318.76  |
|             |      |                 |                  | LABOR     | 620.00  |
| 13300056    |      |                 | SEGMENT TOTAL==> |           | 938.76  |

SEGMENT# 3 C 05396 NA 07/25/22 07/25/22

2- REPALCE ALL 3 FEEDER WEAR PLATES AND BOLTS

2.00 HRS

#### CORRECTION:

- loosen off feeder chain
- unbolted and removed old feeder chain wear plates
- put in and aligned new feeder chain wear plates and tighten down
- retighten up feeder chain to spec
- clean up tools

|          |                  |                  |        |         |
|----------|------------------|------------------|--------|---------|
| FREIGHT  | FREIGHT          | 1                | 20.00  | 20.00   |
| SH310203 | 3/8 FLANG NUT    | 5                | .14    | .70     |
| 247780   | FLANGE NUT 3/8   | 1                | .45    | .45     |
| 86624124 | SCREW, SER       | 6                | 3.70   | 22.20   |
| 87299946 | KIT, SHAKER BUSH | 1 N              | 631.13 | 631.13  |
| 87523833 | SUPPORT          | 1 N              | 131.00 | 131.00  |
| 87523842 | SUPPORT          | 1 N              | 69.75  | 69.75   |
| 87530580 | SUPPORT          | 1 N              | 33.79  | 33.79   |
| 87613203 | WASHER           | 6 N              | 5.95   | 35.70   |
|          |                  |                  | PARTS  | 944.72  |
|          |                  |                  | LABOR  | 310.00  |
| 13300056 |                  | SEGMENT TOTAL==> |        | 1254.72 |

CONTINUED ON PAGE 04

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                    |                      |                                 |
|--------------------|----------------------|---------------------------------|
| Branch<br>MOOSOMIN |                      |                                 |
| Date<br>08/24/22   | Time<br>08:44:29 (O) | Page<br>04                      |
| Account No.        | Phone No.            | Reference No.<br>W37537         |
| Ship Via           |                      | Purchase Order                  |
| SE31-15-31W1       |                      | G.S.T. No.<br>79759 4660 RT0001 |
| Credit Card No.    |                      | Salesperson<br>H40              |

### Description of Work and Parts

| STK#/FLEET# | HRS  | PIN/EIN | WARRANTY DATE | HRS       | Fold -- |
|-------------|------|---------|---------------|-----------|---------|
| 052881      | 2588 | COMBINE | 1580          | HAJ304834 |         |

2588

X

SEGMENT# 4 C 05396 NA 07/25/22 07/25/22

2- BEATER BLADES SHOULD BE ADJUSTED - MAY BE MAXED OUT 1.00 HRS

#### CORRECTION:

- opened up rock trap to see beater blades
- noticed still had alot of adjustment left to them
- slid beater blades out and tighted back up
- cleaned up tools

LABOR

155.00

13300056

SEGMENT TOTAL==>

155.00

SEGMENT# 5 C 05396 NA 07/25/22 07/25/22

3- FEEDER DRIVE GEAR BOX HUB AND CROSS SHAFT WORN OUT 5.00 HRS

#### CORRECTION:

- drained hydraulic system
- removed hydraulic hoses
- unhook hydraulic cylinder
- unbolted gear box from feeder house
- removed gear box
- removed hydraulic motor from gear box
- un bolted two half's of gear box
- split gear box
- removed big gear out of gear box
- removed slip gears from gear box
- pressed new bearings on to new big gear
- put new seals on bearing holders for big gear
- put apart slip gear assemble
- replaces cone bearings and support bearings on slip gear
- put slip gear back in to gear box
- put big gear back in to gear box
- cleaned up sealing surfaces on both half's of gear box

CONTINUED ON PAGE 05

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                 |              |                   |
|-----------------|--------------|-------------------|
| Branch          |              |                   |
| MOOSOMIN        |              |                   |
| Date            | Time         | Page              |
| 08/24/22        | 08:44:29 (O) | 05                |
| Account No.     | Phone No.    | Reference No.     |
|                 |              | W37537            |
| Ship Via        |              | Purchase Order    |
| SE31-15-31W1    |              | G.S.T. No.        |
| Credit Card No. |              | 79759 4660 RT0001 |
|                 |              | Salesperson       |
|                 |              | H40               |

### Description of Work and Parts

| STK#/FLEET# | HRS          | PIN/EIN        | WARRANTY DATE | HRS | Fold - |
|-------------|--------------|----------------|---------------|-----|--------|
| 052881      | 2588 COMBINE | 1580 HAJ304834 |               |     |        |

2588

X

- sealed and bolted the two half's back together
- clean sealing surfaces on the hydraulic motor and where it mounts to gear case
- sealed and bolted on hydraulic motor
- removed pully off of cross shaft on right hand side
- removed right side bearing
- unbolted and removed bearing from feeder house
- removed cross shaft
- in stalled new cross shaft
- installed new bearings on cross shaft and bolted in to place
- put new spacing collar on to cross shaft
- put new retaining clip on cross shaft
- spun spacing collar out to it was pressed against retaining clip and tighten down set screw
- mounted gear box back on to combine
- hooked up hydraulic lines
- reattached hydraulic cylinder
- filled gear case with hydraulic oil as box says
- refilled hydraulic system
- cleaned up tools

#### ADDITIONAL DESCRIPTION:

REPLACE HUB, CROSS SHAFT, BEARINGS AND GEAR BOX SEALS

|          |               |     |        |        |
|----------|---------------|-----|--------|--------|
| FREIGHT  | FREIGHT       | 3   | 18.98  | 56.95  |
| 132709   | CUP           | 2 N | 8.21   | 16.42  |
| 132710   | BEARING, CONE | 2 N | 14.64  | 29.28  |
| 163024   | SEAL          | 2 N | 18.15  | 36.30  |
| 253462A1 | RING, SPECIAL | 1 N | 46.62  | 46.62  |
| 253469A1 | COLLAR        | 1 N | 237.44 | 237.44 |
| 253533A1 | HUB           | 1 N | 104.21 | 104.21 |

CONTINUED ON PAGE 06

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                           |                             |                                        |
|---------------------------|-----------------------------|----------------------------------------|
| Branch<br><b>MOOSOMIN</b> |                             |                                        |
| Date<br><b>08/24/22</b>   | Time<br><b>08:44:29 (O)</b> | Page<br><b>06</b>                      |
| Account No.               | Phone No.                   | Reference No.<br><b>W37537</b>         |
| Ship Via                  |                             | Purchase Order                         |
| <b>SE31-15-31W1</b>       |                             | G.S.T. No.<br><b>79759 4660 RT0001</b> |
| Credit Card No.           |                             | Salesperson<br><b>H40</b>              |

### Description of Work and Parts

| STK#/FLEET# |               | HRS  | PIN/EIN          | WARRANTY DATE | HRS     | Fold -- |
|-------------|---------------|------|------------------|---------------|---------|---------|
| 052881      | 2588 COMBINE  | 1580 | H4J304834        |               |         |         |
|             | 2588          | X    |                  |               |         |         |
| 330052      | BEARING, B    | 1 N  | 48.47            |               | 48.47   |         |
| 388771A1    | SHAFT         | 1 N  | 722.15           |               | 722.15  |         |
| 609654R91   | BEARING, BALL | 1 M  | 65.40            |               | 65.40   |         |
| 681627      | GEAR          | 1 N  | 1075.00          |               | 1075.00 |         |
| 681631      | HOUSING       | 1 N  | 590.00           |               | 590.00  |         |
| 781754      | RING          | 2 N  | 30.98            |               | 61.96   |         |
| 86575514    | BEARING, BALL | 1    | 162.49           |               | 162.49  |         |
| 87304415    | SET SCREW 3/8 | 5 N  | 4.30             |               | 21.50   |         |
| 87591960    | BEARING, BALL | 2 N  | 45.79            |               | 91.58   |         |
| 9707565     | PIN, GROOV    | 2 N  | 10.06            |               | 20.12   |         |
|             |               |      | PARTS            |               | 3385.89 |         |
|             |               |      | LABOR            |               | 775.00  |         |
| 13300056    |               |      | SEGMENT TOTAL==> |               | 4160.89 |         |

SEGMENT# 6 C 05396 NA 07/25/22 07/25/22

3- CHANGE ECCENTRIC ARM BEARINGS

2.50 HRS

#### CORRECTION:

- removed eccentric arms from combine
- removed snap rings from center hubs
- pressed center hub out
- removed snap ring holding bearing in to eccentric arms
- press baring out
- pressed new bearings in
- reinstall snap ring
- press center hubs back in
- re install snap ring that holds it in
- cleaned up tools

|          |                 |   |        |        |
|----------|-----------------|---|--------|--------|
| 47509176 | BEARING HIGH SP | 2 | 192.24 | 384.48 |
|          |                 |   | PARTS  | 384.48 |
|          |                 |   | LABOR  | 387.50 |

CONTINUED ON PAGE 07

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                    |                      |                                 |
|--------------------|----------------------|---------------------------------|
| Branch<br>MOOSOMIN |                      |                                 |
| Date<br>08/24/22   | Time<br>08:44:29 (O) | Page<br>07                      |
| Account No.        | Phone No.            | Reference No.<br>W37537         |
| Ship Via           |                      | Purchase Order                  |
| SE31-15-31W1       |                      | G.S.T. No.<br>79759 4660 RT0001 |
| Credit Card No.    |                      | Salesperson<br>H40              |

### Description of Work and Parts

| STK#/FLEET# |              | HRS  | PIN/EIN   | WARRANTY DATE    | HRS    | Fold -- |
|-------------|--------------|------|-----------|------------------|--------|---------|
| 052881      | 2588 COMBINE | 1580 | HAJ304834 |                  |        |         |
|             | 2588         | X    |           |                  |        |         |
| 13300056    |              |      |           | SEGMENT TOTAL==> | 771.98 |         |

SEGMENT# 7 C 05396 NA 07/25/22 07/25/22  
3- CHANGE SHAKER ARM BEARINGS - RHS ALREADY COLLAPSED 8.00 HRS

#### CORRECTION:

- remove straw blowers off back
- remove upper sieves
- remove lower sieves
- remove drive belts for shaker decks
- remove slip clutch pulley assemblies to get at right side essentric arm
- removed back right shaker arms
- measured the stick out each bushing
- pressed out the old bushings
- pressed in new bushing to measured depth
- remount shaker arms
- removed left rear shaker arms
- measured stick out of bushing
- pressed old bushing out
- pressed new bushing in to measured depth
- remount shaker arms back on to combine
- removed front left shaker arms
- measured stick out of bushing
- pressed old bushing out
- pressed new bushing in to shaker arms to measured depth
- remounted shaker arms to combine
- removed front right shaker arms
- measured stick out of bushings
- pressed old bushing out
- pressed new bushings in till at measured depth

CONTINUED ON PAGE 08

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                    |                      |                                 |
|--------------------|----------------------|---------------------------------|
| Branch<br>MOOSOMIN |                      |                                 |
| Date<br>08/24/22   | Time<br>08:44:29 (O) | Page<br>08                      |
| Account No.        | Phone No.            | Reference No.<br>W37537         |
| Ship Via           |                      | Purchase Order                  |
| SE31-15-31W1       |                      | G.S.T. No.<br>79759 4660 RT0001 |
| Credit Card No.    |                      | Salesperson<br>H40              |

### Description of Work and Parts

| STK#/FLEET#                                                                                                                                                                                                                                                                                                    | HRS    | PIN/EIN          | WARRANTY DATE | HRS       | Fold - |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|------------------|---------------|-----------|--------|
| 052881                                                                                                                                                                                                                                                                                                         | 2588   | COMBINE          | 1580          | HAJ304834 |        |
|                                                                                                                                                                                                                                                                                                                | 2588   | X                |               |           |        |
| <ul style="list-style-type: none"><li>- remounted on to combine</li><li>- remount lower sieves in to combine</li><li>- remount upper sieves</li><li>- reinstall straw spreaders</li><li>- reinstall slip clutch pulleys</li><li>- reinstall drive belt and processing belts</li><li>- clean up tools</li></ul> |        |                  |               |           |        |
| <u>ADDITIONAL DESCRIPTION:</u>                                                                                                                                                                                                                                                                                 |        |                  |               |           |        |
| RESHIM SHAKER FRAME ONCE BACK TOGETHER                                                                                                                                                                                                                                                                         |        |                  |               |           |        |
| 87613198                                                                                                                                                                                                                                                                                                       | WASHER | 2 N              | 3.10          | 6.20      |        |
| 87613199                                                                                                                                                                                                                                                                                                       | WASHER | 5 N              | .97           | 4.85      |        |
|                                                                                                                                                                                                                                                                                                                |        | PARTS            |               | 11.05     |        |
|                                                                                                                                                                                                                                                                                                                |        | LABOR            |               | 1240.00   |        |
| 13300056                                                                                                                                                                                                                                                                                                       |        | SEGMENT TOTAL==> |               | 1251.05   |        |

SEGMENT# 8 C 05396 NA 07/25/22 07/25/22  
3- REPLACE SUPPORT ASSEMBLY BEARINGS 5.00 HRS

#### CORRECTION:

- remove support arms on each side and brackets
- pressed out support arm pins
- pressed in new support arm pins
- removed old needle bearings from support arm brackets
- pressed new needle bearings in to support arm brackets
- put new seals in support arm brackets
- reinstall support arm brackets on to combine
- reinstall support arms in to brackets
- reinstall washer spacers on to support arms
- installed new cotter pins holding arms on
- cleaned up tools

#### ADDITIONAL DESCRIPTION:

CONTINUED ON PAGE 09

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                    |                      |                                 |
|--------------------|----------------------|---------------------------------|
| Branch<br>MOOSOMIN |                      |                                 |
| Date<br>08/24/22   | Time<br>08:44:29 (O) | Page<br>09                      |
| Account No.        | Phone No.            | Reference No.<br>W37537         |
| Ship via           |                      | Purchase Order                  |
| SE31-15-31W1       |                      | G.S.T. No.<br>79759 4660 RT0001 |
| Credit Card No.    |                      | Salesperson<br>H40              |

### Description of Work and Parts

| STK#/FLEET#                         | HRS             | PIN/EIN        | WARRANTY DATE    | HRS     | Fold -- |
|-------------------------------------|-----------------|----------------|------------------|---------|---------|
| 052881                              | 2588 COMBINE    | 1580 HAJ304834 |                  |         |         |
|                                     | 2588            | X              |                  |         |         |
| 3X BEARINGS EACH SIDE SEALS AND PIN |                 |                |                  |         |         |
| FREIGHT                             | FREIGHT         | 1              | 9.00             | 9.00    |         |
| G10642                              | BEARING NEEDLE  | 6 N            | 26.88            | 161.28  |         |
| 1979251C1                           | SHAFT           | 3 N            | 100.84           | 302.53  |         |
| 2010-55-01                          | ADAPTER 1/8FNPT | 1              | 16.99            | 16.99   |         |
| 372756R91                           | SEAL            | 6 M            | 13.48            | 80.88   |         |
| 87399                               | PIN COTTER 3/16 | 2 M            | 3.13             | 6.26    |         |
|                                     |                 |                | PARTS            | 576.94  |         |
|                                     |                 |                | LABOR            | 775.00  |         |
| 13300056                            |                 |                | SEGMENT TOTAL==> | 1351.94 |         |

|                                                          |                   |          |        |  |
|----------------------------------------------------------|-------------------|----------|--------|--|
| SEGMENT# 9 C 05396 NA                                    | 07/25/22 08/15/22 |          |        |  |
| 3- ADJUST BEVEL DRIVE GEARS                              |                   | 1.50 HRS |        |  |
| <u>CORRECTION:</u>                                       |                   |          |        |  |
| - loosen off the brackets the holds drive gears in place |                   |          |        |  |
| - slid gears over to make good contact with other gears  |                   |          |        |  |
| - tighten up brackets holding drive gears in place       |                   |          |        |  |
| - cleaned up tools                                       |                   |          |        |  |
|                                                          | LABOR             |          | 232.50 |  |
| 13300056                                                 | SEGMENT TOTAL==>  |          | 232.50 |  |

|                                                  |                   |          |                      |       |
|--------------------------------------------------|-------------------|----------|----------------------|-------|
| SEGMENT#10 C 05396 NA                            | 07/25/22 07/25/22 |          |                      |       |
| 3- REPLACE THRUST BEARING ON CLEANING FAN PULLEY |                   | 1.00 HRS |                      |       |
| <u>CORRECTION:</u>                               |                   |          |                      |       |
| - pulled variable pulley for fan off             |                   |          |                      |       |
| - removed old thrust bearing off end of pulley   |                   |          |                      |       |
| - installed new thrust bearing on to pulley hub  |                   |          |                      |       |
| - re install pulley on to combine                |                   |          |                      |       |
| - clean up tools                                 |                   |          |                      |       |
| 168215C92                                        | BEARING           | 1        | 64.63                | 64.63 |
|                                                  |                   |          | CONTINUED ON PAGE 10 |       |

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                           |                             |                                        |
|---------------------------|-----------------------------|----------------------------------------|
| Branch<br><b>MOOSOMIN</b> |                             |                                        |
| Date<br><b>08/24/22</b>   | Time<br><b>08:44:29 (O)</b> | Page<br><b>10</b>                      |
| Account No.               | Phone No.                   | Reference No.<br><b>W37537</b>         |
| Ship via                  |                             | Purchase Order                         |
| <b>SE31-15-31W1</b>       |                             | G.S.T. No.<br><b>79759 4660 RT0001</b> |
| Credit Card No.           |                             | Salesperson<br><b>H40</b>              |

### Description of Work and Parts

| STK#/FLEET# |              | HRS  | PIN/EIN   | WARRANTY DATE    | HRS    | Fold -- |
|-------------|--------------|------|-----------|------------------|--------|---------|
| 052881      | 2588 COMBINE | 1580 | H4J304834 |                  |        |         |
|             | 2588         |      | X         |                  |        |         |
|             |              |      |           | PARTS            | 64.63  |         |
|             |              |      |           | LABOR            | 155.00 |         |
| 13300056    |              |      |           | SEGMENT TOTAL==> | 219.63 |         |

SEGMENT#11 C 05396 NA 07/25/22 07/25/22  
3- PLAY ON VARIABLE PULLEY FOR CLEANING FAN MIGHT BE DOWELS 1.50 HRS

#### CORRECTION:

- removed pin and cotter pin holding plate
- removed bolt holding pulley on
- removed pulley and belt
- removed half pull off of hub
- pressed dowels out of hub
- pressed new dowels in to hub
- remounted half pulley back on to hub
- removed other half of pulley off combine
- put new half pulley back on to combine
- put bel back on
- put other half of pulley on
- tightened retaining bolt back up
- put cover back on
- put back in pin and cotter pin back in
- greased bearing
- cleaned up tools

#### ADDITIONAL DESCRIPTION:

OR PULLEY WORN OUT

|          |            |     |        |        |
|----------|------------|-----|--------|--------|
| FREIGHT  | FREIGHT    | 1   | 9.00   | 9.00   |
| 14463680 | O-RING     | 1   | 7.44   | 7.44   |
| 244638   | RING, SNAP | 1 M | 4.38   | 4.38   |
| 48007763 | PULLEY     | 1 N | 123.22 | 123.22 |
| 81854    | DOWEL      | 3 N | 23.24  | 69.72  |

CONTINUED ON PAGE 11

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                           |                             |                                        |
|---------------------------|-----------------------------|----------------------------------------|
| Branch<br><b>MOOSOMIN</b> |                             |                                        |
| Date<br><b>08/24/22</b>   | Time<br><b>08:44:29 (O)</b> | Page<br><b>11</b>                      |
| Account No.               | Phone No.                   | Reference No.<br><b>W37537</b>         |
| Ship Via                  |                             | Purchase Order                         |
| <b>SE31-15-31W1</b>       |                             | G.S.T. No.<br><b>79759 4660 RT0001</b> |
| Credit Card No.           |                             | Salesperson<br><b>H40</b>              |

### Description of Work and Parts

| STK#/FLEET#                             |                                                 | HRS  | PIN/EIN   | WARRANTY DATE    | HRS    | Fold -- |
|-----------------------------------------|-------------------------------------------------|------|-----------|------------------|--------|---------|
| 052881                                  | 2588 COMBINE                                    | 1580 | HAJ304834 |                  |        |         |
|                                         | 2588                                            | X    |           |                  |        |         |
|                                         |                                                 |      |           | PARTS            | 213.76 |         |
|                                         |                                                 |      |           | LABOR            | 232.50 |         |
| 13300056                                |                                                 |      |           | SEGMENT TOTAL==> | 446.26 |         |
| SEGMENT#12 C 05396 NA 07/25/22 08/15/22 |                                                 |      |           |                  |        |         |
|                                         | 2- FLIP CHOPPER BLADES                          |      |           | 2.40 HRS         |        |         |
|                                         | CORRECTION:                                     |      |           |                  |        |         |
|                                         | remove knives one by one and flip and retighten |      |           |                  |        |         |
|                                         |                                                 |      |           | LABOR            | 372.00 |         |
| 13300056                                |                                                 |      |           | SEGMENT TOTAL==> | 372.00 |         |
| SEGMENT#13 C 05396 NA 07/25/22 07/25/22 |                                                 |      |           |                  |        |         |
|                                         | 3- CHOPPER DRIVEN PULLEY SPLINES WORN OUT       |      |           | 1.75 HRS         |        |         |
|                                         | CORRECTION:                                     |      |           |                  |        |         |
|                                         | - chopper drive pully has play in it            |      |           |                  |        |         |
|                                         | - removed drive belt                            |      |           |                  |        |         |
|                                         | - removed nut holding on chopper pully          |      |           |                  |        |         |
|                                         | - removed spacing washers                       |      |           |                  |        |         |
|                                         | - removed old pulley                            |      |           |                  |        |         |
|                                         | - put new pully on to chopper shaft             |      |           |                  |        |         |
|                                         | - put washers back on in order                  |      |           |                  |        |         |
|                                         | - put nut back on shaft and tighten back up     |      |           |                  |        |         |
|                                         | - put drive belt back on                        |      |           |                  |        |         |
|                                         | - clean up tools                                |      |           |                  |        |         |
| 84151573                                | NUT                                             | 1    |           | 4.15             | 4.15   |         |
| 87735266                                | PULLEY                                          | 1 N  |           | 383.65           | 383.65 |         |
|                                         |                                                 |      |           | PARTS            | 387.80 |         |
|                                         |                                                 |      |           | LABOR            | 271.25 |         |
| 13300056                                |                                                 |      |           | SEGMENT TOTAL==> | 659.05 |         |

CONTINUED ON PAGE 12

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

C- DOUG OUTHWAITE

Invoice to:

DOUG OUTHWAITE  
BOX 22  
ROCANVILLE SK S0A 3L0

|                           |                             |                                        |
|---------------------------|-----------------------------|----------------------------------------|
| Branch<br><b>MOOSOMIN</b> |                             |                                        |
| Date<br><b>08/24/22</b>   | Time<br><b>08:44:29 (O)</b> | Page<br><b>12</b>                      |
| Account No.               | Phone No.                   | Reference No.<br><b>W37537</b>         |
| Ship Via                  |                             | Purchase Order                         |
| <b>SE31-15-31W1</b>       |                             | G.S.T. No.<br><b>79759 4660 RT0001</b> |
| Credit Card No.           |                             | Salesperson<br><b>H40</b>              |

### Description of Work and Parts

| STK#/FLEET#                                               | HRS              | PIN/EIN  | WARRANTY DATE | HRS       | Fold - |
|-----------------------------------------------------------|------------------|----------|---------------|-----------|--------|
| 052881                                                    | 2588             | COMBINE  | 1580          | HBJ304834 |        |
|                                                           | 2588             | X        |               |           |        |
| SEGMENT#14 C 05396 NA                                     | 07/25/22         | 07/25/22 |               |           |        |
| 3- LOWER CLEAN GRAIN AUGER BEARINGS ROUGH                 |                  |          | 4.00          | HRS       |        |
| <u>CORRECTION:</u>                                        |                  |          |               |           |        |
| - removed lock collar                                     |                  |          |               |           |        |
| - unbolt bearing holder                                   |                  |          |               |           |        |
| - removed bearing                                         |                  |          |               |           |        |
| - removed collar that holds elevator chain sprocket chain |                  |          |               |           |        |
| - added two shims beside sprocket to get rid of the play  |                  |          |               |           |        |
| - put back on collar to hold sprocket in place            |                  |          |               |           |        |
| - put new bearing back on to shaft                        |                  |          |               |           |        |
| - tighten back up bearing holder                          |                  |          |               |           |        |
| - put new bearing lock collar on                          |                  |          |               |           |        |
| - blue lock tight the set screw                           |                  |          |               |           |        |
| - tightened up elevator chain                             |                  |          |               |           |        |
| - cleaned up tools                                        |                  |          |               |           |        |
| <u>ADDITIONAL DESCRIPTION:</u>                            |                  |          |               |           |        |
| ALSO SHIM PADDLE DRIVE SPROCKET AND TENSION CHAIN         |                  |          |               |           |        |
| 473093R92                                                 | BEARING          | 1 N      | 72.27         |           | 72.27  |
| 47577188                                                  | COLLAR           | 1        | 25.35         |           | 25.35  |
| 87613234                                                  | WASHER           | 4 N      | 3.10          |           | 12.40  |
|                                                           | PARTS            |          |               |           | 110.02 |
|                                                           | LABOR            |          |               |           | 620.00 |
| 13300056                                                  | SEGMENT TOTAL==> |          |               |           | 730.02 |

SEGMENT#15 C 05396 NA 07/25/22 07/25/22  
2- REPLACE WOODEN BLOCKS FOR ELEVATOR CHAIN .50 HRS

CORRECTION:

- wooden guide blocks worn out on elevator chain
- removed bolts holding them on
- put new blocks on bolts

CONTINUED ON PAGE 13

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                    |                      |                                 |
|--------------------|----------------------|---------------------------------|
| Branch<br>MOOSOMIN |                      |                                 |
| Date<br>08/24/22   | Time<br>08:44:29 (O) | Page<br>13                      |
| Account No.        | Phone No.            | Reference No.<br>W37537         |
| Ship Via           |                      | Purchase Order                  |
| SE31-15-31W1       |                      | G.S.T. No.<br>79759 4660 RT0001 |
| Credit Card No.    |                      | Salesperson<br>H40              |

### Description of Work and Parts

| STK#/FLEET#                       | HRS   | PIN/EIN          | WARRANTY DATE | HRS       | Fold -- |
|-----------------------------------|-------|------------------|---------------|-----------|---------|
| 052881                            | 2588  | COMBINE          | 1580          | HAJ304834 |         |
|                                   | 2588  | X                |               |           |         |
| - tighten bolts back down in spot |       |                  |               |           |         |
| - clean up tools                  |       |                  |               |           |         |
| 582018R1                          | BLOCK | 2                | 30.92         | 61.84     |         |
|                                   |       |                  | PARTS         | 61.84     |         |
|                                   |       |                  | LABOR         | 77.50     |         |
| 13300056                          |       | SEGMENT TOTAL==> |               | 139.34    |         |

SEGMENT#16 C 05396 NA 07/25/22 07/25/22  
2- REPLACE 2 SPHERICAL BEARING ON ELEVATOR TENSIONER SUPPORT 1.00 HRS

#### CORRECTION:

- loosened off tension on chain
- unhooked tension rod
- unbolted idler sprockets
- removed front cover
- move chain out of way
- took out pin holding shaft in to the bearings
- removed shaft from bearings
- unbolted bearings
- bolted in new bearings
- put back in shaft threw the bearings and re pined it
- put chain back in to position
- put front cover back on
- put idler sprockets back in
- reattach tensioning rod
- tighten chain back up to proper tensions
- clean up tools

|          |        |                  |       |        |
|----------|--------|------------------|-------|--------|
| A63366   | FLANGE | 2 N              | 19.28 | 38.56  |
|          |        |                  | PARTS | 38.56  |
|          |        |                  | LABOR | 155.00 |
| 13300056 |        | SEGMENT TOTAL==> |       | 193.56 |

CONTINUED ON PAGE 14

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                           |                             |                                        |
|---------------------------|-----------------------------|----------------------------------------|
| Branch<br><b>MOOSOMIN</b> |                             |                                        |
| Date<br><b>08/24/22</b>   | Time<br><b>08:44:29 (O)</b> | Page<br><b>14</b>                      |
| Account No.               | Phone No.                   | Reference No.<br><b>W37537</b>         |
| Ship Via                  |                             | Purchase Order                         |
| <b>SE31-15-31W1</b>       |                             | G.S.T. No.<br><b>79759 4660 RT0001</b> |
| Credit Card No.           |                             | Salesperson<br><b>H40</b>              |

## Description of Work and Parts

|             |      |         |               |           |         |
|-------------|------|---------|---------------|-----------|---------|
| STK#/FLEET# | HRS  | PIN/EIN | WARRANTY DATE | HRS       | Fold -- |
| 052881      | 2588 | COMBINE | 1580          | H4J304834 |         |
|             | 2588 |         | X             |           |         |

SEGMENT#17 C 05396 NA 07/25/22 07/25/22  
3- DELIVERY AUGER HAS END PLAY REPLACE INNER BEARING AND 2.00 HRS

### CORRECTION:

- removed drive chain
- removed drive sprocket
- unbolted and removed tailings delivery auger
- removed key way
- pulled off mounting plate off auger shaft
- removed grease seals out of mounting plate
- removed needle bearings out of mounting plate
- put in new needle bearings
- put new grease seals in
- put new thrust bearing on to auger shaft and reinstalled shims
- put mounting plate back on to auger shaft
- mounted auger back on to combine
- put new shims in behind drive sprocket to line up sprockets
- put drive sprocket on
- reinstall drive chain
- greased
- cleaned up tools

### ADDITIONAL DESCRIPTION:

SPACER

FREIGHT

G13609

T38017

297931A1

564592R91

FREIGHT

BEARING THRUST

WASHER

PLATE

SEAL

|     |       |       |
|-----|-------|-------|
| 1   | 20.00 | 20.00 |
| 2 N | 8.17  | 16.34 |
| 1 M | 12.88 | 12.88 |
| 1 N | 31.46 | 31.46 |
| 2 N | 20.34 | 40.68 |

CONTINUED ON PAGE 15

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                           |                             |                                        |
|---------------------------|-----------------------------|----------------------------------------|
| Branch<br><b>MOOSOMIN</b> |                             |                                        |
| Date<br><b>08/24/22</b>   | Time<br><b>08:44:29 (O)</b> | Page<br><b>15</b>                      |
| Account No.               | Phone No.                   | Reference No.<br><b>W37537</b>         |
| Ship Via                  |                             | Purchase Order                         |
| <b>SE31-15-31W1</b>       |                             | G.S.T. No.<br><b>79759 4660 RT0001</b> |
| Credit Card No.           |                             | Salesperson<br><b>H40</b>              |

### Description of Work and Parts

| STK#/FLEET# | HRS  | PIN/EIN          | WARRANTY DATE | HRS       | Fold -- |
|-------------|------|------------------|---------------|-----------|---------|
| 052881      | 2588 | COMBINE          | 1580          | H4J304834 |         |
|             | 2588 | X                |               |           |         |
| 574940R91   |      | BEARING          | 2 N           | 34.69     | 69.38   |
| 86624169    |      | WASHER 1-1/32    | 3 M           | 3.00      | 9.00    |
| 87367       |      | WASHER 1"        | 1 M           | 2.25      | 2.25    |
|             |      | PARTS            |               |           | 201.99  |
|             |      | LABOR            |               |           | 310.00  |
| 13300056    |      | SEGMENT TOTAL==> |               |           | 511.99  |

SEGMENT#18 C 05396 NA 07/25/22 07/25/22

3- ACCESSORY BELT AND TENSIONER NEED REPLACED

1.00 HRS

#### CORRECTION:

- removed fan belt
- removed a/c belt
- removed tensioner pulley
- installed new tensioner
- installed new fan belt
- reinstalled a/c belt
- cleaned up tools

|          |                  |     |        |        |
|----------|------------------|-----|--------|--------|
| 87317615 | TENSIONER, BELT  | 1 N | 282.47 | 282.47 |
| 90487255 | V-BELT           | 1 N | 25.82  | 25.82  |
|          | PARTS            |     |        | 308.29 |
|          | LABOR            |     |        | 155.00 |
| 13300056 | SEGMENT TOTAL==> |     |        | 463.29 |

SEGMENT#19 C 05396 NA 07/25/22 07/25/22

2- SUCTION HOSES ON HYDRO LEAKING

1.50 HRS

#### CORRECTION:

- drained hydraulic tank
- removed hose from hydraulic tank over to pto gear box
- replace hose with new one
- refilled hydraulic tank

CONTINUED ON PAGE 16

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                           |                             |                                        |
|---------------------------|-----------------------------|----------------------------------------|
| Branch<br><b>MOOSOMIN</b> |                             |                                        |
| Date<br><b>08/24/22</b>   | Time<br><b>08:44:29 (O)</b> | Page<br><b>16</b>                      |
| Account No.               | Phone No.                   | Reference No.<br><b>W37537</b>         |
| Salesperson               |                             | Purchase Order                         |
| <b>SE31-15-31W1</b>       |                             | G.S.T. No.<br><b>79759 4660 RT0001</b> |
| Credit Card No.           |                             | Salesperson<br><b>H40</b>              |

### Description of Work and Parts

| STK#/FLEET#        | HRS          | PIN/EIN        | WARRANTY DATE    | HRS   | Fold -- |
|--------------------|--------------|----------------|------------------|-------|---------|
| 052881             | 2588 COMBINE | 1580 HAJ304834 |                  |       |         |
|                    | 2588         | X              |                  |       |         |
| - cleaned up tools |              |                |                  |       |         |
| FREIGHT            |              | FREIGHT        | 1                | 24.00 | 24.00   |
| 1541953C1X         |              | HOSE           | 6 M              | 45.68 | 274.08  |
|                    |              |                |                  | PARTS | 298.08  |
|                    |              |                |                  | LABOR | 232.50  |
| 13300056           |              |                | SEGMENT TOTAL==> |       | 530.58  |

|                                                   |                   |                  |         |       |  |
|---------------------------------------------------|-------------------|------------------|---------|-------|--|
| SEGMENT#20 C 05396 NA                             | 07/25/22 07/25/22 |                  |         |       |  |
| 3- REPLACE ORING ON COOLANT RESERVOIR SIGHT GLASS |                   |                  | .50 HRS |       |  |
| <u>CORRECTION:</u>                                |                   |                  |         |       |  |
| -pulled out sight glass                           |                   |                  |         |       |  |
| - removed old o-ring                              |                   |                  |         |       |  |
| - put in new o-ring                               |                   |                  |         |       |  |
| - put sight glass back in and tightened down      |                   |                  |         |       |  |
| - clean up tools                                  |                   |                  |         |       |  |
| 272142                                            | O-RING            | 1                | 3.41    | 3.41  |  |
|                                                   |                   |                  | PARTS   | 3.41  |  |
|                                                   |                   |                  | LABOR   | 77.50 |  |
| 13300056                                          |                   | SEGMENT TOTAL==> |         | 80.91 |  |

|                                                        |                   |  |          |  |  |
|--------------------------------------------------------|-------------------|--|----------|--|--|
| SEGMENT#21 C 05396 NA                                  | 07/25/22 07/25/22 |  |          |  |  |
| 3- WHEEL BEARINGS HAVE PLAY                            |                   |  | 4.00 HRS |  |  |
| <u>CORRECTION:</u>                                     |                   |  |          |  |  |
| - lifted up right side rear axel                       |                   |  |          |  |  |
| - removed bearing cover                                |                   |  |          |  |  |
| - remove cotter pin from castle nut                    |                   |  |          |  |  |
| - spun wheel and tighten castle nut to set pre load on |                   |  |          |  |  |
| bearings till there is slight resistance               |                   |  |          |  |  |
| - replaced cotter pin locking castle nut               |                   |  |          |  |  |
| - cleaned up sealing surface on wheel bearing cover    |                   |  |          |  |  |

CONTINUED ON PAGE 17

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                           |                             |                                        |
|---------------------------|-----------------------------|----------------------------------------|
| Branch<br><b>MOOSOMIN</b> |                             |                                        |
| Date<br><b>08/24/22</b>   | Time<br><b>08:44:29 (O)</b> | Page<br><b>17</b>                      |
| Account No.               | Phone No.                   | Reference No.<br><b>W37537</b>         |
| Ship Via                  |                             | Purchase Order                         |
| <b>SE31-15-31W1</b>       |                             | G.S.T. No.<br><b>79759 4660 RT0001</b> |
| Credit Card No.           |                             | Salesperson<br><b>H40</b>              |

### Description of Work and Parts

| STK#/FLEET#                                                                                                                                                                                                                     | HRS  | PIN/EIN          | WARRANTY DATE | HRS       | Fold -- |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|------------------|---------------|-----------|---------|
| 052881                                                                                                                                                                                                                          | 2588 | COMBINE          | 1580          | H4J304834 |         |
|                                                                                                                                                                                                                                 | 2588 | X                |               |           |         |
| <ul style="list-style-type: none"> <li>- tighten down wheel bearing cover</li> <li>- lifted up left side rear axel</li> <li>- remove wheel bearing cover</li> <li>- removed cotter pin from castle nut</li> </ul>               |      |                  |               |           |         |
| spun wheel and tighten castle nut to set pre load on bearings till there is slight resistance                                                                                                                                   |      |                  |               |           |         |
| <ul style="list-style-type: none"> <li>- replaced cotter pin locking castle nut</li> <li>- cleaned up sealing surface on wheel bearing cover</li> <li>- tighten down wheel bearing cover</li> <li>- cleaned up tools</li> </ul> |      |                  |               |           |         |
| ADDITIONAL DESCRIPTION:                                                                                                                                                                                                         |      |                  |               |           |         |
| SHOULD BE ABLE TO ADJUST                                                                                                                                                                                                        |      |                  |               |           |         |
| MRKDIS                                                                                                                                                                                                                          |      | MARKETING DISC   | 1-            | 1.00      | 1.00-   |
| OIL1                                                                                                                                                                                                                            |      | ENVIRO OIL LTR   | 1             | .15       | .15     |
| 73344349                                                                                                                                                                                                                        |      | MP GREASE 14OZ   | 1             | 6.49      | 6.49    |
| 87399                                                                                                                                                                                                                           |      | PIN COTTER 3/16  | 2 M           | 3.13      | 6.26    |
|                                                                                                                                                                                                                                 |      | PARTS            |               |           | 11.90   |
|                                                                                                                                                                                                                                 |      | LABOR            |               |           | 620.00  |
| 13300056                                                                                                                                                                                                                        |      | SEGMENT TOTAL==> |               |           | 631.90  |

SEGMENT#22 C 05396 NA 07/25/22 07/25/22  
3- REPLACE ALL GEARBOX OILS - OIL IS BURNT 4.00 HRS

#### CORRECTION:

- drained hydraulic tank oil changed filters refilled with new hytran
- drained pto gear box and refilled with new hytran
- drained transmission and refilled with new hytran
- drained final drives and refilled with new hytran
- drained chopper drive gear box and filled with new hytran
- drained unloaded gear box and refilled with 85W-140

CONTINUED ON PAGE 18

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                           |                             |                                        |
|---------------------------|-----------------------------|----------------------------------------|
| Branch<br><b>MOOSOMIN</b> |                             |                                        |
| Date<br><b>08/24/22</b>   | Time<br><b>08:44:29 (O)</b> | Page<br><b>18</b>                      |
| Account No.               | Phone No.                   | Reference No.<br><b>W37537</b>         |
| Ship via                  |                             | Purchase Order                         |
| <b>SE31-15-31W1</b>       |                             | G.S.T. No.<br><b>79759 4660 RT0001</b> |
| Credit Card No.           |                             | Salesperson<br><b>H40</b>              |

### Description of Work and Parts

| STK#/FLEET# | HRS              | PIN/EIN        | WARRANTY DATE | HRS | Fold -- |
|-------------|------------------|----------------|---------------|-----|---------|
| 052881      | 2588 COMBINE     | 1580 HAJ304834 |               |     |         |
|             | 2588             | X              |               |     |         |
| B85143      | 85W140 2.5G      | 1              | 76.30         |     | 76.30   |
| FIL2        | ENVIR FILT>8"    | 2              | 1.00          |     | 2.00    |
| FREIGHT     | FREIGHT          | 1              | 33.20         |     | 33.20   |
| OIL1        | ENVIRO OIL LTR   | 20             | .15           |     | 3.00    |
| OIL2        | ENVIRO OIL>30    | 158            | .05           |     | 7.90    |
| 1329214C1   | ELEMENT          | 1              | 185.00        |     | 185.00  |
| 73344238    | 15W40 OIL BULK   | 40             | 5.75          |     | 230.00  |
| 73344271    | HYTRAN BULK      | 78             | 6.25          |     | 487.50  |
|             | PARTS            |                |               |     | 1024.90 |
|             | LABOR            |                |               |     | 620.00  |
| 13300056    | SEGMENT TOTAL==> |                |               |     | 1644.90 |

SEGMENT#23 C 05396 NA 07/25/22 07/25/22  
3- FEEDER DRIVE RESERVOIR SHOULD BE DRAINED AND FLUSHED - 2.00 HRS

#### CORRECTION:

- drained old oil out of reservoir
- flushed with diesel fuel
- refilled with fresh oil
- put in new dipstick
- cleaned up tools
- cleaned up any spilled oil

#### ADDITIONAL DESCRIPTION:

CONTAMINATED WITH DEBRIS NEEDS NEW DIPSTICK

|          |                  |     |        |  |        |
|----------|------------------|-----|--------|--|--------|
| OIL1     | ENVIRO OIL LTR   | 8   | .15    |  | 1.20   |
| 336513A1 | DIPSTICK         | 1 N | 108.07 |  | 108.07 |
| 73344316 | 3.78L 85W140     | 1   | 39.53  |  | 39.53  |
|          | PARTS            |     |        |  | 148.80 |
|          | LABOR            |     |        |  | 310.00 |
| 13300056 | SEGMENT TOTAL==> |     |        |  | 458.80 |

CONTINUED ON PAGE 19

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3868  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                 |              |                   |
|-----------------|--------------|-------------------|
| Branch          |              |                   |
| MOOSOMIN        |              |                   |
| Date            | Time         | Page              |
| 08/24/22        | 08:44:29 (O) | 19                |
| Account No.     | Phone No.    | Reference No.     |
|                 |              | W37537            |
| Ship Via        |              | Purchase Order    |
| SE31-15-31W1    |              | G.S.T. No.        |
|                 |              | 79759 4660 RT0001 |
| Credit Card No. |              | Salesperson       |
|                 |              | H40               |

### Description of Work and Parts

| STK#/FLEET#                                     | HRS      | PIN/EIN  | WARRANTY DATE    | HRS       | Fold - |
|-------------------------------------------------|----------|----------|------------------|-----------|--------|
| 052881                                          | 2588     | COMBINE  | 1580             | H4J304834 |        |
|                                                 | 2588     | X        |                  |           |        |
| SEGMENT#24 C 05396 NA                           | 07/25/22 | 08/16/22 |                  |           |        |
| 3- SIEVE HARNESS CHAFFING - REPAIR AND RE-ROUTE | 2.00     | HRS      |                  |           |        |
| <u>CORRECTION:</u>                              |          |          |                  |           |        |
| - removed protective cover from wiring harness  |          |          |                  |           |        |
| - found to worn through wires                   |          |          |                  |           |        |
| - spliced the wires back together               |          |          |                  |           |        |
| - heat shrink and taped over splice             |          |          |                  |           |        |
| - put loom over that                            |          |          |                  |           |        |
| -clean up tools                                 |          |          |                  |           |        |
| 13300056                                        |          |          | LABOR            | 310.00    |        |
|                                                 |          |          | SEGMENT TOTAL==> | 310.00    |        |

|                                                                 |          |          |  |  |  |
|-----------------------------------------------------------------|----------|----------|--|--|--|
| SEGMENT#25 C 05396 NA                                           | 07/25/22 | 07/25/22 |  |  |  |
| 3- ROLLER BEARINGS SEIZED ON LHS                                | 2.50     | HRS      |  |  |  |
| <u>CORRECTION:</u>                                              |          |          |  |  |  |
| - hooked up header on to combine                                |          |          |  |  |  |
| - ran header up                                                 |          |          |  |  |  |
| - found bearing worn out on the drive side for center canvas    |          |          |  |  |  |
| - removed drive belt                                            |          |          |  |  |  |
| - removed pulley                                                |          |          |  |  |  |
| - cut lock collar off                                           |          |          |  |  |  |
| - unbolted bearing and removed bearing                          |          |          |  |  |  |
| - installed new bearing                                         |          |          |  |  |  |
| - installed new lock caller                                     |          |          |  |  |  |
| - put pulley back on to shaft and aligned it with other pulleys |          |          |  |  |  |
| - put belt back on                                              |          |          |  |  |  |
| - cleaned up tools                                              |          |          |  |  |  |
| - reinstall drive belt                                          |          |          |  |  |  |

CONTINUED ON PAGE 20

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                    |                      |                                 |
|--------------------|----------------------|---------------------------------|
| Branch<br>MOOSOMIN |                      |                                 |
| Date<br>08/24/22   | Time<br>08:44:29 (O) | Page<br>20                      |
| Account No.        | Phone No.            | Reference No.<br>W37537         |
| Purchase Order     |                      |                                 |
| SE31-15-31W1       |                      | G.S.T. No.<br>79759 4660 RT0001 |
| Credit Card No.    |                      | Salesperson<br>H40              |

### Description of Work and Parts

| STK#/FLEET#                    | HRS     | PIN/EIN   | WARRANTY DATE    | HRS    | Fold - - |
|--------------------------------|---------|-----------|------------------|--------|----------|
| 052881 2588 COMBINE<br>2588    | 1580    | HBJ304834 |                  |        |          |
| - cleaned up tools             | X       |           |                  |        |          |
| <u>ADDITIONAL DESCRIPTION:</u> |         |           |                  |        |          |
| HEADER 2015 - CCC0021254       |         |           |                  |        |          |
| 373987A1                       | HOUSING | 1         | 118.80           | 118.80 |          |
|                                |         |           | PARTS            | 118.80 |          |
|                                |         |           | LABOR            | 387.50 |          |
| 13300056                       |         |           | SEGMENT TOTAL==> | 506.30 |          |

|                                                                                        |                   |      |                  |        |  |
|----------------------------------------------------------------------------------------|-------------------|------|------------------|--------|--|
| SEGMENT#26 C 05396 NA                                                                  | 07/25/22 08/18/22 |      |                  |        |  |
| 2- 4 DRAPER BELTS LOOSE WHILST OTHERS TIGHT                                            |                   | 3.00 | HRS              |        |  |
| <u>CORRECTION:</u>                                                                     |                   |      |                  |        |  |
| - when running up header notice out side belts where not turning                       |                   |      |                  |        |  |
| - pulled the side panels up off the belts so they can turn                             |                   |      |                  |        |  |
| - tighten up the belts up                                                              |                   |      |                  |        |  |
| - ran header up to make sure all belts turn                                            |                   |      |                  |        |  |
| - everything was turning now                                                           |                   |      |                  |        |  |
| - cleaned up tools                                                                     |                   |      |                  |        |  |
| <u>ADDITIONAL DESCRIPTION:</u>                                                         |                   |      |                  |        |  |
| RECOMMEND CHANGING - PUT HEADER ON AND CALL DOUG BEFORE CHANGING WHEN REST IS COMPLETE |                   |      |                  |        |  |
|                                                                                        |                   |      | LABOR            | 465.00 |  |
| 13300056                                                                               |                   |      | SEGMENT TOTAL==> | 465.00 |  |

|                               |                   |     |     |  |  |
|-------------------------------|-------------------|-----|-----|--|--|
| SEGMENT#27 C 05396 NA         | 07/25/22 08/17/22 |     |     |  |  |
| CHECK PROCESSOR BELT          |                   | .50 | HRS |  |  |
| <u>CORRECTION:</u>            |                   |     |     |  |  |
| - check belt found a crack    |                   |     |     |  |  |
| - removed fan belt            |                   |     |     |  |  |
| - remove clean elevator chain |                   |     |     |  |  |

CONTINUED ON PAGE 21

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:  
Box 1200  
Moosomin, SK S0G 3N0  
Tel: (306) 435-3866  
Fax: (306) 435-2415

## INVOICE

Ship to:

Invoice to:

|                 |              |                   |
|-----------------|--------------|-------------------|
| Branch          |              |                   |
| MOOSOMIN        |              |                   |
| Date            | Time         | Page              |
| 08/24/22        | 08:44:29 (O) | 21                |
| Account No.     | Phone No.    | Reference No.     |
|                 |              | W37537            |
| Ship via        |              | Purchase Order    |
| SE31-15-31W1    |              | G.S.T. No.        |
|                 |              | 79759 4660 RT0001 |
| Credit Card No. |              | Salesperson       |
|                 |              | H40               |

### Description of Work and Parts

| STK#/FLEET# |                                                                                                                                                                                                                                                                                                                                                                                                                                 | HRS         | PIN/EIN   | WARRANTY DATE    | HRS    |        |
|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|-----------|------------------|--------|--------|
| 052881      | 2588 COMBINE                                                                                                                                                                                                                                                                                                                                                                                                                    | 1580        | HAJ304834 |                  |        |        |
|             | 2588                                                                                                                                                                                                                                                                                                                                                                                                                            |             | X         |                  |        |        |
|             | <ul style="list-style-type: none"><li>- remove screening auger chain</li><li>- removed support bracket to get belt out</li><li>- removed processing belt</li><li>- put new belt on</li><li>- put support bracket back on</li><li>- put fan belt back on</li><li>- put clean elevator chain back on</li><li>- put screening auger chain back on</li><li>- tighten up all the belts and chains</li><li>- clean up tools</li></ul> |             |           |                  |        |        |
| 87034815    |                                                                                                                                                                                                                                                                                                                                                                                                                                 | CHN CONN 50 |           | 1                | 2.68   | 2.68   |
| 87476486    |                                                                                                                                                                                                                                                                                                                                                                                                                                 | BELT        |           | 1 N              | 286.20 | 286.20 |
|             |                                                                                                                                                                                                                                                                                                                                                                                                                                 |             |           |                  | PARTS  | 288.88 |
|             |                                                                                                                                                                                                                                                                                                                                                                                                                                 |             |           |                  | LABOR  | 77.50  |
| 13300056    |                                                                                                                                                                                                                                                                                                                                                                                                                                 |             |           | SEGMENT TOTAL==> |        | 366.38 |

#### \*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

|                      |          |
|----------------------|----------|
| PARTS                | 8903.50  |
| LABOR                | 10253.25 |
| DISPOSAL FEE         | 213.74   |
| SHOP SUPPLIES        | 908.41   |
| DISCOUNT             | 2307.02- |
| SUB TOTAL==>         | 17971.88 |
| GST 797594660        | 898.63   |
| TOTAL CASH/DEBIT/CHK | 18870.51 |

CHQ# 142

Land Description: Sec \_\_\_\_\_ Twsp \_\_\_\_\_ R \_\_\_\_\_ M \_\_\_\_\_

CONTINUED ON PAGE 22

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)