



www.youngs.ca

.0



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To: .

Invoice To:

Branch		
REPRINT		
Date 08/16/24	Time 22:00:58 (B)	Page 01
Account #	Phone #	Inv #
Ship Via	Purchase Order # 23-24 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UH4351	Combine	1640	YJG235579	08/14/19	CB
	9240	1278		08/15/23	PP

SEGMENT# 1 C 34023 L. COMBINE 07/30/24 07/30/24
FLAGSHIP COMBINE INSPECTION
*SPENT 2 HOURS BLOWING OUT COMBINE
11030099

SEGMENT# 2 C 34023 NA 07/30/24
FLAGSHIP COMBINE INSPECTION WASH
W12699

SEGMENT# 3 C 34023 NA 07/30/24
INSPECTION TRUCKING
CUSTOMER BROUGHT UNIT IN

SEGMENT# 4 C 34023 NA	08/02/24	08/02/24		
ELECTRICAL SYSTEM				
+BATTERY WAS VACUUMED AND CLEANED				
REPLACED RH FRONT SIGNAL LAMP - TESTED OK.				
48006407	LAMP	1 O	142.10	142.10
			PARTS	142.10
			LABOR	669.46
11030099		SEGMENT TOTAL==>		811.56

SEGMENT# 5 C 34023 NA 08/02/24 08/02/24
FEEDER CHAIN
REMOVED FEEDERHOUSE
REMOVED BEATER
REMOVED FEEDERCHAIN
REMOVED TOP SPROCKET
INSTALLED GEARBOX AND LASER ALIGNED.

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date	Time	Page
08/16/24	22:00:58 (B)	02
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
	23-24 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UH4351	Combine	1640	YJG235579	08/14/19	CB
	9240	1278		08/15/23	PP
REMOVED GEARBOX					
WELDED SHIMS TO FEEDERHOUSE					
REMOVED STRIPPERS.					
INSTALLED NEW SPROCKET					
INSTALLED NEW STRIPPERS AND TORQUED TO SPEC.					
INSTALLED FEEDER CHAIN					
REPLACED 11 BROKEN/BENT SLATS ON FEEDERCHAIN.					
INSTALLED BEATER					
INSTALLED FEEDERHOUSE BACK ONTO COMBINE.					
FRTCP	FREIGHT-CASE	1	30.00		30.00
SL1155L	LEFT SLAT	RETAIL	57.50		
		5 N	57.00		285.00
SL1155R	RIGHT SLAT	2 N	57.00		114.00
SL1156	CENTER SLAT	4 S	57.00		228.00
48106916	KIT	1	4008.92		4008.92
TOP SPROCKET KIT					
86050279	10M NUT FLANGE	1	1.55		1.55
86610200	INSERT, TH	1	14.05		14.05
86610201	INSERT	2	17.00		34.00
86980516	NUT	2	7.47		14.94
87698833	BOLT	2	2.07		4.14
				PARTS	4734.60
				LABOR	2625.93
11030099	SEGMENT TOTAL==>				7360.53

SEGMENT# 6 C 34023 NA 08/02/24 08/02/24
FEEDER GEARBOX
REMOVED OLD SEALS AND SNAP RING
REMOVED SPROCKET SHAFT, BEARING AND SHIMS.
INSTALLED NEW SHAFT AND BEARING USING ORIGINAL SHIMS.

CONTINUED ON PAGE 03

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repair, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
Estimates are for the items specifically identified in the estimate only, and are non-binding.
Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 08/16/24	Time 22:00:58 (B)	Page 03
Account #	Phone #	Inv #
Ship Via	Purchase Order # 23-24 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
UH4351	Combine	1640	YJG235579	08/14/19		CB
	9240	1278		08/15/23		PP
INSTALLED SNAP RING AND NEW SEAL.						
INSTALLED FELT AND BRUSH SEALS.						
47510326	SEAL	2		51.42		102.84
48067478	SHAFT	1		973.05		973.05
84312857	BEARING, BALL	1		77.30		77.30
84415750	SEAL, FELT	2		20.71		41.42
87612665	SEAL	1		60.21		60.21
	PARTS					1254.82
	LABOR					352.63
11030099	SEGMENT TOTAL==>					1607.45

SEGMENT# 7 C 34023 NA	08/02/24 08/08/24	
FRONT DRUM		
ADJUSTED DRUM HEIGHT TO HIGHEST POSITION AND TENSIONED CONVEYOR CHAIN.		
	LABOR	35.80
11030099	SEGMENT TOTAL==>	35.80

SEGMENT# 8 C 34023 NA	08/02/24 08/02/24	
CONCAVES		
REPLACED BROKEN STOP BOLTS.		
UNHOOKED CONCAVE HANGER AND REMOVED ROCKSHAFT		
REMOVED CONCAVE MOTOR MOUNT.		
MOVED MOTOR AND WORM GEAR TO NEW MOUNT AND INSTALLED.		
INSTALLED ROCKSHAFT AND CONNECTED HANGER.		
REPLACED RH FRONT PIVOT BUSHING AND BOLT.		
BUSHING IS A LITTLE SLOPPY IN HANGER.		
FABRICATED A PLATE TO HOLD BUSHING TRUE AND INSTALLED.		
RAN HANGER UP AND DOWN TO ENSURE NO BINDING.		
CHECKED LEVEL AND PINCH OK.		

CONTINUED ON PAGE 04

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 7% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 08/16/24	Time 22:00:58 (B)	Page 04
Account #	Phone #	Inv #
Ship Via	Purchase Order # 23-24 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
UH4351	Combine	1640	YJG235579	08/14/19		CB
	9240	1278		08/15/23		PP
ADJUSTED STOP BOLTS AND CALIBRATED OK.						
47581464	PIVOT	1		517.60		517.60
86998150	SPACER	1		28.85		28.85
87547587	NUT, LOCK	1		5.47		5.47
87698838	BOLT	1		5.18		5.18
9837937	SCREW	2		17.39		34.78
	PARTS					591.88
	LABOR					893.21
11030099				SEGMENT TOTAL==>		1485.09

SEGMENT# 9 C 34023 NA	08/02/24	08/02/24				
CONE						
++ REPLACED MISSING TRANSITION BOLTS						
++ REPLACED 2 TRANSITION VANES						
100016	NUT	8		.95		7.60
140219	WASHER	3		8.43		25.29
84567289	VANE	1		75.08		75.08
87106338	BOLT	9		7.32		65.88
87107892	ANGLE	1		63.39		63.39
	PARTS					237.24
	LABOR					574.59
11030099				SEGMENT TOTAL==>		811.83

SEGMENT#10 C 34023 NA	08/02/24	08/02/24				
SHOE SYSTEM						
REPLACED SHOE BELT						
87317063	BELT	1		100.61		100.61
	PARTS					100.61
	LABOR					370.53
11030099				SEGMENT TOTAL==>		471.14

CONTINUED ON PAGE 05

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 08/16/24	Time 22:00:58 (B)	Page 05
Account #	Phone #	Inv #
Ship Via		Purchase Order # 23-24 INSPECTION
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UH4351	Combine	1640	YJG235579	08/14/19	CB
	9240	1278		08/15/23	PP
SEGMENT#11 C 34023 NA 08/02/24 08/05/24					
CLEAN GRAIN ELEVATOR					
WELDED DIVIDER WEAR PLATE BACK TO FLAT.					
TENSIONED PADDLECHAIN					
LABOR					125.30
11030099 SEGMENT TOTAL==>					125.30
SEGMENT#12 C 34023 NA 08/02/24 08/02/24					
TAILINGS PROCESSOR					
WELDED HOLE IN BOTTOM PADDLE.					
REPLACED TAILINGS SENSOR					
84212481	SENSOR	1		419.25	419.25
PARTS					419.25
LABOR					270.29
11030099 SEGMENT TOTAL==>					689.54
SEGMENT#13 C 34023 NA 08/02/24 08/02/24					
AUGER TROUGH					
+BEARING COVER BOLTS WAS REMOVED					
+BEARING WAS PULLED OUT WITH A PULLER					
+CHAIN WAS SLACKED					
+CHAIN WAS LOOSEN					
+SPROCKET WAS TAKEN OUT					
+FOR AUGER TO COME OUT, LEFT END BEARING WAS TAKEN OUT					
+AUGER WAS PULLED OUT					
+NEW AUGER WAS INSTALLED					
+NEW LEFT END BEARING AND COLLAR WAS INSTALLED					
+NEW CLEAN GRAIN SPROCKET AND KEY WAS INSTALLED					
+CHAIN WAS TIGHTEN					

CONTINUED ON PAGE 06

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. hereby releases from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for accidents left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees are at own risk.

* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

* I estimate as for the items specifically identified in the estimate only, and are non-binding.

* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Branch		
Date 08/16/24	Time 22:00:58 (B)	Page 06
Account #	Phone #	Inv #
Ship Via		Purchase Order # 23-24INSPECTION
Tax ID #		
		Salesperson

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
UH4351	Combine	1640	YJG235579	08/14/19		CB
	9240	1278		08/15/23		PP
+NEW BEARING AND COLLAR WAS INSTALLED						
+COVER WAS PUT BACK IN PLACE						
+THE CHAIN WAS TIGHTEN						
+						
84577868	AUGER	1	1437.71			1437.71
87044350	BEARING ASSY	1	81.15			81.15
87283201	KEY	1	26.92			26.92
87283436	SPROCKET	1	166.44			166.44
87605593	BEARING	1	135.15			135.15
	PARTS					1847.37
	LABOR					733.90
11030099	SEGMENT TOTAL==>					2581.27

SEGMENT#14 C 34023 NA 08/02/24 08/06/24
 KNIVES AND DISCHARGE PAN
 HOOKED UP EST
 IN MACHINE CONFIG - CHANGED INTERNAL CHOPPER TO BEATER.
 ERROR CODES NO LONGER PRESENT FOR COUNTERKNIFE AND BUTTON
 FOR RAISE/LOWER IS DISABLED.

++ STATIONARY KNIVES WERE TAKEN OUT ON THE BENCH
 ++ RESET WAS MADE
 ++ ONE MISSING BOLT WAS REPLACED
 +STATIONARY KNIVES WERE REINSTALLED
 ++OLD REDEKOP CHOPPER KNIVES WERE REMOVED
 ++ GROOVES WERE CLEANED
 ++ NEW REDEKOP CHOPPER KNIVES WERE INSTALLED WITH NEW NUTS
 ++ BOLTS WERE TORQUED

BK553X	BUSHING	2 M	18.50	37.00
48035327	KIT	12 N	357.47	4289.64
9706693	BOLT	1	4.22	4.22

CONTINUED ON PAGE 07

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 * It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
 * Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repair, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 * An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 * Estimates are for the items specifically identified in the estimate only, and are non-binding.
 * Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Received By

Thank You!
 We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Branch		
Date 08/16/24	Time 22:00:58 (B)	Page 07
Account #	Phone #	Inv #
Ship Via	Purchase Order # 23-24 INSPECTION	
Tax ID #		
		Salesperson

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
UH4351	Combine	1640	YJG235579	08/14/19		CB
	9240	1278		08/15/23		PP
				PARTS		4330.86
				LABOR		1457.06
11030099				SEGMENT TOTAL==>		5787.92

SEGMENT#15 C 34023 NA	08/02/24 08/02/24				
GRAINTANK					
++ REMOVED AUGER BRACKET BOLTS					
++ PULLED OUT AUGER					
++REMOVED BEARING TO GET OUT BRACKET					
++ REINSTALLED BRACKET INTO NEW AUGER					
++ INSTALLED NEW BEARINGS AND COLLAR					
++ INSTALLED AUGER INTO ITS HOUSING					
++ TIGHTEN THE BRACKET BOLTS					
++ REPLACED GRAIN TANK TOP FRAME					
87605590	BEARING	1	72.50		72.50
87733275	AUGER	1	1418.65		1418.65
			PARTS		1491.15
			LABOR		379.48
11030099			SEGMENT TOTAL==>		1870.63

SEGMENT#16 C 34023 NA	08/02/24 08/10/24				
UNLOADING AUGER					
ADJUSTED CRADLE TO LOWEST POSITION.					
LUBED CRADLE WITH DRY MOLY.					
AUGER NOW SADDLES ON FIRST ATTEMPT.					
*THIS MAY GET WORSE AS SHIM ON UNLOADER ELBOW DETERIORATES					
FURTHER.					
			LABOR		191.53
11030099			SEGMENT TOTAL==>		191.53

CONTINUED ON PAGE 08

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the item specifically identified in the estimate only, and are non binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To: .

Branch		
Date 08/16/24	Time 22:00:58 (B)	Page 08
Account # -----	Phone #	Inv #
Ship Via		Purchase Order # 23-24 INSPECTION
Tax ID #		
		Salesperson

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
UH4351	Combine	1640	YJG235579	08/14/19		CB
	9240	1278		08/15/23		PP
SEGMENT#17 C 34023 NA		08/02/24	08/02/24			
ENGINE						
++ WAND POLYS OLD RIVET WAS DRILLED OUT						
++ NEW WAND POLYS WAS INSTALLED						
++ NEW RIVET AND WASHER WAS USED TO MOUNT						
++ NEW PIN WAS INSTALLED						
445395		RIVET	14	.94		13.16
47514305		RING	1	54.74		54.74
47662307		CLIP	1	70.86		70.86
87472745		RING	1	114.29		114.29
		PARTS				253.05
		LABOR				554.90
11030099		SEGMENT TOTAL==>				807.95
SEGMENT#18 C 34023 NA						
PTO SYSTEM		08/02/24	08/02/24			
++ SOLENOID NUT REPLACED						
349292A1		NUT	1	14.42		14.42
		PARTS				14.42
		LABOR				26.85
11030099		SEGMENT TOTAL==>				41.27
SEGMENT#19 C 34023 NA						
HYDRAULIC SYSTEM		08/02/24	08/07/24			
++ HOSE WERE CLAMPS TIGHTENED						
		LABOR				50.12
11030099		SEGMENT TOTAL==>				50.12
SEGMENT#20 C 34023 NA						
GROUND DRIVE SYSTEM		08/02/24	08/02/24			

CONTINUED ON PAGE 09

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereon. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

* Estimates are for the items specifically identified in the estimate only, and are non binding.

* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 08/16/24	Time 22:00:58 (B)	Page 09
Account #	Phone #	Inv #
Ship Via		Purchase Order # 23-24 INSPECTION
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UH4351	Combine	1640	YJG235579	08/14/19	CB
	9240	1278		08/15/23	PP
++ COPPER WASHER WAS REPLACED ++ TRANSMISSION WAS CLEANED AND BREATHER WAS BLOWN OUT ++ DRIVE SHAFT COUPLER RING WAS SLIDE OFF ++ DRIVE SHAFT WAS PULLED OUT ON BOTH ENDS ++ DRIVE SHAFT WAS CLEANED ++ RIGHT SHAFT HAD PLAY ON ONE SIDE OF THE COUPLER ++ COUPLER WAS REPLACED ++ SHAFTS WERE MOUNTED AND RINGS REINSTALLED ++ SHAFTS WERE GREASED					
220025	SEAL, RING	1		8.72	8.72
				PARTS	8.72
				LABOR	323.99
11030099	SEGMENT TOTAL==>				332.71

SEGMENT#21 C 34023 NA 08/02/24 08/02/24

STEERING AND REAR AXLE
 REMOVED RH TIRE
 REMOVED STEERING CYLINDER BALL JOINT FROM STEERING ARM.
 DISCONNECTED HYDRAULICS.
 REMOVED CYLINDER FROM AXLE.
 DISASSEMBLED CYLINDER AND REPLACED WORN SEALS
 INSTALLED CYLINDER AND CONNECTED HYDRAULICS.
 INSTALLED RH TIRE
 REMOVED LEFT SIDE TIRE
 REMOVED BALL JOINT FROM STEERING ARM
 DISCONNECTED HYDRAULICS
 REMOVED CYLINDER.
 DISASSEMBLED CYLINDER
 ROD END BALL JOINT SEIZED ONTO ROD - EXTRA TIME TO CUT OFF
 JAM NUT

CONTINUED ON PAGE 10

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for accidents left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

* Estimates are for the items specifically identified in the estimate only, and are non-binding.

* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 08/16/24	Time 22:00:58 (B)	Page 10
Account #	Phone #	Inv #
Ship Via	Purchase Order # 23-24 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UH4351	Combine	1640	YJG235579	08/14/19	CB
	9240	1278		08/15/23	PP

TO REMOVE. ORDERED NEW JAM NUT.
RESEALED CYLINDER USING SEAL KIT.
INSTALLED NEW JAM NUT AND INSTALLED BALL JOINT.
INSTALLED CYLINDER AND TIGHTENED.
INSTALLED TIRE.
TESTED STEERING OK.
NO LEAKS FOUND.
CALIBRATED STEERING CYLINDER FOR AUTOSTEER.
TESTED AUTOSTEER OK.

FRTCP	FREIGHT-CASE	2	17.50	35.00
80412321	NUT	1 N	15.89	15.89
84439102	WASHER, SEALING	3	1.58	4.74
84455606	KIT, SEALS	2 N	370.21	740.42
87586665	BUSHING, SPLINE	1	225.74	225.74
	PARTS			1021.79
	LABOR			753.59
11030099	SEGMENT TOTAL==>			1775.38

SEGMENT#22 C 34023 NA 08/02/24 08/02/24
MAINTENANCE
+REPLACED ENGINE CRANKCASE BREATHER - TORQUED TO SPEC
+REPLACED ENGINE OIL FILTER
+REPLACED FUEL FILTER
+REPLACED SEALING WASHER ON TRANSMISSION DRAIN PLUG
+REPLACED ENGINE AIR FILTERS
+REPLACED CAB AIR FILTERS
++ REPLACE ROTOR GREARBOX OIL
++ REPLACE TRANSMISSION OIL
+TOPPED UP HYDRAULIC OIL (18.5L)
++ REPLACED HYDRAULIC FILTER

CONTINUED ON PAGE 11

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non-binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 08/16/24	Time 22:00:58 (B)	Page 11
Account #	Phone #	Inv #
Ship Via	Purchase Order # 23-24 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UH4351	Combine	1640	YJG235579	08/14/19	CB
	9240	1278		08/15/23	PP
+TOPPED UP PTO OIL (30L)					
++ REPLACED PTO FILTER AND BREATHER					
+REPLACED FUEL BREATHER					
++ REPLACED ENGINE OIL (30L)					
++ REPLACED FINAL DRIVE OILS					
++ REPLACED HEADER GEAR BOX					
++ REPLACED BOTH INCLINE AUGER GEARBOX OIL					
++ REPLACED LOWER UNLOADER GEARBOX OIL					
REPLACED FEEDER GEARBOX OIL (4L HYTRAN)					
TOPPED UP ENGINE OIL AFTER FIRST RUN. (5L 15W40)					
TOPPED UP PTO AFTER FIRST RUN (3L HYTRAN)					
TOPPED UP HYDRAULIC OIL (6L HYTRAN)					
EHCFLT1	ENV FEE	3		.50	1.50
EHCFLT2	EHC CHARGE	3		1.00	3.00
EHC0IL	EHC CHARGE	135		.05	6.75
EHC5GL	EHC CHARGE	2		4.40	8.80
1971726C1	BREATHER	1		27.74	27.74
254353A1	ELEMENT/A	1		173.73	173.73
360260A2	FILTER, CAB	1		145.77	145.77
47437399	FILTER, FUEL	1		74.65	74.65
47888462	FILTER AIR	1		476.41	476.41
48007134	AIR FILTER	1		646.28	646.28
504387088	GASKET	1		56.96	56.96
51508555	FILTER HYDRAUL	1		168.66	168.66
5801472560	BOLT	3		4.22	12.66
5801516883	FUEL FILTER	1		242.22	242.22
5801856860	FILTER	1		212.28	212.28
74645001US	15W40 BULK	35		5.20	182.00
76927QY1US	80W90 18.9L	2		158.54	317.08
77400001US	ULTRACTION BULK	100		5.92	592.00

CONTINUED ON PAGE 12

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. hereby releases from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



www.youngs.ca



Regina 306-565-2405
Chamberlain 306-638-4516
Davidson 306-567-3074
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To:

Invoice To:

Branch		
Date 08/16/24	Time 22:00:58 (B)	Page 12
Account #	Phone #	Inv #
Ship Via	Purchase Order # 23-24 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
UH4351	Combine	1640	YJG235579	08/14/19		CB
	9240	1278		08/15/23		PP
84217229		FILTER, AIR	1	93.65		93.65
84423586		PRE FUEL FITLER	1	295.89		295.89
84572228		ENG OIL FILTER	1	158.80		158.80
		PARTS				3896.83
		LABOR				1559.25
11030099		SEGMENT TOTAL==>				5456.08

***** WORK ORDER TOTALS *****

PARTS	20344.69
LABOR	11948.41
shop supplies	300.00
EST SOFTWARE FEE	75.00
10-40 Ser Comb	2199.00
SUB TOTAL==>	34867.10
GST 5%	1743.43
TOTAL ON ACCOUNT	36610.53

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business