



www.youngs.ca



Regina 306-565-2405
Chamberlain 306-638-4516
Davidson 306-567-3074
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To:

A07-I

Invoice To:

Branch		
REPRINT		
Date 04/21/23	Time 22:01:42 (B)	Page 01
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
UT2209 Tractor 4WD ST535Q	6068	ZAF118526		

SEGMENT# 1 C 34031 QUAD INSP. 03/23/23 03/23/23
QUADTRAC INSPECTION
11030099

SEGMENT# 2 C 34031 NA 03/23/23
QUADTRAC INSPECTION WASH
W10454

SEGMENT# 3 C 34031 NA 03/23/23
INSPECTION TRUCKING
CUSTOMER BROUGHT UNIT IN

SEGMENT# 4 C 34031 NA 03/29/23 03/29/23
STEERING SYSTEM

++REMOVED LINES GOING TO RH STEERING CYLINDER				
++REMOVED GREASE LINE FROM CYLINDER				
++REMOVED MOUNTING PINS AND REMOVED CYLINDER FROM TRACTOR				
++TRANSFERRED FITTINGS TO NEW CYLINDER				
++INSTALLED NEW CYLINDER ONTO THE TRACTOR				
++REPLACED LEAKING STEERING LINE				
++CONNECTED STEERING LINES TO THE CYLINDER				
CRIMP	END	1	2.00	2.00
P-HR2C08-250	1/2" HYD HOSE	4	6.63	26.52
ZJM43	FITTING	1	26.05	26.05
ZJM56	FITTING	2 O	47.63	95.26
84577088	CYLINDER S	1 N	2618.21	2618.21
9992298	O-RING	1	1.25	1.25
	PARTS			2769.29
	LABOR			559.68

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 04/21/23	Time 22:01:42 (B)	Page 02
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
UT2209	6068	ZAF118526		
Tractor 4WD				
ST535Q				
11030099			SEGMENT TOTAL==>	3328.97

SEGMENT# 5 C 34031 NA 03/29/23 03/29/23
 HYDRAULIC SYSTEM
 ++REMOVED AND REPLACED RETURN TUBE BOOT
 ++DRAINED HYDRAULIC TANK INTO CLEAN PAILS
 ++LOOSENEED OFF CLAMPS FOR THE RUBBER BOOTS ON THE
 +MAIN PUMP SUPPLY TUBES
 ++REMOVED BOOTS FROM TUBES AND INSTALLED NEW BOOTS
 ++REINSTALLED CLAMPS AND TIGHTENED ALL BOOTS
 ++REMOVED AND REPLACED RUBBER BOOT FOR RETURN TO TANK TUBE
 ++REMOVED AND REPLACED LINE FOR THE REAR TRACK
 +TENSION SYSTEM
 ++CHECKED RETURN HOSE FOR FRONT DIFF, FOUND CLAMPS
 +WERE SLIGHTLY LOOSE, JUST TIGHTENED CLAMPS AT THE TIME
 ++INSPECTED PRIORITY VALVE BLOCK FOR LEAK, FOUND THAT
 +STEERING LINE WAS LEAKING DOWN ONTO THE BLOCK
 ++HAD TO REMOVE FLOOR MAT AND ACCESS PANEL TO
 +AT STEERING COLUMN TO GAIN ACCESS TO THE
 +UPPER HALF OF THE LINE
 ++REMOVED LINE FROM TRACTOR AND REPLACED THE TWO
 +HOSES THAT ATTACH TO THE STEEL LINE
 ++REINSTALLED STEERING LINE INTO TRACTOR AND
 +CONNECTED TO VALVE BLOCK
 ++CHECKED FOR A HYDRAULIC OIL LEAK AROUND THE
 +ARTICULATING POINT BUT COULDN'T FIND ANYTHING WITH
 +FRESH OIL ON IT
 ++CUSTOMER HAD A REPAIR DONE IN THIS AREA THE
 +PREVIOUS SPRING THAT LEAKS A LOT OF OIL IN THE AREA
 ++TALKED TO CUSTOMER TO SEE IF HE HAD WASHED TRACTOR

CONTINUED ON PAGE 03

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 • An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.
 • Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Thank You!
 We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



www.youngs.ca



Regina 306-565-2405
Chamberlain 306-638-4516
Davidson 306-567-3074
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To:

Invoice To:

Branch		
Date 04/21/23	Time 22:01:42 (B)	Page 03
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UT2209	Tractor 4WD ST535Q	6068	ZAF118526		
+SINCE REPAIR, HE HAD NOT ++ONCE TRACTOR IS WASHED WILL VERIFY THAT NO +LEAK IS PRESENT ++INSPECTED HYDRAULIC COOLER HOSE FOR A LEAK +FOUND THAT FITTING WAS A LITTLE LOOSE, TIGHTENED IT UP					
CRIMP	END	4		2.00	8.00
EHCOIL	EHC CHARGE	20		.05	1.00
P-HR2C06-250	3/8 HYD HOSE	1		6.63	6.63
P-HR2C08-250	1/2" HYD HOSE	4		6.63	26.52
S118383X	HOSE, LARGE	3		43.43	130.29
ZJM41	FITTING	1		24.19	24.19
ZJM43	FITTING	1		26.05	26.05
ZJM76	FITTING	1		58.05	58.05
1-4482	HOSE, LARGE	1		58.59	58.59
1-4568	HOSE 1 FT.	1		76.63	76.63
77400001US	ULTRACTION BULK	RETAIL		5.27	
		20		5.17	103.40
86625031	HOSE CLAMP	1		9.00	9.00
87347199	HOSE	1		200.95	200.95
				PARTS	729.30
				LABOR	3035.31
11030099				SEGMENT TOTAL==>	3764.61

SEGMENT# 6 C 34031 NA 03/29/23 03/29/23

MAINTENANCE

++ONCE ENGINE WORK WAS DONE ADDED NEW
 +ENGINE OIL AND FILTER (53L)
 ++CUSTOMER ALSO DECIDED TO HAVE AIR FILTER CHANGED
 +AFTER SEEING HOW PLUGGED IT WAS
 EHCOIL EHC CHARGE

53 .05 2.65

CONTINUED ON PAGE 04

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 * It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
 * Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 * An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 * Estimates are for the items specifically identified in the estimate only, and are non-binding.
 * Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



www.youngs.ca



Regina 306-565-2405
Chamberlain 306-638-4516
Davidson 306-567-3074
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To:

Invoice To:

Branch		
Date 04/21/23	Time 22:01:42 (B)	Page 04
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UT2209	Tractor 4WD ST535Q	6068	ZAF118526		
74645001US		15W40 BULK	RETAIL	4.84	
			88	4.73	416.07
84372057		FILTER ASSY	1	112.15	112.15
			PARTS		530.87
			LABOR		97.02
11030099			SEGMENT TOTAL==>		627.89

SEGMENT# 7 C 34031 NA 03/29/23 03/29/23
VALVE SET / BOTTOM END ROLL IN
++UNBOLTED AND REMOVED RADAR
++UNBOLTED DRIVE SHAFT TO FRONT DIFFERENTIAL
++UNBOLTED BOTH SIDES OF FRONT DIFFERENTIAL FROM FRAME
++JACKED FRAME UP TRACTOR UP AND SET ON STANDS
+LEAVING THE FRONT DIFF/TRACKS ON THE GROUND
++REMOVED ENGINE OIL PAN
++ONE BY ONE REMOVED THE CRANKSHAFT MAIN BEARING
+CAPS, REMOVED OLD BEARINGS AND ROLLED NEW ONES IN
++APPLIED 518 SEALANT TO EACH BEARING CAP BEFORE
+INSTALLED AND TORQUING THEM ACCORDING TO SERVICE MANUAL
++ROTATED ENGINE OVER BY HAND UNTIL TWO CONNECTING
+RODS WERE AT THE BOTTOM OF THEIR STROKE
++REMOVED THE CONNECTING ROD CAPS AND REPLACED
+CONNECTING ROD BEARINGS
++REPEATED PROCEDURE FOR THE REMAIN 4 CONNECTING RODS
++REINSTALLED ENGINE OIL PAN WITH NEW GASKET
++COOLANT DRAINED ON DIFFERENT SEGMENT
++REMOVED COOLANT TANK FROM THE ENGINE
++LOOSENEED CLAMPS ON AIR COOLER TUBE AND
+REMOVED TUBE/BELLOWS
++ONE END OF THE BELLOWS WAS FUSED TO THE TURBO

CONTINUED ON PAGE 05

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
Estimates are for the items specifically identified in the estimate only, and are non-binding.
Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 04/21/23	Time 22:01:42 (B)	Page 05
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UT2209	Tractor 4WD ST535Q	6068	ZAF118526		
+AND WAS DAMAGED WHEN REMOVED, HAD TO REPLACE +BELLOW WITH NEW ONE ++UNBOLTED AND REMOVED ENGINE VALVE COVER ++FOLLOWED SERVICE MANUAL AND SET ALL VALVES +AND INJECTORS TO SPEC ++INSTALLED NEW GASKET TO VALVE COVER AND REINSTALLED +REASSEMBLED ALL PARTS BACK ONTO THE ENGINE ++ONCE ENGINE OIL AND FILTER WERE INSTALLED, STARTED ENGINE ++TOOK TRACTOR FOR A DRIVE AND CHECK PERFORMANCE +OF THE ENGINE, ENGINE RUNNING SMOOTH					
CU3104392	GSKT VALVE COVE	1 N	143.71		143.71
CU4026684	GASKET	1 N	580.49		580.49
CU4089405	ROD BEARING	6 N	193.60		1161.60
CU5406110	MAIN BRG KIT	1 N	860.48		860.48
FRTCP	FREIGHT-CASE	1	20.00		20.00
HC24	CLAMP, HOSE #24	1	1.67		1.67
251400A1	BELLOWS	1	268.42		268.42
87727665	FILTER, AIR	1	340.03		340.03
	PARTS				3376.40
	LABOR				5720.82
11030099	SEGMENT TOTAL==>				9097.22

SEGMENT# 8 C 34031 NA 03/29/23 03/29/23
 ADDITIONAL ENGINE WORK
 ++FOUND THAT FLEX TUBE FOR MUFFLER HAD BROKEN IN HALF
 ++REMOVED CLAMPS AND BRACKETS IN ORDER TO REMOVE
 +AND REPLACE FLEX TUBE AND CLAMPS
 ++DRAINED COOLANT INTO CLEAN PAILS
 ++REMOVED BOTTOM RAD HOSE AND INSTALLED NEW ONE
 ++PUT COOLANT BACK IN AND TOPPED UP SYSTEM (20L)

CONTINUED ON PAGE 06

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 • An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.
 • Young's Equipment Inc. and its manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
 We Appreciate Your Business



www.youngs.ca



Regina 306-565-2405
Chamberlain 306-638-4516
Davidson 306-567-3074
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To:

Invoice To:

Branch		
Date 04/21/23	Time 22:01:42 (B)	Page 06
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UT2209	Tractor 4WD ST535Q	6068	ZAF118526		
++UNBOLTED OVERFLOW TANK AND BRACKET FROM THE ENGINE ++CLEANED AREA AROUND FAN PUMP AND TIMING COVER ++WITH VARSOL AND AIR TO LOCATE ENGINE OIL LEAK ++FOUND THAT LEAK IS COMING BETWEEN THE ENGINE TIMING ++COVER AND ENGINE BLOCK ++TALKED TO CUSTOMER ABOUT LEAK AND HOW MUCH ++TIME IT WOULD TAKE, CUSTOMER WANTS TO WAIT A YEAR ++REINSTALLED BRACKET AND OVERFLOW TANK					
A145619	HOSE	1		65.13	65.13
CC2825	ANTIFREEZE	4		21.65	86.60
CU4907446	EXHAUST GASKET	1 N		64.21	64.21
CU4907447	EXHAUST GASKET	4 N		16.74	66.96
CU4955383	SEAL KIT	1 N		243.25	243.25
CU4962722	SEAL RECT	1 N		67.00	67.00
FRTCP	FREIGHT-CASE	1		20.00	20.00
GLYCOL 1G 50/50	ENVIRO FEE	4		.99	3.96
87376393	EXHAUST TUBE	1 M		317.09	317.09
87406903	COLLAR CLAMP	2 M		80.01	160.02
	PARTS				1094.22
	LABOR				650.31
11030099	SEGMENT TOTAL==>				1744.53

SEGMENT# 9 C 34031 NA 03/29/23 03/29/23

TRACK AND UNDERCARRIAGE SYSTEM
 +17 LEAKING BOGIE WHEELS
 ++JACKED UNIT UP AND PLACED ON JACKSTANDS
 ++LOOSENEED TRACK TENSION ON ALL 4 TRACKS
 ++REPLACED SEALS IN 17 BOOGIE WHEELS
 ++WHEN CHANGING SEALS INSPECTED BEARINGS AND
 +ENDED UP HAVING TO CHANGE 5 SETS ON BEARINGS

CONTINUED ON PAGE 07

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 • An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.
 • Young's Equipment Inc. and its manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



Phone: • Fax
www.youngs.ca



Regina 306-565-2405
Chamberlain 306-638-4516
Davidson 306-567-3074
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To:

Invoice To:

Branch		
Date 04/21/23	Time 22:01:42 (B)	Page 07
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UT2209	Tractor 4WD ST535Q	6068	ZAF118526		
++FILLED ALL BOOGIES THAT WERE REPAIRED WITH NEW OIL					
EHC1GL	EHC CHARGE	1		.88	.88
EHC1L	1 LITRE CONTAIN	2		.22	.44
48194035	SEAL	17		178.62	3036.54
648861	BEARING, ROLLER	10		71.08	710.80
73344258	OIL ENGINE 30	1		37.55	37.55
74633DX6US	SAE30 1QT	2		8.13	16.26
				PARTS	3802.47
				LABOR	6026.10
11030099				SEGMENT TOTAL==>	9828.57

SEGMENT#10 C 34031 NA 03/29/23 04/14/23
DIAGNOSE AND REPAIR HIGH BEAMS NOT TURNING ON
++TURNED ON ALL LIGHTS TO FIND WHICH HIGH BEAMS
+WERE NOT WORKING, FOUND THAT BOTH CENTER ONES
+WOULDN'T TURN ON
++CHECKED FUSE PANEL AND FOUND FUSE BLOWN FOR THEM
++INSTALLED NEW FUSE AND TRIED TURNING LIGHTS ON, FUSE
+BLEW INSTANTLY FOR THEM
++REMOVED SWITCH FROM THE OVERHEAD CONSOLE AND
+CHECKED WIRING, LOOKED GOOD
++DISCONNECTED BOTH CENTER HEADLAMPS, REPLACED FUSE
+AND TURN LIGHTS ON, FUSE DIDN'T BLEW
++RECONNECTED THE LEFT CENTER LIGHT, LIGHT CAME ON
++CONNECTED RIGHT CENTER LIGHT AND FUSE BLEW INSTANTLY
++UNBOLTED AND REMOVE RIGHT CENTER LIGHT AND BALLAST
++TRIED CONNECTING THE RIGHT LIGHT TO THE LEFT BALLAST
+LIGHT CAME ON, DIAGNOSED BALLAST FOR RIGHT LIGHT TO BE BAD
++TALKED TO CUSTOMER AND DECIDED TO INSTALL
+A AFTER MARKET LIGHT ASSEMBLY (CHEAPER THEN BALLAST)

CONTINUED ON PAGE 08

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
• It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
• Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
• An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
• Estimates are for the items specifically identified in the estimate only, and are non-binding.
• Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



Phone:

• Fax:

www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 04/21/23	Time 22:01:42 (B)	Page 08
Account #	Phone #	Inv #
Ship Via		Purchase Order # 22-23 INSPECTION
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UT2209	Tractor 4WD ST535Q	6068	ZAF118526		
++CHECKED OPERATION OF LIGHT WAS INSTALLED, ALL +FRONT LIGHTS WORK NOW					
LIGTL6010	MX, STX STEIGER	1	260.76		260.76
TWX500013	LINK, CONN	2	3.42		6.84
TWX500156	LINK, CONN	1	14.37		14.37
	PARTS				281.97
	LABOR				715.50
11030099	SEGMENT TOTAL==>				997.47

***** WORK ORDER TOTALS *****

PARTS	12584.52
LABOR	16804.74
shop supplies	300.00
QUADTRAC INSPEC	1699.00
SUB TOTAL==>	31388.26
GST 5%	1569.39
TOTAL ON ACCOUNT	32957.65

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other insurers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!