



www.youngs.ca



Regina 306-565-240
Chamberlain 306-638-451
Davidson 306-567-307
Moose Jaw 306-694-180
Raymore 306-746-228
Watrous 306-946-338
Weyburn 306-842-262
Windthorst 306-224-211

Ship To:

Invoice To:

Branch		
REPRINT		
Date 09/29/21	Time 22:03:05 (B)	Page 01
Account #	Phone #	Inv #
Ship Via	Purchase Order # SCR FAULT	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1051	YJG236802		
	9240	629			
SEGMENT# 1 C INTER NA 09/28/21 09/10/21					
SERVICE CALL					
SEPT 10-SERVICE CALL (96KM)					
SV	Service Call	96	1.15		110.40
(Vehicle Fee)					
					PARTS 110.40
					LABOR 303.69
11030099	SEGMENT TOTAL==>				414.09

SEGMENT# 2 C INTER NA 09/28/21
DIAGNOSE AND REPAIR SCR FAULT
COMPLAINT:
Code FBBF "Inducement system is locked due to 3 detections in 40 hours" is active.
CAUSE:
Faulty DEF tank sender unit, found infinite resistance within sending unit.
CORRECTION:
Examined SCR components for obvious damage, cleared active codes using EST. Code 119A "DEF adblue level sensor voltage is too high" returned. Disconnected DEF sender harness, tested harness for resistance, tested sending unit for resistance, found infinite resistance within sending unit, sending unit has failed internally. Removed tank access cover and machine corner shield, removed all coolant and def lines, removed sending unit, reinstalled new sending unit, reinstalled coolant and def lines, installed sender harness, reinstalled access cover. Connected EST and cleared faults, attempted to unlock inducement through easy

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
Estimates are for the items specifically identified in the estimate only, and are non-binding.
Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business



www.youngs.ca



Regina 306-565-2400
Chamberlain 306-638-4510
Davidson 306-567-3070
Moose Jaw 306-694-1800
Raymore 306-746-2280
Watrous 306-946-3380
Weyburn 306-842-2620
Windthorst 306-224-2110

Ship To:

Invoice To:

Branch		
Date 09/29/21	Time 22:03:05 (B)	Page 02
Account #	Phone #	Inv #
Ship Via		Purchase Order # SCR FAULT
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1051	YJG236802		
	9240	629			

tool and EST, would not unlock, updated engine software and unlocked inducement. Connected EST to run urea dosing system test, connected EST to run dosing flushing cleaning routine, connected EST to run system emptying test, connected EST to run dosing valve test, connected EST to run heater valve test, connected EST to run SCR fault repair verification test, all tests determined faults have been repaired and system is operating properly.

ADDITIONAL DESCRIPTION:

*EMISSIONS WARRANTY SUBMITTED ON W08542

*EMISSIONS WARRANTY PAID LABOUR AND PARTS ON THE REPAIR.

***** WORK ORDER TOTALS *****

PARTS	110.40
LABOR	303.69
shop supplies	68.17
EST SOFTWARE FEE	69.00
SUB TOTAL==>	551.26
GST 5%	27.56
TOTAL ON ACCOUNT	578.82

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees are at owner's risk.

An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business