



www.youngs.ca



Regina 306-565-240
Chamberlain 306-638-451
Davidson 306-567-307
Moose Jaw 306-694-180
Raymore 306-746-228
Watrous 306-946-338
Weyburn 306-842-267
Windthorst 306-224-211

Ship To:

Invoice To:

Branch		
REPRINT		
Date 07/27/23	Time 22:02:05 (B)	Page 01
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE 9240	1355 1043	YJG236802		
SEGMENT# 1 C 34045 L. COMBINE 06/06/23 06/06/23 FLAGSHIP COMBINE INSPECTION 11030099					
SEGMENT# 2 C 34031 NA 06/06/23 FLAGSHIP COMBINE INSPECTION WASH W11096					
SEGMENT# 3 C 34031 NA 06/06/23 07/27/23 INSPECTION TRUCKING SEPT 26-TRUCKED IN W/PILOT (64KM) TRUCKED OUT W/PILOT (64KM) *BILLED \$899 FOR INSPECTION TRUCKING PILOTLOADED Pilot Vehicle 128 2.65 339.20 -Taking out a load PARTS 339.20 11030099 SEGMENT TOTAL==> 339.20					
SEGMENT# 4 C 34045 NA 07/20/23 07/20/23 ELECTRICAL SYSTEM +CLEANED ALL CHASSIS GROUNDS +CLEANED OUT BATTERY BOX +CALIBRATED COMBINE AFTER REPAIRS +ALL CALIBRATIONS SUCCESSFUL +UPDATED SOFTWARE 322358 WASHER, SPRING 8 .25 2.00 86507066 M8 FLG NUT 4 1.22 4.88 PARTS 6.88 LABOR 709.14 CONTINUED ON PAGE 02					

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business!



www.youngs.ca



Regina 306-565-2400
Chamberlain 306-638-4500
Davidson 306-567-3000
Moose Jaw 306-694-1800
Raymore 306-746-2200
Watrous 306-946-3300
Weyburn 306-842-2600
Windthorst 306-224-2100

Ship To:

Invoice To:

Branch		
Date 07/27/23	Time 22:02:05 (B)	Page 02
Account #	Phone #	Inv #
Ship Via		Purchase Order # 22-23 INSPECTION
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1355	YJG236802		
	9240	1043			
11030099				SEGMENT TOTAL==>	716.02

SEGMENT# 5 C 34045 NA 07/20/23 07/20/23

FEEDER CHAIN

+RH TENSIONER HAD TO BE REMOVED BY ACETYLENE TORCH
+REPLACED TENSIONER ROD AND SPACER
+RE-TENSIONED FEEDER CHAIN
+REPLACED WEAR STRIPS
+INSERT BROKEN ON FEEDER HOUSE PANEL COVERS
+REPLACED INSERT
+HARDWARE MISSING ON REDEKOP TENSIONER
+ADDED HARDWARE TO SECURE REDEKOP TENSIONER
+IMPROPER HARDWARE TO HALF MOON ON CONE
+REPLACED HALF MOON HARDWARE
+LH HALF MOON BOLT HOLE STRIPPED
+DRILLED OUT AND TAPPED BOLT HOLE
+REINSTALLED HALF MOON WITH PROPER HARDWARE
+CONCAVES UNABLE TO BE INSTALLED AS THERE WERE 3 LH ONES
+AND ONE RH ONE
+SPOKE TO CUSTOMER - CUSTOMER STATED NOT TO INSTALL CONCAVES
+AS HE WOULD BE SWITCHING THEM OUT ANYWAYS
+CONCAVE HARDWARE LEFT IN CUSTOMERS CAB

325594	WASHER	1	5.65	5.65
412066	NUT	1	.81	.81
412126	NUT, LOCK	1	3.15	3.15
84147444	SPACER	1 M	27.12	27.12
84155550	ROD, THREADED	1	47.27	47.27
86560521	PIVOT	1	12.75	12.75
86610200	INSERT, TH	1	13.93	13.93

CONTINUED ON PAGE 03

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non-binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business!



www.youngs.ca



Regina 306-565-240
Chamberlain 306-638-451
Davidson 306-567-307
Moose Jaw 306-694-180
Raymore 306-746-228
Watrous 306-946-338
Weyburn 306-842-262
Windthorst 306-224-211

Ship To:

Invoice To:

Branch		
Date 07/27/23	Time 22:02:05 (B)	Page 03
Account #	Phone #	Inv #
Ship Via		Purchase Order # 22-23 INSPECTION
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE 9240	1355	YJG236802		
		1043			
86610201	INSERT	1		16.86	16.86
86629542	NUT, LOCK	1		1.01	1.01
86638209	STRIP	4		42.42	169.68
87030775	BOLT	8		3.82	30.56
87364	WASHER	1		1.19	1.19
				PARTS	329.98
				LABOR	596.25
11030099				SEGMENT TOTAL==>	926.23

SEGMENT# 6 C 34045 NA	07/20/23 07/20/23				
FEEDER GEARBOX					
+CLEANED UPPER AND LOWER FEEDER GEARBOX BREATHERS					
+REPLACED FELT SEALS AND BRUSHES					
+WELDED WASHER ON FEEDER HOUSE FOR GEARBOX POSITIONING					
+GREASED SHAFTS					
+GEARBOX TORQUED TO SPEC					
47510326	SEAL	2		51.72	103.44
84415750	SEAL, FELT	2		20.84	41.68
				PARTS	145.12
				LABOR	566.04
11030099				SEGMENT TOTAL==>	711.16

SEGMENT# 7 C 34045 NA	07/20/23 07/20/23				
SHOE SYSTEM					
+REPLACED SHOE BELT					
87317063	BELT	1		101.22	101.22
				PARTS	101.22
				LABOR	79.50
11030099				SEGMENT TOTAL==>	180.72

CONTINUED ON PAGE 04

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non-binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business



www.youngs.ca



Regina 306-565-2400
Chamberlain 306-638-4500
Davidson 306-567-3000
Moose Jaw 306-694-1800
Raymore 306-746-2200
Watrous 306-946-3300
Weyburn 306-842-2600
Windthorst 306-224-2100

Ship To:

Invoice To:

Branch		
Date 07/27/23	Time 22:02:05 (B)	Page 04
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1355 YJG236802		
	9240	1043		
SEGMENT# 8 C 34045 NA	07/20/23	07/20/23		
CLEAN GRAIN ELEVATOR				
+REPLACED TENSIONER HARDWARE FOR PADDLE CHAIN				
+TENSIONED PADDLE CHAIN				
FRTCP	FREIGHT-CASE	1	10.00	10.00
378245	WASHER	1	.71	.71
86560521	PIVOT	1 O	12.95	12.95
87719434	SPRING, COIL	1 N	53.21	53.21
9706685	NUT	2	1.79	3.58
	PARTS			80.45
	LABOR			124.02
11030099	SEGMENT TOTAL==>			204.47

SEGMENT# 9 C 34045 NA	07/20/23	07/20/23		
AUGER TROUGH				
+TAILINGS PULLEY DESTROYED WHILE TRYING TO REMOVE				
+TAILINGS PULLEY SEIZED TO SHAFT				
+PULLEY REMOVED BY BEARING PULLER				
+LOCKING COLLAR SEIZED TO SHAFT				
+LOCKING COLLAR REMOVED WITH AIR HAMMER				
+INNER BEARING RACE SEIZED TO SHAFT				
+BEARING RACE CUT OFF WITH ZIP CUTS				
+CLEANED SHAFT				
+REPLACED TAILINGS BEARING				
+REPLACED BEARING LOCKING COLLAR				
+REPLACED TAILINGS PULLEY				
+ADDITIONAL TIME REQUIRED TO REINSTALL BATTERY/TOOL BOX				
151-573	RIVET	4	1.13	4.52
47508360	BEARING, BALL	1	93.40	93.40
47577185	COLLAR S1108kt	1	32.74	32.74

CONTINUED ON PAGE 05

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to release the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non-binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business!



www.youngs.ca



Regina 306-565-240
Chamberlain 306-638-451
Davidson 306-567-307
Moose Jaw 306-694-180
Raymore 306-746-228
Watrous 306-946-338
Weyburn 306-842-267
Windthorst 306-224-211

Ship To:

Invoice To:

Branch		
Date 07/27/23	Time 22:02:05 (B)	Page 05
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1355	YJG236802		
	9240	1043			
87313372	PULLEY	1		267.26	267.26
87528798	SEAL	1		24.93	24.93
				PARTS	422.85
				LABOR	957.18
11030099				SEGMENT TOTAL==>	1380.03

SEGMENT#10 C 34045 NA	07/20/23 07/20/23				
ENGINE					
+COMBINE BLOWN OUT BEFORE REPAIRS, MATERIAL BUILT UP IN ENGINE BAY WITH SIGNS OF MICE NESTING					
+TOPPED UP COOLANT (9.46L)					
+ADDED SECOND HOSE CLAMP TO COOLANT SUPPLY HOSE					
+TIGHTENED EXISTING HOSE CLAMP ON COOLANT SUPPLY HOSE					
+COOLANT NOT LEAKING OUT OF SUPPLY HOSE ON FINAL RUN					
EHC2.5GL	EHC CHARGE	2		1.90	3.80
L115549	CLAMP	1		44.34	44.34
76971NXYCA	OT COOLANT9.46L	2 O		54.34	108.68
				PARTS	156.82
				LABOR	631.23
11030099				SEGMENT TOTAL==>	788.05

SEGMENT#11 C 34045 NA	07/20/23 07/20/23				
FUEL SYSTEM					
+FUEL BREATHER CLAMP MISSING - ADDED HOSE CLAMP TO BREATHER					
+REPLACED FUEL SYSTEM BREATHER					
+REPLACED WIF SENSOR					
+CLEANED TOP OF TANK					
EHCFLT1	ENV FEE	1		.50	.50
47437399	FILTER, FUEL	1		75.11	75.11
84409712	SENSOR	1		345.60	345.60

CONTINUED ON PAGE 06

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at owner's risk.
* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non-binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business



www.youngs.ca



Regina 306-565-240
Chamberlain 306-638-451
Davidson 306-567-307
Moose Jaw 306-694-180
Raymore 306-746-228
Watrous 306-946-338
Wayburn 306-842-267
Windthorst 306-224-211

Ship To:

Invoice To:

Branch		
Date 07/27/23	Time 22:02:05 (B)	Page 06
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1355	YJG236802		
	9240	1043			
86625022	HOSE CLAMP	1		1.83	1.83
				PARTS	423.04
				LABOR	211.47
11030099				SEGMENT TOTAL==>	634.51

SEGMENT#13 C 34045 NA	07/20/23 07/20/23				
HYDRAULIC SYSTEM					
+REPLACED LEAKING HOSE FOR QUICK ATTACH COUPLER					
+TOPPED UP HYDRAULIC RESERVOIR (3L OF HYTRAN)					
FRTCP	FREIGHT-CASE	1		10.00	10.00
87109347	HOSE	1 N		184.57	184.57
				PARTS	194.57
				LABOR	162.18
11030099				SEGMENT TOTAL==>	356.75

SEGMENT#14 C 34045 NA	07/20/23 07/20/23				
HYDRO SYSTEM					
+INSTALLED RUBBER STRIPS INSIDE CLAMP TO PROTECT HOSE					
+REPLACED TOP MOUNTING CLAMP					
84444101	CLAMP	1 M		47.63	47.63
				PARTS	47.63
				LABOR	159.00
11030099				SEGMENT TOTAL==>	206.63

SEGMENT#15 C 34045 NA	07/20/23 07/20/23				
GROUND DRIVE SYSTEM					
+CLEANED OUT FINAL DRIVE BREATHERS					
+CLEANED OUT TRANSMISSION BREATHER					
				LABOR	122.43
11030099				SEGMENT TOTAL==>	122.43

CONTINUED ON PAGE 07

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
= It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
= Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
= An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to release the release and/or delivery of equipment until such a point as invoices have been paid.
= Estimates are for the items specifically identified in the estimate only, and are non-binding.
= Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business



www.youngs.ca



Regina 306-565-240
Chamberlain 306-638-451
Davidson 306-567-307
Moose Jaw 306-694-180
Raymore 306-746-228
Watrous 306-946-338
Wayburn 306-842-262
Windthorst 306-224-211

Ship To:

Invoice To:

Branch		
Date 07/27/23	Time 22:02:05 (B)	Page 07
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1355	YJG236802		
	9240	1043			

***** WORK ORDER TOTALS *****

PARTS	2247.76
LABOR	4318.44
shop supplies	300.00
INSPECT TRUCKNG	899.00
10-40 Ser Comb	2199.00
SUB TOTAL==>	9964.20
GST 5%	498.28
TOTAL ON ACCOUNT	10462.48

07272023

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business