



Phone

www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

A01-53

Invoice To:

Branch		
REPRINT		
Date 05/27/24	Time 22:01:32 (B)	Page 01
Account #	Phone #	Inv #
Ship Via	Purchase Order # 23-24 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
UP0858 HC Sprayer 4420	3735	Y8T022720		

SEGMENT# 1 C 34023 SPRAYER INSP 05/08/24 05/08/24
 SPRAYER INSPECTION
 INSPECTION COMPLETED ON
 **SPRAYER INSPECTION BILLED OUT ON
 11030099

SEGMENT# 2 C 34023 NA 05/08/24
 SPRAYER INSPECTION WASH
 W12303

SEGMENT# 3 C 34023 NA 05/08/24
 INSPECTION TRUCKING
 CUSTOMER BROUGHT UNIT IN

SEGMENT# 4 C 34023 NA 05/09/24 05/09/24
 ENGINE
 REMOVE AND REPLACE ENGINE COOLANT THERMOSTAT
 DRAIN COOLANT
 REPLACE COOLANT TANK TO TOP END ENGINE COOLANT HOSE
 REMOVE FRONT TIMING COVER CASE PLUG, PLUG AND GASKET IS
 DAMAGED. REPLACE WITH NEW PLUG AND GASKET.
 REMOVE MUFFLER, CLEAN UP FLANGES, SEAL WITH EXHAUST
 SEALANT, REINSTALL MUFFLER.
 FILL COOLING SYSTEM.
 CHECKED AUTOSTEER.
 REPLACED PINCHED STEERING ANGLE SENSOR HARNESS.
 DECREASED P-GAIN TO 10 FROM 17
 RAN AUTOGUIDANCE LINE AND TESTED OPERATION AT 18MPH OK.
 CHECKED ROLL CALIBRATION OK.

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc. and/or in possession of the above-noted equipment.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Thank You!
 We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



Phone: _____ Fax: _____
www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To: _____

Invoice To: _____

Branch		
Date 05/27/24	Time 22:01:32 (B)	Page 02
Account #	Phone #	Inv #
Ship Via	Purchase Order # 23-24 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UP0858	HC Sprayer 4420	3735	Y8T022720		
FRTCP	FREIGHT-CASE	1		5.00	5.00
HC12	CLAMP, HOSE #12	2		1.17	2.34
J903463	COVER	1		41.42	41.42
J903475AM	SEAL	1 S		2.09	2.09
R134A	FREON	4		25.25	101.00
27004	3/8 FUEL HOSE	3		4.63	13.89
84427136	THERMOSTAT	1		182.05	182.05
86625022	HOSE CLAMP	4		2.07	8.28
87743200	HARNESS	1		91.21	91.21
	PARTS				447.28
	LABOR				1701.83
11030099	SEGMENT TOTAL==>				2149.11

SEGMENT# 5 C 34023 NA 05/09/24 05/10/24
BOOM
REMOVE BROKEN BOLT FROM PIN, ROTATE PIN TO ALIGN HOLE,
INSTALL NEW BOLT, TORQUE AND LOCK-TIGHT.
OUTER LH BOOM LOCK CYLINDER DAMAGED
FOUND SEVERAL LOOSE BOLTS ON BOOM, TORQUE AND ADD
LOCK-TIGHT TO PREVENT VIBRATION LOOSENING.
ADJUSTED BOOM STOPS
REPLACED LH OUTER BOOM LOCK CYLINDER AND HARDWARE. ON
TESTING THE BRACKET BROKE (IT WAS WELDED BEFORE).
EXTRA TIME TO REMOVE BRACKET AND RE-WELDED IT. PAINTED
BRACKET AN INSTALLED. TESTED OPERATION OK.

11030099

LABOR 833.17
SEGMENT TOTAL==> 833.17

SEGMENT# 6 C 34023 NA 05/09/24 05/10/24
HYDRAULIC & HYDROSTATIC SYSTEM

CONTINUED ON PAGE 03

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
• It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
• Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
• An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
• Estimates are for the items specifically identified in the estimate only, and are non-binding.
• Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Phone: • Fax:
www.youngs.ca



Regina 306-565-2405
Chamberlain 306-638-4516
Davidson 306-567-3074
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: .

Invoice To:

Branch		
Date 05/27/24	Time 22:01:32 (B)	Page 03
Account #	Phone #	Inv #
Ship Via	Purchase Order # 23-24 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
UP0858 HC Sprayer 3735 Y8T022720

4420

HYDRAULIC TANK LEAKING FROM 2 LINES AT BACK OF TANK,
REMOVED FITTINGS AND INSTALLED NEW O-RINGS, REINSTALL
FITTING. REPLACED O-RINGS ON 2 HOSES COMING OFF OF MAIN
PRESSURE BLOCK. REPLACE O-RINGS ON SEVERAL FITTINGS AT HYD
DRIVE CONTROL BLOCK. LR WHEEL HYDRAULIC LINE LOOSE, REMOVE
AND REPLACE O-RINGS, REINSTALL.

WRAP FRONT HYDRAULIC HOSES TO PREVENT FURTHER DAMAGE.

BN21982	CLEVIS- 1" DIA	1 N	182.27	182.27
BN50075	NUT	1 M	4.44	4.44
FRTCP	FREIGHT-CASE	1	10.00	10.00
439-1824	PIN, HEADED	1 M	16.20	16.20
80756	PKG-PIN, SPLIT	1	.25	.25
83-6043	15" ZIPTIE WIDE	10	.74	7.40
84414496	PROTECTOR	1	69.16	69.16
87266443	HYDRAULIC CYLIN	1 N	609.97	609.97
	PARTS			899.69
	LABOR			652.34
11030099	SEGMENT TOTAL==>			1552.03

SEGMENT# 7 C 34023 NA 05/09/24 05/09/24
CHASSIS

FRONT INNER FOLD CYLINDER RODS ARE FACING WRONG WAY AND
GREASE ZERKS ARE DAMAGED (SERVICE COVERED THIS REPAIR)

SEGMENT# 8 C 34023 NA 05/09/24 05/09/24
SPRAY SYSTEM

BOOM VALVE 3 MAY BE INTERMITTENT. DID NOT WORK FIRST TIME
SWITCHING ON BUT WORKED EVER SINCE. NO VISIBLE DAMAGE
FOUND, LAMP DOES NOT ILLUMINATE ON SWITCH.
REPLACED LEAKING FILTER HEADS TO LEFT AND RIGHT BOOM.

CONTINUED ON PAGE 04

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to release the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non-binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



Phone: Fax
www.youngs.ca



Regina 306-565-2405
Chamberlain 306-638-4516
Davidson 306-567-3074
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To:

Invoice To:

Branch		
Date 05/27/24	Time 22:01:32 (B)	Page 04
Account #	Phone #	Inv #
Ship Via	Purchase Order # 23-24 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UP0858	HC Sprayer 4420	3735	Y8T022720		
FILLED AND SPRAY TESTED. LEAKAGE AT PRODUCT PUMP. (WHEN IMPELLER WAS CHANGED, THE SEAL WAS DAMAGED) REPLACED PUMP SEAL USING KIT. TESTED SPRAY OPERATION OK.					
FC220	CLAMP- FLANGE 2	1		10.93	10.93
4199	IMPELLER NUT, H	1		12.20	12.20
87265476	SEAL	1		374.90	374.90
87610600	IMPELLER	1		234.84	234.84
87706933	STRAINER, FILTE	2 N		213.78	427.56
				PARTS	1060.43
				LABOR	424.19
11030099				SEGMENT TOTAL==>	1484.62

SEGMENT# 9 C 34023 NA	05/09/24 05/11/24
CAB	
AFTER REPLACING CHARCOAL FILTER, FAN NO LONGER MAKING NOISE. NOTICE FAN WAS NOT BLOWING COLD, CHECK A/C SYSTEM PRESSURES, NO PRESSURE FOUND. PRESSURE TEST A/C SYSTEM WITH NITROGEN, NO LEAKS OR EXCESSIVE LOSS OF PRESSURE FOUND. PULL VACUUM, WAIT FOR LOSS, NO EXCESSIVE VACUUM LOSS FOUND. PULL VACUUM AND CHARGE SYSTEM WITH 3.6LB R134A. CHECK FUNCTION, FAN NOW BLOWS COLD.	
	LABOR 392.08
11030099	SEGMENT TOTAL==> 392.08

SEGMENT#10 C 34023 NA	05/09/24 05/09/24
MAINTENANCE	
ADDED 25L HYDRAULIC FLUID	
REPLACED ENGINE OIL AND FILTER (20L 15W40)	
REPLACED BOTH ENGINE AIR FILTERS	
REPLACED 3 FUEL FILTERS AND BLEED FUEL SYSTEM	

CONTINUED ON PAGE 05

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Phone

www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 05/27/24	Time 22:01:32 (B)	Page 05
Account #	Phone #	Inv #
Ship Via	Purchase Order # 23-24 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UP0858	HC Sprayer 4420	3735	Y8T022720		
REPLACE 2 SCREW-ON HYD FILTERS AND 1 IN TANK HYD FILTER. REPLACE CHARCOAL FILTER DRAIN AND FILL GEAR INCREASER OIL.					
BN304339	CAP HYDRAULIC	1		81.37	81.37
BN319388	FILTER, FUEL	1		74.11	74.11
CC2848	ANTIFREEZE	3		139.71	419.13
EHCFLT1	ENV FEE	3		.50	1.50
EHCFLT2	EHC CHARGE	4		1.00	4.00
EHCOIL	EHC CHARGE	55		.05	2.75
EHC1L	1 LITRE CONTAIN	3		.22	.66
N14232	FILTER	2		149.30	298.60
74645001US	15W40 BULK	35		5.20	182.00
77400001US	ULTRACTION BULK	20		5.92	118.40
81135DX6US	75W90 SYN 1L	3		14.24	42.72
84475951	FILTER, AIR	1		176.38	176.38
84476647	FILTER	1		110.07	110.07
84477358	FILTER, FU	1		41.40	41.40
84477359	FILTER, FUEL	1		71.60	71.60
84485647	FILTER, ENGI	1		85.51	85.51
87267363	CHARCOAL FILTER	1		387.00	387.00
87272033	FILTER- TANK HY	1		114.01	114.01
				PARTS	2211.21
				LABOR	495.00
11030099				SEGMENT TOTAL==>	2706.21

***** WORK ORDER TOTALS *****

PARTS	4618.61
LABOR	4498.61

CONTINUED ON PAGE 06

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to release the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Phone: _____

Fax: _____

www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To: _____

Invoice To: _____

Branch		
Date 05/27/24	Time 22:01:32 (B)	Page 06
Account #	Phone #	Inv #
Ship Via	Purchase Order # 23-24 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#

UP0858

HC Sprayer
4420

HRS

3735

PIN/EIN

Y8T022720

WARRANTY DATE

HRS

shop supplies

300.00

SUB TOTAL==>

9417.22

GST 5%

470.91

TOTAL ON ACCOUNT

9888.13

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to release the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By _____

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business