



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To: .

Branch		
REPRINT		
Date 12/30/22	Time 22:01:19 (B)	Page 01
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

Invoice To: .

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
002771 TRACTOR STX 530 HD	5200	Z6F100504		
SEGMENT# 1 C 34002 4WD INSPECTI 10/20/22 10/20/22 4 WD STEIGER TRACTOR INSPECTION 11030099				
SEGMENT# 2 C 34002 NA 10/20/22 4WD STEIGER INSPECTION WASH W10166				
SEGMENT# 3 C 34034 NA 10/20/22 12/29/22 INSPECTION TRUCKING SEPT 8-TRUCKED IN (56KM) PLUS RETURN TRUCKING (56KM) *BILLED MILEAGE (LESS THAN \$899 INSPECTION TRUCKING) SEMILOADED Semi 112 7.50 840.00 (Hauling Loaded) PARTS 840.00 11030099 SEGMENT TOTAL==> 840.00				
SEGMENT# 4 C 34002 NA 12/15/22 12/15/22 OPERATIONAL CHECKS +FRONT AND REAR SUN SCREEN WILL NOT RETRACT +ROLLED UP SCREENS LABOR 162.18 11030099 SEGMENT TOTAL==> 162.18				
SEGMENT# 5 C 34002 NA 12/15/22 12/15/22 ELECTRICAL SYSTEM +REPLACED HEAD LIGHT BULB +CALIBRATED REMOTE HYDRAULICS +CALIBRATED REMOTE LEVERS				

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 12/30/22	Time 22:01:19 (B)	Page 02
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
002771	TRACTOR	5200	Z6F100504		
	STX 530 HD				
44995162		BULB		1	16.33
					PARTS
					LABOR
11030099				SEGMENT TOTAL==>	494.92

SEGMENT# 6 C 34002 NA	12/15/22 12/15/22		
ENGINE			
+REPLACED HOT INTAKE BOOT AND CLAMPS			
+REPLACED ENGINE OIL DRAIN PLUG SEALS			
+REPLACED ENGINE AIR FILTER HOUSING SEAL			
BN29710	WEATHERSTRIP	6	18.18
251400A1	BELLOWS	1	257.36
84183778	CLAMP, SPECIAL	2 N	34.51
			PARTS
			LABOR
11030099		SEGMENT TOTAL==>	1079.41

SEGMENT# 7 C 34002 NA	12/15/22 12/15/22		
HYDRAULIC SYSTEM			
+FOUND LOOSE HOSE CLAMPS			
+TIGHTENED ALL HOSE CLAMPS			
+ADDED 2 NEW CLAMPS ON THE SUCTION LINE			
+ADDED 2 NEW CLAMPS TO THE SECOND SUCTION LINE			
86624194	CLAMP	4	7.19
			PARTS
			LABOR
11030099		SEGMENT TOTAL==>	357.89

SEGMENT# 8 C 34002 NA	12/15/22 12/15/22
CHASSIS	

CONTINUED ON PAGE 03

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 12/30/22	Time 22:01:19 (B)	Page 03
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
002771	TRACTOR	5200	Z6F100504		
	STX 530 HD				
	+HOOD IS CLOSING NOW				
	+HOOD WOULDN'T CLOSE WHEN COLD				
	+ADJUSTED CABLE AND LATCH				
	+OILED THE CABLE AND LATCH				
	+RESEALED CAB FILTER HOUSING				
187874C1	GASKET	13		1.41	18.33
				PARTS	18.33
				LABOR	500.85
11030099				SEGMENT TOTAL==>	519.18

SEGMENT# 9 C 34002 NA	12/15/22 12/15/22				
HYDRAULIC TESTS					
+REPLACED TRANS REGULATOR MAIN SPOOL AND SPRING					
+THIS BROUGHT UP THE TRANS SYSTEM PRESSURE 15PSI					
+HIGH END IS 305PSI LOW END IS 290-295PSI					
+ADJUSTED REGULATED PRESSURE					
+295PSI AT IDLE					
+310PSI AT 1500RPM					
+365PSI AT HIGH IDLE					
+SPEC IS 300PSI AT 1500RPM					
+CALIBRATED TRANSMISSION WITH HIGHER PRESSURE					
47496084	SPRING	1		149.91	149.91
87350419	SPOOL	1 N		837.79	837.79
				PARTS	987.70
				LABOR	955.59
11030099				SEGMENT TOTAL==>	1943.29

SEGMENT#10 C 34002 NA	12/15/22 12/15/22
MAINTENANCE	
+REPLACED COOLANT FILTER AND TOPPED UP COOLANT	

CONTINUED ON PAGE 04

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees are at own risk.

* An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

* Estimates are for the items specifically identified in the estimate only, and are non-binding.

* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To: .

Invoice To:

Branch		
Date 12/30/22	Time 22:01:19 (B)	Page 04
Account #	Phone #	Inv #
Ship Via		Purchase Order # 22-23 INSPECTION
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
002771	TRACTOR	5200	Z6F100504	

STX 530 HD

+GREASED TRACTOR
 +REPLACED BOTH CAB FILTERS
 +REPLACED FUEL FILTER
 +REMOVED INLINE FUEL FILTER AND CLEANED
 +REPLACED TRANS OIL AND FILTER
 +REPLACED HYDRAULIC OIL AND FILTER
 +REPLACED AXLE LUBE FILTER
 +DRAINED OIL FROM FRONT AND REAR DIFFS (PART OF HYD SYSTEM)
 +REMOVED HYDRAULIC TANK ACCESS AND CLEANED SUCTION FILTERS
 +PUT BACK TOGETHER WITH NEW GASKET
 +CHANGED BOTH ENGINE AIR FILTERS
 +REPLACED ENGINE OIL AND FILTER
 +REPLACED FRONT AND REAR DIFF OIL

EHCFLT1	ENV FEE	1	.50	.50
EHCFLT2	EHC CHARGE	5	1.00	5.00
EHCOIL	EHC CHARGE	309	.05	15.45
EHC4L	EHC CHARGE	2	.88	1.76
435031A1	GASKET	1	73.10	73.10
48142232	FILTER HYDRAUL	1	191.47	191.47
74645001US	15W40 BULK	48	4.84	232.32
76980JXYCA	COOLANT 3.79L	2	17.46	34.92
77400001US	ULTRACTION BULK	261	5.27	1375.47
84239751	FILTER, HYDRAUL	2	102.99	205.98
84372057	FILTER ASSY	1	112.68	112.68
84477273	FILTER, COOLANT	1	138.41	138.41
84477362	FILTER, FUEL	1	98.72	98.72
87443714	FILTER, AIR	1	236.94	236.94
87684088	CAB AIR FILTER	1	80.89	80.89
87727665	FILTER, AIR	1	335.52	335.52
	PARTS			3139.13

CONTINUED ON PAGE 05

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at our risk.

An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereon. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (2% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Thank You!
 We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To: .

Invoice To

Branch		
Date 12/30/22	Time 22:01:19 (B)	Page 05
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
002771		26F100504		
TRACTOR	5200			
STX 530 HD				
			LABOR	1142.46
11030099			SEGMENT TOTAL==>	4281.59

SEGMENT#11 C 34002 NA 12/15/22 12/15/22

BOTTOM END ROLL IN/TOP END SET

+DRAINED COOLANT

+REMOVED INTAKE TUBES

+REMOVED COOLANT TANK

+REMOVED VALVE COVER

+SET ROCKERS FOR VALVES AND INJECTORS

+MADE NO ADJUSTMENTS TO INTAKE ROCKERS

+EXHAUST AND INJECTORS NEED ADJUSTMENT

+TIGHTENED EXHAUST AND INJECTORS TO SPEC

+TORQUED ALL PARTS

+INSTALLED VALVE COVER WITH A NEW GASKET AND TORQUED

+PUT ALL PARTS BACK TOGETHER AND PUT IN COOLANT

+ADDED SOLVENT AND HYDRAULIC OIL TO THE ENGINE OIL

+RAN ENGINE TILL WARM AND DRAINED OIL

+THIS HELPS CLEAN THE BLOCK

+JACKED UP TRACTOR AND UNBOLTED DRIVE SHAFT AND FRONT DIFF

+DROPPED FRONT DIFF

+REMOVED ENGINE OIL PAN

+REMOVED OIL PICK UP

+CLEANED ALL PARTS AND FINISHED CLEANING THE INSIDE OF THE

+BLOCK THAT IS ACCESSIBLE

+REPLACED ROD BEARINGS MEASURED NEW BEARINGS

+NUMBER 2 HAD NOTICEABLE WEAR

+ALL ROD BEARINGS HAD SOME WEAR

+NUMBER 2 WAS THE MOST

+MEASURED AND REPLACED ALL MAIN CRANK BEARINGS AND

CONTINUED ON PAGE 06

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering as my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

* Estimates are for the items specifically identified in the estimate only, and are non-binding.

* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



www.youngs.ca



Regina 306-363-2403
Chamberlain 306-638-4516
Davidson 306-567-3074
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To:

Invoice To:

Branch		
Date 12/30/22	Time 22:01:19 (B)	Page 06
Account #	Phone #	Inv #
Ship Via		Purchase Order # 22-23 INSPECTION
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
002771 TRACTOR 5200 Z6F100504

STX 530 HD

+THRUST BEARINGS
+MAIN BEARINGS TOOK TIME TO CHANGE DIFFICULT TO REMOVE
+TORQUED ALL BEARINGS TO SPEC
+CLEANED AND REINSTALLED ALL PARTS
+ENGINE STIFFENER PLATE, OIL PUMP, OIL PICK UP
+TORQUED ALL PARTS
+HAD TO REMOVE OIL FILL TO TURN THE ENGINE OVER
+OIL FILL SEAL IS HARD AND BRITTLE
+REPLACED SEAL
+REPLACED PLASTIC FITTING AND SEAL
+REPLACED OIL PICK UP SEAL
+INSTALLED OIL PAN WITH A NEW GASKET AND TORQUED
+MEASURED CRANK END CLEARANCE WITH NEW THRUST BEARINGS
+ALL MEASUREMENTS ARE WITHIN SPEC
+INSTALLED RADAR
+INSTALLED FRONT DIFF AND DRIVE SHAFT
+TORQUED PARTS
+PUT OIL IN ENGINE AND RAN ENGINE

CU3903475	SEAL	1 N	6.59	6.59
CU3914766	TUBE,OIL FILLER	1 N	52.00	52.00
CU3936876	SEAL	1 N	5.74	5.74
CU4026507	GSKT	1 N	408.12	408.12
CU4026684	GASKET	1 N	580.49	580.49
CU4089405	ROD BEARING	6 N	193.60	1161.60
CU5406110	MAIN BRG KIT	1 N	860.48	860.48
FRTCP	FREIGHT-CASE	3	17.50	52.50
221964	O-RING	1	6.68	6.68
271913	O-RING	1	4.15	4.15
			PARTS	3138.35
			LABOR	4436.10

CONTINUED ON PAGE 07

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby relieved from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repair, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non-binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



www.youngs.ca



Regina	306-555-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To: .

Invoice To:

Branch		
Date 12/30/22	Time 22:01:19 (B)	Page 07
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
002771	TRACTOR	5200	Z6F100504		
	STX 530 HD				
11030099				SEGMENT TOTAL==>	7574.45

***** WORK ORDER TOTALS *****

PARTS	8604.06
LABOR	8648.85
shop supplies	200.00
4WD INSPECTION	1699.00
SUB TOTAL==>	19151.91
GST 5%	957.64
TOTAL ON ACCOUNT	20109.55

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

* Estimates are for the items specifically identified in the estimate only, and are non-binding.

* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business