

Quan Part Number/Description Price

2.0 19 AC DELCO PLUG 11.98 23.96
 1.0 TPSS309 TPS SENSOR 102.57 102.57

Recommendations:
 Total Parts: 126.53

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLES OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OF ANY OTHER CAUSE BEYOND OUR CONTROL.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

LJ AUTOMOTIVE
 415 W. SIERRA HWY,
 PALMDALE CA 93550
 661-267-0600
 BAR #: AE210460
 04/30/25 03:07 pm
 17360

Customer Name [REDACTED]
 Address [REDACTED]
 City [REDACTED] State [REDACTED] Zip [REDACTED]
 Year Make Model Vin Number License Mileage
 88 Jeep CAMANCHE 1JTMW6611JT210169 5S81133 320017
 Oper Repair Instructions Labor Charge

01 CHECK EMISSIONS
 REPLACE SPARK PLUGS , FOUND VEHICLE HAD THE WROMG TPS SENSOR. REPLACE TPS. THE HYDRON CARBON AND CO HAS COME DOWN A LOT, BUT NEEDS TO GO TO SMOG SHOP

240.00

Quotes: 1 04/29 08:13am 120.00 [REDACTED]

Payments: 1 04/30/25 379.50 MCard 03:07 pm

Surcharge Total: 0.00

Total Labor: 240.00
 Total Parts: 126.53
 Haz Waste: 0.00
 Shop Supplies: 0.00
 Non Taxable: 0.00
 Sub Total: 0.00
 Tax: 12.97
Total Amount: 379.50
 Payment: 379.50
 Bal Due: .00