

West Edmonton

17104 - 118 Ave., Edmonton, AB, T5S 2L7 Tel: 780.452.2790 Fax: 780.451.2678 www.horizonagturf.com

г			Branch					
	IN STORE PICKUP			EDMONTON		*REPRI	NT*	
.: ::				Date	Time		_	Pa
Ship to:				11/28/24		3:00:54 (01
σ				Account No.	Phone	No.		Invoice N
Į				INTER01 Ship Via		Purchase (Order	S7486
[TIMEDINA GUGEONED							
e to:	INTERNAL CUSTOMER INTERNAL CUSTOMER					MADE B	BY DE	SREK
Invoice	INTERNAL W/O AB T5S 2	т.7						
ا ک	INTERNAL W/O AB 135 Z				Sales	person		
			SERVICE IN	VOICE				
			SERVICE III	VOICE				
omr# /nr nc	m#	IIDa	DIN /DIN		3 mm	IID C		
STK#/FLEE 143532A		HRS	•	WARRANTY D		HRS 2000		
143532A	JOHN DEERE 6130R 6130R	5050	ILUGISURAFP	829808 08/27	/ 1 /	2000		
	0130K							
lave you	heard about MyDealer ye	t? We ha	ave a great :	new way to help	you sta	ay		
connected	to your equipment. Eit	her mobi	ile or lapto	o - look up par	ts, orde	er		
	ne, view past purchases							
	Ask a parts or servic							
	11011 0 P01100 01 001110							
				-				
SEGMENT#	1 C 2438 NA	11/12/24	1 11/14/24	-				
	1 C 2438 NA PF ISSUE PO M016402	11/12/24	1 11/14/24		1.83 HRS	5		
REPAIR D				1	1.83 HRS	5		
REPAIR D	PF ISSUE PO M016402			1	1.83 HRS	5		
REPAIR D	PF ISSUE PO M016402 go through the interact			1	1.83 HRS	5		
REPAIR D -Please get to t	PF ISSUE PO M016402 go through the interact	ive solu	ition that y	ou can	1.83 HRS	5		
REPAIR D -Please get to tFound c	PF ISSUE PO M016402 go through the interact hrough service center	ive solu	ition that y	ou can	1.83 HRS	5		
REPAIR D -Please get to tFound c occasion	PF ISSUE PO M016402 go through the interact hrough service center ode ECU 3720.15 for DPF	ive solu	ution that y	1 ou can n is	1.83 HRS	5		
REPAIR D -Please get to tFound c occasion -Found c	PF ISSUE PO M016402 go through the interact hrough service center ode ECU 3720.15 for DPF ally active.	ive solu	ution that you ted with as active alo	ou can h is ng with	1.83 HRS	5		
REPAIR D -Please get to tFound c occasion -Found c DPF code	pr ISSUE PO M016402 go through the interact hrough service center ode ECU 3720.15 for DPF ally active. ode SCO 2173.09 is usua	restrically also	ution that you ted with as active alo	ou can h is ng with	1.83 HRS	5		
REPAIR D -Please get to tFound c occasion -Found c DPF code -SCO cod	pF ISSUE PO M016402 go through the interact hrough service center ode ECU 3720.15 for DPF ally active. ode SCO 2173.09 is usua but is not always acti	restrically also ve when issue.	ution that you ted with as active alo	ou can h is ng with	1.83 HRS	5		
REPAIR D -Please get to tFound c occasion -Found c DPF code -SCO cod -Codes d	PF ISSUE PO M016402 go through the interact hrough service center	restrically also ve when issue.	ation that y cted with as condition active along DPF code is	1 ou can h is ng with active.	1.83 HRS	6		
REPAIR D -Please get to tFound c occasion -Found c DPF code -SCO cod -Codes d -Checked	pF ISSUE PO M016402 go through the interact hrough service center ode ECU 3720.15 for DPF ally active. ode SCO 2173.09 is usua but is not always acti e is likely a separate id not come back for no	restrically also ve when issue.	ation that y cted with as cactive alo DPF code is	1 Du can n is ng with active.	1.83 HRS	5		
REPAIR D -Please get to tFound c occasion -Found c DPF code -SCO cod -Codes d -Checked -All emi	pF ISSUE PO M016402 go through the interact hrough service center ode ECU 3720.15 for DPF ally active. ode SCO 2173.09 is usua but is not always acti e is likely a separate id not come back for no	restrice solution illy also ve when issue. ow. a cold sare with	cted with as continuous active aloo by code is sook recording the norm	1 ou can n is ng with active. ng. al range.	1.83 HRS	50		
REPAIR D -Please get to tFound c occasion -Found c DPF code -SCO cod -Codes d -Checked -All emi -It is l	pF ISSUE PO M016402 go through the interact hrough service center	restrice solution illy also ve when issue. The cold is a cold is are with the period is the removement of the solution is the	cted with as continuous properties.	1 ou can n is ng with active. ng. al range. aned as	1.83 HRS	5		
REPAIR D -Please get to tFound c occasion -Found c DPF code -SCO cod -Codes d -Checked -All emi -It is l the unit	pF ISSUE PO M016402 go through the interact hrough service center ode ECU 3720.15 for DPF ally active. ode SCO 2173.09 is usua but is not always acti e is likely a separate id not come back for no snapshot info and did ssions related sensors ikely that DPF needs to	restrice solution in the cold sare with the cold has found has followed as followed by the cold has followed by the cold	cted with as continuous properties.	1 ou can n is ng with active. ng. al range. aned as	1.83 HRS	5		
REPAIR D -Please get to tFound c occasion -Found c DPF code -SCO cod -Codes d -Checked -All emi -It is l the unit	pr ISSUE PO M016402 go through the interact hrough service center ode ECU 3720.15 for DPF ally active. ode SCO 2173.09 is usua but is not always acti e is likely a separate id not come back for no snapshot info and did ssions related sensors ikely that DPF needs to has 5000 hours on it a	restrice restrice restrice restrice restrice restriction and sold sold sold sold sold restriction and has folder	cted with as of active alogous DPF code is soak recording the norm oved and clessailed 6 reg	1 Du can h is ng with active. ng. al range. aned as ens.	1.83 HRS	5		
REPAIR D -Please get to tFound c occasion -Found c DPF code -SCO cod -Codes d -Checked -All emi -It is l the unit -Followe -Determi	pF ISSUE PO M016402 go through the interact hrough service center	restriction along the solution of the solution	cted with as of active alogous DPF code is soak recording the norm oved and clessailed 6 reg	1 Du can h is ng with active. ng. al range. aned as ens.	1.83 HRS	5		
REPAIR D -Please get to tFound c occasion -Found c DPF code -SCO cod -Codes d -Checked -All emi -It is l the unit -Followe -Determi -Made qu	pF ISSUE PO M016402 go through the interact hrough service center ode ECU 3720.15 for DPF ally active. ode SCO 2173.09 is usua but is not always acti e is likely a separate id not come back for no snapshot info and did ssions related sensors ikely that DPF needs to has 5000 hours on it a d interactive solution. ned DPF needs to be sen ote to have DPF cleaned	restriction along the solution of the solution	cted with as of active alogous DPF code is soak recording the norm oved and clessailed 6 reg	1 Du can h is ng with active. ng. al range. aned as ens.	1.83 HRS	5		
REPAIR D -Please get to tFound c occasion -Found c DPF code -SCO cod -Codes d -Checked -All emi -It is l the unit -Followe -Determi -Made qu -Brought	pr Issue PO M016402 go through the interact hrough service center ode ECU 3720.15 for DPF ally active. ode SCO 2173.09 is usua but is not always acti e is likely a separate id not come back for no snapshot info and did ssions related sensors ikely that DPF needs to has 5000 hours on it a d interactive solution. ned DPF needs to be sen ote to have DPF cleaned the unit in the shop	restriction along the solution of the solution	cted with as of active alogous DPF code is soak recording the norm oved and clessailed 6 reg	1 Du can h is ng with active. ng. al range. aned as ens.	1.83 HRS	6		
REPAIR D -Please get to tFound c occasion -Found c DPF code -SCO cod -Codes d -Checked -All emi -It is l the unit -Followe -Determi -Made qu -Brought -Removed	pr ISSUE PO M016402 go through the interact hrough service center ode ECU 3720.15 for DPF ally active. ode SCO 2173.09 is usua but is not always acti e is likely a separate id not come back for no snapshot info and did ssions related sensors ikely that DPF needs to has 5000 hours on it a d interactive solution. ned DPF needs to be sen ote to have DPF cleaned the unit in the shop the hood	restrice solution issue. a cold solution are with the removement has further than the cold is are with the cold in the cold i	cted with as of active aloo DPF code is soak recording the norm oved and clessailed 6 regular be cleaned	1 Du can h is ng with active. ng. al range. aned as ens.	1.83 HRS	5		
REPAIR D -Please get to tFound c occasion -Found c DPF code -SCO cod -Codes d -Checked -All emi -It is l the unit -Followe -Determi -Made qu -Brought -Removed	pr Issue PO M016402 go through the interact hrough service center	restrice solution issue. a cold solution are with the removement has further than the cold is are with the cold in the cold i	cted with as of active aloo DPF code is soak recording the norm oved and clessailed 6 regular be cleaned	1 Du can h is ng with active. ng. al range. aned as ens.	1.83 HRS			
REPAIR D -Please get to tFound c occasion -Found c DPF code -SCO cod -Codes d -Checked -All emi -It is l the unit -Followe -Determi -Made qu -Brought -Removed -Removed	pr Issue PO M016402 go through the interact hrough service center ode ECU 3720.15 for DPF ally active. ode SCO 2173.09 is usua but is not always acti e is likely a separate id not come back for no snapshot info and did ssions related sensors ikely that DPF needs to has 5000 hours on it a d interactive solution. ned DPF needs to be sen ote to have DPF cleaned the unit in the shop the hood all the hood support m	restriction of restriction of the removed in the re	cted with asing active along the code is sook recording the norm by the code and clessished 6 regression be cleaned than the code and clessished 6 regression be cleaned than the code and clessished 6 regression be cleaned than the code and clessished 6 regression be cleaned than the code and cleaned the cleaned than the cleaned than the cleaned that cleaned the cleaned than the cleaned that cleaned the cl	1 Du can h is ng with active. ng. al range. aned as ens.	1.83 HRS			
REPAIR D -Please get to t -Found c occasion -Found c DPF code -SCO cod -Codes d -Checked -All emi -It is l the unit -Followe -Determi -Made qu -Brought -Removed -Removed -Removed	pr Issue PO M016402 go through the interact hrough service center	restriction of restriction of the removed in the re	cted with asing active along the code is sook recording the norm by the code and clessished 6 regression be cleaned than the code and clessished 6 regression be cleaned than the code and clessished 6 regression be cleaned than the code and clessished 6 regression be cleaned than the code and cleaned the cleaned than the cleaned than the cleaned that cleaned the cleaned than the cleaned that cleaned the cl	1 Du can h is ng with active. ng. al range. aned as ens.	1.83 HRS	5		
REPAIR D -Please get to tFound c occasion -Found c DPF code -SCO cod -Codes d -Checked -All emi -It is l the unit -Followe -Determi -Made qu -Brought -Removed -Removed	pr Issue PO M016402 go through the interact hrough service center ode ECU 3720.15 for DPF ally active. ode SCO 2173.09 is usua but is not always acti e is likely a separate id not come back for no snapshot info and did ssions related sensors ikely that DPF needs to has 5000 hours on it a d interactive solution. ned DPF needs to be sen ote to have DPF cleaned the unit in the shop the hood all the hood support m	restriction of restriction of the removed in the re	cted with asing active along the code is sook recording the norm by the code and clessished 6 regression be cleaned than the code and clessished 6 regression be cleaned than the code and clessished 6 regression be cleaned than the code and clessished 6 regression be cleaned than the code and cleaned the cleaned than the cleaned than the cleaned that cleaned the cleaned than the cleaned that cleaned the cl	1 Du can h is ng with active. ng. al range. aned as ens.				

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,

SIGNATURE RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



West Edmonton

17104 - 118 Ave., Edmonton, AB, T5S 2L7 Tel: 780.452.2790 Fax: 780.451.2678 www.horizonagturf.com

	TN CMODE DICKUD	Branch						
	IN STORE PICKUP	EDMONTON Date	Time			Page		
:o								
Ship		11/28/24		00:54 (B)		02		
S		Account No.	Phone N	٥.	Invo	ice No.		
		INTER01			s7	4860		
		Ship Via		Purchase Ord	er			
::	INTERNAL CUSTOMER			MADE BY	DERE	K		
8	INTERNAL CUSTOMER							
Invoice	INTERNAL W/O AB T5S 2L7							
_				Sa	lespers	on		
					JES			
	SERVICE INVOICE							

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS 143532A JOHN DEERE 6130R 5050 1L06130RAFP829808 08/27/17 2000 6130R

- -Removed the DPF sensor cover
- -Removed the 2 after treatment sensors
- -Removed the DPF outlet sensor
- -installed lifting eyes on the hood support
- -Removed the hood support and exhaust with the crane
- -Marked the DPF
- -Removed all DPF clamps and removed the DPF
- -Sent the DPF out to get cleaned
- -Cleaned the DPF mating surfaces
- -Installed the DPF and lines up the marks
- -Tightened all DPF clamps
- -Picked up the DPF and hood support with the crane and set it into place
- -Connected the hood wiring harness
- -Installed all hood support mounting bolts
- -Had to install a new DPF sensor because the old one broke during removal
- -Connected the DPF sensor
- -Installed the sensor cover
- -Installed the exhaust inlet pipe
- -Installed the exhaust outlet pipe
- -Installed the exhaust shields
- -Installed the hood
- -Took the unit for a drive and checked for any codes
- -Performed a service regen and DPF differential pressure
- -Performed a DPF calibration
- -Checked for any leaks and none were found
- -Repair complete

L213282 Gasket

1 N 12.28 12.28 CONTINUED ON PAGE 03

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



West Edmonton

17104 - 118 Ave., Edmonton, AB, T5S 2L7 Tel: 780.452.2790 Fax: 780.451.2678 www.horizonagturf.com

Ship to:	IN STORE PICKUP
Invoice to:	INTERNAL CUSTOMER INTERNAL CUSTOMER INTERNAL W/O AB T5S 2L7

Branch					
EDMONTON					
Date	Time				Page
11/28/24		00:54	(B)		03
Account No.	Phone N	Phone No.			ice No.
INTER01				S74	4860
Ship Via		Purchase	e Order	•	
		MADE	BY D	ERE	K
	·	·	Sale	spers	on
				JES	

SERVICE INVOICE

STK#/FLEET# 143532A	JOHN DEERE 6130R	6130R	HRS 5050	PIN/EIN 1L06130RAFP82		ANTY DATE 08/27/17	HRS 2000
L218135			Gasket		2 N	28.20	56.40
RE546719			Pressure	e Sensor	1	214.92	214.92
R530552			Gasket		2	126.78	253.56
SUBLET			dpf clea	aning	1	600.00	600.00
						PARTS	537.16
						LABOR	2129.40
						SUBLET	600.00
	1600	1001			SEGMENT	TOTAL==>	3266.56

****** WORK ORDER TOTALS ******
INTERNAL CUSTOMER

PARTS 537.16
LABOR 2129.40
SUBLET 600.00
Shop Supplies 228.06
INTERNAL TOTAL 3494.62

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO