

LJ AUTOMOTIVE

415 W. SIERRA HWY,
PALMDALE CA 93550
661-267-0600

17408

07/11/25 09:22 am

Customer Name: [REDACTED]
Address: [REDACTED]
City: [REDACTED] State: [REDACTED] Zip: [REDACTED]
Year Make: [REDACTED] Model: [REDACTED] Vin Number: [REDACTED] License: [REDACTED] Mileage: [REDACTED]

Reference Info

Received Terms: BAR #: AE210460
88 Jeep CAMANCHE 1JTMW6611JT210169 5S81133 320012
Repair Instructions Labor Charge

ion	Price
1.0 GENERAL VAC MODULATOR V	89.98
1.0 566543 FAN SHROUD	94.43
1.0 GENERAL HEAD SET	94.43
1.0 GENERAL HEAD BOLTS	146.70
6.0 GENERAL SPARK PLUGS	159.00
6.0 5/30 OIL	159.00
2.0 GREEN COOLANT	11.78
1.0 GSEO OIL FILTER	5.79
1.0 432268 FC NW RADIATOR	20.41
1.0 B80400 Z HOSE	8.97
1.0 5030122 FC RM GEAR BOX	N/C
1.0 00000 P/S FLUID	N/C
1.0 3680 FAN ASSEMBLY	N/C
	348.87
	9.97
	148.97

Recommendations:
LUBE & OIL SERVICE

Total Parts: 1,153.13

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLES OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OF ANY OTHER CAUSE BEYOND OUR CONTROL.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

01	CHECK OVERHEATING CHECK HYDRO CARBON IN COOLING SYSTEM, HYDROCARBONS ARE VERY HIGH, THIS SHOWS HEAD GASKET LEAKING INTO COMBUSTION CHAMBER.,	0.00
02	CHECK EMISSIONS NEEDS FAN SHROUD... AS PER READ OUT WE HAVE CHECKED FOR VAC TO DISTRIBUTOR AND FOUND NO VACCUMM. REPLACE MODULATOR VALVE, THIS WILL CAUSE HIGH KNOX	120.00
03	REPLACE FAN SHROUD FAN SHROUD MISSING	120.00
04	R&R CYLINDER HEAD	1200.00
06	R&R RADIATOR ASSEMBLY WE HAVE FOUND RADIATOR IS RESTRICTED, LOWER PART OF RADIATOR IS COLD	N/C
07	R&R P/S GEAR BOX	420.00
08	REPLACE AUX FAN ASSEMBLY * HEAD WORK	0.00
		300.00

Quotes: 1 05/02 08:34am

240.00

Payments: 1 07/11/25 3438.83 MCard 09:22 am

Surcharge Total: 0.00

Total Labor: 1,860.00
Total Parts: 1,153.13
Haz Waste: 7.50
Shop Supplies: 0.00
Non Taxable: 0.00
Sub Total: 0.00
Tax: 118.20
Total Amount: 3438.83
Payment: 3438.83
Bal Due: .00