

Sladen D Markham, LLC

148 W Industrial Drive
Bldg A
Washington, UT 84780
tracey.sdm@gmail.com
435-319-9469



Invoice:

Date: **3/29/2022****Bill To**

Remit Payment To
Sladen D Markham, LLC
148 W Industrial Drive
Bldg A
Washington, UT 84780

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
34531	Due Upon Receipt	3/29/2022			Markham, Sladen	960F 4CL00265

Item	Description	Quantity	Rate	Amount
Drive to unit				
Labor	Drive to unit (Service Call); Special instructions caramel	mt	4.00000	\$125.00
	mt caramel - Jace Kirk			
Subtotal				\$500.00

Complaint: engine miss when warm. Customer wants new injectors and turbo.**Cause:** wear

Labor	Correction:	8.00000	\$125.00	\$1,000.00
	Engine / Camshaft / T/S engine miss. Removed failed turbo and found turbo shaft was broken. Removed valve cover to replace injectors and found # 6 exhaust valve is loose, measured valve stem and found valve or seal is failing. Visually inspected cam on # 6 and found lobe flaking off. Pull engine from machine and take back to shop. - Jace Kirk - 12/15/2021			
Subtotal				\$1,000.00

Complaint: R & I & Recon diesel engine.**Cause:** valve and cam failure, high hours.

(Inspection)

Labor	Correction:	24.00000	\$125.00	\$3,000.00
	Engine / Bottom End / Remove hood and side panels from machine, drain coolant and remove radiator assembly from machine. Unhook electrical, hoses and tubes from engine, pull engine out of machine and take back to shop. Steam clean engine for repairs to be completed. Clean grease, dirt and oil from frame before installing engine. Install engine into machine, tighten housing bolts and motor mounts, install new hoses for coolant system, install new belts for cooling system, a/c system and water pump.			

Item	Description	Quantity	Rate	Amount
	Install radiator assembly and hook up cooling hoses, hook up electrical and tighten down structure. Fill engine with oil and fill radiator with coolant, start machine and check for leaks, top off engine oil and coolant after machine gets to operating temp. Replace coolant temp-flow sensor and engine oil pressure sender. Install hood, air cleaner, exhaust and install side panels and doors. The machine would not move when put in any directional operation, found that trans hold switch was toggled, once switch is disengaged the machine now moves. - Jace Kirk - 12/15/2021			
Parts	nut	4.00000	\$9.2225	\$36.89
Parts	gasket	1.00000	\$12.0575	\$12.06
Parts	turbo	1.00000	\$1,954.868	\$1,954.87
Parts	gasket	1.00000	\$2.1175	\$2.12
Parts	gasket	1.00000	\$1.50	\$1.50
Parts	oring	1.00000	\$7.0525	\$7.05
Parts	oring	1.00000	\$3.4125	\$3.41
Parts	stud	4.00000	\$31.215	\$124.86
Parts	ring	2.00000	\$11.2875	\$22.58
Parts	hose	1.00000	\$85.55	\$85.55
Parts	oring	6.00000	\$11.445	\$68.67
Parts	oring	6.00000	\$6.265	\$37.59
Parts	rack	1.00000	\$749.5375	\$749.54
Parts	gasket	1.00000	\$56.7095	\$56.71
Parts	spring	1.00000	\$12.425	\$12.43
Parts	valve	1.00000	\$3.99	\$3.99
Parts	oring	1.00000	\$5.6175	\$5.62
Parts	filter	1.00000	\$28.785	\$28.79
Parts	filter	1.00000	\$40.1505	\$40.15
Parts	injector	6.00000	\$442.221	\$2,653.33
Parts	filter	1.00000	\$26.955	\$26.96
Parts	filter	1.00000	\$87.58	\$87.58
Parts	filter	1.00000	\$65.4985	\$65.50
Parts	Dirty Core for turbo	-1.00000	\$1,091.1125	-\$1,091.11
Parts	Inherent Core for turbo	1.00000	\$1,091.1125	\$1,091.11
Parts	Freight	1.00000	\$437.554	\$437.55
Parts	3116 reman	1.00000	\$18,351.336	\$18,351.34
Parts	Starter	1.00000	\$404.60	\$404.60
Parts	ORING	1.00000	\$19.515	\$19.52
Parts	HOSE	1.00000	\$1.54	\$1.54
Parts	CLAMP	6.00000	\$22.005	\$176.04
Parts	HOSE	60.00000	\$0.92	\$55.20

Item	Description	Quantity	Rate	Amount
Parts	HOSE	1.00000	\$1.26	\$1.26
Parts	CLAMP	4.00000	\$17.50	\$70.00
Parts	BELT	1.00000	\$93.5105	\$93.51
Parts	BELT	1.00000	\$48.7925	\$48.79
Parts	BELT	1.00000	\$23.835	\$23.84
Parts	HOSE	53.00000	\$1.54	\$81.62
Parts	HOSE	100.00000	\$1.26	\$126.00
Parts	KGLOVE	1.00000	\$15.30	\$15.30
Parts	bolt	2.00000	\$1.74	\$3.48
Parts	spacer	2.00000	\$28.575	\$57.15
Parts	ring	2.00000	\$11.9175	\$23.84
Subtotal				\$29,078.33

Complaint: t/s and repair CAT CMS panel

Cause: CMS panel

(Inspection)

Labor	Correction: Chassis / Instrument & Controls / Trouble shoot CMS panel and make sure panel is getting power before ordering new panel. Find used panel instead of purchasing new due to price. Install new CMS panel an install panel. CMS panel works correctly. - Jace Kirk - 12/15/2021	2.00000	\$125.00	\$250.00
Parts	CMS panel	1.00000	\$1,800.00	\$1,800.00
Parts	coolant sensor	1.00000	\$264.236	\$264.24
Parts	oil switch	1.00000	\$141.9115	\$141.91
Parts	seal	2.00000	\$1.8725	\$3.75
Parts	freight	1.00000	\$38.57	\$38.57
Subtotal				\$2,498.47

Complaint: hydraulic stalling

Cause: adjust hydraulic pressures

(Inspection)

Labor	Correction: Hydraulic System / Hydraulic Valve / Set hydraulic reliefs, get machine to operating temp, stall out hydraulics and set line relief to 3200psi and main relief to 3000psi. Machine hydraulic power work good, can only get machine to stall when engine is at an idle and you load the hydraulics real heavy, install covers and panels. - Jace Kirk - 12/15/2021	5.00000	\$125.00	\$625.00
Subtotal				\$625.00

Return from unit

Item	Description	Quantity	Rate	Amount
Labor	Return from unit; Special instructions / Location rules: lamb gravel pit, mt caramel mt caramel - Jace Kirk	4.00000	\$125.00	\$500.00
			Subtotal	\$500.00

Unit: 960F 4CL00268 VIN: 4CL00268

CAT 960F

Chassis: 13,100 Miles

Engine: 13,100 Hours

Labor \$5,875.00

Parts \$28,326.80

Shop Supplies \$29.38

Pre Tax Total \$34,231.18

Washington, UT (6.7500% of \$34,231.18) \$2,310.60

Total \$36,541.78

Payments & Credits \$36,541.78

Balance Due \$0.00

****** The service and operational fee, billed as a percentage of labor costs, helps us cover the daily non-billable items, such as specialized tooling, technology, waste disposal and shop supplies. By factoring these expenses into a standard fee, we are able to keep our labor rates competitive. ******

Any warranties on the parts and accessories sold hereby are made by the manufacturer. Customer understands and agrees that Sladen D Markham, LLC makes no warranties of any kind unless expressed in writing. Customer agrees that Sladen D Markham, LLC will not be responsible for towing charges, substitute transportation, lodging, lost profits, sales or income due to delays caused by the unavailability of parts or delays in parts shipments by the supplier or transporter.

Payment Terms: All charges are due and payable at time of service unless you have set up and received written approval for a Net 30 credit account with us. An active form of payment must be on file for all credit accounts.

Overdue balances will accrue a finance charge at the rate of 1.5% per month (an Annual Percentage Rate of 18%) on any unpaid portion past the due date. In the event of non-payment, the client agrees to pay all reasonable collection costs and legal fees incurred in Washington County courts if necessary to recover outstanding debts.