

RCH Heavy Truck and Mechanical Ltd.

P.O. Box 128
 Hanley SK S0G 2E0
 rchsask@gmail.com
 GST/HST Registration No.:
 PST SK Registration No.:

INVOICE

BILL TO _____ SHIP TO _____ INVOICE DATE _____
 TERMS _____ DUE DATE _____


DATE	ACTIVITY	DESCRIPTION	TAX	QTY	RATE	AMOUNT
	B2 N1456 Release Bearing W/ Collar	B2 N1456 Release Bearing W/ Collar	GST/PST SK	1	250.00	250.00
	Labor	Labor- Chevrolet C60, Yellow, Plate 684 BSH, ODO 49594, VIN CCE615V164795	GST/PST SK	6	140.00	840.00
	Shop Supplies	Shop Supplies, Freight, Tooling	GST/PST SK	1	92.00	92.00

Terms: Due and payable upon receipt of invoice. Charging 3% on all credit card purchases and payments.
 Remove cables, wiring, PTO Shaft, driveshaft, shifter and inspection plate, remove transmission, replace release bearing, reinstall transmission and all components, removed, checked fluid level, adjusted clutch, test drive.

SUBTOTAL	1,182.00
GST @ 5%	59.10
PST (SK) @ 6%	70.92
TOTAL	1,312.02
<hr/>	
BALANCE DUE	\$1,312.02

TAX SUMMARY

	RATE	TAX	NET
GST @ 5%		59.10	1,182.00
PST (SK) @ 6%		70.92	1,182.00



Thall's Service Centre (1988) Ltd.
 Box 333, 607 Lincoln Avenue
 Hanley, Sask. S0G2E0
 Phone: 306-544-2512 Fax: 306-544-2909

INVOICE

INVOICE

Printed Date: 05/12/2026 Work Completed: 05/12/2026

1975 Chevrolet - C60 -

Lic # :

Odometer In : 49594

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
BOOSTER B9 X2512065	1.00	721.55	721.55	BRAKE BOOSTER - replace hydroboost - bleed brakes	3.88	496.00
FREIGHT FREIGHT	1.00	65.00	65.00			
BRAKE FLUID 1L - KLEENFLO Size: 1L 528 Shop Supplies	1.50	14.95	22.43			
			39.68			
Taxes						
GST						67.23
PST						76.78

Org. Estimate 1,488.67 Revisions 0.00 Current Estimate 1,488.67

Labor:	496.00
Parts:	848.66
SubTotal:	1,344.66
Tax:	144.01
Total:	1,488.67
Bal Due:	\$1,488.67

[Payments -]

Vehicle Received: 5/12/2026

Customer Number

All Parts removed will be discarded unless instructed otherwise: Save all Parts_____.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. WHEELS MUST BE RE-TORQUED AFTER 100KMS.
 THALL'S SERVICE IS NOT RESPONSIBLE IF A WHEEL COMES LOOSE OR IF YOU LOSE A WHEEL. WE WILL NOT BE RESPONSIBLE FOR ANY LOST HUB CAPS OR CENTER CAPS.

LAND DESCRIPTION SEC.____TWSP____R____M____

I HEREBY CERTIFY THE GOODS LISTED ON THIS INVOICE WILL BE USED SOLELY IN THE OPERATIONS OF MY FARM.

Signature _____ Date _____

Email Address: thalls@sasktel.net