

Box 1000 • Highway #13 West Weyburn, SK S4H 2L2 Phone: 306-842-2629 • Fax: 306-842-1650 www.youngs.ca



Regina 306-565-2405 Assiniboia 306-642-5991 Chamberlain 306-638-4516 Davidson 306-567-3074 Moose Jaw 306-694-1800 306-746-2288 Raymore Watmus 306-946-3387

Ship To:

Invoice To:			

	***	I IQUI IOI SC	300-224-2110
Branch WEYBURN			
Date	Time		Page
08/05/22	11:12:34	(0)	03
Account #	Phone #		v #
Ship Via	Purchase	Order #	
Tax ID #			
	1		
		Salesper	'son
		50	7

SERVICE PRELIMINARY STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS UP1304 HC Sprayer 1697 YGT043402 04/14/18 CB 4440 04/14/19 EB must have been cracked upon removal or install as it wasn't leaking when it came in. removed housing and installed a new housing. EHCFILT1 EHC CHARGE 2 .50 1.00 5801439820 FILTER, FUEL 102.00 1 102.00 84348882 CARTRIDGE, FUEL 1 39.11 39.11 PARTS 142.11 LABOR 105.40 11001005 SEGMENT TOTAL ==> 247.51 SEGMENT# 5 5 44005 NA 07/12/22 07/12/22 TRUCK UNIT TO SHOP SEMILOADED Semi 35 7.50 262.50 (Hauling Loaded) **PARTS** 262.50 11001005 SEGMENT TOTAL ==> 262.50

***** WORK ORDER TOTALS ***** PARTS 6110.74 LABOR 3803.70 shop supplies 200.00 SUB TOTAL ==> 10114.44 GST 5% 505.77 CUSTOMER TOTAL 10620.21

tioning a reported by a terropress own hose.
An expression of the report of the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice, Interest will be changed at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point

rates are for the items specifically identified in the estimate only, and are non-binding



Authorized By



^{*} I hereby authorize the above repair work to be completed, including any necessary materia's, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as we'll as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delevering arm york. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to cold-son, fire theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young



Box 1000 • Highway #13 West Weyburn, SK S4H 2L2 Phone: 306-842-2629 • Fax: 306-842-1650 www.youngs.ca



Regina 306-565-2405 Assinibola 306-642-5991 Chamberlain 306-638-4516 Davidson 306-567-3074 Moose Jaw 306-694-1800 Raymore 306-746-2288 306-946-3387 Watrous Windthorst 306-224-2110

Ship To:

Invoice	e To:			

Branch WEYBURN		19.50		W
Date	Time		Page	
08/05/22	11:12:34	(0)	02	
Account #	Phone #	Ir	ıv#	
Ship Via	Purchase	Order #		
Tax ID #				Ī
		Salespe 5 (

SERVICE PRELIMINARY STK#/FLEET# PIN/BIN WARRANTY DATE HRS HRS 04/14/18 **UP1304** 1697 YGT043402 CB HC Sprayer 04/14/19 4440 EB SEGMENT# 2 5 44005 QC 07/12/22 Young's Complimentary QuickCheck Inspection .15 .15 HRS 1. Young's Complimentary QuickCheck Inspection 0.15 (QC) Perform complimentary QuickCheck Inspection Only items identified have been inspected. ===== Quantity x1===== 0.15 SEGMENT# 3 5 44005 SV 07/12/22 07/12/22 SERVICE CALL 110.40 Service Call 1.60 SV (Vehicle Fee) 110.40 PARTS LABOR 155.00 265.40 SEGMENT TOTAL ==> 11001005

SEGMENT# 4 5 44005 NA

07/12/22 07/12/22

CHANGE BOTH FUEL FILTERS

CORRECTION:

changed both fuel filters. when starting sprayer we found a leak coming from the fuel filter on the side of the engine. found it to be coming from the housing. there to be a crack in the side of the housing. housing

CONTINUED ON PAGE 03

 I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other changes as may be applicable. Young's Equipment Inc., it
employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing
Inspecting, repairing, and/or detreting at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or as contents, whether due to
coloron, fire, their, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released
from are and all risking factors and for stomage and a sixed by the perimeter of Young's Foundation.

ment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by

Use is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice, interest will be charged rish (24% per annum). Young's Equipment inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point

have been paid. are for the items specifically identified in the estimate only, and are nor

X

Authorized By





Box 1000 • Highway #13 West Weyburn, SK S4H 2L2 Phone: 306-842-2629 • Fax: 306-842-1650 www.youngs.ca



306-565-2405 Regina 306-642-5991 Assinibola 306-638-4516 Chamberlain 306-567-3074 Davidson 306-694-1800 Moose Jaw 306-746-2288 Raymore 306-946-3387 Watrous 306-224-2110 Windthorst

Ship To:

		K	
Invoice	To:		

WEYBURN				Page
08/05/22	Time 11:	12:34 (01
Account #	Phone #		Inv	#
Ship Via		Purchase O	rder #	
Tax ID #				
			Salespers 507	

SERVICE PRELIMINARY

STK#/FLEET# UP1304	HC Sprayer	HRS PIN/EIN WARRANTY DATE HRS 1697 YGT043402 04/14/18 04/14/19	CB
***** UNIT	DESCRIPTION	*************	
		HC Sprayer	

SEGMENT# 1 5 44005 NA COOLANT LEAKING BADLY 07/12/22 07/12/22

CORRECTION:

Travel out to customer's yard to diagnose coolant leak. put 1 jug of coolant into reservoir. started and found the leak to be coming right out of the rad. sprayer got brought into the shop. drained coolant out. removed coolant reservoir. removed air to air lines. removed front hood. removed grill covers. removed fan. removed installed new rad. installed fan shroud. removed rad. fan shroud. installed fan. installed rad hoses. installed air to air hoses. installed coolant reservoir. filled system with coolant. started and checked for leaks. no leaks found.

BN302681 EHC10L FRTCP S1020-BA	SEAL ENVIRO CHARGE hex nipple OT COOLANT9.46L	2 M 6 2 1 6	97.01 1.90 225.00 4.53 50.17	
76971NXYCA 86625234 87266225	1/4" DRAIN COCK RADIATOR	1 O RETAIL 1 N	7.02 4721.60 4627.74 PARTS	
11001005			LABOR TOTAL==> INUED ON PAGI	E 02

5595.73 3543.30 9139.03

ees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate sals vehicle, for the purposes of testing, diagnoring, not assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate sals vehicle, for the purposes of testing, diagnoring, not personally the purpose of testing, diagnoring, not personally the purpose of testing, diagnoring, not personally the purpose of the pu

a squamers and a temporal statements.

The squamers are cannot recent of those some above noted equipment to secure the amount of repairs thereto. Terms are cannot recent of those sinterest will be charged press methanks then a acknowledged on the above noted equipment includes the right, as a solid repairs the release and/or delivery of equipment and in account of the release and/or delivery of equipment and in account of the release and/or delivery of equipment and in account of the release and/or delivery of equipment and in account of the release and/or delivery of equipment and in account of the release and/or delivery of equipment and in account of the release and/or delivery of equipment and in account of the release and/or delivery of equipment and in account of the release and/or delivery of equipment and in account of the release and/or delivery of equipment and account of the release and/or delivery of equipment and account of the release and/or delivery of equipment and account of the release and/or delivery of equipment and account of the release and/or delivery or account of the relative or account of the rel

Authorized By

Thank You! We Appreciate Your Business

194.02

450.00

301.02

4627.74

11.40

4.53

7.02