





Page

SAMEORE

Box 89, Paradise Hill, SK SOM 2G0 • www.novlanbros.com GST# 10980 4724 RT0001

Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433

SO # 123459

Printed

SERVICE ORDER



RDS

1 **Customer No** Priority

11/27/2025 9:49:55 AM

INTERNAL COPY Advisor Ryan Singer **Promised** Shop S3 Opened

01/10/2025 5:00 PM Tag# 01/10/2025 2:03 PM Location PO# 02/18/2025 2:31 PM

User

PRINT

Bus (306) 344-4448 Home Cell Today Email

Odom In **Odom Out** In Service Date Stock No License C2463B 943 943 06/07/2021 **Model Number** Color Model Year Make **NEW HOLLAND** CR10.90Z CR10.90Z 2021 Selling Dealer **Extended Warranty Delivery Date** Vehicle ID No 06/30/2025 7N2045009 NOVLAN BROS. Engine Fleet#

Cashiered

Term Cash **CSR** Job **Status** Description Request RDS CHECKOVER Original AG MISC Type Tech Amount Description Labor IAG **HDS** 2,028.00 **CHECKOVER** AG MISC Price **Amount** Description Shp Bin Type Part 267.03 KL001 267.03 SG4PACK KIT 1 20.00 1 20.00 P FREIGHT sg4pack 107.76 107.76 1 NHRTN 51433723 **DECAL** MN081 69.87 69.87 47693920 **DECAL** **08** SHAFT 900.30 900.30 48125077 1 P FREIGHT 48125077,48008688 1 165.00 165.00 443898 BEARING BALL 2 KE143 25.72 51.44 4 **BOLT22** 0.44 1.76 M12FN HEXFLNGNUT **SPACER** 4 MB052 27.40 109.60 9500969 4 BOLT22 2.36 9.44 M12X60 12MM BOLT 1 6.50 6.50 ESO 122123 ep2 grease S/R 1 KM037 80.54 80.54 86570754 CAP 575.32 575.32 1 48008688 SHIELD 7.05 5 FD04B 35.25 **BOLT SHEAR** 246309 10MM LOCK 5 BOLT21 1.14 5.70 M10LN 2,405.51 Technician HDS -Parts Total Labor Total 2,028.00 Request Total 4,433.51

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST, ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$	BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE
ACCOMPANYING WORK ORDER.	













Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433

SO # 123459

SERVICE ORDER INTERNAL COPY

Odom In

943

Page

PRINT

RDS

Customer No

11/27/2025 9:49:55 AM

Ryan Singer Advisor Shop **Priority**

Make

01/10/2025 5:00 PM Tag# 01/10/2025 2:03 PM Location 02/18/2025 2:31 PM PO #

User

Stock No

Home Cell Email

Printed

(306) 344-4448 Bus Today

NEW HOLLAND 2021 Vehicle ID No

License

Year

Model CR10.90Z Selling Dealer

Promised

Cashiered

Odom Out

Opened

06/07/2021 **Model Number** CR10.90Z **Extended Warranty**

In Service Date

Delivery Date 06/30/2025

C2463B

Color

Term Cash

7N2045009 **Engine**

NOVLAN BROS.

943

Fleet#

ENG HOURS: 943 Correction

THRESH HOURS: 662 USED SERVICE TRUCK TO BOOST COMBINE

MOVE 1 HOUR TO CHECK ACTIVE SPREADER ERROR FOR DIAGNOSTICS MOVE 1 HOUR TO YARD JOB FOR FIXING MULTIPLE LEAKS IN WASHBAY

EQUIPMENT

CLEARED PCM BACKUP BATTERY CODES AFTER CHARGING BATTERY

REPLACED MISSING HITCH **INSTALLED CONCAVES**

ADJUSTED CONCAVE CLEARANCE CALIBRATED CONCAVE OPENING ADJUST CONCAVE STOP POINT INSTALLED CONCAVE EXTENSIONS

REMOVED BROKEN LATCH AND CLIP FROM RIGHT SIDE ACCESS DOOR

INSTALLED NEW LATCH AND CLIP

LATCH DID NOT LINE UP FROM BENT PANELS

LOOSENED PANEL MOUNTS AND RETIGHTENED IN POSITION THAT LINE

LATCH UP WITH CLIP

REMOVED PANELS ON BOTH SIDES OF FEEDERHOUSE

STRAIGHTENED BENDS OUT OF PANELS

CHECKED FOR PROPER FITMENT

ADJUSTED BELT TENSIONS AS NEEDED

GREASED ALL GREASE POINTS

CHARGED BATTERIES BACK TO FULL

MOVE 2 HOURS FOR DECAL REPLACEMENT

PEELED OLD DECAL OFF OF RIGHT REAR PANEL

CLEANED DECALAREA

INSTALLED NEW DECAL TO RIGHT REAR PANEL

TIGHTENED LOOSE LEAKING PLUG ON VALVE BLOCK UNDER HOPPER

AND CLEANED AREA

CLEANED CLEAN GRAIN SENSOR AND CAMERA

CHECKED ALL FLUID LEVELS

TOPPED UP TRANSMISSION OIL AFTER RUNNING COMBINE

TOPPED UP ENGINE GEARBOX OIL

REMOVED CHOPPER KNIFE DRIVE BELT COVER

UNSEIZED AND REMOVED CHOPPER KNIFE ENGAGEMENT SPROCKET

CLEANED SPLINES OF CHAFT AND ENGAGEMENT SPROCKET

INSTALLED CHOPPER KNIFE ENGAGEMENT SPROCKET

TIGHTENED CLEAN GRAIN ELEVATOR CHAIN

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$	_ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE
ACCOMPANYING WORK ORDER.	







Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433



SO # 123459

Printed

Home

Email

Cell

ALEORD

SERVICE ORDER INTERNAL COPY

PRINT

RDS

Location

Tag#

PO#

1 **Customer No**

11/27/2025 9:49:55 AM

User Advisor Ryan Singer Promised 01/10/2025 5:00 PM 01/10/2025 2:03 PM Opened Shop 02/18/2025 2:31 PM Priority Cashiered

Stock No **Odom Out** In Service Date License Odom in C2463B 06/07/2021 943 Color Model Number Make Model CR10.90Z NEW HOLLAND CR10.90Z **Delivery Date** Vehicle ID No Selling Dealer **Extended Warranty** 06/30/2025 7N2045009 NOVLAN BROS.

Fleet #

Term Cash

CHECKED FOR UPDATED REAR BEARINGS

CHECKED LUG TORQUE SET TIRE PRESSURES

Bus

Today

BROUGHT IN PICKUP HEADER FOR CHECKOVER

(306) 344-4448

TIGHTENED HEADER AUGER DRIVE CHAIN LUBRICATED HEADER AUGER DRIVE CHAIN

HEADER MARKER LIGHT HARNESSES WERE LOOSE AND DANGLING

TUCKED MARKER LIGHT HARNESSES INTO SAFE LOCATION AND SECURE

Year

2021

Engine

WITH ZIP TIES

DRAPER BELT ADJUSTMENT HARDWARE WAS LOOSE WHEN HEADER

WAS BROUGHT IN

TIGHTENED DRAPER BELTS

TIGHTENED PICKER BELTS

TINE BAR WOULD NOT GO UP

BLED TINE BAR HYDRAULIC CYLINDERS

TINE BAR MOVED BUT ONLY IF BUTTON WAS PULSED

REMOVED TINE BAR HYDRAULIC CYLINDERS LINES TO FURTHER

INSPECT

SUSPECTED DIRT WAS CLOGGING LEFT CYLINDER

FLUSHED CYLINDER WITH AIR GUN

REPLACED CUT O-RINGS FOR HYDRAULIC LINES

CONNECTED HYDRAULIC LINES AND RE TESTED

TINE BAR WAS MOVING BUT SLUGGISHLY

REMOVED HYDRAULIC LINES

REMOVED TOP CYLINDER PIN

BACKFLUSHED CYLINDER WITH AIR GUN

CHECKED CYLINDER ROD WAS MOVING SMOOTHLY BY HAND

INSTALLED TOP CYLINDER PIN CONNECTED HYDRAULIC LINES

TINE BAR FUNCTIONED PROPERLY

HAMMERED BENT AUGER FLIGHTING ENDS STRAIGHT

TOPPED UP HYDRAULIC OIL TANK

REMOVED BENT SHIELDING FROM RIGHT SIDE OF FEEDERHOUSE

Request	Description	Job	CSR	Status
AG MISC	REMOVE FEEDERHOUSE	2	RDS	Approved
Labor	Description	Type	Tech	Amount
Labor	Description	ιλhα	16011	Amount

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM. WHICHEVER OCCURS FIRST, ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$	_ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE
ACCOMPANYING WORK ORDER.	














Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433

SO # 123459

Printed

SERVICE ORDER

Ryan Singer

\$3

Advisor

Shop

Priority

License

Customer No

11/27/2025 9:49:55 AM

INTERNAL COPY

Promised

Cashiered

Odom Out

943

Opened

Tag# 01/10/2025 5:00 PM Location 01/10/2025 2:03 PM PO# 02/18/2025 2:31 PM

User

PRINT

(306) 344-4448 Bus Home Today Cell

Year Make Model 2021 NEW HOLLAND CR10.90Z Vehicle ID No

943

Model Number CR10.90Z **Extended Warranty**

In Service Date

06/07/2021

Stock No C2463B Color

Email

Selling Dealer NOVLAN BROS. 7N2045009

Odom In

Delivery Date 06/30/2025

RDS

Fleet#

Engine

Term Cash Price Amount Bin Type Shp Description Part 150.00 150.00 WASHERS, BOLT 1 P FREIGHT 237.69 237.69 ME137 1 BUSHING SPLINED 87586665 2.58 5.16 2 **NEW 02 BOLT** 129796A1 2.28 1.14 2 FD05H LOCKNUT 100037 1.45 5.80 WASHER SEALING 4 84439102 MD092 269.46 269.46 SENSOR 51546555 7.22 7.22 1 **BACK** 3/16 Drill Bit 01A012 0.65 6.50 10 **SEAL** 4858606 15.00 15.00 4858606 P FREIGHT 699.11 Parts Total Technician HDS -507.00 Labor Total Cause REMOVE FEEDERHOUSE 1,206.11 Request Total

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$	BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND TH
ACCOMPANYING WORK ORDER.	







Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433



SO # 123459

SAMEORID

SERVICE ORDER INTERNAL COPY

11/27/2025 9:49:55 AM

Ryan Singer

S3

Make

User

RDS

Page

Customer No

Advisor

Promised

Odom In

943

01/10/2025 5:00 PM 01/10/2025 2:03 PM

Tag# Location PRINT

Printed

Shop **Priority**

Opened Cashiered

02/18/2025 2:31 PM PO#

Home

(306) 344-4448 Bus

Year 2021

Engine

License

943 Model

In Service Date 06/07/2021 **Model Number** Stock No C2463B Color

Cell Email

Correction

Today

Vehicle ID No 7N2045009

NEW HOLLAND CR10.90Z Selling Dealer NOVLAN BROS.

Odom Out

CR10.90Z **Extended Warranty**

Fleet #

Delivery Date 06/30/2025

Term Cash

REMOVED FEEDERHOUSE SIDE PANELS

REMOVED FEEDER DRIVE CHAIN COVER

REMOVED FEEDERHOUSE DRIVE BELT COVER REMOVED FEEDERHOUSE DRIVE BELT TENSIONER

REMOVED FEEDERHOUSE DRIVE BELT IDLER PULLEY

REMOVED FEEDERHOUSE DRIVE BELT

DISCONNECTED HYDRAULIC COUPLERS DISCONNECTED ELECTRICAL CONNECTORS

DISCONNECTED HEADER HEIGHT SENSOR ARM

DISCONNECTED CHAIN SPRINGS FROM FRONT STONE TRAP DOOR

REMOVED LOCK BOLTS FROM FEEDER HINGE BLOCK PINS

SUPPORTED FEEDERHOUSE WITH FORKLIFT

REMOVED LOCK BOLTS FROM FEEDERHOUSE HYDRAULIC RAM PINS

REMOVED FEEDERHOUSE HYDRAULIC RAM PINS

REMOVED FEEDERHOUSE HINGE BLOCKS AND PINS REMOVED FEEDERHOUSE AND SET ON JACKSTAND

CLEANED FEEDERHOUSE HINGE POINT

CLEANED FEEDERHOUSE HINGE BLOCK APPLIED GREASE TO ALL HINGE SURFACES

INSTALLED FEEDERHOUSE

INSTALLED FEEDERHOUSE HINGE BLOCKS AND PINS

INSTALLED FEEDERHOUSE HYDRAULIC RAM PINS

INSTALLED LOCK BOLTS TO HYDRAULIC RAM PINS

REMOVED FORKLIFT

INSTALLED LOCK BOLTS TO HINGE PINS

CONNECTED CHAIN SPRINGS TO FRONT STONE TRAP DOOR

CONNECTED HEADER HEIGHT SENSOR ARM

CONNECTED ELECTRICAL CONNNECTORS

CONNECTED HYDRAULIC COUPLERS

INSTALLED FEEDERHOUSE DRIVE BELT

INSTALLED FEEDERHOUSE DRIVE BELT IDLER PULLEY

INSTALLED FEEDERHOUSE DRIVE BELT TENSIONER

INSTALLED FEEDERHOUSE DRIVE BELT COVER

INSTALLED FEEDERHOUSE DRIVE CHAIN COVER INSTALLED DFR BELT COVER

Request AG MISC Description

REPAIR HYDRAULIC LEAKS

Job

CSR

Status RDS Approved

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

ASK US IF YOU WOULD LIKE INFORMATION ABOUT OUR PRIVACY POLICY, INCLUDING OUR SERVICE PROVIDERS AND THEIR DATA PROCESSING IN THE U.S., WHICH MAY BE ACCESSIBLE TO U.S. LAW ENFORCEMENT AND NATIONAL SECURITY AUTHORITIES. WE PROVIDE THIS PERSONAL AND TRANSACTION INFORMATION TO FORD MOTOR COMPANY OF CANADA, LIMITED TO ENABLE FORD TO ADMINISTER YOUR TRANSACTION, PROVIDE YOU WITH REQUESTED SERVICES, IMPROVE AUTOMOTIVE RELATED PRODUCTS AND SERVICES BY CONDUCTING CUSTOMER SURVEYS, AND PROVIDE YOU WITH MARKETING MATERIAL WHICH MAY BE OF INTEREST TO YOU, AS PERMITTED BY APPLICABLE LAWS. FOR THE FORD PRIVACY POLICY (WWW.FORD.CA) INCLUDING USE OF SERVICE PROVIDERS AND U.S. DATA STORAGE OR IF YOU DO NOT WANT TO RECEIVE MARKETING OR SURVEY MATERIALS FROM FORD PLEASE CALL 1-800-565-FORD (3673).

BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$ ACCOMPANYING WORK ORDER.











Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433



SO # 123459

Printed

SERVICE ORDER

Customer No

11/27/2025 9:49:55 AM

INTERNAL COPY

01/10/2025 5:00 PM Tag#

In Service Date

PRINT

Advisor Ryan Singer Promised Opened Shop **S3** Cashiered **Priority**

01/10/2025 2:03 PM Location 02/18/2025 2:31 PM

User

(306) 344-4448 Bus Home Today Cell

943 Year Make Model 2021 NEW HOLLAND CR10.90Z 06/07/2021 **Model Number** CR10.90Z

Odom Out

943

Stock No C2463B Color

Email

Vehicle ID No Selling Dealer NOVLAN BROS. 7N2045009

Odom In

Extended Warranty Delivery Date 06/30/2025

RDS

Engine

License

Fleet #

Term Cash Type Tech Amount Description Labor IAG **HDS** 4,056.00 REPAIR HYDRAULIC LEAKS AG MISC Price Amount Description Shp Bin Type **Part** 2.10 5 **BOARDO** 0.42 **O-RING** 014 787.11 787.11 COUPLING 1 NP125 84231982 154.38 463.14 3 CSC07 73344274 OIL HYDRAULIC MasterTran 3.60 10.80 oil 20L container EHC7 CSD05 278.20 278.20 OIL TRANSMISSION 73344277 3.60 3.60 oil 20L container EHC7 247.63 247.63 KIT SEALS 51200084 25.00 25.00 seal kit P FREIGHT 1,817.58 Parts Total Technician HDS -Labor Total 4.056.00 Request Total 5,873.58

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$	BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE
ACCOMPANYING WORK ORDER.	







Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433

SO # 123459

SERVICE ORDER

INTERNAL COPY

User

RDS

Page

Customer No

Printed

Ryan Singer Promised

01/10/2025 5:00 PM 01/10/2025 2:03 PM

Tag# Location **PRINT**

Advisor Shop **Priority**

Opened Cashiered

02/18/2025 2:31 PM PO #

Stock No

Home Cell Email

Correction

Bus (306) 344-4448 Today

Year 2021

Engine

License

943 Make Model **NEW HOLLAND CR10.90Z**

Odom In

Selling Dealer

943

Odom Out

In Service Date 06/07/2021 **Model Number** CR10.90Z

C2463B Color

Vehicle ID No 7N2045009

S3

NOVLAN BROS.

Extended Warranty

Fleet#

Delivery Date 06/30/2025

11/27/2025 9:49:55 AM

Term Cash

-- ROTOR GEARBOX SHIFTER PLATE LEAK --

REMOVED PANEL ABOVE SIEVES

REMOVED ROTOR GEARBOX SHIFT LINKAGE REMOVED ROTOR GEARBOX SHIFT ARM PLATE CLEANED OLD SILICONE OFF OF MATING SURFACES

LAID NEW SILICONE ON MATING SURFACES INSTALLED ROTOR GEARBOX SHIFT ARM PLATE INSTALLED ROTOR GEARBOX SHIFT ARM LINKAGE

INSTALLED PANEL ABOVE SIEVES

-- ROTOR VARIATOR PISTON SEAL LEAK --REMOVED GRAIN ELEVATOR DRIVE BELT RELEASED TENSION FROM VARIATOR BELT REMOVED VARIATOR BRIDGE

REMOVED ROTATING UNION HYDRAULIC LINE

REMOVED VARIATOR PISTON AND BEARING ASSEMBLY REMOVED 90 DEGREE FITTING FROM ROTATING UNION

REMOVED ROTATING UNION REMOVED VARIATOR PISTON NOTICED PLAY IN BEARING

PRESSED PISTON HOUSING OUT OF BEARING

SPLIT BEARING ARM REMOVED BEARING

CLEANED ALL MATING SURFACES

INSTALLED NEW BEARING

PRESSED PISTON HOUSING INTO BEARING

INSTALLED NEW ROTATING UNION REMOVED OLD PISTON SEALS CLEANED INSIDE HOUSING INSTALLED NEW PISTON SEALS

INSTALLED PISTON

INSTALLED PISTON AND BEARING ASSEMBLY TO VARIATOR

INSTALLED VARIATOR BRIDGE

INSTALLED 90 DEGREE FITTING TO ROTATING UNION

INSTALLED ROTATING UNION HYDRAULIC LINE

-- TRANSMISSION LEAK --

DRAINED TRANSMISSION OIL

REMOVED RIGHT SIDE DRIVESHAFT FROM TRANSMISSION

REMOVED LEFT SIDE DRIVESHAFT FROM COMINE. SPLINES ON INSIDE

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$	BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE
ACCOMPANYING WORK ORDER	







Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433

SO # 123459

SYNUHOLDING

SERVICE ORDER

11/27/2025 9:49:55 AM

INTERNAL COPY

User

RDS

Page

Customer No

Printed

Advisor Ryan Singer Shop **S**3

Promised Opened

Odom Out

01/10/2025 5:00 PM Tag# 01/10/2025 2:03 PM Location PRINT

Priority

Cashiered

02/18/2025 2:31 PM PO#

Home

(306) 344-4448 Bus

Year Make 2021

Engine

License

943 Model NEW HOLLAND CR10.90Z

Odom In

943 06/07/2021 **Model Number** CR10.90Z

C2463B Color

Stock No

Cell Email Today

Vehicle ID No 7N2045009

Selling Dealer NOVLAN BROS. **Extended Warranty**

Fleet#

In Service Date

Delivery Date 06/30/2025

Term Cash

END OF SHAFT WORN OUT

REMOVED HYDRAULIC MOTOR FROM TRANSMISSION AND SUPPORTED

WITH RATCHET STRAP AND JACKSTAND

DISCONNECTED ALL ELECTRICAL CONNECTORS ON TRANSMISSION

DISCONNECTED ALL HYDRAULIC LINES SUPPORTED TRANSMISSION WITH JACK

REMOVED TRANSMISSION MOUNT BOLTS REMOVED TRANSMISSION

CLEANED TRANSMISSION

REMOVED SPEED SENSOR

REMOVED SHIFT MOTOR

REMOVED RIGHT SIDE BRAKE ASSEMBLY

REMOVED LEFT SIDE BRAKE ASSEMBLY

REMOVED TOP COVER

SUPPORTED DIFFERENTIAL WITH ROPE ON FORKLIFT

REMOVED RIGHT SIDE MOUNTING ARM

REMOVED LEFT SIDE MOUNTING ARM

CLEANED MATING SURFACES FOR MOUNTING ARMS

LAID BEAD OF 515 ON LEFT SIDE OF TRANSMISSION HOUSING

INSTALLED LEFT SIDE MOUNTING ARM

INSTALLED DIFFERENTIAL

LAID BEAD OF 515 ON RIGHT SIDE OF TRANSMISSION HOUSING

INSTALLED RIGHT SIDE MOUNTING ARM

TORQUED ALL MOUNTING ARM HARDWARE TO 250 FT-LBS

CLEANED MATING SURFACES FOR BRAKES TO MOUNTING ARMS

LAID BEAD OF 515 ON RIGHT SIDE MOUNTING ARM

INSTALLED RIGHT SIDE BRAKE

LAID BEAD OF 515 ON LEFT SIDE MOUNTING ARM

INSTALLED LEFT SIDE BRAKE

TORQUED BRAKE BOLTS TO 85 FT-LBS

CLEANED MATING SURFACES FOR TOP COVER

LAID BEAD OF 515 ON TOP OF TRANSMISSION HOUSING

INSTALLED TOP COVER

TORQUED TOP COVER BOLTS TO 50 FT-LBS

REPOSITIONED TRANSMISSION ON JACK

INSTALLED SHIFT MOTOR

ORIGINAL OUTPUT SPEED SENSOR CRACKED ON INSTALLATION

REMOVED BROKEN SPEED SENSOR

INSTALLED NEW SPEED SENSOR

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$	BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE
ACCOMPANYING WORK ORDER.	







Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433



SO # 123459

Symbold

SERVICE ORDER

Printed

11/27/2025 9:49:55 AM

INTERNAL COPY

Odom in

943

User

RDS

Page

Customer No

Advisor Ryan Singer **S**3

Promised Opened

01/10/2025 5:00 PM Tag# 01/10/2025 2:03 PM Location **PRINT**

Shop **Priority** License

Cashiered **Odom Out**

943

PO# 02/18/2025 2:31 PM In Service Date

Stock No

Home Cell

(306) 344-4448 Bus

Year Make 2021

Model **NEW HOLLAND CR10.90Z** 06/07/2021 **Model Number** CR10.90Z

C2463B Color

Email

Today

Vehicle ID No 7N2045009

Engine

Selling Dealer NOVLAN BROS. **Extended Warranty**

Fleet #

Delivery Date 06/30/2025

Term Cash

INSTALLED GEAR SENSOR INSTALLED TRANSMISSION IN COMBINE CONNECTED HYDRAULIC LINES CONNECTED ELECTRICAL CONNECTORS INSTALLED RIGHT SIDE DRIVE SHAFT

-- LEAKING HOSE --

HOSE CLAMP WAS LOOSE TIGHTENED HOSE CLAMP -- REVERSER MOTOR -

REMOVED REVERSER MOTOR HYDRAULIC LINES

REMOVED REVERSER MOTOR

REMOVED REVERSER MOTOR FACEPLATE AROUND SHAFT

REMOVED WORN SEALS FROM FACEPLATE

INSTALLED NEW SEALS TO FACEPLATE

INSTALLED REVERSER MOTOR FACEPLATE WITH LOCTITE ON BOLTS CLEANED AREA AROUND REVERSER MOTOR ON FEEDERHOUSE

INSTALLED REVERSER MOTOR

INSTALLED NEW O-RINGS TO LINE CONNECTION POINTS

INSTALLED REVERSER MOTOR HYDRAULIC LINES

CSR Status Job Description Request **RDS** Approved REMOVE AN CLEAN SIEVES AG MISC Amount Tech Type Labor Description **HDS** 676.00 IAG REMOVE AN CLEAN SIEVES AG MISC Shp Price Amount Bin Type Description Part 38.93 38.93 KT245 **SPRING** 449942 38.93 Parts Total HDS -Technician 676.00 REMOVE AND CLEAN SIEVES Labor Total Cause 714.93 Request Total

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.


ASK US IF YOU WOULD LIKE INFORMATION ABOUT OUR PRIVACY POLICY, INCLUDING OUR SERVICE PROVIDERS AND THEIR DATA PROCESSING IN THE U.S., WHICH MAY BE ACCESSIBLE TO U.S. LAW ENFORCEMENT AND NATIONAL SECURITY AUTHORITIES. WE PROVIDE THIS PERSONAL AND TRANSACTION INFORMATION TO FORD MOTOR COMPANY OF CANADA, LIMITED TO ENABLE FORD TO ADMINISTER YOUR TRANSACTION, PROVIDE YOU WITH REQUESTED SERVICES, IMPROVE AUTOMOTIVE RELATED PRODUCTS AND SERVICES BY CONDUCTING CUSTOMER SURVEYS, AND PROVIDE YOU WITH MARKETING MATERIAL WHICH MAY BE OF INTEREST TO YOU, AS PERMITTED BY APPLICABLE LAWS. FOR THE FORD PRIVACY POLICY (WWW.FORD.CA) INCLUDING USE OF SERVICE PROVIDERS ANDU.S. DATA STORAGE OR IF YOU DO NOT WANT TO RECEIVE MARKETING OR SURVEY MATERIALS FROM FORD PLEASE CALL 1-800-565-FORD (3673).

BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$ ACCOMPANYING WORK ORDER.

SIGNATURE











Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433

SO # 123459

SERVICE ORDER

Printed

11/27/2025 9:49:55 AM

INTERNAL COPY

User

RDS

Page

04-4--

Customer No

Advisor Shop **Priority**

Ryan Singer S3

Promised Opened Cashiered

01/10/2025 5:00 PM Tag# 01/10/2025 2:03 PM Location PO# 02/18/2025 2:31 PM

PRINT

(306) 344-4448 Bus

Odom in 943

Odom Out 943 Model NEW HOLLAND CR10.90Z

In Service Date 06/07/2021 Model Number Stock No C2463B Color

Home Cell Email

Correction

Today

2021 Vehicle ID No 7N2045009

Make

License

Engine

Year

Selling Dealer NOVLAN BROS.

CR10.90Z **Extended Warranty**

Fleet#

Delivery Date 06/30/2025

Term Cash

REMOVED DUCKBILL

OPENED ACCESS DOOR TO SIEVE ACTUATING LINKAGE DISCONNECTED UPPER SIEVES ACTUATING LINKAGE REMOVED UPPER SIEVES MOUNTING HARDWARE

REMOVED UPPER SIEVES

DISCONNECTED LOWER SIEVES ACTUATING LINKAGE REMOVED LOWER SIEVES MOUNTING HARDWARE

REMOVED LOWER SIEVES

REMOVED PRE SIEVE MOUNTING HARDWARE

REMOVED PRE SIEVE

CLEANED CHAFF FROM SIEVE RAILS IN COMBINE CLEANED CHAFF FROM ALL MOVING PARTS OF SIEVES

LUBRICATED SIEVES

CHECKED FOR SMOOTH OPERATION OF SIEVES BY HAND

STRAIGHTENED ANY BENT FINGERS ON SIEVES

UPPER SIEVES HAD CANVAS SEAL INSTALLED WRONG

REMOVED CANVAS SEALS FROM UPPER SIEVES AND REINSTALLED

CORRECTLY

INSTALLED PRE SIEVE

INSTALLED PRE SIEVE MOUNTING HARDWARE

INSTALLED LOWER SIEVES

INSTALLED LOWER SIEVES MOUNTING HARDWARE CONNECTED LOWER SIEVES ACTUATING LINKAGE

INSTALLED UPPER SIEVES

INSTALLED UPPER SIEVES MOUNTING HARDWARE CONNECTED UPPER SIEVES ACTUATING LINKAGE

CLOSED ACCESS DOOR TO SIEVE LINKAGE

INSTALLED DUCKBILL

Request	Description REPLACE CHAFF SPREADER COVERS				Job 5	RDS	Approved
AG MISC					Туре	Tech	Amount
Labor AG MISC	Description REPLACE CHAFF SPREADER COVERS				ÍÁG	HDS	253.50
	Description	Shp	Bin	Type	F	Price	Amount
Part 51536349	COVER	1	WJ01	I	42	28.10	428.10
51536347	COVER	1	WJ01	1	42	28.10	428.10
Technician	HDS -	F	Parts Total				856.20

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

ASK US IF YOU WOULD LIKE INFORMATION ABOUT OUR PRIVACY POLICY, INCLUDING OUR SERVICE PROVIDERS AND THEIR DATA PROCESSING IN THE U.S., WHICH MAY BE ACCESSIBLE TO U.S. LAW ENFORCEMENT AND NATIONAL SECURITY AUTHORITIES. WE PROVIDE THIS PERSONAL AND TRANSACTION INFORMATION TO FORD MOTOR COMPANY OF CANADA, LIMITED TO ENABLE FORD TO ADMINISTER YOUR TRANSACTION, PROVIDE YOU WITH REQUESTED SERVICES, IMPROVE AUTOMOTIVE RELATED PRODUCTS AND SERVICES BY CONDUCTING CUSTOMER SURVEYS, AND PROVIDE YOU WITH MARKETING MATERIAL WHICH MAY BE OF INTEREST TO YOU, AS PERMITTED BY APPLICABLE LAWS. FOR THE FORD PRIVACY POLICY (WWW.FORD.CA) INCLUDING USE OF SERVICE PROVIDERS AND U.S. DATA STORAGE OR IF YOU DO NOT WANT TO RECEIVE MARKETING OR SURVEY MATERIALS FROM FORD PLEASE CALL 1-800-565-FORD (3673).

BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$_ ACCOMPANYING WORK ORDER.







Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433



SO # 123459

Printed

Cause

SERVICE ORDER

Customer No

11/27/2025 9:49:55 AM

INTERNAL COPY

Tag# 01/10/2025 5:00 PM Location

User

PRINT

Page

Advisor Ryan Singer Promised 01/10/2025 2:03 PM Shop S3 Opened PO# Cashiered 02/18/2025 2:31 PM **Priority**

License

Year

Engine

Odom In 943

Odom Out 943

Stock No In Service Date 06/07/2021 **Model Number**

RDS

C2463B Color

Bus Home Today Ceil Email

NEW HOLLAND CR10.90Z 2021 Vehicle ID No 7N2045009

Make

Selling Dealer NOVLAN BROS.

Model

CR10.90Z **Extended Warranty**

Fleet#

Delivery Date 06/30/2025

Term Cash

REPLACE CHAFF SPREADER COVERS

(306) 344-4448

REMOVED BROKEN CHAFF SPREADER COVERS

Labor Total Request Total

253.50 1,109.70

Correction CLEANED CHAFF FROM MATING SURFACE INSTALLED NEW CHAFF SPREADER COVERS

Request	Description				Job	CSR	Status
AG MISC	REPLACE TOP SPROCKETS AN FEEDERCHAIN				6	RDS	Approved
Labor	Description				Type	Tech	Amount
AG MISC	REPLACE TOP SPROCKETS AN FEEDERCHAIN				IAG	HDS	1,605.50
Part	Description	Shp	Bin	Туре		Price	Amount
86625263	WASHER	2	FB08D	1		0.66	1.32
47909153	WEAR STRIP	5	NE136	ı		25.37	126.85
47901099	WEAR STRIP	5	NE137	1		22.25	111.25
47456376	SCREW HEX SOC	8	FD06A	1		2.71	21.68
NC12-200GR	3/4X2 GR8	1	BOLT10	1		6.59	6.59
84026027	BEARING BALL	1	ND105	1	3	61.50	361.50
84401598	SPROCKET	1	KR193	I		82.38	82.38
47968251	O-RING	1		1		19.47	19.47
412650	WASHER BELLEVILLE	8	FB08F	1		1.59	12.72
48103500	CHAIN ELEVATOR	1	WD02	1	3,4	41.24	3,441.24
87587027	SEAL	1	FC02B	1		50.05	50.05
9840986	CLIP	1	KO100	I		5.70	5.70
81866169	LATCH	1	KO101	1		40.67	40.67
87658946	BEARING SPHERICAL	2	KH232	1	2	79.40	558.80
51413212	SPROCKET	4	UDB06	1	2	15.72	862.88
87587026	SEAL	1	NO113	J		44.49	44.49
47909110	STRIP PROTECTION	3	NJ280	ŀ	1	20.34	361.02
Technician	HDS -		Parts Total				6,108.61
Cause	REPLACE TOP SPROCKETS AND FEEDERCHAIN		Labor Total				1,605.50
	, <u> </u>		Request Tot	al			7,714.11

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$	_ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THI
ACCOMPANYING WORK ORDER.	







Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433



SO # 123459

Printed

SYMUHORID

SERVICE ORDER INTERNAL COPY

PRINT

RDS

User

1 **Customer No**

11/27/2025 9:49:56 AM

01/10/2025 5:00 PM Tag# Advisor Ryan Singer Promised 01/10/2025 2:03 PM **Location** Shop Opened PO# 02/18/2025 2:31 PM Cashiered **Priority**

(306) 344-4448 Bus Home Today Cell Email

Stock No **Odom Out** In Service Date License Odom In C2463B 943 06/07/2021 Color Model Number Make Model Year 2021 NEW HOLLAND CR10.90Z CR10.90Z **Delivery Date Extended Warranty** Selling Dealer Vehicle ID No 06/30/2025 **NOVLAN BROS.** 7N2045009 Fleet # Engine

Term Cash REMOVED FEEDER FACE PLATE Correction

ROLLED FEEDER CHAIN OVER SO CONNECTING LINKS WERE AT THE

FRONT

REMOVED FEEDER CHAIN TENSIONERS

CLEANED CHAFF AND DIRT OUT OF FEEDER TENSIONERS SLOTS

REMOVED FEEDER DRIVE CHAIN

REMOVED FEEDER CHAIN

REMOVED FEEDER DRIVE CHAIN SPROCKET

REMOVED TOP SHAFT SPEED SENSOR

REMOVED TOP SHAFT COVERS

REMOVED TOP SPROCKETS WEAR STRIPS

REMOVED TOP SPROCKET BOLTS

REMOVED BEARING BOLTS

CUT TAB OFF RIGHT SIDE SO BEARING HUB COULD BE TURNED FOR

REMOVAL

REMOVED TOP SHAFT AND SPROCKETS

REMOVED BEARING FROM LEFT HUB

CLEANED HUB

INSTALLED NEW BEARING TO LEFT HUB REMOVED RIGHT HUB FROM TOP SHAFT

CUT OLD BEARING OFF OF TOP SHAFT

CLEANED TOP SHAFT

CLEANED RIGHT HUB

INSTALLED NEW BEARING TO RIGHT HUB

HEATED LEFT SIDE BEARING AND INSTALLED ONTO TOP SHAFT

CLEANED CHAFF OUT OF FEEDERHOUSE

SLID TOP SHAFT INTO FEEDERHOUSE AND SLID NEW SPROCKETS ONTO

TOP SHAFT

INSTALLED LEFT SIDE BEARING HUB BOLTS

HEATED RIGHT SIDE BEARING AND INSTALLED ONTO TOP SHAFT

INSTALLED RIGHT SIDE BEARING HUB BOLTS

ALIGNED SPROCKETS AND TIGHTENED IN PLACE ON SHAFT

INSTALLED NEW SPROCKET WEAR STRIPS

INSTALLED NEW TOP SHAFT COVERS

CHECKED FRONT DRUM BEARINGS

INSTALLED NEW FEEDER CHAIN

INSTALLED FEEDER CHAIN TENSIONERS AND TIGHTENED TO SPEC

INSTALLED FEEDER NEW FEEDER DRIVE CHAIN

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$	_ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE
ACCOMPANYING WORK ORDER.	







Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433



SO # 123459

SERVICE ORDER

Printed

11/27/2025 9:49:56 AM

INTERNAL COPY

User

RDS

Page 13

Customer No

Ryan Singer **Promised**

Odom In

943

01/10/2025 5:00 PM 01/10/2025 2:03 PM

Tag#

PRINT

Advisor Shop **Priority**

Opened Cashiered

Location 02/18/2025 2:31 PM

Bus Today Year

License

Make

S3

943 Model CR10.90Z

06/07/2021 **Model Number** CR10.90Z

In Service Date

Stock No C2463B Color

Home Cell Email

(306) 344-4448

2021 NEW HOLLAND Vehicle ID No

Selling Dealer NOVLAN BROS. **Extended Warranty**

Delivery Date

Term Cash

7N2045009 Engine

Odom Out

Fleet #

06/30/2025

ROLLED FEEDER CHAIN OVER ONE REVOLUTION TO CENTER FEEDER

CHAIN

CHECKED SPROCKET ALIGNMENT WAS GOOD

INSTALLED FEEDER FACEPLATE

Request	Description				Job	CSR	Status
AG MISC	REPLACE BELTS AN CHAINS AS REQUIRED				7	RDS	Approved
Labor	Description				Type	Tech	Amount
AG MISC	REPLACE BELTS AN CHAINS AS REQUIRED				IAG	HDS	676.00
Part	Description	Shp	Bin	Type	F	rice	Amount
47397260	CHAIN	1	MU286	I	30	2.06	302.06
84566255	CHAIN	1	MJ276	1	59	9.61	599.61
87757537	CHAIN	1	MU284	1	9	2.25	92.25
90481197	CHAIN	1	IJ292	1	23	6.65	236.65
48144638	BELT	1		1	17	1.30	171.30
P FREIGHT	freight	1		1	2	25.00	25.00
47852514	V-BELT	1	UBL101	1	11	9.31	119.31
Technician	HDS -		Parts Total				1,546.18
Cause	REPLACE BELTS AND CHAINS AS NEEDED		Labor Total				676.00
			Request Total	al			2,222.18

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$	_ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THI
ACCOMPANYING WORK ORDER.	













Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433

SO # 123459

SERVICE ORDER

Printed

11/27/2025 9:49:56 AM

INTERNAL COPY

Odom In

943

User

RDS

Page

Customer No

Advisor

Promised Opened

01/10/2025 5:00 PM 01/10/2025 2:03 PM

Tag# Location PRINT

Shop

Ryan Singer \$3

Cashiered

Odom Out

02/18/2025 2:31 PM PO #

Home

Bus (306) 344-4448

Make Year

943 Model

In Service Date 06/07/2021 **Model Number** Stock No C2463B Color

Cell Email Today

2021 Vehicle ID No

NEW HOLLAND CR10.90Z Selling Dealer

CR10.90Z **Extended Warranty**

Delivery Date

Term Cash

7N2045009 Engine

Priority

License

NOVLAN BROS.

Fleet #

06/30/2025

Correction

LOOSENED GRAIN ELEVATOR DRIVE BELT TENSIONER

REMOVED GRAIN ELEVATOR DRIVE BELT

LOOSENED GRAIN ELEVATOR DRIVE CHAIN TENSIONER

REMOVED BUBBLE UP AUGER DRIVE CHAIN

OPENED ACCESS PANEL IN HOPPER TO GRAIN ELEVATOR DRIVE CHAIN

REMOVED GRAIN ELEVATOR DRIVE CHAIN INSTALLED NEW GRAIN ELEVATOR DRIVE CHAIN

CLOSED ACCESS PANEL IN HOPPER

INSTALLED NEW BUBBLE UP AUGER DRIVE CHAIN

TIGHTENED GRAIN ELEVATOR DRIVE CHAIN TENSIONER

INSTALLED GRAIN ELEVATOR DRIVE BELT

TIGHTENED GRAIN ELEVATOR DRIVE BELT TENSIONER LOOSENED UNLOADING AUGER DRIVE CHAIN TENSIONER

REMOVED UNLOADING AUGER DRIVE CHAIN FOUND 1 IDLER SPROCKET WITH BAD BEARING

REMOVED IDLER SPROCKET

INSTALLED NEW IDLER SPROCKET

INSTALLED NEW UNLOADING AUGER DRIVE CHAIN

TIGHTENED UNLOADING AUGER DRIVE CHAIN TENSIONER

REMOVED FEEDER HOUSE DRIVE CHAIN

INSTALLED NEW FEEDERHOUSE DRIVE CHAIN

LOOSENED ROTARY SCREEN DRIVE BELT TENSIONER

REMOVED NUTS FROM ROTARY SCREEN CLEANING BRUSH ARMS

REMOVED ROTARY SCREEN DRIVE BELT

REMOVED FORWARD ENGINE FAN FROM PULLEY

LOOSENED ENGINE FAN TIMING BELT FROM ENGINE PULLEY

REMOVED ENGINE FAN DRIVE BELT

REMOVED ACCESS PANEL IN HOPPER TO ROTOR COVERS

REMOVED ACCESS PANEL TO TURBO SIDE OF ENGINE

LOOSENED BELT FROM ENGINE TO ROTARY SCREEN INTERMEDIATE

SHAFT

REMOVED ENGINE TO INTERMEDIATE SHAFT BELT

CHECKED BEARINGS ON INTERMEDIATE SHAFT

INSTALLED NEW ENGINE TO INTERMEDIATE SHAFT BELT

TIGHTENED ENGINE TO INTERMEDIATE SHAFT BELT OPENED ACCESS PANEL ABOVE SIEVES INSTALLED ENGINE FAN DRIVE BELT INSTALLED ENGINE FANS TIMING BELT

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$	BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE
ACCOMPANYING WORK ORDER.	















Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433

SO # 123459

SERVICE ORDER

Printed

11/27/2025 9:49:56 AM

INTERNAL COPY

User

RDS

Page 15

Customer No

Ryan Singer S3

Promised Opened Cashiered

01/10/2025 5:00 PM Tag# 01/10/2025 2:03 PM 02/18/2025 2:31 PM PO#

Location

Job

Type

IAG

8

PRINT

Advisor Shop Priority License Year

Odom In 943

Odom Out 943

In Service Date 06/07/2021 **Model Number** CR10.90Z

Stock No C2463B Color

Home Cell Email Bus (306) 344-4448 Today

NEW HOLLAND CR10.90Z 2021 Vehicle ID No 7N2045009

Engine

Make

Selling Dealer NOVLAN BROS.

Model

Extended Warranty

Delivery Date 06/30/2025

CSR

RDS

Tech

HDS

Status

Approved

Amount

422.50

422,50

422.50

Fleet #

Labor Total

Request Total

Term Cash

TIGHTENED ENGINE FANS TIMING BELT TENSIONER

CLOSED ACCESS PANEL ABOVE SIEVES

INSTALLED NEW ROTARY SCREEN DRIVE BELT INSTALLED NUTS FOR ROTARY SCREEN CLEANING BRUSH ARMS

TIGHTENED ROTARY SCREEN DRIVE BELT TENSIONER

Description Request AG MISC TURN DFR PLATES Labor Description **TURN DFR PLATES** AG MISC Technician HDS -

Cause **TURN DFR PLATES**

Correction

REMOVED DFR DRIVE BELT REMOVED DFR PLATES FROM 1 ROW

STRAIGHTENED ANY BENT FLANGES ON DFR DRUM GROUND OUT BROKEN WELDS AND RE WELDED TURNED AND INSTALLED DFR PLATES

REPEATED UNTIL EVERY ROW WAS TURNED

Request	Description				Job	CSR	Status
AG MISC	REPLACE ROTARY SCREEN BRUSHES				9	RDS	Approved
Labor	Description				Type	Tech	Amount
AG MISC	REPLACE ROTARY SCREEN BRUSHES				IAG	HDS	507.00
Part	Description	Shp	Bin	Type		Price □	Amount
73340447	KIT	1	UHB01	1	63	32.77	632.77
425519	RIVET	1	NE121	1		0.65	0.65
84073020	BRUSH COMMUTATOR	3	UEB03	1	29	96.99	890.97
Technician	HDS -		Parts Total				1,524.39
Cause	REPLACE ROTARY SCREEN BRUSHES	j	Labor Total				507.00
		!	Request Tot	al			2.031.39

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$	_ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE
ACCOMPANYING WORK ORDER.	













Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toli Free: 1-877-344-4433

SO # 123459

SERVICE ORDER INTERNAL COPY

11/27/2025 9:49:56 AM

Advisor Ryan Singer User

RDS

Page 16

Customer No

Printed

Shop **Priority**

License

Engine

Promised Opened Cashiered

Odom Out

943

01/10/2025 5:00 PM Tag# 01/10/2025 2:03 PM 02/18/2025 2:31 PM PO#

Location

PRINT

Home Cell

Email

Correction

Bus (306) 344-4448 Today

Make Year 2021

S3

Model NEW HOLLAND CR10.90Z Selling Dealer Vehicle ID No 7N2045009 NOVLAN BROS.

Odom In

943

06/07/2021 **Model Number** CR10.90Z **Extended Warranty**

Fleet#

In Service Date

Stock No C2463B Color

> **Delivery Date** 06/30/2025

Term Cash

LOOSENED ROTARY SCREEN DRIVE BELT TENSIONER

REMOVED CENTER NUTS FROM FRONT BRUSH ARMS REMOVED ROTARY SCREEN DRIVE BELT

REMOVED ROTARY SCREEN FRONT BRUSH ARMS

LOOSENED BOLTS AND SWUNG AC CONDENSER OUT OF THE WAY

REMOVED LOCK BOLTS FROM ROTARY SCREEN SHAFTS

REMOVED REAR ROTARY SCREEN REMOVED FRONT ROTARY SCREEN

DRILLED OUT OLD RIVETS HOLDING BRUSHES ON RIVETED NEW BRUSH ONTO ROTARY SCREENS

INSTALLED FRONT ROTARY SCREEN INSTALLED REAR ROTARY SCREEN

INSTALLED LOCK BOLTS TO ROTARY SCREEN SHAFTS

SWUNG AC CONDENSER BACK INTO POSITION AND SECURED WITH

BOLTS

INSTALLED ROTARY SCREEN FRONT BRUSH ARMS INSTALLED NEW ROTARY SCREEN DRIVE BELT INSTALLED CENTER NUTS FOR FRONT BRUSH ARMS TIGHTENED ROTARY SCREEN DRIVE BELT TENSIONER

Request	Description				Job	CSR	Status
AG MISC	REPAIR EXHAUST LEAKS				10	RD\$	Approved
Labor	Description				Type	Tech	Amount
AG MISC	REPAIR EXHAUST LEAKS				IAG	HDS	1,074.00
Part	Description	Shp	Bin	Type	Pr	ice	Amount
47684297	GASKET	2		1	26	.49	52.98
48173627	HEAT SHIELD	1	NEW	I	48	.02	48.02
P FREIGHT	freight	1		1	45	.00	45.00
P FREIGHT	47390973,48173626	1		1	15	.00	15.00
47390973	CLAMP	1		1	126	.94	126.94
98453300	GASKET	1	GSKT07	1	41	.36	41.36
48173626	HEAT SHIELD	1	NEW	1	44	.04	44.04
P FREIGHT	ORDER #: 8049325 freight	1		1	35	.00	35.00
90360265	TUBE	1		1	3,687	.34	3,687.34
Technician	HDS -		Parts Total		•		4,095.68

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$	_ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE
ACCOMPANYING WORK ORDER.	













Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433

SO # 123459

SERVICE ORDER

Printed

11/27/2025 9:49:56 AM

INTERNAL COPY

Ryan Singer

S3

User

RDS

Page 17

1.074.00

5,169.68

Customer No

Advisor Shop Priority

Promised Opened Cashiered

01/10/2025 5:00 PM Tag# 01/10/2025 2:03 PM Location PO# 02/18/2025 2:31 PM

PRINT

(306) 344-4448 Bus

Odom In 943 Model **Odom Out** 943

In Service Date 06/07/2021 **Model Number** Stock No C2463B Color

Home Cell Email

Today

NEW HOLLAND 2021 Vehicle ID No 7N2045009

Make

License

Year

Engine

CR10.90Z Selling Dealer NOVLAN BROS.

CR10.90Z **Extended Warranty**

Delivery Date

Term Cash

Fleet#

Request Total

Labor Total

06/30/2025

Cause Correction REPAIR EXHAUST LEAKS -- TORN FLEX PIPE --

REMOVED HEAT SHIELDS FROM TORN EXHAUST PIPE

FRONT HEAT SHIELD WAS BROKEN

REMOVED V BAND CLAMPS FROM EXHAUST PIPE REMOVED EXHAUST PIPE AND OLD GASKETS

CLEANED MATING SURFACES

INSTALLED NEW FLEX PIPE WITH NEW GASKETS

INSTALLED V BAND CLAMPS TO EACH END OF FLEX PIPE

INSTALLED HEAT SHIELDS TO EXHAUST PIPE -- EXHAUST LEAK FROM MANIFOLD TO TURBO --REMOVED V BAND CLAMP FROM HOT SIDE OF TURBO REMOVED V BAND CLAMP FROM CHARGE PIPE LOOSENED HOSE CLAMP ON INTAKE BOOT AT TURBO

REMOVED TURBO MOUNTING NUTS SLID TURBO OFF OF MANIFOLD STUDS

REMOVED OLD GASKET

CLEANED BOTH MATING SURFACES WITH EMRY CLOTH

INSTALLED NEW GASKET

SLID TURBO ONTO MANIFOLD STUDS INSTALLED TURBO MOUNTING NUTS

TIGHTENED HOSE CLAMP ON INTAKE BOOT AT TURBO

INSTALLED V BAND CLAMP TO CHARGE PIPE EXHAUST SIDE V BAND CLAMP WAS BROKEN INSTALLED NEW V BAND CLAMP TO EXHAUST

STARTED COMBINE TO CHECK FOR EXHAUST LEAKS

NO MORE EXHAUST LEAKS

CSR Request Description Job Status REPAIR ROTARY VACUMM RDS Approved AG MISC 11 Tech Labor Description Type Amount REPAIR ROTARY VACUMM **HDS** AG MISC IAG 447.50 Price Description Shp Amount Part Bin Type HOUSING FAN 47431449 398.98 398.98 UEG01 coming from lloyd P FREIGHT 47431449 10.00 10.00 Technician HDS -Parts Total 408.98

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE, WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

ASK US IF YOU WOULD LIKE INFORMATION ABOUT OUR PRIVACY POLICY, INCLUDING OUR SERVICE PROVIDERS AND THEIR DATA PROCESSING IN THE U.S., WHICH MAY BE ACCESSIBLE TO U.S. LAW ENFORCEMENT AND NATIONAL SECURITY AUTHORITIES. WE PROVIDE THIS PERSONAL AND TRANSACTION INFORMATION TO FORD MOTOR COMPANY OF CANADA, LIMITED TO ENABLE FORD TO ADMINISTER YOUR TRANSACTION, PROVIDE YOU WITH REQUESTED SERVICES, IMPROVE AUTOMOTIVE RELATED PRODUCTS AND SERVICES BY CONDUCTING CUSTOMER SURVEYS, AND PROVIDE YOU WITH MARKETING MATERIAL WHICH MAY BE OF INTEREST TO YOU, AS PERMITTED BY APPLICABLE LAWS. FOR THE FORD PRIVACY POLICY (WWW.FORD.CA) INCLUDING USE OF SERVICE PROVIDERS AND U.S. DATA STORAGE OR IF YOU DO NOT WANT TO RECEIVE MARKETING OR SURVEY MATERIALS FROM FORD PLEASE CALL 1-800-565-FORD (3673).

INDERTEDNESS IS ACKNOWLEDGED LITTE SUM OF \$ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE ACCOMPANYING WORK ORDER.









Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433

SO # 123459

SERVICE ORDER INTERNAL COPY

11/27/2025 9:49:56 AM

Advisor Ryan Singer

S3

User

RDS

Customer No

Printed

Shop Priority License

Promised Opened Cashiered

01/10/2025 5:00 PM Tag# 01/10/2025 2:03 PM Location 02/18/2025 2:31 PM PO#

PRINT

Home Cell

(306) 344-4448 Bus

Year 2021

Engine

943 Make Model **NEW HOLLAND**

Odom In

943 06/07/2021 **Model Number** CR10.90Z

Request Total

Stock No C2463B Color

Email

Today

CR10.90Z Vehicle ID No Selling Dealer 7N2045009 NOVLAN BROS.

Extended Warranty

In Service Date

Delivery Date 06/30/2025

Term Cash

Fleet# Labor Total

Odom Out

447.50

856.48

Cause Correction REPAIR ROTARY VACUUM

REMOVED ROTARY VACUUM EXHAUST TUBE REMOVED ROTARY VACUUM INTAKE TUBE

REMOVED ROTARY VACUUM HOUSING

LOOSENED ROTARY VACUUM DRIVE BELT TENSIONER

REMOVED ROTARY VACUUM DRIVE BELT ROTARY VACUUM BEARINGS WERE GRINDING

REMOVED ROTARY VACUUM FAN

REMOVED ROTARY VACUUM BEARING AND SHAFT ASSEMBLY

REMOVED SHAFT FROM BEARINGS

REMOVED OLD BEARINGS FROM HOUSING

CLEANED HOUSING CLEANED SHAFT

INSTALLED NEW BEARINGS

HOUSING WAS NOT TIGHT ENOUGH ON BEARINGS

REMOVED BEARINGS

STAKED HOUSING AND COATED WITH GREEN LOCTITE

INSTALLED BEARINGS INSTALLED SHAFT

INSTALLED BEARING AND SHAFT ASSEMBLY TO COMBINE

INSTALLED ROTARY VACUUM FAN TO SHAFT INSTALLED ROTARY VACUUM DRIVE BELT

TIGHTENED ROTARY VACUUM DRIVE BELT TENSIONER

INSTALLED ROTARY VACUUM HOUSING INSTALLED ROTARY VACUUM INTAKE TUBE **INSTALLED ROTARY VACUUM EXHAUST TUBE**

Request Description AG MISC

CHECK ACTIVE SPREADER ERROR

Lahor AG MISC Description

CHECK ACTIVE SPREADER ERROR Technician

CHECK ACTIVE SPREADER ERROR Cause

Type IAG

Job

12

RDS Approved Tech **Amount** HDS 447.50

CSR

Labor Total Request Total 447.50 447.50

Status

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

ASK US IF YOU WOULD LIKE INFORMATION ABOUT OUR PRIVACY POLICY, INCLUDING OUR SERVICE PROVIDERS AND THEIR DATA PROCESSING IN THE U.S., WHICH MAY BE ACCESSIBLE TO U.S. LAW ENFORCEMENT AND NATIONAL SECURITY AUTHORITIES. WE PROVIDE THIS PERSONAL AND TRANSACTION INFORMATION TO FORD MOTOR COMPANY OF CANADA, LIMITED TO ENABLE FORD TO ADMINISTER YOUR TRANSACTION, PROVIDE YOU WITH REQUESTED SERVICES, IMPROVE AUTOMOTIVE RELATED PRODUCTS AND SERVICES BY CONDUCTING CUSTOMER SURVEYS, AND PROVIDE YOU WITH MARKETING MATERIAL WHICH MAY BE OF INTEREST TO YOU, AS PERMITTED BY APPLICABLE LAWS. FOR THE FORD PRIVACY POLICY (WWW.FORD.CA) INCLUDING USE OF SERVICE PROVIDERS AND U.S. DATA STORAGE OR IF YOU DO NOT WANT TO RECEIVE MARKETING OR SURVEY MATERIALS FROM FORD PLEASE CALL 1-800-565 FORD (3673).

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE ACCOMPANYING WORK ORDER.













Phone: (306) 344-4448 • Fax: (306) 344-4892 • Toll Free: 1-877-344-4433

SO # 123459

SERVICE ORDER

943

Printed

11/27/2025 9:49:56 AM

INTERNAL COPY

User

RDS

Customer No

Advisor Ryan Singer Shop **S3**

Promised Opened Cashiered

01/10/2025 5:00 PM Tag# 01/10/2025 2:03 PM 02/18/2025 2:31 PM PO#

Location

PRINT

Priority License

Year

Odom In

Model

Odom Out 943

In Service Date 06/07/2021 Model Number Stock No C2463B Color

Home Cell Email

Correction

Bus (306) 344-4448 Today

2021 **NEW HOLLAND** Vehicle ID No

7N2045009

Engine

Make

CR10.90Z Selling Dealer NOVLAN BROS.

CR10.90Z **Extended Warranty**

Fleet #

Delivery Date 06/30/2025

Term Cash

TESTED VOLTAGE AT SENSOR

SENSOR WAS NOT RECEIVING FULL VOLTAGE

UNPLUGGED CONNECTOR X-1038P

CHECKED FOR CONTINUITY BETWEEN X-1038P AND X-126

NO CONTINUITY

CUT ZIP TIES SECURING HARNESS TO SPREADER HOUSING

REMOVED LOOMING AND INSPECTED WIRES FOUND 6 CORRODED WIRE IN HARNESS **CUT CORRODED PART OUT OF 6 WIRES**

SOLDERED NEW WIRES IN

CHECKED FOR CONTINUITY ON REPAIRED WIRES

INSTALLED LOOMING

SECURED HARNESS TO SPREADER HOUSING

PLUGGED CONNECTORS X-1038P AND X-126 BACK IN KEYED COMBINE ON AND CHECKED CODE WAS GONE

Request	Description						, , , , , , , , , , , , , , , , , , , ,		Job	CSR	Status
WASH	WASH UN	IIT							13	CDF	Approved
Labor	Description								Туре	Tech	Amount
WASH	WASH UN	IIT							IAGDETL	PDM	500.00
Technician	PDM -						Labor	Total			500.00
Correction	WASH CO	MBINE					Reque	est Total			500.00
Detail											
Pay Type	Labor	Parts	Fees	Misc	Supplies	Sublet	Env	Ded	GST	PST	Total
Customer	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Warranty	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Internal	13,200.50	19,501.17	0.00	0.00	300.00	0.00	0.00	0.00	0.00	0.00	33,001.67
Total	13,200.50	19,501.17	0.00	0.00	300.00	0.00	0.00	0.00	0.00	0.00	33,001.67

INTERNAL

ACCOUNT P1443C

DESCRIPTION

INV COMBINE (USED)

TYPE CONTROL#

C2463B

AMOUNT COMMENTS

33001.67 045009 - 2021 NEW HOLLAND CR10.90Z

COMBINE

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE, WHICH MAY BE MORE OR LESS THAN THE ACTUAL TIME CLOCK RATE. WE WARRANT ALL AUTOMOTIVE PARTS AND LABOUR FOR 90 DAYS/6500 KM, WHICHEVER OCCURS FIRST. ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED.

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$	BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE
ACCOMPANYING WORK ORDER.	- THIS TERMINE IN THE PROPERTY OF THE PROPERTY