

ABC Service & Maintenance - 01.07.2024 to 30.06.2025

PM03 - XB75IW - 2003 Kenworth T400 - VIN: 6F50000003A425311

[illegible]

DATE	DESCRIPTION OF WORKS	QTY	COMPLETED/SUPPLIED BY
10.07.2023	Kenworth Gold Pres G 5 (72504B)	1	Brown & Hurley
12.07.2023	Turned PM03 around and put up on ramps. Pulled sump out and order new one		Morgan Scriven
12.07.2023	Gasket Series 60 Sump Gasket (23539104)	1	Wideland Group
13.07.2023	Diagnose fault with oil pressure light coming on. Repair/replace faulty wiring to oil pressure senders and replace gauge sender and switch Oil Pressure Sender VDO 0-500 KPA Oil Pressure Switch 21KPA N/C VDO 2 Pin Deutsch Plug Labour hours	 1 1 1 2	Onsite Auto Electrical SEQ
14.07.2023	Front Well Sump	1	CPF Detroit
17.07.2023	Detroit S60 Filter Kit (23518686)	1	Wideland Group
24.07.2023	Bushing-Anti Vibration Mt (K066-338)	16	Brown & Hurley
24.07.2023	Pin-Hood Locating (K179-499)	2	Brown & Hurley
24.07.2023	Plate-Hood Locating Pin, T650 (K350-1577)	1	
24.07.2023	Drum Tap	4	Brown & Hurley
25.07.2023	Checked over for oil leaks after sump change		Morgan Scriven
31.07.2023	Wire new Anderson plug 2 B&S battery Cable Anderson Plug 175Amp MIDI fuse holder ACX6508 80amp Midi Fuse 35mm2 Cable lug Labour hours	 2.5 1 1 1 4 1	Onsite Auto Electrical SEQ
10.08.2023	Mirror Heated 7 x 16 Rear Len (6364RH/S)	1	Brown & Hurley
	Glass Door Drop Window (R44-1073-2)	1	
11.08.2023	M6 S/S 304 Nyloc Hex Nut (NN04PCM06)	2	Maryborough Bolts
	¼ x 5/8 x 18G S/S 304 Rnd F/Wsh (WR04P0250662)	4	
	M6 x 25 S/S 304 Pan Phil Mtr (MS04PPM060025)	2	
28.08.2023	Odometer: 829261 Tyre Puncture P/R Pos 7	1	Bob's Tyre Centre
01.09.2023	Gasket (8929529)	1	Wideland Group
	Gasket turbo drain (8929285)	1	
03.0.2023	Odometer: 832914 Hours: 14143 Underwash Washer – broken wire Service engine Adjust bonnet Replace LHS mount Change gearbox filter		Todd Warren
08.09.2023	Mileage: 835715 REPAIR EXHAUST MANIFOLD		Broken Hill Truck Centre

ABN 99 626 549 871

	Remove the turbo & air intake. Remove studs from Manifold & drill out the broken studs & fit new ones. Refit the turbo with the new gasket & repair wiring to the oil pressure gauge GSKT – Turbo Mount (A*1S4295) Nut Exhaust Manifold (O*53Z0110) Manifold Stud 10x48mm (O*53Z0410X48)	1 4 4	
12.09.2023	Drum Tap (HXBT)	2	Brown & Hurley
15.09.2023	7" High/Low Beam & Position (WDH-7R7H-M)	2	Brown & Hurley
22.09.2023	Removed damage number plates (XQ64EK) and replaced with new ones (XB17IW)		Department of Transport & Main Roads
29.09.2023	Greased and good check over		Morgan Scriven
10.10.2023	Beacon Led 12/24V	1	BDS Mechanical
19.10.2023	Odometer 895090 11R22.5 Runouts (ZMTYRETBR) Tyre Labour fitting	1 1	Bob's Tyre Centre
23.10.2023	Hose ASM 1 2in 3 8in ends 36in (R955550536BK) Hose ASM 1 2in 3 8in ends 22in (R955550522BK)	1 1	Wideland Group
07.11.2023	Repair Air-Con system Replace Leaking service valve, re-gas & test Refrigerant R134A Labour hours	1.2 1.5	Onsite Auto Electrical SEQ
16.11.2023	Kit-Cab/Sleeper Door Lock (K345/4616)	1	Brown & Hurley
16.11.2023	½ UNC X 2 ½ Grade 8 Z/P Hex B/O (BHG8ZC0500250) ½ UNC Grade 8 Z/P Nyloc Hex Nut (NNG8ZC050)	10 10	Maryborough Bolts & Accessories
04.12.2023	M8 Short Captive Nut (C2265-6)	4	Maryborough Bolts & Accessories
04.12.2023	5/16X1 1/4X16G M/Steel Z/P Rnd F/wsh (WRMSZU03112516) M8X75 Class 8.8 Z/P Hexset Screw (BS88ZCM080075)	4 2	Maryborough Bolts & Accessories
04.12.2023	Detroit S60 Filter Kit (23518686)	1	Wideland Group
08.12.2023	Kit-Shock Absorber A/G (K374-38K1T)	4	Brown & Hurley
14.12.2023	Core-Radiator (MLF1554/K) Kit-gasket, Klinger (SP-1289/C6327K) Bush-Anti vibration (K066-177) Fan-32" 9 blade acs (391200-32)	1 1 2 1	Brown & Hurley
15.12.2023	5/16 UNC Frade 8 X/p Nyloc Hex Nut (NNG8ZC031) 5/16x3/4x18G M/Steel Z/P Ren F/Wsh (WRMSZ03107518) 5/16 UncX1 ½ Grade 8 Plain Hex B/O (BHG8PC0310125) 5/16 UncX1 Grade 8 Z/P Hex B/O (BHG8ZC0310100)	200 200 100 16	Maryborough Bolts & Accessories
15.12.2023	Bushing-Anti Vib Top (K066-516) Bushing-Anti Vib Bottom (K066-517)	2 2	Brown & Hurley
02.01.2024	Tyre Puncture	1	Bob's Tyre Centre


ABN 99 626 549 871

15.01.2024	Degrease underneath truck Adjusted brakes Washed outside of truck Checked over all interior		Morgan Scriven
15.01.2024	Amber Marker Clear Lens Colour (RDP86AM)	3	Wideland Group
16.01.2024	Sensor TRS (8929388)	1	Wideland Group
16.01.2024	Defect Notice – SD 38807263 Replacement, Repairs or Alterations required to the following: Lights & Electrical components Engine/Drivelines/Emissions Details of other items rejected: 1. Lights – passenger side high beam inoperable – rectify 2. Brakes – Axle 3 – drivers side over stroked – adjust 3. Engine – Engine oil leak dripping to road way left hand side – rectify		Self-Clear Todd Warren
18.01.2024	Certificate of Inspection – SA 38713224 Effective date – 29.01.2024 Expire date – 28.01.2025		Department of Transport & Main Roads
19.01.2024	Detroit S60 Filter Kit (23518686) Element-Oil Filter (23530573)	1 1	Wideland Group
19.01.2024	Install GPS Tracker QK3 Connector Labour hours	1 1	Onsite Auto Electrical SEQ
19.01.2024	Odometer: 886517 kms Hours: 14979 Services truck Engine Oil & Fuel Filter replaced		Morgan Scriven
24.01.2024	Gasket (8929299)	1	Wideland Group
02.02.2024	7/16 Z/Y Rnd Hard F/Wsh (WR43Y043) 7/16 Uncx1 ¼ Grade 8 Z/P Hex B/O (BHG8ZC0430125)	5 3	Maryborough Bolts & Accessories
02.02.2024	Viton O'Ring (V113)	1	Wide Bay Industrial Group
05.02.2024	Vehicle & Trailer Maintenance Change Diff oils Change Gearbox oil & Filter Weld RH muffler Replacement ordered		Mark Warren
06.02.2024	Muffler (M100580)	1	Wideland Group
07.02.2024	Odometer: 887,704km RECIFY CAUSE OF INTERMITTENT SHUTDOWN Labour hours Check fuel pro level Check for fuel leaks Check for visual breaks in throttle potentiometer wiring		Amet Diesel

ABN 99 626 549 871

	Connect computer & perform wiggle test, no faults found Test drive vehicle & found fault to be present under early load scenario Removed ECM plug, found moisture & loose terminals Rectified found issues & test drove vehicle, fault still present Check resistance from wiring to ECM. All OK Removed P-clamps from main harness, removed conduit & inspected harness Found rubbed through wires above tappet cover Repaired harness & function test vehicle All OK Cleaned up harness All OK		
21.02.2023	Airbag Kenworth Airglide 200 (GY1R11221)	1	Wideland Group
01.03.2024	Valve (SD118181)	1	Wideland Group
06.03.2024	11R22.5 16PR Black Belt B209 Drive (B/S M722) (ATL11225B209) Tyre labour fitting <i>Tyres fitted to Pos 3 to 10</i>	8 8	Bob's Tyre Fitting
12.03.2024	Arm, Pitman (K029-280) UJ Kit 100 (5.103X) Gr8 Bolt Unf ¾ x 5 (3/4X5.00NF) Nut Nyloc UNF ¾ (3/4NFNYL) Washer ¾ x 38.00 x3.2mm (3/4HDWASZP)	1 3 1 1 2	Wideland Group
13.03.2024	Handle-door, Car inside RH (K294-426RPAK)	1	Brown & Hurley
14.03.2024	Greaseless wear ring kit (SK310594)	1	Wideland Group
18.03.2024	Plate 8mm 250gr 325 x 325 SHS 89 x 89 x6 400mm long	16 8	ISM Manufacturing
18.03.2024	75 x 10 GR300+ FB – 1600mm long	1	ISM Manufacturing
20.03.2024	Labour hours Adjust clutch	0.25	Amet Diesel
20.03.2024	AB Service Odometer 909500 New Pitman & Unis. Replace bonnet straps New drives & steers		Mark Warren
01.05.2024	Tie Rod End LH (R230068PZ)	1	Brown & Hurley
18.06.2024	Valve Tractor Protection (TRP288605) Isolator Bushing Kit (K-3399) Spacer-Transmission Sup (K221-3694) Screw-Socket 1/4x2 Unc (6746/TW)	1 1 1 1	Brown & Hurley

DATE	DESCRIPTION OF WORKS	QTY	COMPLETED/SUPPLIED BY
08.07.2022	11R22.5TL (16) 148/145M LR166D Loadrunner (TOT11225LR166D) Tyre Labour Fitting 9.5R17.5 XTE2 TL 143/141J Mich Tyre Rotate <i>11R22.5 Loadrunners fitted POS 7, 8, 9, 10</i> <i>9.5R 17 fitted to loose rims</i> <i>Best to 3, 4, 5, 6</i>	4 1	Bob's Tyre Centres
26.07.2022	Microphone TX3500 Series (GMEMC557B) <i>Supply Loose</i>	1	Bob's Tyre Centres
08.08.2022	Governor D2 Style (RDP275707) Insert Male Seal Quick Release (SA9393) Coupling Fem Sealing Quick Release (SA9335)	1 1 1	Wideland Trucks & Equipment
17.08.2022	Trp 16.5 x 7 Steel Jacket Dru (DB017TRP) Kit brake shoe drive 16.5 x 7" (TRP214707QP)	4 4	Brown & Hurley
23.08.2022	Seal (23519651)	1	Wideland Trucks & Equipment
23.08.2022	Clutch Kit Inc KW X Shafts (K-4460-PAC) Kit – Hex Flange Crimp Nut (K-4122) Bushing- Rear Engine Barry (D13-1001-4) Bushing Snubber Bar (K066-421) Bush-Anti Vibration (K066-229) 1810 U.J. Kit (5.281X) Lever (K-4464)	1 1 2 2 2 2 1	Brown & Hurley
25.08.2022	Belt-V 17/32 TX X 55 EL (17550BLT)	1	Brown & Hurley
25.08.2022	Bush-Shock Absorber (73D2002) Spring-Airbag (1102-A082) Lever-Clutch Control (K160-2491) Collar-Clamping (K220-614) Spacer-Transmission Sup (K221-3694) Screw-Socket 1/4X2 Unc Csk (6746/TW)	8 2 1 1 4 4	Brown & Hurley
25.08.2022	Replace Clutch Odometer: 716,059 kms Labour hours Travel to Site Adjust clutch as requested Advise customer clutch needs to be replace ASAP Travel back to workshop Travel to site and attempt to adjust clutch, not able to adjust Remove all components required to remove transmission Unbolt and remove transmission from vehicle Collect flywheel from machine shop	20	Anderson Diesel Service



	Travel to site Clean bell housing Remove and replace rear main seal Install flywheel Remove and replace rear engine mounts Install new clutch, spigot and throw out bearing Remove and replace cross shaft bushes Install new cross shafts Install input shaft kit into transmission Re-install transmission Torque all bell housing bolts to spec Re-install shift tower with new gasket Re-install exhaust system Top up Trans Fluid (Customer supplied) Adjust clutch to spec Test drive vehicle, all ok Clean working area Clutch-advantage Eaton (308935529) Flywheel machine (external charge) (FWM) Clutch Brake 2" – 85541 (127760) 4IN Lap Clamp (90358A)		
26.09.2022	Filter Kit S60 Detroit (23518686)	1	Anderson Diesel Service
30.09.2022	Sutton M 10x1.5 Hand Inter (M2011000)	1	City & Country Industrial Supplies Pty Ltd
12.10.2022	Cmpr Air (R23522123) Core Charge (C23522123) Gasket Power Steering Pump (F4HZ3K506C) Gasket (8929299)	1 1 1 1	Wideland Trucks & Equipment
13.10.2022	Lubricant Spray MPSP (97946TLC)	2	Wideland Trucks & Equipment
17.10.2022	Core Charge returned (C23522123)	1	Wideland Trucks & Equipment
24.10.2022	Pipe-Turbo Outlet Exhaust (K180-20354)	1	Brown & Hurley
27.10.2022	REPAIR MANIFOLD LEAK Odometer: 731,675 kms Labour hours Travel to site Remove air intake Remove turbo Remove exhaust manifold Clean all mating surfaces and reassemble Install intake piping and run up NOTES Exhaust manifold cracked Turbo has chipped fin Turbo mount threads need attention	3.25	Anderson Diesel Service
31.10.2022	Thermo-Tech Premix (PG) 20L (ZDFP903107) ¾" Nylon Brake Hose (12-250)	2 1	Wideland Trucks & Equipment

ABN 99 626 549 871

31.10.2022	All items taken on 25.10.2022 Gasket (23539193) Gasket Flange Oil Drain (3680324) Cartridge Aire Dry (2992261)	3 1 1	Wideland Trucks & Equipment
01.11.2022	3/8 x 1 Unc Zinc Plated Ht (381UNCZPHT)	10	City & Country Industrial Supplies Pty Ltd
01.11.2022	NR0ZZ MF Century HP Battery (CEN123120)	4	Bob's Tyre Centres
07.11.2022	Oversize Sign Banner 1200 x 450 mm (130.0017) Premium Heavy Duty Grease 450 GR (3377124CA)	1 1	Truckline
10.11.2022	Rep Kit (81.52102.6114) Purge Valve Kit-NLA (R950014)	1 1	Wideland Trucks & Equipment
12.11.2022	Lubricant Spray MPSP (97946TLC) Hand cleaner Fast Orange (25122)	1 1	Wideland Trucks & Equipment
12.11.2022	Front R/H Windscreen	1	Rocky's Glass Direct
29.11.2022	Replace faulty Main Cab Power circuit Breaker and test Circuit Breaker 140AMP Panel Mount Labour hours	 1 1	Onsite Auto Electrical SEQ
06.12.2022	Vehicle Maintenance Odometer/hrs: 12755 hrs Comments/Description of Works: New turbo 2000 air dryer fitter Replace elbow on exhaust		Todd Warren
06.12.2022	Lube Filter (LF3620)	2	Brown & Hurley
06.12.2022	Socket Rail 1/4" Dr 12pt deep 10pc met (SP20142) Leftwing welders glove (GWL164) Ninja Gloves black L (NIGRPXHPTBK000L) Maxisafe Candy Stripe Glove (GLC145) M4 S/S 304 Nyloc Hex Nut (NN04PCM04) M4X40 S/S 304 Pan Phil Mtr (MS04PPM040040) M4X9X0.8 S/S 304 Rnd F/Wsh (WR04PM04) M4X7.6x0.9 S/S 316 Spr wsh (WR16SM04)	1 1 1 1 2 2 2 2	Maryborough Bolts & Accessories
07.12.2022	Kit – Potentiometer (K128499)	1	Brown & Hurley
16.12.2022	11R22.5 Loadrunner LR188 145/148M (TOT11225LR188) Tyre Labour Fitting Tyre Labour SVC Nmlhrs/15mins Loose Tyres	2 2 4	Bobs Tyre Centre
19.12.2022	11R22.5 16PR Att312 Prem Dr Haulmax (ATT11225312) Tyre Labour Fitting Tyre Labour SVC Nmlhrs/15mins Fit 11R22.5 Haulmax 312 to Pos 7,8 FTSD 8750	2 2 4	Bob's Tyre Centres
11.01.2023	11R22.5 16PR Att312 Prem DR Haulmax (Att11225312) Tyre Labour Fitting Loose wheels PM03	2 2	Bob's Tyre Centres

ABN 99 626 549 871

	Tyre Puncture <i>Loose spider wheel puncture</i>	1	
18.01.2023	Handle-Assy (K294-418)	2	Brown & Hurley
23.01.2023	Amber marker Clear Lens Colo (RDP86AM)	2	Wideland Trucks & Equipment
23.01.2023	Defect Notice – SD 36902074 Replacement, Repairs, or Alterations required to the following: Lights and Electrical Components Details of other items rejected: 1. Roof clearance light right of centre not working 2. Indicator side light (on front mudguard) left hand side not working 3. Indicator flash rate too quick 4. Windscreen washers not working 5. Hi beam warning light in dash not working 6. Window winder handles left and right		Self clear Todd Warren
25.01.2023	Certificate of Inspection – SA 37038452 Effective date: 29.01.2023		Department of Transport & Main Roads
01.02.2023	Silicone 1 in Sold per foot (26244GAT-FT) Thermo-Tech Premix (PG) 20L (ZDFP903107)	4 2	Wideland Group
27.02.2023	Hose ASM 1 2in 3 8in Ends 36in (R95550536BK)	1	Wideland Group
03.03.2023	Lube Filter, Spin-on F/Flow (ZDFP552100)	2	Wideland Group
05.03.2023	Vehicle Maintenance Odometer/Hrs: 13092 hrs Comments/description of works: B-Service Change oil & grease & good check over		Morgan Scriven
08.03.2023	Odometer: 765780 Load Breakdown Truck Travel to Jail brake inn Diagnose throttle to be the issue Remove potentiometre Supply & fit new potentiometre Issue still present Inspect wiring between potentiometre & ECM Found broken wire in the back of ECM plug Remove terminal from plug and solder terminal Refit to plug Refit original ECM Start truck Issue resolved Tape & tie up wiring Clear fault codes Follow truck to Wagga All OK Return to workshop		O'Reilly Trucks

ABN 99 626 549 871

	Kit-Sensor 227 (132034)	1	
30.05.2023	Odometer: 788812.8 Tyre Labour Fitting <i>Fit Customer runouts pos 3,4,5,6</i> <i>Customer runouts in rack</i>	4	Bob's Tyre Centre
02.06.2023	Element-Fuel Filter (23530706) Lube Filter, Spin-On F/Flow (ZDFP552100) Element-Fuel Filter (23530707)	2 4 1	Wideland Group
08.06.2023	Odometer: 795174 385/65R22.5 Hankook AH15 (HAN38565225AH15) Tyre Labour Fitting Tyre Balance <i>Tyres Fitted Pos 1,2</i>	 2 2 2	Bob's Tyre Centre
13.06.2023	Support-Hood (R85-1236) Support-Hood (R85-1236R) Pin-Hood Locating (K179-499)	1 1 2	Brown & Hurley

PM03 – XQ64EK
 2003 Kenworth T404 Prime Mover
 VIN: 6F5000003A425311

	QK4 Connector	1	
	QK1 Connector	2	
29/11/2021	Name Plate – Kenworth	1	Brown and Hurley
7/01/2022	385/65R22.5 Yokohama 106ZS 160J 158L Tyre Labour fitting Tyre Balance Fit to Pos 1, 2	2	Bob's Tyre Centres
20/01/2022	Filter Kit S60 Detroit	1	Anderson Diesel
25/01/2022	11R22.5 16PR TL Att101 Steer Tyre Labour fitting Fitted New Tyres to Pos 15, 16, 17, 18 Fitted Runout to Pos 20 FTSD 9251	4	Bob's Tyre Centres
4/02/2022	Battery Calcium 850 STD	2	Wideland Trucks & Equipment
5/02/2022	Endurance 12V 750CCA Assy C	1	Wideland Trucks & Equipment
10/02/2022	H1 12V 55W BL PK 1	1	Wideland Trucks & Equipment
22/02/2022	Certificate of Inspection – effective 10/2/2022 SA 35508539		Department of Transport and Main Roads
21/03/2022	Switch-Turn Indicator	1	Brown and Hurley
23/03/2022	Fuel Filter, Water Sep Cart	1	Wideland Trucks & Equipment
24/03/2022	Jost JSK37CW G/Less Repair Kit Wear ring insert Type E Wear ring E type G Less	1 1 1	Wideland Trucks & Equipment
25/03/2022	Wire new combo switch to suit truck wiring		Onsite Auto Electrical SEQ
28/03/2022	Remove and replace engine oil and filter Remove and replace 2 x fuel filters Remove and clean air filter Grease spring pins Assist in removing steering wheel Assist with Service Remove and replace fuel pro filter Travel to yard Remove and replace lube plate on turntable Remove and replace turntable foot bushes and bolts Remove and replace Jaw Kit Remove and replace 4 bolt wear ring		Anderson Diesel
10/05/2022	Pipe-Turbo Outlet Exhaust Gasket AFM Device Clamp" V-Band	1 1 1	Brown and Hurley
10/05/2022	Plant Number Sticker "PM03"	1	Auswide Signage
10/06/2022	Spotter Round 8"/230 MM SS	1	Wideland Trucks & Equipment

PM03 – XQ64EK
2003 Kenworth T404 Prime Mover
VIN: 6F50000003A425311

30/06/2022	Element – Oil Filter	2	Wideland Trucks & Equipment