



814 Saint Etienne Road
Broussard, LA 70518

337-252-7263
powerhouserv@yahoo.com

Bill To

Aucoins Transport (Landstar)
203 Ave B
Broussard, La 70518

Invoice

Date	Invoice #
9/19/2025	4336

VIN Number	Terms	P.O. Number	Make	Mileage
1XKYDP9X1HJ154615	Due on receipt		2016 KW	663839

Qty	Item	Description	Rate	Amount
10	Labor	Labor	130.00	1,300.00T
1	MISC.	Mounting Hardware	36.10	36.10T
1	81630	Red RTV	15.16	15.16T
2	2866636	Gasket, Exhaust, Circular 4"	20.01	40.02T
1	2866337	Gasket, Circular, 5"	21.94	21.94T
1	90-0012	Clamp, Band, 4"	26.38	26.38T
		Replaced DPF filter customer furnished filter		

Subtotal	\$1,439.60
Sales Tax (9.5%)	\$136.76
Total	\$1,576.36



814 Saint Etienne Road
Broussard, LA 70518

Invoice

Date	Invoice #
10/13/2025	4381

337-252-7263
powerhouserv@yahoo.com

Bill To

Aucoins Transport (Landstar)
203 Ave B
Broussard, La 70518

VIN Number	Terms	P.O. Number	Make	Mileage
1XKYDP9X1HJ154615	Due on receipt		2016 KW	664,127

Qty	Item	Description	Rate	Amount
15	Labor	Labor COMPLAINT: Check Engine Light CAUSE: EGR Valve had all faults, system very dirty and clogged CORRECTION: Plugged autel and retrived fault codes. Ran test on system and did not respond as should. Pulled a couple of egr ports and sensor and seen how dirty. Customer approved a complete egr flush. Pulled cooler and cross over tube and cleaned. Customer furnished new egr valve and misc parts. Installed parts and ran truck. Needed OEM software for further installation and diags. Performed a stationary regen, system passed and no check engine lights came on.	130.00	1,950.00

Subtotal	\$1,950.00
Sales Tax (9.5%)	\$185.25
Total	\$2,135.25



814 Saint Etienne Road
Broussard, LA 70518

Invoice

Date	Invoice #
10/13/2025	4381

337-252-7263
powerhouserv@yahoo.com

Bill To

Aucoins Transport (Landstar)
203 Ave B
Broussard, La 70518

VIN Number	Terms	P.O. Number	Make	Mileage
1XKYDP9X1HJ154615	Due on receipt		2016 KW	664,127

Qty	Item	Description	Rate	Amount
15	Labor	Labor COMPLAINT: Check Engine Light CAUSE: EGR Valve had all faults, system very dirty and clogged CORRECTION: Plugged autel and retrived fault codes. Ran test on system and did not respond as should. Pulled a couple of egr ports and sensor and seen how dirty. Customer approved a complete egr flush. Pulled cooler and cross over tube and cleaned. Customer furnished new egr valve and misc parts. Installed parts and ran truck. Needed OEM software for further installation and diags. Performed a stationary regen, system passed and no check engine lights came on.	130.00	1,950.00

Subtotal	\$1,950.00
Sales Tax (9.5%)	\$185.25
Total	\$2,135.25



814 Saint Etienne Road
Broussard, LA 70518

Invoice

Date	Invoice #
10/13/2025	4381

337-252-7263
powerhouserv@yahoo.com

Bill To

Aucoins Transport (Landstar)
203 Ave B
Broussard, La 70518

VIN Number	Terms	P.O. Number	Make	Mileage
1XKYDP9X1HJ154615	Due on receipt		2016 KW	664,127

Qty	Item	Description	Rate	Amount
15	Labor	Labor COMPLAINT: Check Engine Light CAUSE: EGR Valve had all faults, system very dirty and clogged CORRECTION: Plugged autel and retrived fault codes. Ran test on system and did not respond as should. Pulled a couple of egr ports and sensor and seen how dirty. Customer approved a complete egr flush. Pulled cooler and cross over tube and cleaned. Customer furnished new egr valve and misc parts. Installed parts and ran truck. Needed OEM software for further installation and diags. Performed a stationary regen, system passed and no check engine lights came on.	130.00	1,950.00

Subtotal	\$1,950.00
Sales Tax (9.5%)	\$185.25
Total	\$2,135.25



814 Saint Etienne Road
Broussard, LA 70518

337-252-7263
powerhouserv@yahoo.com

Bill To

Aucoins Transport (Landstar)
203 Ave B
Broussard, La 70518

Invoice

Date	Invoice #
10/13/2025	4381

VIN Number	Terms	P.O. Number	Make	Mileage
1XKYDP9X1HJ154615	Due on receipt		2016 KW	664,127

Qty	Item	Description	Rate	Amount
15	Labor	Labor COMPLAINT: Check Engine Light CAUSE: EGR Valve had all faults, system very dirty and clogged CORRECTION: Plugged autel and retrived fault codes. Ran test on system and did not respond as should. Pulled a couple of egr ports and sensor and seen how dirty. Customer approved a complete egr flush. Pulled cooler and cross over tube and cleaned. Customer furnished new egr valve and misc parts. Installed parts and ran truck. Needed OEM software for further installation and diags. Performed a stationary regen, system passed and no check engine lights came on.	130.00	1,950.00

Subtotal	\$1,950.00
Sales Tax (9.5%)	\$185.25
Total	\$2,135.25