



Box 9 • 105 Angus Street
 Windthorst, SK S0G 5G0
 Phone: 306-224-2110 • Fax: 306-224-4343
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Davidson 306-567-3074
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629

Ship To: .

Branch WINDTHORST		
Date 03/30/26	Time 08:42:48 (O)	Page 01
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson S81

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UT2222	Tractor 4WD	3341	ZFF303822	03/31/17	CB
	ST620Q			04/22/19	PP

SEGMENT# 1 C 44015 QUAD INSP. 02/05/26 02/06/26
 QUADTRAC INSPECTION
CORRECTION:
 -am- 2/27/26 - help with flow checks
 LM-completed inspection
 went through it with costumer and made a list of repairs to
 be done.
 11008004

SEGMENT# 2 C 44015 QUAD INSP WA 02/05/26
 QUADTRAC INSPECTION WASH

SEGMENT# 3 C 44015 NA 02/05/26 02/23/26
 SCR ERROR COMING UP
CORRECTION:
 - AM- 2/23/26 - test def system and diag problem
 - found coolant coming out of the electrical plug on def
 pump causing the def faults. Replaced def pump hooked
 new one up will have to let it thaw out before we can run a
 udst test, cleared all the faults , cleared faults in easy
 engine, and re set the inducements
 no active faults no leaks topped up coolant with 1.5 L oat
 coolant
 - am- 2/24/26 - hooked est up and ran udst test wouldn't
 prime up hooked inlet up to a small bottle of def worked
 good but def quality code came up so i drained the def
 rinsed tank and cleaned up sensor put back together and
 put 5 jugs of new def back in cleaned up mess and put
 tools away ran a couple more tests they all passed so i

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 • An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.
 • Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

Thank You!
 We Appreciate Your Business



Box 9 • 105 Angus Street
 Windthorst, SK S0G 5G0
 Phone: 306-224-2110 • Fax: 306-224-4343
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Davidson 306-567-3074
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629

Ship To: .

Branch WINDTHORST		
Date 03/30/26	Time 08:42:48 (O)	Page 02
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson S81

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UT2222	Tractor 4WD	3341	ZFF303822	03/31/17	CB
	ST620Q			04/22/19	PP

kicked unit out side and let it run to make sure no more def codes come up
 LM-03/13/26- SCR code came back up. hooked up est and had a code for SCR fault under high pressure, ran a udst test to test system under high pressure and everything worked good. cleared code but the fault wouldn't go away on A post, opened up easy tool and it said there was 2 active codes but couldn't identify them. went back into est and ran a SCR repair verification test which took some time had to get the exhaust gas temp up to 464 F. after going through the test it said complete and everything looked good. code went away after test and there was no codes in est or easy tool.

-03/16/2026- checked again and code came back, drained DEF disconnected battery cables from batteries then removed battery box and frame that goes around def tank above the fender. removed 12v/24v kill switch and fuse control panel and tied it up out of the way. marked and removed inlet/outlet and backflow DEF lines then removed coolant lines from sender and dosing module. covered hoses in plastic and tied them out of the way. removed retaining bar for tank. removed DEF lines and hoses from tank, loosened hose clamp on bottom DEF line then pryed tank up and pulled it out enough to get at the sender. pulled old sender out of tank and put on bench, opened new sender and realized it was the wrong one, ordered new sender. cleaned up tools. got the different sender in and installed into tank making sure it fit, hooked up def and coolant lines and plugged in wiring harness. pushed DEF tank back in place and hooked up

CONTINUED ON PAGE 03

- I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
- It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
- Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
- An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
- Estimates are for the items specifically identified in the estimate only, and are non-binding.
- Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

Received By

X

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

Thank You!
 We Appreciate Your Business



Box 9 • 105 Angus Street
 Windthorst, SK S0G 5G0
 Phone: 306-224-2110 • Fax: 306-224-4343
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Davidson 306-567-3074
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629

Ship To: .

Invoice To:

Branch WINDTHORST		
Date 03/30/26	Time 08:42:48 (O)	Page 03
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson S81

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
UT2222	Tractor 4WD ST620Q	3341	ZFF303822	03/31/17 04/22/19		CB PP
retaining bar securing tank in place. hooked up wiring harnesses back to 12v/24v control board and set it in place, lifted fender frame back into place and installed bolts. hooked up battery cables and installed battery box and lid. connected def lines on outside of tank then rinsed tank with water then filled with DEF. hooked up est and ran def tests everything was working as it should, ran unit for a while and no codes came up. parked unit outside, cleaned up stall and tools.						
EHC9.46	ENVIRO CHARGE	5		1.80		9.00
YE25	9.46L DEF JUG	5		16.89		84.45
47962045	SENSOR, LEVEL	1 M		850.15		850.15
5802855463R	REMAN-MODULE	1		2482.77		2482.77
5802855463C	CORE-ELECTRONIC			6.84		6.84
769714Z1USX	ACTIFULL OT Co	2		4.91		9.82
				PARTS		3443.03
				LABOR		3950.15
11008004			SEGMENT TOTAL==>			7393.18

SEGMENT#						
4 C 44015 NA	REPAIR BEACON	02/05/26	03/06/26			
<u>CORRECTION:</u> changed light bulb						
14151095	BULB	1		10.51		10.51
				PARTS		10.51
				LABOR		59.70
11008004			SEGMENT TOTAL==>			70.21

SEGMENT#						
5 C 44015 NA	CLEAN OUT FUSE BOX/MICE, REPAIR FILTER HOUSING	02/05/26	03/06/26			

CONTINUED ON PAGE 04

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 • An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.
 • Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

Thank You!
 We Appreciate Your Business



Box 9 • 105 Angus Street
 Windthorst, SK S0G 5G0
 Phone: 306-224-2110 • Fax: 306-224-4343
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Davidson 306-567-3074
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629

Ship To: .

Invoice To:

Branch WINDTHORST		
Date 03/30/26	Time 08:42:48 (O)	Page 04
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson S81

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UT2222	Tractor 4WD	3341	ZFF303822	03/31/17	CB
	ST620Q			04/22/19	PP

CORRECTION:

LM-removed buddy seat and back rest, under floor mat removed nuts holding fuse panel in place then removed panel. removed RH rear A post which i had to remove mounting bar for Pottinger control box. removed screws, plastic clips and wiring from plugs then removed panel behind operator seat. removed top hose from cab filter housing then went underneath and removed intake tube from housing, removed 4 mounting nuts then pulled filter housing out. vacuumed and blew out dust and mouse droppings from behind operator seat and in fuse box. sprayed area with disinfectant spray and wiped everything down.

put new filter housing inplace and installed intake tube then had to pry housing a bit to get it to line up then installed nuts, and top air line.
 put some mouse repellent in behind seat.
 cleaned up cab panels then reinstalled them in cab, cleaned up tools after all panels were in place.

KZ0011	FRESH SCENT	1	16.79	16.79
87596194	HOUSING	1 M	574.78	574.78
	PARTS			591.57
	LABOR			1420.86
11008004	SEGMENT TOTAL==>			2012.43

SEGMENT# 6 C 44015 NA 02/05/26 03/06/26
 REPLACE TOP RAD HOSE, CLEAN RAD AND COOLERS

CORRECTION:

ls- drained a pail of coolant, replaces hose, filled coolant back in, bled system

CONTINUED ON PAGE 05

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 • An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.
 • Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By



Box 9 • 105 Angus Street
 Windthorst, SK S0G 5G0
 Phone: 306-224-2110 • Fax: 306-224-4343
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Davidson 306-567-3074
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629

Ship To: .

Invoice To:

Branch WINDTHORST		
Date 03/30/26	Time 08:42:48 (O)	Page 05
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson S81

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
UT2222	Tractor 4WD ST620Q	3341	ZFF303822	03/31/17		CB
				04/22/19		PP
LM-added 1L OT coolant to secondary coolant tank. backed unit up and washed floor. LM-backed unit into middle of shop and pressure washed rads and coolers used garden hose with rad wand to clean in the tighter areas.						
769714Z1USX	ACTIFULL OT Co			1	4.91	4.91
92713187	HOSE RADIATOR			1	98.30	98.30
					PARTS	103.21
					LABOR	817.89
11008004				SEGMENT TOTAL==>		921.10

SEGMENT# 7 C 44015 NA	02/05/26 03/06/26					
TOP UP A/C, INSTALL MISSING CAP <u>CORRECTION:</u> LM-checked with parts, you cant order the caps. recovered freon from system 3.90lbs. put a vacuum on system, then filled 5.5lbs r134.						
R134A	FREON			2	24.50	49.00
51518288	HOSE			2 M	48.52	97.04
					PARTS	146.04
					LABOR	222.88
11008004				SEGMENT TOTAL==>		368.92

SEGMENT# 8 C 44015 NA	02/05/26 03/06/26					
REPAIR FUEL LEAK ON WATER FILTER <u>CORRECTION:</u> drained fuel, changed sensor o ring and cleaned fuel bowl						
					LABOR	179.10
11008004				SEGMENT TOTAL==>		179.10

CONTINUED ON PAGE 06

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 • An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.
 • Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

Thank You!
 We Appreciate Your Business



Box 9 • 105 Angus Street
 Windthorst, SK S0G 5G0
 Phone: 306-224-2110 • Fax: 306-224-4343
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Davidson 306-567-3074
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629

Ship To: .

Invoice To:

Branch WINDTHORST		
Date 03/30/26	Time 08:42:48 (O)	Page 06
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson S81

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UT2222	Tractor 4WD ST620Q	3341	ZFF303822	03/31/17 04/22/19	CB PP

SEGMENT# 9 C 44015 NA	02/05/26 03/06/26				
REPLACE BOTTOM STEERING HOSES					
<u>CORRECTION:</u>					
LM-removed clamp and hose changed o-rings in fittings, installed new hoses and reinstalled clamps did the same for both sides. cleaned up tools.					
48159419	HOSE HYDRAULIC	2 M	86.52		173.04
			PARTS		173.04
			LABOR		115.42
11008004			SEGMENT TOTAL==>		288.46

SEGMENT#10 C 44015 NA	02/05/26 03/09/26				
REPAIR HOSE LEAK ON FRONT DIFF					
<u>CORRECTION:</u>					
LM-hose clamp was as tight as it would go, removed clamp and got a smaller size and tightened it up. cleaned up oily hose.					
			LABOR		3.98
11008004			SEGMENT TOTAL==>		3.98

SEGMENT#11 C 44015 NA	02/05/26 03/06/26				
HYDRAULIC SYSTEM REPAIRS					
<u>CORRECTION:</u>					
ls- tightened hose clamps on trans supply boot, replaced rubber boots on hyd tank supply lines, replaced o rings in fan motor fitting and trans pump fitting					
LM-removed side panel above hyd tank and cleaned area around boots before replacing them. reinstalled steel line					

CONTINUED ON PAGE 07

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 • An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.
 • Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

Thank You!
 We Appreciate Your Business



Box 9 • 105 Angus Street
 Windthorst, SK S0G 5G0
 Phone: 306-224-2110 • Fax: 306-224-4343
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Davidson 306-567-3074
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629

Ship To: .

Invoice To:

Branch WINDTHORST		
Date 03/30/26	Time 08:42:48 (O)	Page 07
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson S81

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UT2222	Tractor 4WD	3341	ZFF303822	03/31/17	CB
	ST620Q			04/22/19	PP

for hyd fan motor cleaned oil spills and cleaned up tools.
 changed hyd breather, reinstalled panel.
 filled 10L hytran.
 discarded oil from catch pales and cleaned them.
 -removed hyd hose clamp that was missing a bolt, made sure
 the threaded hole was good and didnt need repaired.
 reinstalled clamp with new bolt. removed bolt on other
 clamp and put a new washer on it used plyers to hold rivot
 in place then tightened bolt into it. cleaned up tools

ADDITIONAL DESCRIPTION:

Fix leak on fitting on hyd motor
 repair boot on trans pump
 repair line on trans pump
 replace breather
 repair lines on tank
 repair clamps on hyd lines

EHCOIL	EHC CHARGE	10	.06	.60
PHAS-20	#20 HOSE CLAMP	1	1.70	1.70
11030431	BOLT	1 M	6.33	6.33
1971726C1	BREATHER	1	31.08	31.08
77400001US	ULTRACTION BULK	RETAIL	5.92	
		10	5.79	57.90
86598104	O-RING	1	8.57	8.57
9991976	O-RING	1	2.16	2.16
	PARTS			108.34
	LABOR			1333.30
11008004	SEGMENT TOTAL==>			1441.64

SEGMENT#12 C 44015 NA 02/05/26 03/06/26
 REPLACE LH HOOD SHOCK

CONTINUED ON PAGE 08

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 • An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.
 • Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

Thank You!
 We Appreciate Your Business



Box 9 • 105 Angus Street
 Windthorst, SK S0G 5G0
 Phone: 306-224-2110 • Fax: 306-224-4343
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Davidson 306-567-3074
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629

Ship To: .

Branch WINDTHORST		
Date 03/30/26	Time 08:42:48 (O)	Page 08
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson S81

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
UT2222	Tractor 4WD ST620Q	3341	ZFF303822	03/31/17 04/22/19		CB PP
<u>CORRECTION:</u>						
replaced the hood shock						
84561096			GAS STRUT	1	293.07	293.07
					PARTS	293.07
					LABOR	85.57
11008004				SEGMENT TOTAL==>		378.64

SEGMENT#13	C 44015 NA	02/05/26	03/06/26			
REDO SILICONE ON CAB ROOF						
<u>CORRECTION:</u>						
LM-scraped off old silicone and buffed up paint for new sealant to stick on.						
drilled 2 holes and used metal bracket and 2 screws to stitch up the crack so it cant flex and crack again/more.						
put sealant over crack and stitch, cleaned up tools.						
					LABOR	232.83
11008004				SEGMENT TOTAL==>		232.83

SEGMENT#14	C 44015 NA	02/05/26	03/06/26			
SERVICE AND GREASE						
<u>CORRECTION:</u>						
ls- replaces crankcase filter and gasket						
ls- changed all hydrylic filters						
<u>ADDITIONAL DESCRIPTION:</u>						
Replace crankcase filter						
Replace Hyd and trans filters						
Replace cab filter						
EHCFLT2			EHC CHARGE	3	1.25	3.75
47833556			FILTER, HY	1	146.11	146.11
504387088			GASKET	1	61.18	61.18

CONTINUED ON PAGE 09

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 • An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.
 • Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

Thank You!
 We Appreciate Your Business



Box 9 • 105 Angus Street
 Windthorst, SK S0G 5G0
 Phone: 306-224-2110 • Fax: 306-224-4343
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Davidson 306-567-3074
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629

Ship To: .

Invoice To:

Branch WINDTHORST		
Date 03/30/26	Time 08:42:48 (O)	Page 09
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson S81

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
UT2222	Tractor 4WD ST620Q	3341	ZFF303822	03/31/17		CB
				04/22/19		PP
5949768015	FILTER			1	103.31	103.31
84196445	HYD OIL FILTER			2	215.98	431.96
87684088	CAB AIR FILTER			1	81.29	81.29
	PARTS					827.60
	LABOR					252.45
11008004	SEGMENT TOTAL==>					1080.05

SEGMENT#15 C 44015 NA 02/05/26 03/06/26

RESEAL BOGIE A7

CORRECTION:

LM-put block behind front left track and backed up until the track was up on the block. released tension on track seemed like it was a bit siezed up and wouldnt loosen enough to get bogie off, had to used a come along and suck the idlers together. drained oil from bogie, removed cap and bolt then pulled bogie off. washed dirt out of bogie and cleaned it all up. hammered bearing races out of bogie wheel. used a puller and pulled old seal cup off shaft. used tool and installed new seal cup, and new bearing races into bogie wheel. buffed and cleaned seal surface in bogie then used tool and pressed seal into bogie and into cup on shaft. cleaned again with alcohol then installed bogie onto shaft, put some oil on bolt and torqued it to 350ft-lbs. made sure it spun good then reinstalled cap and snap ring, pressure tested with air to make sure nothing leaks out. filled with sae 30 motor oil. put shop tools away, cleaned up my tools.

48194035	SEAL			1	206.36	206.36
648861	BEARING, ROLLER			2	93.23	186.46

CONTINUED ON PAGE 10

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 • An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.
 • Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

Thank You!
 We Appreciate Your Business



Box 9 • 105 Angus Street
 Windthorst, SK S0G 5G0
 Phone: 306-224-2110 • Fax: 306-224-4343
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Davidson 306-567-3074
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629

Ship To: .

Invoice To:

Branch		
WINDTHORST		
Date	Time	Page
03/30/26	08:42:48 (O)	10
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
	Salesperson	
	S81	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
UT2222	Tractor 4WD	3341	ZFF303822	03/31/17		CB
	ST620Q			04/22/19		PP
84223194		CUP		1	93.52	93.52
					PARTS	486.34
					LABOR	1040.77
11008004				SEGMENT TOTAL==>		1527.11

***** WORK ORDER TOTALS *****

PARTS	6182.75
LABOR	9714.90
shop supplies	400.00
EST SFTWARE FEE	75.00
QUADTRAC INSPEC	1799.00
WASH DISCOUNT	400.00-
SUB TOTAL==>	17771.65
PST 6%	5.06
GST 5%	888.65
TOTAL CREDIT CARD	18665.36

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

Thank You!
 We Appreciate Your Business