

Apremier Auto Shops
1418 S Interstate 35
San Marcos, TX. 78666
Phone: 512-216-6246

INVOICE

1429

4/01/2026
152,294

INVOICE

Printed Date: 04/01/2026

Work Completed: 04/01/2026

2012 BMW - 128i - 3L, In-Line6 (183CI) VIN(C)

Lic # : RZZ3087

Odometer In : 152294

Home [REDACTED]

VIN # : WBAUP7C59 CVP22844

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
EiKO Automotive Lighting Standard Lamp - Single Pa H755BP	1.00	9.60	9.60	Test and Replace Battery	90.00
				Replace headlight bulbs	90.00
MicroGard Engine Oil Filter MGL57327	1.00	18.09	18.09	Oil Change	19.00
ENGINE OIL sh	7.00	5.18	36.26	Hazardous Materials	5.00
Shop Supplies			8.46		

Org. Estimate 282.38 Revisions 0.00 Current Estimate 282.38

Labor:	199.00
Parts:	72.41
HazMat:	5.00
SubTotal:	276.41
Tax:	5.97
Total:	282.38
Bal Due:	\$0.00

[Payments - Elec - Credit Card - \$282.38]

Vehicle Received: 4/1/2026

Customer Number : 933

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Agudelo, Julian Paid \$ 282.38 Card#: xxxxxxxxxxxxxxx0564 Transaction: 685301763-Debi-0564 Approval:

DEBIT:313228:242204688:685301763::: Date/Time: 4/1/2026 12:09:22PM

TRANSACTIONTYPE: DEBIT TRANSACTIONRESULT: APPROVED TIMESTAMP: 4/1/2026 12: 09: 20 PM MERCHANTORDERNUMBER:

1429 AMOUNT: 282.38 ENTRYMETHOD: C NAME: JULIAN F AGUDELO ACCOUNTTYPE: Debit ACCOUNT: XXXXXXXXXXXX0564

ORDERID: 545966115 TRANSACTIONID: 685301763 AUTHCODE: 313228

APPLABEL:USDEBIT AID:A0000000980840 TVR:8080048000 IAD:06011203A00000 TSI:6800 ARQC:57E2DCA396776EE9 ARC:00 CVM:P

Signature x

04/01/2026

Buyer agrees to pay total amount above according to cardholder's agreement with issuer.

Email Address: apremiautosshops.i35s.smtx@gmail.com

No. 186217



Take 5 Oil Change #0202 (Drawer #2)
1200 THORPE LANE
SAN MARCOS, TX 78666
5126677631
11/04/2025 02:17 PM

11/04/2
149,

WE ARE GREATFUL FOR YOUR BUSINESS

Customer

MR. [REDACTED] (REP)
4310 LANLAN
77521

Vehicle

2012 BMW 128I
ACCT # BACP22844 VIN: WBAUP7C59CVP22844
PLATE #: RZZ3087 Present Mileage: 149,655

Description

Quantity

Lubricant

Part

Taxable

Price

DURAMAX FULL SYN XLT	5.00	XLTOW30EUQT X5607		\$54.00	\$101.99
Lubricant Description: DURAMAX FS XLT OW30 EU QT					
Shop Service Charge	1.00			\$5.99	\$5.99
Extra oil over 5 units	1.90	XLTOW30EUQT		\$20.88	\$20.88
Lubricant Description: DURAMAX FS XLT OW30 EU QT					
Non-Taxable					

SubTotal \$47.99 \$80.87 \$128.86

Tax (8.250%) \$6.67

TOTAL (VISA) \$135.53

SERVICE CHECK LIST

1. Oil Change.....Complete
2. Oil Filter.....Replaced
3. Drain Plug.....Drained OK
4. Plug Gasket ...Replaced
6. Air Filter.....Rec Repl
7. PS Fluid..... N / A
8. Coolant.....Rec Serv
9. Transmission... N / A
10. Washer Fluid...Filled
11. Wiper Blades...OK
12. Cabin Filter...Rec Repl
13. Oil Level.....Safe Level
14. Windshield.....Cleaned
15. Tires.....Checked

Techs: ZAIDEN (Hood) NOA (Pit)
ZAIDEN (Safety) OMAR (MoD)
ZAIDEN (Svc Writer)

WATER FIND IN OIL CAP
MEATL SHAVINGS OUT OF OIL PAN 11/23/2024

Customer Signature

Please retain this receipt. It will provide a record of the date and mileage for warranty purposes.

If a problem should arise related to workmanship or product and you are seeking a refund, reimbursement, and/or repair, you must inform Take 5 Oil Change immediately by contacting the shop where the services were provided. Do not have any diagnostic or repair work performed on your vehicle without first securing approval from a Take 5 District Manager. Take 5 is not responsible for any repairs, towing, diagnostics, or other services completed without Take 5's authorization. See warranty information on the back of this invoice for details. We do not service manual transmissions.



No. 33006

Take 5 Oil Change #0547 (Drawer #6)
2425 Center St.
Deer Park, TX 77536
281-478-4100 www.take5oilchange.com
05/30/2025 01:08 PM

5/30/25
146,213

WE OFFER COOLANT EXCHANGES FOR \$140.99 W \$15 OFF OIL

Customer	Vehicle
MR. [REDACTED] (REP) [REDACTED] 77521 [REDACTED] take5.shop552@take5oilchange.com	2012 BMW 128I ACCT # BACP22844 VIN: WBAUP7C59CVP22844 PLATE #: RZZ3087 Present Mileage: 146,213

Description	Quantity	Lubricant	Part #	Taxable	Price
DURAMAX FULL SYN XLT	5.00	XLTOW30EUQT X5607		\$54.00	\$101.99
Lubricant Description: DURAMAX FS XLT OW30 EU QT					
Shop Service Charge	1.00			\$4.99	\$4.99
Extra oil over 5 units	1.90	XLTOW30EUQT		\$18.98	\$18.98
Lubricant Description: DURAMAX FS XLT OW30 EU QT					
STATE INSPECTION	1.00			\$0.00	\$18.50
Non-Taxable					
SubTotal	\$66.49			\$77.97	\$144.46
Coupon (DMDOOP10)					\$10.00
Tax (8.000%)					\$5.81
TOTAL (VISA)					\$140.27

SERVICE CHECK LIST

1. Oil Change.....Complete
2. Oil Filter.....Replaced
3. Drain Plug.....OK
4. Plug Gasket ...Replaced
6. Air Filter.....Clean
7. PS Fluid.....Safe Level
8. Coolant.....Safe Level
9. Transmission...Safe Level
10. Washer Fluid...Filled
11. Wiper Blades...OK
12. Cabin Filter... N / A
13. Oil Level.....Safe Level
14. Windshield.....Cleaned
15. Tires.....Checked

moderate oil leak from oil pan o/a 5/30/25

Techs: ANTHONY (Hood) MICHAEL (Pit)
ANTHONY (Safety) MICHAEL (MoD)
ANTHONY (Svc Writer)

Please retain this receipt. It will provide a record of the date and mileage for warranty purposes.

Customer Signature

If a problem should arise related to workmanship or product and you are seeking a refund, reimbursement, and/or repair, you must inform Take 5 Oil Change immediately by contacting the shop where the services were provided. Do not have any diagnostic or repair work performed on your vehicle without first securing approval from a Take 5 District Manager. Take 5 is not responsible for any repairs, towing, diagnostics, or other services completed without Take 5's authorization. See warranty information on the back of this invoice for details. We do not service manual transmissions.



No. 164233

Take 5 Oil Change #0202
1200 THORPE LANE
SAN MARCOS, TX 78666
5126677631
11/23/2024 02:46 PM

11/23/24
139,386

WE ARE GREATFUL FOR YOUR BUSINESS

Customer

MR. [REDACTED] (NEW)
[REDACTED]
[REDACTED]@gmail.com

Vehicle

2012 BMW 128I
ACCT # BACP22844 VIN: WBAUP7C59CVP22844
PLATE #: RZZ3087 Present Mileage: 139,386

Description

Quantity

Lubricant

Part #

Taxable

Price

DURAMAX FULL SYN XLT	5.00	XLTOW30EUQT X5607		\$54.00	\$101.99
Lubricant Description: DURAMAX FS XLT OW30 EU QT					
Shop Service Charge	1.00			\$4.99	\$4.99
Extra oil over 5 units	1.90	XLTOW30EUQT		\$18.98	\$18.98
Lubricant Description: DURAMAX FS XLT OW30 EU QT					
Non-Taxable					

SubTotal \$47.99 \$77.97 \$125.96

Tax (8.250%) \$6.43

TOTAL (VISA) \$132.39

SERVICE CHECK LIST

1. Oil Change.....Complete
2. Oil Filter.....Replaced
3. Drain Plug.....Drained OK
4. Plug Gasket ...Replaced
6. Air Filter.....Clean
7. PS Fluid.....Safe Level
8. Coolant.....Safe Level
9. Transmission...Safe Level
10. Washer Fluid...Filled
11. Wiper Blades...OK
12. Cabin Filter... N / A
13. Oil Level.....Safe Level
14. Windshield.....Cleaned
15. Tires.....Checked

Techs: ANDRES (Hood) OMAR (Pit)
ANDRES (Safety) OMAR (Mod)
STEVO (Svc Writer)

WATER FIND IN OIL CAP
MEATL SHAVINGS OUT OF OIL PAN 11/23/2024

Customer Signature

retain this receipt. It will provide a record of the date and mileage for warranty purposes.

problem should arise related to workmanship or product and you are seeking a refund, reimbursement, and/or repair, you must inform Take 5 Oil Change immediately by contacting the shop where the services were provided. Do not have any diagnostic or repair work performed on your vehicle without first approval from a Take 5 District Manager. Take 5 is not responsible for any repairs, towing, diagnostics, or other services completed without approval from a Take 5 District Manager. Take 5 is not responsible for any repairs, towing, diagnostics, or other services completed without approval from a Take 5 District Manager. Take 5 is not responsible for any repairs, towing, diagnostics, or other services completed without approval from a Take 5 District Manager. We do not service manual transmissions or differentials.