

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
22026					
	76448	Adjust and set reverse beeper switch to finish.	14/01/2005		
	76449	Grease all points, adjust tracks, reseal poly roller quick coupler.	19/01/2005		
	76450	1000 hour service.	14/07/2005		
	76451	Mark and remove hose's in control box. Raise console and started re-running new wiring.	29/08/2005	208	
	76452	Re-run new hoses and wiring into front console. Console modification.	30/08/2005	208	
	76453	Continue with dash.	1/09/2005		
	76454	Finish off raising dash and re-running hoses. Washed down machine, run and test.	2/09/2005		
	76414	Fit new cat key starting switch.	28/06/2006	176	
	76415	Replace alternator.	30/06/2006	222	
	76416	Replace entire engine to dash wiring harness and fuel pump solenoid.	6/07/2006	230	
	76417	Install new fuel stop solenoid.	13/07/2006		
	76418	R/R broken track drive motor fitting.	25/07/2006	302	
	76419	Reseal track drive motor leg 1.	8/08/2006	315	
	76420	Remove re-fab rake on TC set up shock absorbers on rake frame.	25/08/2006	355	
	76421	Reseal hand control valves at operator panel.	26/08/2006	357	
	76422	Finish fabricating bump stop for TC rake.	28/08/2006	362	
	76423	Swap track drive motors to identify steering problem	15/09/2006	390	
	76424	Replace resin screens to available strainer assemblies	9/11/2006	470	
	76425	Shorten machine and load out	1/12/2006	14027	
	76426	Check over travel operation	11/01/2007	503	
	76427	Fit up new valves for resin spraying	16/01/2007	504	
	76428	Check out lack of drive power found relief valve adjuster worn adjusted and ordered new screw	22/01/2007	510	

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	76429	Repair broken wiring loom caught in steering ram	16/02/2007	530	
	76430	Fit new Hr meter. Old meter failed at 547hrs	28/03/2007		
	76431	Pack up and prepare for transport	5/06/2007		
	76432	Repair leg drive problem replace drive pin	29/06/2007	36	
	76433	Adjust rake chain and drive chain	6/07/2007	36	
	76434	Wire up travel micro switch for travel warning	10/08/2007	42	
	76435	Remove stringline sensor setup and reposition leg control boxes	23/10/2007	101	
	53358	Remove leg 1 strip and clean out bearing parts that are jamming leg, clean replace parts	22/04/2008	189	
	76436	Remove leg 1 strip and clean out bearing parts that are jamming leg, clean replace parts	22/04/2008	189	
	53359	100HR service	13/05/2008	206	
	76437	100hr service	13/05/2008	206	
	53360	Replace pivot dowel in carriage control lever	7/07/2008	231	
	76438	Replace pivot dowel in carriage control lever	7/07/2008	231	
	53361	Frabricate flashing light bracket	30/09/2008		
	53715	500 hr service	17/01/2009	497	
	76440	500 hr service	17/01/2009	497	
	53716	Bleed fuel system	14/02/2009	540	
	76441	Bleed fuel system	14/02/2009	540	
	53717	Replace blown hydraulic hose on pump	27/03/2009	651	
	76442	Replace blown hydraulic hose on pump	27/03/2009	651	
	53718	Remove and re-seal spray control valve, replace battery and fabricate hold down bracket	9/05/2009		
	53719	Mechanical Inspection	15/05/2009		
	53720	Mechanical inspection	16/05/2009		

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	53721	Repair pos 4 leg elevation drive	14/07/2009	777	
	53722	Fit new fuel transfer pump	13/08/2009	805	
	33576	Cleaned out resin tanks and spray system	14/04/2011		
	35203	REMOVED PUMP #1 AND CLEAN OUT HARDENED RESIN	23/06/2011		
	35210	REPAIRED BROKEN FITTING ON BOTTOM OF WAX TANK	30/06/2011		
	33286	FIT FLOW METERS TO WAX LINES	8/07/2011	858	
	60413	REMOVE AND REPLACE RADIATOR AFTER CLEANING OUT	19/03/2013	1034	
	57955	REMOVE AND REPLACE RADIATOR AFTER CLEANING OUT	19/03/2013	1034	
	77802	FIT NEW MIDDLE SPRAY BOOM LIFT CYLINDER	9/03/2015	1294	Planned
	78004	REPLACE TRACK CONTROL HOSE UNDER CAB DUE TO CRIMP LEAK	20/03/2015	1304	Planned
	78376	REPLACE BLOWN TRACK DRIVE MOTOR HOSE ON POS 4	9/04/2015	1317	Planned
	78567	REPLACE HYDRAULIC COOLER 12V FAN AND HARNESS AS SHORTED AND MELTED	6/05/2015	1341	Planned
	78728	Replace rocker cover gasket	15/06/2015	1366	Correct
	78800	Repair product tank mounts after tank was dropped.	8/07/2015	1388	Job Damage
	79426	250HR SERVICE AND MECH CHECK COMPLETE	24/05/2016	1762	
	80048	Replace BE product tank.	18/07/2016	1767	Planned
	80051	Service radiator.	19/07/2016	1767	Planned
	80047	Fit new track frame assemblies including FD's and tracks.	21/07/2016	1767	Overhaul
	80046	Fit new Hydraulic cooler	25/07/2016	1767	Planned
	80049	Repair frame cracks and damage.	27/07/2016	1767	Planned
	80050	Replumb product hoses and replace spray nozzles and jets.	28/07/2016	1767	Planned
	80625	Spray circuit valve faulty. Found failed relay in circuit, replace test ok. Dave from Rutherford helped with diagnosis.	7/09/2016	1786	
	80653	Fit rebuilt radiator and new starter motor, test ok.	15/09/2016	1659	

Asset History Report

Asset Number	Work Order Number	Description	Date	SMU Reading	Job Type
	81497	Repair mix actuator wiring	21/12/2016	1861	
	81270	Fit new suction line for wax length of machine to fill from both sides	1/02/2017	1890	
	81386	FLOAT FROM NORTH END TO SOUTH OF JOB	12/04/2017		
	84164	continue demob repairs. clean all spray parts, Pull pumps apart soak and clean, reseal. Remove spray bars and replace with new. Replace directional valve on system 2. Clean down machine.	18/09/2017	1919	
	82966	Extend frame to allow for 11.1m paving	15/11/2017	1915	Request
	82970	Reseal Pos 4 FD	25/01/2018	1918	Correct
	82964	Carry out 2000hr service early	2/02/2018	1920	PM
	82967	Replace fan belt	5/02/2018	1920	Planned
	82968	Replace one product pump.Clean tanks and replace hoses and nozzles.	20/02/2018	1921	Planned
	82969	Replace various leaking track rollers.	6/03/2018	1922	Planned
	82971	Replace sensor arm adjustment bearings.	23/05/2018	1924	Correct
	82972	Tidy up electrical, dash and various components	31/05/2018	1925	Planned
	86625	Fit Extra work lights	16/01/2019		
	86626	Diagnose slow hydraulics, found hydraulic filters collapsed and oil to be gluggy. Suspect wrong top up oil used. Flush system and fit new filters.	20/01/2019		
	86758	Replace stolen battery.	29/07/2019		Job Damage
	86793	Auto steering solenoid failed. Replace.	21/08/2019		Break
	91097	Replace failed load conveyor tail drum bearings with new. Adjust belts.	21/04/2021	5330	Correct
	90992	Torn lower feed belt after metal object went through cutter spearing belt. Replace feed belt.	29/04/2021	5363	Correct