

Estimate

BARNEY TRUCKING, INC.

Estimate: ET07-000066 Shop: SAL
Estimate Dt: 4/16/2026 **Unit:** B1184
8:07:00 PM
Customer: Barney Trucking Inc License: Z062454

Remit To:
BARNEY TRUCKING, INC.
235 SOUTH SR24
SALINA UT 84654
Ph: 435-529-3701 Ext:
Fax: 435-529-7314
Email:

Barney Trucking Inc
235 South SR. 24
Salina UT 84654
Email:
Cust Ph: Ext: Fax:

VIN: 1XPCD49X5KD602475
Make: PTRBL Odometer: 312,987
Model: 567
Year: 2019
Division: 00
Dept: TRACTOR
Cost Cntr: 000

Section: 1 Priority: 5 Complaint: 169/WORN Comp.Descrip: Clutch Assembly
Component: 023-002 Correction:
Cause:
Job Code: TAM - Time and Material
Rep Reason: INSPECTION
Comments: Clutch was replaced due to being worn out

Labor	Description	Hours	Currency	Rate/Unit Price/Charge	Total
	Time and Material	12.00	US\$	150.00	1,800.00

Part	Description	Qty	Currency	Rate/Unit Price/Charge	Total
308925-25	Clutch Assembly, 2050 Torque lb-ft	1.00	US\$	1,194.88	1,194.88
127760	Brake - Clutch Plate, single piece	1.00	US\$	26.35	26.35

Section: 2 Priority: 5 Complaint: BROKEN Comp.Descrip: Air Ride Suspension
Component: 016-008 Correction:
Cause:
Job Code: TAM - Time and Material
Rep Reason: INSPECTION
Comments: Number 2 Front Spring Hanger on Drivers Side Replaced due to being Broken.

Estimate

BARNEY TRUCKING, INC.

Estimate: ET07-0000066

Customer: BARTRU01

Unit: B1184

Labor	Description	Hours	Currency	Rate/Unit Price/ Charge	Total
	Time and Material	2.50	US\$	150.00	375.00

Part	Description	Qty	Currency	Rate/Unit Price/ Charge	Total
C11-6023M02	BRACKET-46K AIR TRAC ASSY	1.00	US\$	1,097.27	1,097.27

Section: 3 Priority: 5 Complaint: COMPONETFAIL Comp.Descrip: Alignment
 Component: 016-020 Correction:
 Cause:
 Job Code: TAM - Time and Material
 Rep Reason: INSPECTION
 Comments: Truck Alignment After Spring Hanger Was Replaced

Labor	Description	Hours	Currency	Rate/Unit Price/ Charge	Total
	Time and Material	3.00	US\$	150.00	450.00

No Pre-defined Tax Rate	US\$	0.00
-------------------------	------	------

Total Parts Issued:	3.00
Total Labor Hours:	17.50
Total Part Charges:	2,318.50
Total Labor Charges:	2,625.00
Total Service Charges:	0.00
Repair Total:	4,943.50
Taxes:	0.00
Fees:	0.00
Estimate Total:	4,943.50

Total Cost per Line Type

