



Warner Diesel Trucks & Equipment Ltd.
JCT HWY 2N & NORTH SE MOOSE JAW, SK S6H 7N7

TEL: (306) 693-7253
 FAX: (306) 692-9253
 TOLL FREE: (877) 302-0253
 (IN SASKATCHEWAN)

G.S.T. Registration Number [REDACTED]
 P.S.T. Registration Number [REDACTED]

SERVICE INVOICE: [REDACTED]

BILL TO



DELIVER TO



ENGINE HOURS 0

| DATE PROMISED | DATE INVOICE | SALES TYPE | ADVISOR | TERMS | CUSTOMER REFERENCE | | | |
|---------------------|--------------|--------------|-------------------|-----------------|--------------------|------------|-------------|--------------|
| 2/24/2026 4:41:24PM | 3/30/2026 | SC | MORGAN | NET30 | | | | |
| YEAR | MAKE | MODEL | VIN | CUSTOMER UNIT # | CAB CARD | IN SERVICE | ODOMETER IN | ODOMETER OUT |
| 2012 | DOEPKER | TANDEM GRAIN | 2DEGBSZ24C1027363 | | | | 1 | 1 |

Sold Operations (Cont.)

TOTAL JOB #2 42-00 3,773.52

JOB #3 32-00 SC SUSPENSION

CONCERN MOCK SAFETY REPAIRS

- FRONT AXLE AIR BAGS BOTH SIDES

ROOT CAUSE BOTH FRONT AXLE AIR BAG WERE CRACKED AND WORN OUT.

CORRECTION REMOVED AIR LINES FROM BOTH FRONT AXLE AIR BAGS AND REMOVED FITTINGS. FOUND BOTTOM NUTS ON BOTH AIR BAGS WERE SEIZED, USED HEAT TO REMOVE THEM. REMOVED TOP MOUNTING NUTS, JACKED UP FRAME, AND REMOVED AIR BAGS. INSTALLED NEW AIR BAGS, LOWERED FRAME, AND ALIGNED THEM PROPERLY. INSTALLED NEW TOP AND BOTTOM NUTS AND TIGHTENED ON BOTH AIR BAGS. REINSTALLED FITTINGS AND AIR LINES, AND SECURED AIR LINES NEATLY. AIRED UP SYSTEM AND CHECKED FOR LEAKS. CLEANED TOOLS AND WORK AREA.

TOTAL JOB #3 32-00 576.70

| QTY | ITEM | VMRS | DESCRIPTION | UNIT PRICE | EXTD PRICE |
|-----|-----------------|------|-------------|------------|------------|
| 2 | ABP N32 0187091 | | AIR SPRING | 131.35 | 262.70 |
| | LABOR 32-00 | | SUSPENSION | | 314.00 |

JOB #4 00-00 SC MISC REPAIR

CONCERN GREASE TRAILER.

ROOT CAUSE MAINTENANCE.

CORRECTION GREASED UNIT.

TOTAL JOB #4 00-00 83.46

| QTY | ITEM | VMRS | DESCRIPTION | UNIT PRICE | EXTD PRICE |
|-----|-------------|------|--------------------------------|------------|------------|
| | LABOR 00-00 | | MISC REPAIR | | 78.50 |
| 1 | ESO 121928 | | MOBILGREASE XHP 222, 40 X 0 *D | 4.96 | 4.96 |