

E01-7

PATTISON AGRICULTURE LIMITED
P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Belcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 62445

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3328880
		Invoice Date	02/21/2025
		Location:	12
		Work Order Number:	480135
		Payment Type:	Finance
		Page:	1 of 14

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	2033	1H0S790SAJ0800165	821858	

Service Reminders:

JGLC JD S SERIES ALL Retail

COMPLAINT:

02 S SERIES COMBINE VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION:

VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST

HEADER SERIAL # ____na____

ENGINE HOURS _____2033_____

SEPERATOR HOURS _____1471_____

DOES THIS UNIT GET A VALUEMAX STICKER __ YES __ NO

HAS THE STICKER BEEN INSTALLED __ YES __ NO

THIS UNIT HAS HAD THE CAB CLEANED ____SP____ (INITIAL)

THIS UNIT HAS HAD A FINAL CHECKOVER ____LB____ (INITIAL)

THIS UNIT HAS HAD A COMPLETE GREASE JOB ____LB____ (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:

Job Total: \$3,226.00**JFCC JD ALL Retail**

COMPLAINT:

03 FREE CLEANUP OF CAB

CORRECTION:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
LABDIS	LAB DISC CUST	-1.00	172.50	-\$172.50	Y
Labor: \$172.50	Parts: \$0.00	OL&M: \$0.00	Misc: -\$172.50	Sub-Total: \$0.00	

J06001600 JD ALL Retail

COMPLAINT:

04 REPLACE MISCELLANEOUS HARDWARE

PATTISON AGRICULTURE LIMITED

P.O. Box 860
 Preeceville, SK S0A 3B0
 Phone: (306) 547-2007
 Fax: (306) 547-3382
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No: 62445

Deliver To:

Bus Phone:
 Prv Phone:

Bus Phone:
 Prv Phone:

Invoice Number: **3328880**
 Invoice Date: 02/21/2025
 Location: 12
 Work Order Number: 480135
 Payment Type: Finance
 Page: 2 of 14

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	2033	1H0S790SAJ0800165	821858	

Service Reminders:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY26575	COOL-GARDII 3.78L 50/50 PREMIX	1.00	20.34	\$20.34	Y
TY27730	Diesel Fuel Emergency Thaw/Flow Improver	2.00	29.02	\$58.04	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF25	ENVIRO FEE	1.00	0.25	\$0.25	Y

Labor: \$0.00 Parts: \$78.38 OL&M: \$0.00 Misc: \$0.25 Sub-Total: \$78.63

JSOFTWARE JD S790 Retail**COMPLAINT:**

05 UPDATE ALL CONTROLLER SOFTWARE

CORRECTION:

UPDATED SOFTWARE ON
 LC1, LC2, RC1, RC2, PDU, MHC, GLM, DISPLAY CONTROLLERS.
 HAD TO PERFORM THE FOLLOWING CALIBRATIONS.

Labor: \$400.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$400.00

J06171104 JD S790 Retail**COMPLAINT:**

06 FEEDERHOUSE BACKSHAFT BEARING, REPLACE
 RH side has play

CORRECTION:

R & R feeder house back shaft bearing.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE68018	Bearing With Housing	1.00	224.87	\$224.87	Y

Labor: \$300.00 Parts: \$224.87 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$524.87

EXPERT-1000000088990 Retail

PATTISON AGRICULTURE LIMITED

P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No: 62445

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone: (

Invoice Number: **3328880**
Invoice Date: 02/21/2025
Location: 12
Work Order Number: 480135
Payment Type: Finance
Page: 3 of 14

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	2033	1H0S790SAJ0800165	821858	

Service Reminders:

COMPLAINT:

07 Feederhouse Reverser Drive Belt Tensioner J-Bolt, Replace

CORRECTION:

Lower safety stop and remove left-hand feeder house shields.
Remove shields.
Loosen nuts to relieve tension on drive belt.
Remove drive belt from sheaves.
Disassemble tensioner and replace tensioner J-bolt and related parts as required.
Assemble tensioner.
Install drive belt and tighten nuts to position washer between end of gauge and bottom of step.
Swing bracket into position and retain with cap screw and nut.
Install feeder house shields previously removed.
DONE.

Labor: \$140.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$140.00

J06171002 JD S790 Retail**COMPLAINT:**

08 REPLACE FEED ACCELERATOR WING. (EACH)
6 need to be replaced

CORRECTION:

Start combine and lower feederhouse down.
Loosen off and remove all wear strips from accelerator.
Remove and discard all 6 bent wings.
Lots of straw wrapped up on accelerator shaft RH and LH sides next to bearings.
Spend the time and cut and pulled and cleaned out all the straw and debris from bearing holders.
Install 6 new wings into place but leave bolts loose.
Reinstall all the wear strips. Had to replace 3 bolts and nuts. Torque all wear strips up to spec.
Torque all accelerator wings to spec.
Reinstall belt and tension it to spec. All good.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Incl
H137329	M12x1.75 Flg DT Lock	3.00	1.79	\$5.37	Y
HXE84113	BEATER WING RH	4.00	205.80	\$823.20	Y
HXE84114	BEATER WING LH	2.00	205.80	\$411.60	Y
L215374	BOLT	3.00	2.92	\$8.76	Y

PATTISON AGRICULTURE LIMITED
P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 62445

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3328880 Invoice Date: 02/21/2025 Location: 12 Work Order Number: 480135 Payment Type: Finance Page: 4 of 14
--------------------------	--------------------------	---

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	2033	1H0S790SAJ0800165	821858	

Service Reminders:

Labor: \$800.00 Parts: \$1,248.93 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$2,048.93

J10040091 JD S790 Retail

COMPLAINT:

09 REPLACE ELECTROMAGNETIC CLUTCH ANTI ROTATION STRAP.

CORRECTION:

R & R electromagnetic clutch harness strap.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H134773	STRAP	1.00	3.43	\$3.43	Y

Labor: \$50.00 Parts: \$3.43 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$53.43

EXPERT-1000000026146 Retail

COMPLAINT:

10 Primary Countershaft Gear Case Oil, Change

CORRECTION:

Drain at cap and refill at dipstick.
Oil level must show on knurled part of dipstick.
DONE.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY26372	80W140 Synth 946ml GL5	2.00	42.56	\$85.12	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF15	ENVIRO FEE	2.00	0.15	\$0.30	Y

Labor: \$110.00 Parts: \$85.12 OL&M: \$0.00 Misc: \$0.30 Sub-Total: \$195.42

EXPERT-1000000042363 Retail

COMPLAINT:

11 Cleaning Fan Blade Inserts, Remove and Replace REPLACE CLEANING FAN BLADES AND INSERTS.
replace pins with bolts

CORRECTION:

PATTISON AGRICULTURE LIMITED
P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 62445

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number: **3328880**
Invoice Date: 02/21/2025
Location: 12
Work Order Number: 480135
Payment Type: Finance
Page: 5 of 14

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	2033	1H0S790SAJ0800165	821858	

Service Reminders:

Cut all old plastic push pins from fan blade inserts and discard on both LH and RH
Pull inserts off of fan blades a turn them one blade and reinstall so that new holes can be used.
Get 8 bolts and lock nuts from parts. 4 on each side.
Install bolts in place of the plastic push pins. Torque up all hardware. All good.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
14M7397	M6x1.0 Flg NyLock	8.00	0.68	\$5.44	Y
19M8321	Screw M6x45 Flg 10.9	8.00	1.57	\$12.56	Y
Labor: \$450.00		Parts: \$18.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$468.00

EXPERT-1000000122018 Retail

COMPLAINT:

12 Aftertreatment Blower Drive Belt Tensioner and Idler, Replace REPLACE AFTERTREATMENT BLOWER DRIVE BELT TENSIONER AND IDLER.

CORRECTION:

REMOVED SHIELDING.
Remove belt from blower.
Loosen off and remove tensioner and remove the idler pulley.
Remove bearings from both tensioner and idler pulleys and discard.
Press new bearings into place and reinstall tensioner and idler onto combine.
Reinstall belt.
Test run unit. All good.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
JD29980	NEEDLE BEA	1.00	5.62	\$5.62	Y
JD9449	BALL BEARING	1.00	6.44	\$6.44	Y
Labor: \$300.00		Parts: \$12.06	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$312.06

JGEN02- Retail

COMPLAINT:

13 replace active tailings drive chain tensioner sprocket bearing

CORRECTION:

R& R active tailings drive chain tensioner sprocket.

PATTISON AGRICULTURE LIMITED
P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 62445

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number: **3328880**
Invoice Date: 02/21/2025
Location: 12
Work Order Number: 480135
Payment Type: Finance
Page: 6 of 14

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	2033	1H0S790SAJ0800165	621858	

Service Reminders:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE23133	IDLER SPRO	1.00	45.69	\$45.69	Y
H114395	SPACER	1.00	4.06	\$4.06	Y

Labor: \$150.00 Parts: \$49.75 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$199.75

JGEN03- Retail

COMPLAINT:

14 replace tailings return auger bearing

CORRECTION:

Remove sprocket. Remove tailing return auger bearing and collar. Replace bearing with new one. Install back remove stuff.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH129452	ECCENTRIC	1.00	14.69	\$14.69	Y
AH168161	BALL BEARI	1.00	53.82	\$53.82	Y

Labor: \$300.00 Parts: \$68.51 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$368.51

JGEN04- Retail

COMPLAINT:

15 diagnose tailings quality sample motor intermittently loses power

CORRECTION:

Tailings bypass motor tests good.
Wiring to bypass motor tests good.
Intermittent power coming from Right Power Module behind tailings elevator.
Ordered a new module Feb.14/2025. Should be here Tuesday.

Tuesday, Feb. 18/25
Shut battery disconnect off
Unplug Right power module connectors.
Unbolt and remove power module from side of combine.
Bolt new module into place and plug in connectors.
Switch batteries back on and turn key on.
Check for codes. No codes. All good.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE100327	Electronic Control Unit	1.00	319.47	\$319.47	Y

PATTISON AGRICULTURE LIMITED
P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Mooseomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 62445

Deliver To:

Bus Phone:
Prv Phone: (

Bus Phone:
Prv Phone:

Invoice Number: **3328880**
Invoice Date: 02/21/2025
Location: 12
Work Order Number: 480135
Payment Type: Finance
Page: 7 of 14

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	2033	1H0S790SAJ0800165	821858	

Service Reminders:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
FRT	FREIGHT	1.00	35.00	\$35.00	Y

Labor: \$300.00 Parts: \$319.47 OL&M: \$0.00 Misc: \$35.00 Sub-Total: \$654.47

JGEN06- Retail

COMPLAINT:

16 hydraulic leak at pump suction under hydraulic tank, hose clamp

CORRECTION:

Tightened up all hose clamps.

Labor: \$100.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$100.00

JGEN06- Retail

COMPLAINT:

17 repair coolant leaks at radiator hose clamps, tighten

CORRECTION:

Tightened up all hose clamps.

Labor: \$50.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$50.00

JGEN07- Retail

COMPLAINT:

18 grease chopper drive jackshaft

CORRECTION:

grease chopper drive jackshaft

Labor: \$25.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$25.00

JENGOILCHNG JD S790 Retail

COMPLAINT:

PATTISON AGRICULTURE LIMITED

P.O. Box 860

Preeceville, SK S0A 3B0

Phone: (306) 547-2007

Fax: (306) 547-3382

Http://www.pattisonag.com

GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No: 62445

Deliver To:

		Invoice Number:3328880 Invoice Date02/21/2025 Location:12 Work Order Number:480135 Payment Type:Finance Page:8 of 14
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	2033	1H0S790SAJ0800165	821858	

Service Reminders:

19 REPLACE ENGINE OIL AND FILTER

CORRECTION:

DRAIN ENGINE OIL AND REMOVE FILTER.
CLEAN AREA.
INSTALL NEW OIL AND FILTER.
RUN UNIT AND LEAK CHECK
ADJUST OIL LEVEL AS REQUIRED.
DONE.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE572785	ENGINE OIL FILTER	1.00	96.43	\$96.43	Y
TY26673	15W40 3.78L Plus-50II CK4/SN	1.00	33.62	\$33.62	Y
TY26679	15W-40 18.9L PLUS-50 II	2.00	152.04	\$304.08	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.25	\$1.25	Y
EF300	ENVIRO FEE	2.00	3.00	\$6.00	Y
EF60	ENVIRO FEE	1.00	0.80	\$0.80	Y

Labor: \$150.92 Parts: \$434.13 OL&M: \$0.00 Misc: \$7.85 Sub-Total: \$692.90

J10030100 JD S790 Retail

COMPLAINT:

20 REPLACE ENGINE FUEL FILTERS

CORRECTION:

REPLACED PRIMARY AND SECONDARY FUEL FILTERS.
REMOVED AND CLEANED FUEL STRAINER.
BLED FUEL SYSTEM.
FUNCTION AND LEAK CHECKED.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
DZ112918	FILTER ELE	1.00	150.22	\$150.22	Y
DZ130550	Filter Element	1.00	147.86	\$147.86	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	2.00	1.25	\$2.50	Y

Labor: \$80.00 Parts: \$298.08 OL&M: \$0.00 Misc: \$2.60 Sub-Total: \$380.68

PATTISON AGRICULTURE LIMITED
P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 62445

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3328880
		Invoice Date	02/21/2025
		Location:	12
		Work Order Number:	480135
		Payment Type:	Finance
		Page:	9 of 14

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	2033	1H0S790SAJ0800165	821858	

Service Reminders:

J06070005 JD S790 Retail

COMPLAINT:

21 REPLACE HYDRAULIC FILTERS

CORRECTION:

REPLACE TRANSMISSION FILTER.
REPLACE HYDRO CHARGE FILTER.
DONE.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AN207368	Hydro Charge Filter	1.00	124.08	\$124.08	Y
AXE12964	HYDRAULIC	1.00	113.02	\$113.02	Y
N309233	O-RING	1.00	17.35	\$17.35	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.25	\$1.25	Y
EF50	ENVIRO FEE	1.00	0.55	\$0.55	Y
Labor: \$60.00		Parts: \$264.45	OL&M: \$0.00	Misc: \$1.80	Sub-Total: \$306.25

JPRODRFILT JD S790 Retail

COMPLAINT:

22 REPLACE PRODRIVE HYDRAULIC FILTER

CORRECTION:

R & R prodrive hydraulic filter.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH128449	HYDRAULIC	1.00	93.75	\$93.75	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.25	\$1.25	Y
Labor: \$25.00		Parts: \$93.75	OL&M: \$0.00	Misc: \$1.25	Sub-Total: \$120.00

J06030020 JD S790 Retail

COMPLAINT:

23 REPLACE ROTARY SCREEN DRIVE BELT

PATTISON AGRICULTURE LIMITED
P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 62445

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number: **3328880**
Invoice Date: 02/21/2025
Location: 12
Work Order Number: 480135
Payment Type: Finance
Page: 10 of 14

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	2033	1H0S790SAJ0800165	821858	

Service Reminders:

CORRECTION:

Loosen off and remove large nut from centre of rotary screen.
Pull old belt out from screen.
Slide new rotary screen belt into place and reinstall nut. Torque to spec.
Hook belt back up to drive and tensioner pulleys. All good.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H221273	Rotary Screen Belt	1.00	46.53	\$46.53	Y
Labor: \$140.00		Parts: \$46.53	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$186.53

JGEN08- Retail

COMPLAINT:

24 repair radiator trash propeller bearings have play

CORRECTION:

Open up rotary screen door.
Remove snap ring and pull propeller off of hub.
Remove bearing holders and install new bearings. Torque to spec.
Remove hub spindle from radiator and install new one. Torque to spec.
Reinstall propeller onto hub and install snap ring.
Close up rotary screen door. All good.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
HXE66282	HUB	1.00	61.37	\$61.37	Y
JD29980	NEEDLE BEA	2.00	5.62	\$11.24	Y
Labor: \$300.00		Parts: \$72.61	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$372.61

JGEN09- Retail

COMPLAINT:

25 repair broken ether line in engine compartment

CORRECTION:

Remove and replace ether start line.

PATTISON AGRICULTURE LIMITED

P.O. Box 860
 Preeceville, SK S0A 3B0
 Phone: (306) 547-2007
 Fax: (306) 547-3382
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No: 62445

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone: (
Prv Phone:

Invoice Number:	3328880
Invoice Date:	02/21/2025
Location:	12
Work Order Number:	480135
Payment Type:	Finance
Page:	11 of 14

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	2033	1H0S790SAJ0800165	821858	

Service Reminders:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
HXE21149	Ether Line 50"	1.00	34.45	\$34.45	Y

Labor: \$100.00 Parts: \$34.45 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$134.45

JGEN10- Retail

COMPLAINT:

26 change 2 speed rotor gearbox oil

CORRECTION:

Drain and replace with fresh oil til full mark.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY26372	80W140 Synth 946ml GL5	5.00	42.56	\$212.80	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF15	ENVIRO FEE	5.00	0.15	\$0.75	Y

Labor: \$100.00 Parts: \$212.80 OL&M: \$0.00 Misc: \$0.75 Sub-Total: \$313.55

JGEN11- Retail

COMPLAINT:

27 repair bent panel above feed accelerator

CORRECTION:

Removed panel from above feederhouse.
 Take panel over to press and straighten panel back out.
 Straighten the mounting points on the combine itself.
 Reinstall panel and torque bolts to spec. All good.

Labor: \$200.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$200.00

DIAG-1000000170719 Retail

COMPLAINT:

28 diagnose - hydraulic lube pump driven off of engine gearcase shakes badly when engine running

CORRECTION:

PATTISON AGRICULTURE LIMITED
P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 62445

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<table border="0" style="width: 100%;"> <tr> <td>Invoice Number:</td> <td style="text-align: right;">3328880</td> </tr> <tr> <td>Invoice Date</td> <td style="text-align: right;">02/21/2025</td> </tr> <tr> <td>Location:</td> <td style="text-align: right;">12</td> </tr> <tr> <td>Work Order Number:</td> <td style="text-align: right;">480135</td> </tr> <tr> <td>Payment Type:</td> <td style="text-align: right;">Finance</td> </tr> <tr> <td>Page:</td> <td style="text-align: right;">12 of 14</td> </tr> </table>	Invoice Number:	3328880	Invoice Date	02/21/2025	Location:	12	Work Order Number:	480135	Payment Type:	Finance	Page:	12 of 14
Invoice Number:	3328880													
Invoice Date	02/21/2025													
Location:	12													
Work Order Number:	480135													
Payment Type:	Finance													
Page:	12 of 14													

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	2033	1H0S790SAJ0800165	821858	

Service Reminders:

Disconnect anti rotation strap from hydraulic pump.
Loosen off and remove bolts holding pump hub to gearcase pulley.
Remove hydraulic pump with hub from combine and set off to the side.
Inspect mating surface of pump and gearcase pulley.
Large slab of chaff was stuck between hub and pulley causing the pump to not bolt up square.
Using a wire wheel on a drill I was able to buff the mating surfaces nice and clean.
Reinstall pump onto combine. Torque bolts to spec.
Reinstall anti rotation strap.
Start combine. Pump is nice and smooth now. All good.

Labor: \$200.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$200.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

EXPERT-1000000122725 Retail

COMPLAINT:

29 Engine Valve Clearance, Adjust ADJUST ENGINE VALVE CLEARANCE recommended at 2,000 hrs

CORRECTION:

REMOVED APPLICABLE ENGINE SHIELDS AND SUPPORTS TO GAIN ACCESS TO VALVE COVER
Loosen off and remove intake air pipe from air filter housing to turbo.
Remove charge pipe from between both turbos.
Loosen off and remove all valve cover bolts.
Slide valve covers towards fan and remove from engine.
Follow service advisor and set valve lash and injector preload.
Clean up valve covers and mating surface.
Install valve covers with new gaskets. Torque to spec.
Reinstall charge pipe between both turbos with new gasket and seal. Torque clamp and hardware to spec.
Reinstall intake air pipe from turbo to air filter housing.
Reinstall engine shields.
Turn battery switch back on and start combine. Runs like it should. No leaks. All good.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
OZ128752	GASKET	1.00	15.29	\$15.29	Y
R528620	GASKET	1.00	59.89	\$59.89	Y
R531581	GASKET	1.00	55.92	\$55.92	Y
R531582	GASKET	1.00	56.43	\$56.43	Y

Labor: \$2,000.00	Parts: \$187.63	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,187.63
--------------------------	------------------------	-------------------------	---------------------	------------------------------

EXPERT-1000000019917 Retail

PATTISON AGRICULTURE LIMITED

P.O. Box 860
 Preeceville, SK S0A 3B0
 Phone: (306) 547-2007
 Fax: (306) 547-3382
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Belcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No: 62445

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:	3328880
Invoice Date	02/21/2025
Location:	12
Work Order Number:	480135
Payment Type:	Finance
Page:	13 of 14

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	2033	1H0S790SAJ0800165	821858	

Service Reminders:

COMPLAINT:

30 Concave, Level and Calibrate

CORRECTION:

Install centre 2 concaves back into combine and torque hardware to spec.
 Install concave leveling screws and close up concaves until rotor ticks.
 Back off leveling screws until ticking stops and lock into place.
 Adjust concave cylinders till pins are able to be installed.
 Install cylinder pins and locks.
 Perform leveling calibration in cab. Calibration passed.
 Start combine and perform threshing clearance calibration.
 Calibration failed.
 Repeat leveling procedure and launch threshing clearance cal again.
 Calibration failed again.
 Get other tech to start the calibration as I watched the concaves. Concaves only seem to be opening partially before hanging up and failing cal.
 Disconnect concave cylinders. (Front and back)
 Using a large bar pry up and down on concaves while another tech tries to see what they are catching on as they will not open up very much at all. Even with cylinders disconnected.
 Tech noticed front lip of #1 concave is bent and catching on the front partition. Unsure how it bent as on the inspection it functioned as it should.
 Unbolt front 2 concaves and remove from combine.
 Remove bent and damaged transition lip from #1 concave. We do not have any new ones but found a used one in the lean.
 Patched up the two thin spots on new lip and installed onto concave.
 Pressed front partition back into place and buffed off the sharp edge that may of caught the concave.
 Reinstalled concaves, pinned concaves back up into place. Perform threshing clearance calibration. Passed All good.
 Reinstall separator grates and shift rotor back into gear. All good.

Labor: \$1,000.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,000.00
-------------------	---------------	--------------	--------------	-----------------------

J06171152 JD S790 Retail**COMPLAINT:**

31 REPLACE FEEDERHOUSE CONVEYOR CHAIN WEAR STRIPS -one of four is pulled out of place

CORRECTION:

Loosen off and remove bolts holding feederchain wear strips in place.
 Remove all 4 old wear strips and discard.
 Slide new wear strips into place and install bolts.
 Torque hardware to spec. All good.

PATTISON AGRICULTURE LIMITED
P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kinderley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Sheunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 62445

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:	3328880
Invoice Date	02/21/2025
Location:	12
Work Order Number:	480135
Payment Type:	Finance
Page:	14 of 14

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	2033	1H0S790SAJ0800165	821858	

Service Reminders:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H171980	FH ConveyChain Return Strip	4.00	21.34	\$85.36	Y

Labor: \$200.00	Parts: \$85.36	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$285.36
-----------------	----------------	--------------	--------------	---------------------

JDISC JD ALL Retail

COMPLAINT:

32 GREEN LIGHT INSPECTION DISCOUNTS

CORRECTION:

ValueMax Greenlight = YES

Parts discount = 395.25

One Greenlight parts and labor warranty start date = August 1/2025

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
DISC	Parts Discount	-1.00	395.25	-\$395.25	Y

Miscellaneous Charges:

SERVICE ACCESSORIES	\$150.00
---------------------	----------

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: -\$245.25	Sub-Total: -\$245.25
---------------	---------------	--------------	-----------------	----------------------

Finance Information

Customer PO No:	Type: JD Multi-Use	Auth No: 979677
Tax Exempt No:	Merchant No: 82001036	
Advertiser:	Card No: xxxxxxxxxxxx1423	
	Bill Code: 784	- JD INSPECTION - COMBINE
	Credit Plan: 11483	- NO PAYMENTS/NO INTEREST WAIVER UNTIL NOVEMBER 15, 2025

Labor:	\$12,493.42
Parts:	\$3,952.46
OL&M:	\$0.00
Misc:	-\$1,567.30
GST:	\$743.93
PST:	\$0.00

Grand Total: \$15,622.51

TERMS AND CONDITIONS

This purchase is subject to the terms of the John Deere Financial Multi-Use Account Agreement. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by:

Date:

EOI-7



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-8351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: 62445

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3279174
		Invoice Date	10/05/2024
		Location:	12
		Work Order Number:	465882
		Payment Type:	Finance
		Page:	1 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	1892	1H0S790SAJ0800165	821858	

Service Reminders:

JSC RADIUS A Retail

COMPLAINT:

01 SERVICE CALL TO AND FROM MACHINE LOCATED IN RADIUS A.

CORRECTION:

September 19/2024 -- Service call

Job Total: \$294.00

J06171003 JD S790 Retail

COMPLAINT:

02 ADJUST FEEDERHOUSE DRIVE CHAIN. REMOVE LINK AND ADJUST.

CORRECTION:

LOOSENED OFF DRIVE CHAIN TENSIONER.
REMOVED MASTER LINK AND SPLIT CHAIN.
CUT OUT A FULL LINK AND INSTALLED AN OFFSET LINK.
REATTACHED CHAIN AND TENSION TO SPEC.
RAN FEEDERHOUSE AND RECHECKED TENSION.

remove drive chain, belt and top cover
loosen feederchain
remove two connector links on lh side, roll chain back on sprockets and install links
set chain tension
install drive chain and belt
chain and sprockets have some wear but should last the year.
ran the combine to ensure all is good

top door was bent, tried to straighten but door was worse, broke a stud trying to tighten door, brought door back to shop, installed new door
on lower section on rework and took back out to install on combine

Miscellaneous Charges:

SERVICE ACCESSORIES

\$42.00

Labor: \$420.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$42.00	Sub-Total: \$462.00
-----------------	---------------	--------------	---------------	---------------------



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 862-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: 62445

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3279174
		Invoice Date:	10/05/2024
		Location:	12
		Work Order Number:	465882
		Payment Type:	Finance
		Page:	2 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	1892	1H0S790SAJ0800165	821858	

Service Reminders:

Finance Information

Customer PO No:	Type:	JD Multi-Use	Auth No:	471442	Labor:	\$630.00
Tax Exempt No:	Merchant No:	82001036			Parts:	\$0.00
Adviser:	Card No:	xxxxxxxxxxxx1423			OL&M:	\$0.00
Gene Klebeck	Bill Code:	725 - COMBINE			Misc:	\$126.00
	Credit Plan:	249 - PURCHASE			GST:	\$37.80
					PST:	\$0.00
					Grand Total:	\$793.80

TERMS AND CONDITIONS

This purchase is subject to the terms of the John Deere Financial Multi-Use Account Agreement. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by:

Date:

EOI-7



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-8351	Yorkton, SK	(306) 783-8459
Maple Creek, SK	(306) 862-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2883	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2698	Wynyard, SK	(306) 564-2636
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3486
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2839		



JOHN DEERE

Invoice To Account No: 62445

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3088708
		Invoice Date:	11/07/2023
		Location:	12
		Work Order Number:	432060
		Payment Type:	Finance
		Page:	1 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	1663	1H0S790SAJ0800165	821858	

Service Reminders:

JSC RADIUS B Retail

COMPLAINT:

01 SERVICE CALL TO AND FROM MACHINE LOCATED IN RADIUS B.

CORRECTION:

October 25 /2023 -- service call -- Billed to R.O# 432095

Job Total: \$0.00

JELECDIAG1 JD ALL Retail

COMPLAINT:

02 FAST sensor code LC1 523558.04

CORRECTION:

Code LC1 523558.04 is active. (Feed accelerator speed sensor circuit fault)

R&R shields to access speed sensor and clean dirt from sensor area.

Loosen off belt and rotate feed accelerator by hand while observing LED on sensor with key on.

LED does not light.

Disconnect sensor and connect new sensor. LED will light up on new sensor when near metallic object.

Code is now inactive.

R&R sensor bracket from bearing and replace sensor.

Clear codes, tighten belt and test operation.

Code does not return.

Reinstall shields.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH221249	SENSOR	1.00	141.94	\$141.94	Y

Miscellaneous Charges:

SERVICE ACCESSORIES

\$19.50

Labor: \$195.00 Parts: \$141.94 OL&M: \$0.00 Misc: \$19.50 Sub-Total: \$366.44



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(308) 783-9459
Maple Creek, SK	(306) 682-2233	Balcarres, SK	(308) 334-2492
Kindersley, SK	(306) 483-2883	Moosomin, SK	(308) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(308) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(308) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(308) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3486
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: 62445

Deliver To:

SERVICE INVOICE

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:	3088708
Invoice Date	11/07/2023
Location:	12
Work Order Number:	432060
Payment Type:	Finance
Page:	2 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	1663	1H0S790SAJ0800165	821858	

Service Reminders:

Finance Information

Customer PO No:
Tax Exempt No:
Advisor: DARLENE WALKER

Type:	JD Multi-Use	Auth No:	886957
Merchant No:	82001036		
Card No:	xxxxxxxxxxxx1423		
Bill Code:	725 - COMBINE		
Credit Plan:	249 - PURCHASE		

Labor:	\$195.00
Parts:	\$141.94
OL&M:	\$0.00
Misc:	\$19.50
GST:	\$7.10
PST:	\$0.00

Grand Total: \$363.54

TERMS AND CONDITIONS

This purchase is subject to the terms of the John Deere Financial Multi-Use Account Agreement. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by:

Date:

EOI-7



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 862-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2883	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2896	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3486
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2839		



JOHN DEERE

Invoice To Account No: 62445

Deliver To:

SERVICE INVOICE

Bus Phone:	Bus Phone:	Invoice Number:	2947317
Prv Phone:	Prv Phone:	Invoice Date:	04/14/2023
		Location:	12
		Work Order Number:	406257
		Payment Type:	Finance
		Page:	1 of 1

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	1318	1H0S790SAJ0800165	821858	

Service Reminders:

J08160020 JD S790 Retail

COMPLAINT:

01 INSTALL MACHINE SYNC ANTENNA KIT. BPF12005

CORRECTION:

DISCONNECT GUARD CHAIN FROM THE RAIL, OPEN THE ACCESS DOOR, REMOVE DOOR CAP SCREW AND NUTS, OPEN GRAIN SAMPLE DOOR AND UN LATCH ACCESS PANEL DOOR, PULL GUARD CHAIN TROUGH THE HOLE, REMOVE ACCESS PANEL DOOR, INSTALL MAGNETIC MOUNTED ANTENNA ON TOP OF THE MACHINE, ROUTE THE ANTENNA CABLE TOWARDS THE CAB, OPEN THE RIGHT HAND GULL WING DOOR, ROUTE THE ANTENNA CABLE BEHIND THE CAB TO THE CONNECTOR, DISCONNECT HARNESS FROM THE CONNECTOR PANEL REMOVE CONNECTOR PANEL BOLTS, DRILL A HOLE ON CONNECTOR PANEL, INSTALL BULK HEAD CONNECTOR TO THE CONNECTOR PANEL, CONNECT ANTENNA WIRELESS CABLE TO THE BULK HEAD CONNECTOR, REMOVE COVER PLATE BELOW THE COMMAND ARM, DISCONNECT EXISTING WIRELESS ANTENNA FROM THE MTG, CONNECT EXTENSION CABLE TO THE MTG, REINSTALL ALL HARDWARE IN THE REVERSE ORDER

Miscellaneous Charges:

SERVICE ACCESSORIES

\$104.40

Labor: \$1,044.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$104.40	Sub-Total: \$1,148.40
-------------------	---------------	--------------	----------------	-----------------------

Finance Information

Customer PO No:

Tax Exempt No:

Advisor:

Gene Klebeck

Type:	JD Multi-Use	Auth No:	357867
Merchant No:	82001036		
Card No:	xxxxxxxxxxxx1423		
Bill Code:	725	-	COMBINE
Credit Plan:	249	-	PURCHASE

Labor:	\$1,044.00
Parts:	\$0.00
OL&M:	\$0.00
Misc:	\$104.40
GST:	\$57.42
PST:	\$0.00

Grand Total: \$1,205.82

TERMS AND CONDITIONS

This purchase is subject to the terms of the John Deere Financial Multi-Use Account Agreement. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by:

Date:

EOI-7



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2883	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2896	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3486
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: 62445

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone: (	Bus Phone: Prv Phone:	<table style="width: 100%;"> <tr> <td style="width: 60%;">Invoice Number:</td> <td style="width: 40%;">3088700</td> </tr> <tr> <td>Invoice Date:</td> <td>11/07/2023</td> </tr> <tr> <td>Location:</td> <td>12</td> </tr> <tr> <td>Work Order Number:</td> <td>427041</td> </tr> <tr> <td>Payment Type:</td> <td>Finance</td> </tr> <tr> <td>Page:</td> <td>1 of 2</td> </tr> </table>	Invoice Number:	3088700	Invoice Date:	11/07/2023	Location:	12	Work Order Number:	427041	Payment Type:	Finance	Page:	1 of 2
Invoice Number:	3088700													
Invoice Date:	11/07/2023													
Location:	12													
Work Order Number:	427041													
Payment Type:	Finance													
Page:	1 of 2													

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	1441	1H0S790SAJ0800165	821858	

Service Reminders:

JSC RADIUS A Retail

COMPLAINT:

01 SERVICE CALL TO AND FROM MACHINE LOCATED IN RADIUS A.

CORRECTION:

September 13/2023 -- service call

Job Total: \$363.00

J06230060 JD S790 Retail

COMPLAINT:

02 REPLACE UNLOADING AUGER DRIVE BELT

CORRECTION:

TT to location
Remove the blower shield, drive belt
Remove hydraulic pump coupler and unload auger belt shields
Remove unload auger chain
Remove old belt set, install new
Install parts removed in reverse order
Tension chain

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH233198	BELT SET	1.00	258.81	\$258.81	Y

Miscellaneous Charges:

SERVICE ACCESSORIES

\$57.52

Labor: \$380.25	Parts: \$258.81	OL&M: \$0.00	Misc: \$57.52	Sub-Total: \$696.58
-----------------	-----------------	--------------	---------------	---------------------



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 882-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2883	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 828-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2538
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 882-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: 62445

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3088700
		Invoice Date	11/07/2023
		Location:	12
		Work Order Number:	427041
		Payment Type:	Finance
		Page:	2 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	1441	1H0S790SAJ0800165	821858	

Service Reminders:

Finance Information

Customer PO No:
Tax Exempt No:
Advisor:

Gene Klebeck

Type: JD Multi-Use **Auth No:** 886457
Merchant No: 82001036
Card No: xxxxxxxxxxxxxx1423
Bill Code: 725 - COMBINE
Credit Plan: 249 - PURCHASE

Labor: \$575.25
Parts: \$258.81
OL&M: \$0.00
Misc: \$225.52
GST: \$52.98
PST: \$0.00

Grand Total: \$1,112.56

TERMS AND CONDITIONS

This purchase is subject to the terms of the John Deere Financial Multi-Use Account Agreement. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by:

Date:

EOI-7



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: 62445

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3298387
		Invoice Date: 11/15/2024
		Location: 12
		Work Order Number: 465072
		Payment Type: Finance
		Page: 1 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	1746	1H0S790SAJ0800165	821858	

Service Reminders:

JSC RADIUS B Retail

COMPLAINT:

01 SERVICE CALL TO AND FROM MACHINE LOCATED IN RADIUS B.

CORRECTION:

Billed to R.O# 464571

Job Total: \$0.00

JGEN01- Retail

COMPLAINT:

02 header will not calibrate

CORRECTION:

Customer could not get HD header to calibrate successfully.
Calibration errors would pop up but he did not document them.
While out at unit, attempted to calibrate the header to the combine.
This time the header calibrated successfully. No faults popped up.
Not sure what happened before but customer thinks he may have been setting the header far enough to the ground when instructed to during calibration.
Verify functions of AHC after calibrating.

Labor: \$105.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$105.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

JGEN02- Retail

COMPLAINT:

03 tailings bypass motor fault - RC1 516889.06

CORRECTION:

Code RC1 516889.06 is active. - tailings bypass motor overcurrent detected.
Inspect auger motor connection.
Also remove auger and clean out the housing.
Disconnect tailings bypass motor connector and force the output of the motor on at AYM control unit.
There is no power available to motor.
Download new RC1 control unit software as per DTAC solution #113910 and update.



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 862-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2883	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2839		



JOHN DEERE

Invoice To Account No: 62445

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3298387
		Invoice Date	11/15/2024
		Location:	12
		Work Order Number:	465072
		Payment Type:	Finance
		Page:	2 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	1746	1H0S790SAJ0800165	821858	

Service Reminders:

Still get no power to tailings motor connector.

Connect the tailings motor to the clean grain bypass motor and force on to verify the motor is functioning.

Follow schematic and test wiring back to the right power module.

Wiring tests good. Suspect either a problem with the power module or power supply to it.

Customer does not want to stop any longer to diagnose. Will have to look into it further when customer is not harvesting or in off season.

Miscellaneous Charges:

SERVICE ACCESSORIES

\$21.00

Labor: \$105.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$21.00	Sub-Total: \$126.00
-----------------	---------------	--------------	---------------	---------------------

Customer PO No:
Tax Exempt No:
Adviser: DARLENE WALKER

Finance Information

Type: JD Multi-Use Auth No: 447660
Merchant No: 82001036
Card No: xxxxxxxxxxxx1423
Bill Code: 725 - COMBINE
Credit Plan: 249 - PURCHASE

Labor: \$210.00
Parts: \$0.00
OL&M: \$0.00
Misc: \$21.00
GST: \$11.55
PST: \$0.00

Grand Total: \$242.55

TERMS AND CONDITIONS

This purchase is subject to the terms of the John Deere Financial Multi-Use Account Agreement. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by:

Date:

E01-7



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 862-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 483-2883	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 828-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2896	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 882-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2839		



JOHN DEERE

Invoice To Account No: 62445

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<table border="0" style="width: 100%;"> <tr> <td>Invoice Number:</td> <td>3190619</td> </tr> <tr> <td>Invoice Date</td> <td>06/21/2024</td> </tr> <tr> <td>Location:</td> <td>12</td> </tr> <tr> <td>Work Order Number:</td> <td>453612</td> </tr> <tr> <td>Payment Type:</td> <td>Finance</td> </tr> <tr> <td>Page:</td> <td>1 of 2</td> </tr> </table>	Invoice Number:	3190619	Invoice Date	06/21/2024	Location:	12	Work Order Number:	453612	Payment Type:	Finance	Page:	1 of 2
Invoice Number:	3190619													
Invoice Date	06/21/2024													
Location:	12													
Work Order Number:	453612													
Payment Type:	Finance													
Page:	1 of 2													

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	1687	1H0S790SAJ0800165	821858	

Service Reminders:

JSC RADIUS B Retail

COMPLAINT:

01 SERVICE CALL TO AND FROM MACHINE LOCATED IN RADIUS B.

CAUSE:

CORRECTION:

June 20/2024 -- service call

Job Total: \$451.00**J06001600 JD ALL Retail**

COMPLAINT:

02 ROCK DAMAGE

CAUSE:

CORRECTION:

FAST wing were all bent.
Remove all wear strips.
Remove FAST wing and replace with new one.
Re use wear strip and replace some damage bolt.
Tighten all bolts and nuts into specs.
Run combine and check its function. Working good.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H137329	M12x1.75 Flg DT Lock	8.00	3.04	\$24.32	Y
HXE84113	SUPPORT	4.00	372.81	\$1,491.24	Y
HXE84114	SUPPORT	4.00	372.81	\$1,491.24	Y
L215374	BOLT	8.00	4.68	\$37.44	Y

Miscellaneous Charges:

SERVICE ACCESSORIES

\$82.00

Labor: \$820.00	Parts: \$3,044.24	OL&M: \$0.00	Miso: \$82.00	Sub-Total: \$3,946.24
------------------------	--------------------------	-------------------------	----------------------	------------------------------



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 682-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: 62445

Deliver To:

SERVICE INVOICE

Bus Phone:	
Prv Phone:	

Bus Phone:	
Prv Phone:	

Invoice Number:	3190619
Invoice Date:	06/21/2024
Location:	12
Work Order Number:	453612
Payment Type:	Finance
Page:	2 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	1687	1H0S790SAJ0800165	821858	

Service Reminders:

Finance Information

Customer PO No:	
Tax Exempt No:	
Advisor:	Tyler Doherty

Type:	JD Multi-Use	Auth No:	813654
Merchant No:	82001036		
Card No:	xxxxxxxxxxxx1423		
Bill Code:	725 - COMBINE		
Credit Plan:	249 - PURCHASE		

Labor:	\$1,103.00
Parts:	\$3,044.24
OL&M:	\$0.00
Misc:	\$250.00
GST:	\$219.86
PST:	\$0.00

Grand Total: \$4,617.10

TERMS AND CONDITIONS

This purchase is subject to the terms of the John Deere Financial Multi-Use Account Agreement. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by:

Date:

E01-7



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 862-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 483-2883	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 828-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 882-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: 62445

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3088402 Invoice Date: 11/06/2023 Location: 12 Work Order Number: 433231 Payment Type: Finance Page: 1 of 2
--------------------------	--------------------------	--

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	1663	1H0S790SAJ0800165	821858	

Service Reminders:

JSC RADIUS B Retail

COMPLAINT:

01 SERVICE CALL TO AND FROM MACHINE LOCATED IN RADIUS B.

CORRECTION:

October 11/2023 -- Service call

Job Total: \$437.00

JGEN01- Retail

COMPLAINT:

02 top floor bent

CORRECTION:

Top floor door is bent and cannot be straightened .
Get parts required.
Go back and install door an hardware.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
14M7401	M12x1.75 Flg NyLock	2.00	1.80	\$3.60	Y
24M7180	WASHER	2.00	2.83	\$5.66	Y
AH223286	Door	1.00	1,145.08	\$1,145.08	Y

Miscellaneous Charges:

SERVICE ACCESSORIES

\$39.00

Labor: \$390.00 Parts: \$1,154.34 OL&M: \$0.00 Misc: \$39.00 Sub-Total: \$1,583.34

Finance Information

Customer PO No:	Type: JD Multi-Use	Auth No: 868798
Tax Exempt No:	Merchant No: 82001036	
Advisor: DARLENE WALKER	Card No: xxxxxxxxxxxx1423	
	Bill Code: 725 - COMBINE	
	Credit Plan: 249 - PURCHASE	

Labor: \$659.00
Parts: \$1,154.34
OL&M: \$0.00
Misc: \$207.00
GST: \$101.02
PST: \$0.00

Grand Total: \$2,121.36



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: 62445

Deliver To:

SERVICE INVOICE

Bus Phone:	Bus Phone:	Invoice Number: 3088402
Prv Phone:	Prv Phone:	Invoice Date: 11/06/2023
		Location: 12
		Work Order Number: 433231
		Payment Type: Finance
		Page: 2 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S790	1663	1H0S790SAJ0800165	821858	

Service Reminders:

TERMS AND CONDITIONS

This purchase is subject to the terms of the John Deere Financial Multi-Use Account Agreement. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by:

Date:

EOI-7



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 862-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	<i>previous owner</i>	<table border="0"> <tr> <td>Invoice Number:</td> <td>2900859</td> </tr> <tr> <td>Invoice Date</td> <td>11/07/2022</td> </tr> <tr> <td>Location:</td> <td>12</td> </tr> <tr> <td>Work Order Number:</td> <td>395976</td> </tr> <tr> <td>Payment Type:</td> <td>Account</td> </tr> <tr> <td>Page:</td> <td>1 of 9</td> </tr> </table>	Invoice Number:	2900859	Invoice Date	11/07/2022	Location:	12	Work Order Number:	395976	Payment Type:	Account	Page:	1 of 9
Invoice Number:	2900859													
Invoice Date	11/07/2022													
Location:	12													
Work Order Number:	395976													
Payment Type:	Account													
Page:	1 of 9													

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S790	1313	1H0S790SAJ0800165	821858	

Service Reminders:

JGLC JD S SERIES ALL Internal

COMPLAINT:

01 S SERIES COMBINE VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION:

VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST

 HEADER SERIAL # _____
 ENGINE HOURS _____ 1313 _____
 SEPERATOR HOURS _____ 1003 _____

DOES THIS UNIT GET A VALUEMAX STICKER x YES
 HAS THE STICKER BEEN INSTALLED NO
 THIS UNIT HAS HAD THE CAB CLEANED _____ SP _____ (INITIAL)
 THIS UNIT HAS HAD A FINAL CHECKOVER _____ BC _____ (INITIAL)
 THIS UNIT HAS HAD A COMPLETE GREASE JOB _____ BC _____ (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:
 All critical repairs completed.

Job Total: \$2,500.00

JGEN01- Internal

COMPLAINT:

02 MISC PARTS

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
---------------	---------------	--------------	--------------	-------------------

JWASH1 JD ALL Internal

COMPLAINT:

03 WASH USED COMBINE. READY FOR DISPLAY.

CORRECTION:



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 862-2233	Balcarres, SK	(306) 334-2482
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2538
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:		Invoice Number: 2900859 Invoice Date: 11/07/2022 Location: 12 Work Order Number: 395976 Payment Type: Account Page: 2 of 9	
--------------------------	--	--	--

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S790	1313	1H0S790SAJ0800165	821858	

Service Reminders:

INCLUDES THE FOLLOWING:

- BLOW OFF ALL CHAFF.
- WASHING OUT RADIATOR AND ALL COOLERS.
- CLEAN OUT GRAIN TANK AND UNLOADING AUGER.
- WASH EXTERIOR PANELS AND ALL SHIELDS.
- VACUUM CAB AND WASH FLOOR MAT
- CLEAN WINDOWS

Labor: \$630.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$630.00

JELECDIAG1 JD ALL Internal

COMPLAINT:

04 RC1 522116.01 - LEFT SPREADER SPEED - DIAGNOSE AND REPAIR

CORRECTION:

Open service advisor and follow diagnostic procedure on active code rc1 522116.01 left spreader speed zero alarm.
Remove tailboard plastic cover.
Unhook lh spreader speed sensor. Check supply voltage to the sensor.
check ground wire into the sensor. everything is good. Replace speed sensor.
Run combine and check the lh spreader speed. works good.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE68069	SENSOR	1.00	135.82	\$135.82	N
Labor: \$255.00	Parts: \$135.82	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$390.82	

JGEN02- Internal

COMPLAINT:

05 TOP FEEDERHOUSE COVER, STRAIGHTEN

CORRECTION:

Straighten feeder house top cover.

Labor: \$85.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$85.00

JSOFTWARE JD S790 Internal

COMPLAINT:



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 682-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3486
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2839		



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<table border="0" style="width: 100%;"> <tr> <td>Invoice Number:</td> <td>2900859</td> </tr> <tr> <td>Invoice Date</td> <td>11/07/2022</td> </tr> <tr> <td>Location:</td> <td>12</td> </tr> <tr> <td>Work Order Number:</td> <td>395976</td> </tr> <tr> <td>Payment Type:</td> <td>Account</td> </tr> <tr> <td>Page:</td> <td>3 of 9</td> </tr> </table>	Invoice Number:	2900859	Invoice Date	11/07/2022	Location:	12	Work Order Number:	395976	Payment Type:	Account	Page:	3 of 9
Invoice Number:	2900859													
Invoice Date	11/07/2022													
Location:	12													
Work Order Number:	395976													
Payment Type:	Account													
Page:	3 of 9													

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S790	1313	1H0S790SAJ0800165	821858	

Service Reminders:

06 UPDATE ALL CONTROLLER SOFTWARE

CORRECTION:

UPDATED SOFTWARE ON CAB, DISPLAY, ARMC, AYM, GQM, LC1, LC2, MHC, PDU, PTP CONTROLLERS.
HAD TO PERFORM THE FOLLOWING CALIBRATIONS.

Labor: \$340.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$340.00
-----------------	---------------	--------------	--------------	---------------------

J10171080 JD S790 Internal

COMPLAINT:

07 REPLACE FEEDERHOUSE CONVEYOR DRIVE CHAIN.

CORRECTION:

REMOVED DRIVE CHAIN.
INSTALLED NEW DRIVE CHAIN.
ADJUSTED TO PROPER TENSION.
RAN MACHINE WITH FEEDERHOUSE ENGAGED, RECHECKED AND ADJUSTED
CHAIN AS NECESSARY.
done

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE80368	LINK CHAIN	1.00	257.61	\$257.61	N

Labor: \$170.00	Parts: \$257.61	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$427.61
-----------------	-----------------	--------------	--------------	---------------------

J06171104 JD S790 Internal

COMPLAINT:

08 FEEDERHOUSE BACKSHAFT BEARING, REPLACE

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE68018	Bearing With Housing	1.00	370.75	\$370.75	N

Labor: \$255.00	Parts: \$370.75	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$625.75
-----------------	-----------------	--------------	--------------	---------------------



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351
Maple Creek, SK (306) 662-2233
Kindersley, SK (306) 463-2683
Kyle, SK (306) 375-2302
Leader, SK (306) 628-3889
Unity, SK (306) 228-2696
North Battleford, SK (306) 445-4468
Humboldt, SK (306) 682-2572
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2839
Yorkton, SK (306) 783-9459
Balcarres, SK (306) 334-2492
Moosomin, SK (306) 435-3301
Preeceville, SK (306) 547-2007
Russell, MB (204) 773-2149
Wynyard, SK (306) 554-2536
Kamsack, SK (306) 542-2814
Swan River, MB (204) 734-3466



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	2900859
		Invoice Date	11/07/2022
		Location:	12
		Work Order Number:	395976
		Payment Type:	Account
		Page:	4 of 9

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S790	1313	1H0S790SAJ0800165	821858	

Service Reminders:

J10180360 JD S790 Internal

COMPLAINT:

09 REPLACE PRIMARY COUNTERSHAFT GEARCASE OIL.

CORRECTION:

DRAINED OIL AND REFILLED WITH NEW OIL.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY26372	80W140 Synth 946ml GL5	2.00	44.43	\$88.86	N
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF15	ENVIRO FEE	2.00	0.15	\$0.30	N

Labor: \$99.00 Parts: \$88.86 OL&M: \$0.00 Misc: \$0.30 Sub-Total: \$188.16

J06001020 JD S790 Internal

COMPLAINT:

10 ENGINE DEBRIS MANAGEMENT AIR FILTERS, BLOW OUT

CORRECTION:

REMOVED AIR FILTERS.
CLEANED FILTER HOUSING AND COVER.
Blow out filters and install

Labor: \$45.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$45.00

J06172030 JD S790 Internal

COMPLAINT:

11 REMOVE AND INSTALL DISCHARGE BEATER BELT.

CORRECTION:

REMOVED AND INSTALLED DISCHARGE BEATER BELT.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
HXE124870	Discharge Beater 2HC V-Belt	1.00	446.78	\$446.78	N



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(308) 783-9459
Maple Creek, SK	(306) 862-2233	Balcarres, SK	(308) 334-2492
Kindersley, SK	(306) 483-2683	Moosomin, SK	(308) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 828-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2538
North Battleford, SK	(306) 445-4468	Kamsack, SK	(308) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Invoice Number:	2900859
Invoice Date:	11/07/2022
Location:	12
Work Order Number:	395976
Payment Type:	Account
Page:	5 of 9

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S790	1313	1H0S790SAJ0800165	821858	

Service Reminders:

Labor: \$204.00	Parts: \$446.78	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$650.78
-----------------	-----------------	--------------	--------------	---------------------

JSEDIMENT JD S790 Internal

COMPLAINT:

12 CLEAN OUT THE WATER SEPERATOR/SEDIMENT BOWL ON S690

CORRECTION:

CLEANED OUT THE WATER SEPERATOR/SEDIMENT BOWL ON S790

Labor: \$47.70	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$47.70
----------------	---------------	--------------	--------------	--------------------

J06171162 JD S790 Internal

COMPLAINT:

13 REPLACE FEEDERHOUSE CONVEYOR CHAIN WEAR GUIDES.

CORRECTION:

R & R feeder chain plastic wear strip 4pcs.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H171960	STRIP	4.00	32.35	\$129.40	N
Labor: \$170.00	Parts: \$129.40	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$299.40	

J06176004 JD S790 Internal

COMPLAINT:

14 REPLACE ACTIVE TAILINGS DRIVE CHAIN.

CORRECTION:

REMOVED SAFETY SHIELDS
REMOVED OLD ACTIVE TAILINGS DRIVE CHAIN.
INSTALLED NEW ACTIVE TAILINGS DRIVE CHAIN.
ADJUSTED CHAIN TO PROPER TENSION.
RAN UNIT, CHECK AND ADJUSTED CHAIN AS NECESSARY.
done.



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 882-2233	Balcarres, SK	(306) 334-2482
Kindersley, SK	(306) 483-2883	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 828-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 882-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Invoice Number: 2900859 Invoice Date: 11/07/2022 Location: 12 Work Order Number: 395976 Payment Type: Account	
Bus Phone: Prv Phone:	Bus Phone: Prv Phone:
Page: 6 of 9	

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S790	1313	1H0S790SAJ0800165	821858	

Service Reminders:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE54619	60@ 114links Rethresher	1.00	273.13	\$273.13	N
Labor: \$136.00		Parts: \$273.13	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$409.13

JGEN03- Internal

COMPLAINT:

15 FRONT PARTITION BOLTS , REPLACE

CORRECTION:

Remove right hand axle
Remove old bolts
Install new bolts and torque to specs.
Install axle

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
14M7296	M10x1.5 FlangeNut	2.00	1.99	\$3.98	N
H174755	M10x30 Carr10.9carbide	2.00	3.08	\$6.16	N
Labor: \$127.50		Parts: \$10.14	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$137.64

J06020131 JD S790 Internal

COMPLAINT:

16 REMOVE AND INSTALL VACUUM FAN DRIVE BELT.

CORRECTION:

R & R vac fan belt.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
HXE38073	V-BELT	1.00	32.67	\$32.67	N
Labor: \$102.00		Parts: \$32.67	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$134.67

JGEN04- Internal

COMPLAINT:

17 TOP UP COOLANT



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 882-2233	Balcarres, SK	(306) 334-2482
Kindersley, SK	(306) 483-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 882-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:	2900859
Invoice Date	11/07/2022
Location:	12
Work Order Number:	395976
Payment Type:	Account
Page:	7 of 9

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S790	1313	1H0S790SAJ0800165	821858	

Service Reminders:

CORRECTION:

Add 4 liters of coolant

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY26575	Cool-GardII 3.78L Premix 50/50	1.00	23.96	\$23.96	N
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF25	ENVIRO FEE	1.00	0.25	\$0.25	N
Labor: \$27.00	Parts: \$23.96	OL&M: \$0.00	Misc: \$0.25	Sub-Total: \$51.21	

JENGAIRFILT JD S790 Internal

COMPLAINT:

18 BLOW OUT PRIMARY ENGINE AIR FILTER

CORRECTION:

Remove filter
Clean out filter housing
Blow out filter
Install filter

Labor: \$45.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$45.00
-----------------------	----------------------	-------------------------	---------------------	---------------------------

J08180071 JD S790 Internal

COMPLAINT:

19 ADJUST ROTOR VARIABLE SHEAVE BELT GAP.

CORRECTION:

Adjust variable sheave gap to 8mm specs.

Labor: \$204.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$204.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

JENGOILCHNG JD S790 Internal

COMPLAINT:

20 REPLACE ENGINE OIL AND FILTER



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 882-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 483-2883	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 828-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2839		



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	I Bus Phone: Prv Phone:	Invoice Number:	2900859
		Invoice Date	11/07/2022
		Location:	12
		Work Order Number:	395976
		Payment Type:	Account
		Page:	8 of 9

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S790	1313	1H0S790SAJ0800165	821858	

Service Reminders:

CORRECTION:

DRAIN ENGINE OIL AND REMOVE FILTER.
CLEAN AREA.
INSTALL NEW OIL AND FILTER.
RUN UNIT AND LEAK CHECK
ADJUST OIL LEVEL AS REQUIRED.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE572785	OIL FILTER	1.00	128.16	\$128.16	N
TY26673	15W40 3.78L Plus-50II CK4/SN	1.00	37.36	\$37.36	N
TY26679	15W40 18.9L Plus-50 II	2.00	169.37	\$338.74	N
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.00	\$1.00	N
EF300	ENVIRO FEE	2.00	3.00	\$6.00	N
EF60	ENVIRO FEE	1.00	0.60	\$0.60	N

Labor: \$112.50 Parts: \$504.26 OL&M: \$0.00 Misc: \$7.60 Sub-Total: \$624.36

JCABFILTER JD S790 Internal

COMPLAINT:

21 REPLACE CAB AIR FILTERS

CORRECTION:

REMOVE CAB AIR FILTERS
CLEAN FILTER HOUSING
INSTALL NEW AIR FILTERS

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
L214634	CabRecirc AirFilter 2/pkg	1.00	40.86	\$40.86	N
RE284091	Cab Air Filter	1.00	113.75	\$113.75	N

Labor: \$45.00 Parts: \$154.61 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$199.61

J06175007 JD 9870STS Internal

COMPLAINT:

22 REPLACE LEFT HAND LOWER TAILINGS AUGER BEARING

CORRECTION:



P.O. Box 860
Preeceville, SK S0A 3B0
Phone: (306) 547-2007
Fax: (306) 547-3382
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 862-2233	Balcarras, SK	(306) 334-2492
Kindersley, SK	(306) 463-2883	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2839		



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Invoice Number:	2900859
Invoice Date:	11/07/2022
Location:	12
Work Order Number:	395976
Payment Type:	Account
Page:	9 of 9

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S790	1313	1H0S790SAJ0800165	821858	

Service Reminders:

Open battery compartment. Remove bottom battery.
R & R tailing bottom auger bearing on the lh side. Install back battery and the cover.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AZ10044	ECCENTRIC	1.00	11.49	\$11.49	N
JD39102	Ball Bearing 205F	1.00	27.49	\$27.49	N

Labor: \$255.00 Parts: \$38.98 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$293.98

J06172012 JD S790 Internal

COMPLAINT:

23 REPLACE POWERCAST SPREADER PLASTIC PADDLES. - parts supplied through sales

CORRECTION:

Replaced paddles as per instructions

Miscellaneous Charges:

SERVICE ACCESSORIES

\$150.00

Labor: \$340.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$150.00 Sub-Total: \$490.00

Customer PO No:
Tax Exempt No:
Advisor: CLINT YANKE

Labor:	\$7,179.70
Parts:	\$2,586.91
OL&M:	\$0.00
Misc:	-\$946.79
GST:	\$0.00
PST:	\$0.00
Grand Total:	\$8,819.82

TERMS AND CONDITIONS

Received by:

Date: