

11-20-15 - REPLACE FRONT ENG BELTS (ALL)
13227 HRS - REPLACE REAR ENG OIL TEMP SENSOR
- CHANGE BOTH BOTTOM ROLLERS ON
EJECTOR DOOR

4/2/16 Replaced front Eng starter w/ Rebuilt from P+G
13,430 HRS Resealed front cover on rear eng. - Replaced Both
Belts on Rear Eng.

7/16/16 - Replaced Left front Brake Chamber w/ rebuilt from
13554 HRS shop
- Service Eng's

9/16 - Replaced Wire harness from Goose neck to Back of Bow
13600 HRS

11/16 - Changed Pilot Control oil Solenoid valve
13746 HRS

6-18 Replaced A/C compressor and receiver/drier
14413 hrs.

7/18 Remove front trans and sent to Roland or HES in
14,480 HRS Wisconsin to get Rebuilt / New trans cooler Lines
Removed and Replaced trans cooler