

7-13-18 Purchased from broker in Canada

Serviced both engines and took samples of transmissions.

Check all other fluids.

7-23-18 Sent Althurter out to replace and reprogram the ~~ECU~~ for implement controls on the tractor Replaced TCU

3/19 - Removed and Replaced front Exhaust Manifold and Studs
10,908 HRS

- Remove and Reseal front Drive Coupler for front Drive shaft
- Changed Hyd Oil and filters
- Replaced main Hyd Line from pump to Goose neck
- Clean Steering Screen