

5-17-12 - REPLACE REAR ENG STARTER
REMAN P+G.

11-24-12 - REPLACE CUTTING EDGES (ROLLAND)
525HRS (BUCKYESS EDGES)

8-8-13 - REPACK LEFT STEER CYL.
725HRS

3-10-14 - REPACK RIGHT STEER CYL

1000HRS - FLIP CUTTING EDGES

4-9-14 - REPLACE 6 REAR FUEL INJECTORS
1010HRS W/ CAT REMAN

- ADJ VALVES

5-9-14 - REPLACE CUTTING EDGES.
1050HRS

6-23-14 - REPLACE ALL WIRING HARNESS FROM
1322HRS CONNECTION UNDER CAB ALL THE WAY
BACK TO REAR MONITOR PANEL,
(5 TOTAL WIRE HARNESS)

- CHANGE SYNCR. SOLENOID OR REAR TRANS

- SERVICE REAR TRANS OIL + FILTERS

NOTE - - STILL HAD SAME PROB SEE SEPERATE
SHEET

7-28-14 - REPLACE COMPLETE FRONT ENG.

1418HRS EXH. MANIFOLD, REPAIR ALL BROKEN
STUDS, NEW INSERTS, GSKTS, + HARDWARE

NOTE: - R+R APRON CYL. REBUILT AT MASTER HYD
CYL WAS

TORN OFF
MACHINE

BY OPERATOR - ALL NEW BUSHINGS IN CYL. NEW HOSES

REAR TRANS PROB.

PARTS
CHANGED

- REPLACED POWER MODUAL UNDER CAB FOR REAR TRANS.

JULY
OF
2014

- REPLACE 2 SHIFT SELONOID ON FRONT TRANS (REPAIR WIRING)
- HOLAFAX SWITCH ~~IN~~ VALVE BODY FRONT TRANS + HARNESS (FULL OF WATER)
- CHANGE BOTH SHIFT SELONIDS ON REAR TRANS. ALSO REPLACE SWITCH FOR SHIFTING MOUNTED ON REAR OF REAR TRANS IN ROUND CASE.

AFTER ALL OF ABOVE TRANS IS
NOW WORKING PROPERLEY!



- 8-25-14 - REPLACE MAGNET ON APRON FLOAT
111 HRS - REPAIR FRONT + REAR TRANS TEMP.
GAUGES, NEW FRONT SENDING UNIT
(OLD ONE BROKEN) REAR - REPAIR RUBBED
THROUGH WIRE AT FRONT BY AC UNIT
IN MAIN HARNESS, WIRE (WAS FOR
REAR TRANS TEMP)
- REPLACE TACH + HOUR METER (CAT)
NOTE - HOURS ON OLD METER 1418
- HOURS NOW 111

- 4-29-15 - RESEAL EJECTOR CYL. IN SHOP
460 HRS - RESEAL LEFT BOWY CYL. (MASTER HYD)
CAT PACKINGS, NEW ROD

- 9-14-15 - REPLACE REAR MUFFLER, OLD ONE
960 HRS CRACKED AT OUTLET.
- REPLACE REAR FAN BELTS

- 10/20/16 - Replaced rear trans temp sender unit
~~REPLACED~~ - Replaced Rear Batteries
1401 HRS - Replaced front trans cooler line

- 7/17 - Remove and Reseal Cushion hitch Cyl
1563 HRS

Internal Vehicle Repair Order

Mechanic: Pat Kelsey

Date: 3/1/16

Serial No.: IDL

Hours/Miles: 1210 HRS

Unit#: 627F #1

Repair Work Performed: Split tractor Replaced Main upper and Lower Pins and Bushings / Replaced all steering Link pins and Bushings / Left J steer cly sent out for Reseal and Got New Reman Rod from CAD / Replaced all 6 Hyd lines that Run threw Goose neck / Replaced Fuel lines from tank up side of Bowl to Goose neck and New lines (fuel) threw Goose neck / Replaced Air line for Rear Air throttle from Goose neck to Eng / Replaced quick Release Valve for front Brakes / Flip Cutting Edges and Replaced Side Cutters / Remove and Rebuild Main Control Valve (pilot valve in cab) / Cut off Ballends on Apron door and weld on New ends and Replaced Balls in Bowl (Bolt on) Remove side cover plate on front Eng injection pump and reseal / Replaced Coolant hoses from water pump to oil cooler and to aftercooler on Rear Engine.

Parts/Material:

Reviewed:

4/20 - Replaced Eng oil Cooler w/ cat Reman front Eng
2,650 HRS Cleaned out Radiator w/ Power Washer