

#5

027 F IDL 561

4-3-15

- ALL NEW BATTERIES + JUMPERS
- RESEAL CUSHION HITCH CYL
- REPLACE 2 SHORT STEER CYL HOSES
- REPLACE 2 HOSES TOP OF GOOSE NECK
- ADD COND. TO RADIATORS
- REPLACE PARKING BRAKE VALVE
- NEW WIRE HARNESS GOOSE NECK TO UNDER CAB
- 2 NEW HARNESSES DOWN RT SIDE OF DRAFT ARM
- ~~NEW REAR PANEL HARNESS~~
- 2 AIR BRAKE HOSES DOWN RT SIDE OF DRAFT ARMS TO REAR BRACES TOP OF GOOSE NECK
- ADD SIDES TO BOWL
- SERVICE ENGS MAJOR
 - SERVICE TRANS FRONT + REAR - ^{NEW} BREATHE_{RS}
 - NEW WIRE HARNESS ON REAR ENG, CONTROL PANEL
- REAR ENG NEW BELTS
- ADJ BRAKES
- TOP OFF AC. UNIT W/ FREE OIL
- SERVICE HYD. FILTERS ONLY
- SERVICE AIR DRIER
- CK ALL FLUIDS

- REPAIR RIF FINAL PLUG
- CK ALL TIRES
- REPAIR REAR STEPS
- FROZEN BRAKE PEDAL REPAIRED
- REPLACE 2 GREASE HOSES TO CUSHION HITCH PIN
- REPAIR CAB FILTER COVER BOLTS

7-7-15 - REPLACE SEAT BACK CUSHION (CAT)

10-1-15 - REPLACE REAR ENG. + TRANS WIRING
5092 HRS HARNESS

7/16 Reseal Hyd + steer pumps install New shaft + bearing
5345 HRS - Replaced cushion Hitch pump w/ New CAT
changed Hyd Filters - Service trans Because Hyd pump was over filling trans w/ Hyd oil
- Replaced steering metering pump

9/17 - Front throttle Valve Replaced
5686 HRS - Changed Injectors on Rear Eng w/ Cat Reman

12/17 Rear Eng Starter
5849 HRS

5-18 - Rebuild both lift and ejector cylinders.
- Front engine fuel pump resealed by HES