



CAMROSE:  
4717 38th St.  
Camrose, AB T4V 3W9  
Phone: 780-672-4463

KILLAM:  
5907 51st Ave  
Killam, AB T0B 2L0  
Phone: 780-385-3993

PROVOST:  
P.O. Box 299  
3403 57 Ave  
Provost, AB T0B 3S0  
Phone: 780-753-2278

WAINWRIGHT:  
1601 - 23 Street  
Wainwright, AB T9W 1L2  
Phone: 780-842-2171

Ship To: IN STORE PICKUP

Invoice To:

Branch KILLAM			*REPRINT*		
Date 10/21/24	Time 22:20:30 (B)		Page 01		
Account No [REDACTED]	Phone No [REDACTED]		Inv No [REDACTED]		
Ship Via		Purchase Order			
Tax ID No					
				Salesperson 218	

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C014605	HD50R HINGED DRAPE	1E	1H0HD50RJN0820023	08/02/23	
	HD50R			08/01/25	750 X

GST# 895703353

SEGMENT# 1 C 228 NA 07/20/23 01/30/24

BRI INSPECTION

CORRECTION:

JULY 10/2024

\*\* had to move headers to make space on Pad to perform work  
- approx. 45 mins to make space and bring this unit into a  
safer workspace

-----

\*\* began BRI Inspection per checklist

JULY 11/2024

\*\* resumed BRI Inspection per checklist

JULY 15/2024

\*\* drove to Kroetsch to figure out the missing side panel  
issue with HD50R's

\*\* stopped @ McKinnon Farm to find header 8200232 >> not on  
site, found unit back at shop

\*\* pulled unit from sales line up to The Pad to be  
inspected

JULY 16/2024

\*\* began BRI Inspection per checklist on unit 820023

\*\* completed BRI Inspection per checklist, completed  
calibrations and run-up.

Went through the BRI inspection checklist and wrote down  
what was needed to be repaired or adjusted. There is one  
code on the header, Right draper speed sensor is out of  
high range. Ran the unit and there wasn't any unusual  
sounds or noises being made from it. Went through

CONTINUED ON PAGE 02

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: \_\_\_\_\_



CAMROSE:  
4717 38th St.  
Camrose, AB T4V 3W9  
Phone: 780-672-4463

KILLAM:  
5907 51st Ave  
Killam, AB T0B 2L0  
Phone: 780-385-3993

PROVOST:  
P.O. Box 299  
3403 57 Ave  
Provost, AB T0B 3S0  
Phone: 780-753-2278

WAINWRIGHT:  
1601 - 23 Street  
Wainwright, AB T9W 1L2  
Phone: 780-842-2171

Ship To: IN STORE PICKUP

Invoice To:

. AB X0X 0X0

Branch KILLAM		
Date 10/21/24	Time 22:20:30 (B)	Page 02
Account No [REDACTED]	Phone No [REDACTED]	Inv No [REDACTED]
Ship Via		Purchase Order
Tax ID No		
		Salesperson 218

## SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
C014605	HD50R HINGED DRAPE	1E 1H0HD50RJN0820023	08/02/23	
	HD50R		08/01/25	750 X

calibrations and made sure they all passed. Greased the unit before it was parked and getting approval. ^^tech #505  
AUGUST 8/2024  
\*\* service call to Kroetsch Farms -- installed missing RH side-sheet panels  
ADDITIONAL DESCRIPTION:  
\*repair 2 flats - o/s mat & lab invoice #IN015072 KILLAM  
TIRE \$190.50  
TY6341

51400402	GREASE	2	11.34	22.68
			PARTS	22.68
			LABOR	744.10
			SEGMENT TOTAL==>	766.78

***** WORK ORDER TOTALS *****	
INTERNAL	CUSTOMER
PARTS	22.68
LABOR	744.10
O/S LABOR & MAT	190.50
INTERNAL TOTAL	957.28

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: \_\_\_\_\_