



CAMROSE:
4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4463

KILLAM:
5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

PROVOST:
P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

WAINWRIGHT:
1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To: IN STORE PICKUP

Invoice To:

Branch CAMROSE			*REPRINT*		
Date 10/22/24	Time 22:20:08 (B)		Page 01		
Account No [REDACTED]	Phone No [REDACTED]		Inv No [REDACTED]		
Ship Via		Purchase Order			
Tax ID No					
		Salesperson 137			

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016156	HD45R HINGED DRAPE HD45R	1E	1H0HD45RCN0820107	08/01/24	

GST# 895703353

SEGMENT# 1 C 148	NA	08/27/24	08/27/24
BRI inspection			

10104001	16001000	LABOR	799.00
SEGMENT TOTAL==>			799.00

SEGMENT# 2 C 148	NA	08/27/24	08/27/24
REPAIRS			

CORRECTION:

- I replaced 3 sections, and 5 guards. I set the knife hold down brackets to the proper clearance. I removed the damaged skid plate and riveted the new one in place. I trimmed the center skid plate so it does not contact the other when the header is flexing. I removed the 2 divider rods and installed the new ones with new hardware, and then adjusted the divider cone height on each side.. I updated the controller software. I ran the header and tested all functions, then put the header back into transport and replaced one pin on the transport system. The header operates as it should.

ADDITIONAL DESCRIPTION:

- REPLACE 2 SECTIONS (0.5) x
- ADJUST KNIFE HOLD DOWNS (1.0) x
- REPLACE LH OUTER SKID SHOE TRIM ONE SKID SHOE (1.5) x
- REPLACE 4 GUARDS AND 1 MISSING BOLT (1.0) x
- REPLACE DIVIDER RODS AND ADJUST HEIGHT (1.5) x
- UPDATE 1 CONTROLLER (1.0) x
- REPLACE 1 TRANSPORT PIN (0.5) x

CONTINUED ON PAGE 02

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



CAMROSE:
4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4463

KILLAM:
5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

PROVOST:
P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

WAINWRIGHT:
1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To: IN STORE PICKUP

Invoice To:

Branch CAMROSE		
Date 10/22/24	Time 22:20:08 (B)	Page 02
Account No [REDACTED]	Phone No [REDACTED]	Inv No [REDACTED]
Ship Via		Purchase Order
Tax ID No		
		Salesperson 137

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016156	HD45R HINGED DRAPE HD45R	1E	1H0HD45RCN0820107	08/01/24	
AA44981	Cable	1		35.48	35.48
AXE94520	Rod	2 N		269.64	539.28
HXE169294	Rivet	20		.67	13.40
HXE171955	Cover	1 N		233.40	233.40
HXE179714	Pin	1		30.05	30.05
HXE180706	Cotter Pin	1		5.35	5.35
H153329	SECTION FINE	3		4.96	14.88
H228526	GUARD/635D	1		24.72	24.72
H229537	Knife Guard	3		39.29	117.87
H229538	Knife Guard	1		39.29	39.29
R80436	RING	1		8.95	8.95
03M7193	BOLT/10/35MM	1		2.85	2.85
14M7296	NUT FLANGE 10M	1		2.96	2.96
19M11334	Screw	6 N		3.23	19.38
34M7037	SPRING PIN	1		2.58	2.58
	PARTS				1090.44
	LABOR				1225.00
10104001	SEGMENT TOTAL==>				2315.44

***** WORK ORDER TOTALS *****

PARTS	1090.44
LABOR	2024.00
SERV ACCESORIES	80.96
SUB TOTAL==>	3195.40
GST	159.78
MASTERCARD CHARGE	3355.18

1234

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____