

KILLAM: 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993

PROVOST P.O. Box 299 3403 57 Ave Provost, AB T0B 3S0 Phone: 780-753-2278

WAINWRIGHT: 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

Ship To: IN STORE PICKUP

Invoice To: BRI KILLAM INTERNAL

X0X 0X0 AB

	REPR	INT		
Time				Page
22:	20:27	(B)		01
Phone No			Inv N	0
	Purchase	Order		
		Sales	sperso	n
			237	
	22:	Time 22:20:27 Phone No	22:20:27 (B) Phone No Purchase Order Sale:	Time

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

C016301 616R SELF-PROPELLE 374E 1N0616RXHP0248122 10/05/24

616R

GST# 895703353

SEGMENT# 1 C 300 11/07/24 11/07/24 NA

BRI INSPECTION

CORRECTION:

Check out machine as per info in inspection and put times

to repairs

ADDITIONAL DESCRIPTION:

BRI INSPECTION

16 SPRAYERWIN WINTERIZING FLU 22.99 367.84 PARTS 367.84

1995.00 LABOR

10102002 16003000 SEGMENT TOTAL ==> 2362.84

SEGMENT# 2 C 300 NA

CONTROL SYSTEM

11/27/24 11/28/24

3.00 HRS

CORRECTION:

Download and install software as needed. Had trouble getting the display update to go but got it to work.

ADDITIONAL DESCRIPTION:

*CLEAR STORED CODES (1)

*UPDATE ALL SOFTWARE (2)

***UNIT HAS NO WARRANTY LEFT (Expires 5.10.2024) ***

525.00 LABOR 10102002 16003000 SEGMENT TOTAL ==> 525.00

SEGMENT# 3 C 300 NA 11/27/24 11/27/24

ENGINE

1.00 HRS CONTINUED ON PAGE 02

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

N: 4		
Signature:		



KILLAM: 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993

PROVOST: P.O. Box 299 3403 57 Ave Provost, AB T0B 3S0 Phone: 780-753-2278

WAINWRIGHT: 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

Ship To: IN STORE PICKUP

Invoice To: BRI KILLAM INTERNAL

. AB X0X 0X0

Branch					
KILLAM					
Date	Time				Page
12/12/24	22:	20:27	(B)		02
Account No	Phone No			Inv N	No
BRI02				W3!	5015
Ship Via		Purchase	Order		
Tax ID No					
			Sale	sperso	n
				237	

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS C016301 616r SELF-PROPELLE 374e 1N0616rXHP0248122 10/05/24	
616R	
CORRECTION:	
Drain motor oil and replace oil filter	
ADDITIONAL DESCRIPTION:	
*CHANGE ENGINE OIL & FILTER - OIL IS LOW (1)	
(FYI) - COOLANT GOOD - TESTS TO -30	
EF4663 RECYC FEE LONG 2 1.00 2.00	
EF4665 RECYC FEE OIL 1 .40 .40	
EF4666 RECYC FEE OIL 1 2.00 2.00	
RE509672 OIL FILTER 1 44.10 44.10	
TY26673 PLUS-50 TM Engi 1 37.14 37.14	
Plus-50 II Oil 15W40 4L/SN	
TY26675 15W40 PLUS 9.46 1 87.45 87.45	
Plus-50 II Oil 15W40 CJ4/SN	
TY26679 15W40 18.9L 1 159.28 159.28	
Plus-50 II Oil 15W40 CJ4/SN	
PARTS 332.37	
LABOR 175.00	
16003000 SEGMENT TOTAL==> 507.37	
SEGMENT# 4 C 300 NA 11/27/24 11/27/24	
FUEL SYSTEM .75 HRS	
CORRECTION:	
Replace both fuel filter and bleed system	
ADDITIONAL DESCRIPTION:	
*CHANGE FUEL FILTERS - PDI ONES STILL INSTALLED (.75)	
DZ112918 Filter Element 1 212.86 212.86	
DZ130550 Filter Element 1 209.51 209.51	
EF4663 RECYC FEE LONG 2 1.00 2.00	
PARTS 424.37	

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature:	

CONTINUED ON PAGE 03



KILLAM: 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993 PROVOST:
P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

WAINWRIGHT: 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

Ship To: IN STORE PICKUP

Invoice To: BRI KILLAM INTERNAL

• --

AB X0X 0X0

Time			Page
22:2	0:27	(B)	03
Phone No			Inv No
F	Purchase	Order	
•		Sales	sperson
			237
	22:2 Phone No	22:20:27 Phone No	22:20:27 (B) Phone No Purchase Order Sales

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

C016301 616R SELF-PROPELLE 616R

374E 1N0616RXHP0248122

10/05/24

131.25

16003000

LABOR 13

SEGMENT TOTAL ==> 555.62

5.00 HRS

SEGMENT# 5 C 300 NA

11/27/24 12/02/24

ELECTRICAL

***(FYI) - REPLACE BOTH FRONT TURN LIGHTS (RE592939)

(WARRANTY "W35068" DEPENDING ON WARRANTY DATE CHANGE) ***

***(FYI) - REPLACE LH SIDE INDICATOR LIGHT (RE593795)

(WARRANTY "W35068" DEPENDING ON WARRANTY DATE CHANGE) ***

(FYI) - BATTERIES TESTED 1047 & 1045 CCA

SEGMENT# 6 C 300

11/27/24 11/27/24

HYDRAULIC SYSTEM

CORRECTION:

Jack up machine and tighten left rear tread shims as

needed. Drain all hubs oils and replace.

ADDITIONAL DESCRIPTION:

*ADJUST LR ONLY - TREAD ADJUST SHIM (1)

*CHANGE PLANETARY HUB OIL (4)

***(FYI) - PDI ON ALL STRAINER FILTERS (1000HR CHANGE

INTERVAL) ***

(FYI) - HYD PUMP TESTS 210 & 3046

***(FYI) - REPLACE HYDROSTATIC FRONT INPUT SEAL (LEAKING)

(WARRANTY "W35068" DEPENDING ON WARRANTY DATE CHANGE) ***

EF4664 RECYC FEE OIL 10 .10 1.00 TY26372 80W-140 GEAR 1L 13 43.62 567.06

PARTS 568.06 LABOR 875.00

10102002 16003000 SEGMENT TOTAL==> 1443.06

CONTINUED ON PAGE 04

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

N: 4		
Signature:		



KILLAM: 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993 PROVOST:
P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

WAINWRIGHT: 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

Ship To: IN STORE PICKUP

Invoice To: BRI KILLAM INTERNAL

•

AB X0X 0X0

Branch					
KILLAM					
Date	Time				Page
	22:	20:27	(B)		04
Account No	Phone No	,		Inv N	No.
Ship Via		Purchase	Order		<u> </u>
Tax ID No					
			Sale	sperso	n
				237	

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

C016301 616R SELF-PROPELLE 374E 1N0616RXHP0248122 10/05/24

616R

SEGMENT# 7 C 300 NA 11/27/24 11/27/24

CAB & MISC

CORRECTION:
Replace both cab filters and put in cab to be installed in

the spring. Up date display as needed.

ADDITIONAL DESCRIPTION:

*REPLACE BOTH CAT 4 CAB AIR FILTERS (.5)

*UPDATE GREENSTAR DISPLAY (1.5)

KK57033 Air Filter 1 1005.16 1005.16

PARTS 1005.16 LABOR 350.00

16003000 SEGMENT TOTAL==> 1355.16

SEGMENT# 8 C 300 NA 11/27/24 11/27/24

CHASSIS 1.00 HRS
CORRECTION:

Remove and replace air dryer filter

ADDITIONAL DESCRIPTION:
*CHANGE AIR DRYER CARTRIDGE (1)

` '

UNIT HAS SKINNY TIRES AND SKINNY FENDERS OM IT

AKK11031 FILTER AIR DRY 1 323.76 323.76

PARTS 323.76

LABOR 175.00

16003000 SEGMENT TOTAL==> 498.76

SEGMENT# 9 C 300 NA 11/27/24 12/02/24

SOLUTION SYSTEM

CORRECTION:

2.00 HRS

2.00 HRS

CONTINUED ON PAGE 05

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

N: 4		
Signature:		



KILLAM: 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993 PROVOST: P.O. Box 299 3403 57 Ave Provost, AB T0B 3S0 Phone: 780-753-2278 WAINWRIGHT: 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

Ship To:	IN	STORE	PICKUP

Invoice To: BRI KILLAM INTERNAL

• --

AB X0X 0X0

Branch					
KILLAM					
Date	Time				Page
12/12/24	22:	20:27	(B)		05
Account No	Phone No	ı		Inv N	No
Ship Via		Purchase	Order		<u>.</u>
Tax ID No					
			Sale	sperso	n
				237	

SERVICE INVOICE

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

C016301

616R SELF-PROPELLE

374E 1N0616RXHP0248122

10/05/24

.

616R

Remove and clean suction screen and put boom screens in cab. Check out 2 leaking nozzles and clean and found one

broken spring. Clean main boom screen. ADDITIONAL DESCRIPTION:

*CLEAN SUCTION STRAINER (.5)

- *2 LEAKING NOZZLE BODIES CLEAN (.5)
- *CLEAN MAIN SOLUTION STRAINER (.5)
- *INSTALL BOOM STRAINERS FROM THE NEW UNITS (.5)

LABOR

350.00

16003000

SEGMENT TOTAL ==>

350.00

SEGMENT#10 C 300

RUN AND CHECK

11/27/24 12/05/24

2.00 HRS

CORRECTION:

Take outside and run to check for leaks

ADDITIONAL DESCRIPTION:

RUN AND CHECK

LABOR

350.00

16003000

SEGMENT TOTAL ==>

350.00

***** WORK ORDER TOTALS *****

INTERNAL CUSTOMER

PARTS 3021.56 LABOR 4926.25 SERV ACCESORIES 100.00 INTERNAL TOTAL 8047.81

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature:		