



CAMROSE:  
4717 38th St.  
Camrose, AB T4V 3W9  
Phone: 780-672-4463

KILLAM:  
5907 51st Ave  
Killam, AB T0B 2L0  
Phone: 780-385-3993

PROVOST:  
P.O. Box 299  
3403 57 Ave  
Provost, AB T0B 3S0  
Phone: 780-753-2278

WAINWRIGHT:  
1601 - 23 Street  
Wainwright, AB T9W 1L2  
Phone: 780-842-2171

Ship To:



Invoice To: BRI KILLAM INTERNAL  
.  
. AB X0X 0X0

Branch KILLAM			*REPRINT*		
Date 04/29/25	Time 22:20:30		Page [REDACTED]		
Account No [REDACTED]	Phone No [REDACTED]		Inv No [REDACTED]		
Ship Via		Purchase Order			
Tax ID No					
				Salesperson 218	

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016667	X9 1000 COMBINE	786E	1H0X910XEN0820102	08/25/23	
	X9 1000	507		08/23/27	1250 X

GST# 895703353

SEGMENT# 1 C 292 NA 01/16/25 03/25/25

BRI INSPECTION

CORRECTION:

inspected combine

TY6341	GREASE	1	11.96	11.96
	PARTS			11.96
	LABOR		2595.00	
16001000	SEGMENT TOTAL==>		2606.96	

SEGMENT# 2 C 292 NA 01/16/25 04/08/25

REMOVE CHOP TO DROP

CORRECTION:

removed chop to drop door for further inspection

ADDITIONAL DESCRIPTION:

REMOVE CHOP TO DROP DOOR

DE32457	Seal	1	71.11	71.11
HXE171982	Bracket	1 N	385.96	385.96
19M8874	M8 X 75MM FLANG	1	6.13	6.13
	PARTS		463.20	
	LABOR		341.25	
16001000	SEGMENT TOTAL==>		804.45	

SEGMENT# 3 C 292 NA 04/08/25 04/22/25

CONTROL SYSTEM

5.00 HRS

CORRECTION:

updated payloads

cleared all codes

CONTINUED ON PAGE 02

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: \_\_\_\_\_



CAMROSE:  
4717 38th St.  
Camrose, AB T4V 3W9  
Phone: 780-672-4463

KILLAM:  
5907 51st Ave  
Killam, AB T0B 2L0  
Phone: 780-385-3993

PROVOST:  
P.O. Box 299  
3403 57 Ave  
Provost, AB T0B 3S0  
Phone: 780-753-2278

WAINWRIGHT:  
1601 - 23 Street  
Wainwright, AB T9W 1L2  
Phone: 780-842-2171

Ship To:



Invoice To: BRI KILLAM INTERNAL  
.  
. AB X0X 0X0

Branch KILLAM		
Date 04/29/25	Time 22:20:30 (B)	Page 02
Account No [REDACTED]	Phone No [REDACTED]	Inv No [REDACTED]
Ship Via		Purchase Order
Tax ID No		
		Salesperson 218

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016667	X9 1000 COMBINE	786E	1H0X910XEN0820102	08/25/23	
	X9 1000	507		08/23/27	1250 X

ADDITIONAL DESCRIPTION:

- \*UPDATE 9 PAYLOADS (3)
- \*DIAGNOSE AND CLEAR ALL CODES ON DISPLAY (2)

	LABOR	875.00
16001000	SEGMENT TOTAL==>	875.00

SEGMENT# 4 C 292 NA 04/08/25 04/09/25  
FEEDER HOUSE AREA 4.75 HRS

CORRECTION:

replaced feeder house chain  
changed pro drive filter  
changed feederhouse front seal  
replaced 1 bent conveyor slat and tensioned chain  
clean feed accelerator drum out

ADDITIONAL DESCRIPTION:

- \*REPLACE FEEDERHOUSE DRIVE CHAIN (WRONG CHAIN ON) (.5)
- \*CHANGE PRO DRIVE FILTER (.25)
- \*CHANGE FEEDER HOUSE FRONT SEAL (.5)
- \*REPLACE 1 BENT CONVEYER CHAIN SLATE AND THEN TENSION CHAIN (1)
- \*CLEAN FEED ACCELERATOR DRUM OUT (VIBRATION) (2.5)

AXE90399	Roller Chain	1	1002.68	1002.68
EF4663	RECYC FEE LONG	1	1.00	1.00
HXE113327	Slat	1	64.61	64.61
HXE138024	Seal	1	38.64	38.64
RESTOCK	RESTOCK CHARGE	1	204.86	204.86
	HXE170300 RESTOCK CHARGE			
RE577612	Filter Element	1	166.75	166.75
14M7517	M10 NYLON LOCK	4	3.41	13.64

PARTS 1492.18

CONTINUED ON PAGE 03

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: \_\_\_\_\_



CAMROSE:  
4717 38th St.  
Camrose, AB T4V 3W9  
Phone: 780-672-4463

KILLAM:  
5907 51st Ave  
Killam, AB T0B 2L0  
Phone: 780-385-3993

PROVOST:  
P.O. Box 299  
3403 57 Ave  
Provost, AB T0B 3S0  
Phone: 780-753-2278

WAINWRIGHT:  
1601 - 23 Street  
Wainwright, AB T9W 1L2  
Phone: 780-842-2171

Ship To:



Invoice To:



INTERNAL

.

. AB X0X 0X0

Branch KILLAM		
Date 04/29/25	Time 22:20:30 (B)	Page 03
Account No [REDACTED]	Phone No	Inv No W35287
Ship Via		Purchase Order
Tax ID No		
		Salesperson 218

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016667	X9 1000 COMBINE	786E	1H0X910XEN0820102	08/25/23	
	X9 1000	507		08/23/27	1250 X
				LABOR	831.25
	16001000			SEGMENT TOTAL==>	2323.43

SEGMENT# 5 C 292 NA 04/08/25 04/09/25  
LEFT HAND SIDE 14.25 HRS

CORRECTION:

installed and zero and leveled concaves  
replaced 2 handles on gull wing doors  
replaced 2 speed chopper gearcase seals and union fitting  
and changed oil

flipped chopper knives and changed locknuts  
changed shoe loss monitor  
tensioned paddle chain  
changed hydrostatic return filters  
changed main hydraulic reservoir filter  
changed main engine gearcase filter  
changed main hydrostatic filter  
cleaned camera and changed desiccant

ADDITIONAL DESCRIPTION:

\*INSTALL AND LEVEL AND ZERO CONCAVES (4)  
\*MISSING FILLER PLATE BRACKET (.5)  
\*CALIBRATE CHAFFER & SEIVE (1)  
\*REPLACE 2 HANDLES ON 2 GULL WINGS (Z63847) (.25)  
\*REPLACE CHOPPER TWO SPEED GEARCASE SEAL AN UNION FITTING  
AND CHANGE OIL (2)  
\*FLIP CHOPPER KNIVES AND REPLACE LOCK NUTS (3)  
\*REPLACE #3 SHOE LOSS MONITOR FROM LEFT (1)  
\*TENSION TAILING ELEVATOR PADDLE CHAIN (.5)  
\*CHANGE HYDROSTATIC RETURN FILTERS (1)  
\*CHANGE MAIN HYDRAULIC RESERVOIR FILTER (.5)

CONTINUED ON PAGE 04

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: \_\_\_\_\_



CAMROSE:  
4717 38th St.  
Camrose, AB T4V 3W9  
Phone: 780-672-4463

KILLAM:  
5907 51st Ave  
Killam, AB T0B 2L0  
Phone: 780-385-3993

PROVOST:  
P.O. Box 299  
3403 57 Ave  
Provost, AB T0B 3S0  
Phone: 780-753-2278

WAINWRIGHT:  
1601 - 23 Street  
Wainwright, AB T9W 1L2  
Phone: 780-842-2171

Ship To:



Invoice To: BRI KILLAM INTERNAL

.

. AB X0X 0X0

Branch KILLAM		
Date 04/29/25	Time 22:20:30 (B)	Page 04
Account No [REDACTED]	Phone No [REDACTED]	Inv No [REDACTED]
Ship Via		Purchase Order
Tax ID No		
		Salesperson 218

## SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
C016667	X9 1000 COMBINE	786E 1H0X910XEN0820102	08/25/23	
	X9 1000	507	08/23/27	1250 X
*CHANGE MAIN ENGINE GEARCASE FILTER (.5)				
*CHANGE MAIN HYDROSTATIC FILTER (.5)				
*CLEAN CAMERA LENS' & CHANGE DESSICANT (.5)				
AXE55969	GRAIN LOSS SENS	1	284.20	284.20
	Uncategorized Sensor			
AXE73798	HYDRAULIC FILTE	1	171.45	171.45
	Hydraulic Filter			
AXE82230	Breather	1	104.84	104.84
DE32460	Seal	1	113.37	113.37
EF4663	RECYC FEE LONG	3	1.00	3.00
EF4665	RECYC FEE OIL	2	.44	.88
HXE118760	M10 Lock Nut	34	3.01	102.34
H137328	M8 FLANGE LOCK	5	1.51	7.55
H165447	LOCK NUT	1	26.49	26.49
KXE10744	Desiccant	1	331.55	331.55
M64720	RIVET	12	1.49	17.88
PM38625	LOCTITE 515	1	42.99	42.99
RE577250	TRANS FILTER	2	130.82	261.64
	Hydraulic Filter			
R110708	O-RING	1 N	9.23	9.23
R530785	O-Ring	1 N	11.54	11.54
TY6354	HY-Gard TM	2	29.99	59.98
Z63847	HANDLE	2	21.46	42.92
14M7275	M12 NUT GR.10	1	1.15	1.15
14M7396	M8 NYLON FLANGE	2	2.53	5.06
19M8874	M8 X 75MM FLANG	5	6.13	30.65
	PARTS			1628.71
	LABOR			2493.75
16001000	SEGMENT TOTAL==>			4122.46

CONTINUED ON PAGE 05

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: \_\_\_\_\_



CAMROSE:  
4717 38th St.  
Camrose, AB T4V 3W9  
Phone: 780-672-4463

KILLAM:  
5907 51st Ave  
Killam, AB T0B 2L0  
Phone: 780-385-3993

PROVOST:  
P.O. Box 299  
3403 57 Ave  
Provost, AB T0B 3S0  
Phone: 780-753-2278

WAINWRIGHT:  
1601 - 23 Street  
Wainwright, AB T9W 1L2  
Phone: 780-842-2171

Ship To:



Invoice To: BRI KILLAM INTERNAL

.  
. AB X0X 0X0

Branch KILLAM		
Date 04/29/25	Time 22:20:30 (B)	Page 05
Account No [REDACTED]	Phone No [REDACTED]	Inv No [REDACTED]
Ship Via		Purchase Order
Tax ID No		
		Salesperson 218

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016667	X9 1000 COMBINE	786E	1H0X910XEN0820102	08/25/23	
	X9 1000	507		08/23/27	1250 X

SEGMENT# 6 C 292 NA 04/08/25 04/09/25  
RIGHT HAND SIDE 13.00 HRS

CORRECTION:

installed and zero and leveled concaves  
tensioned clean grain paddle chain  
repaired chop to drop door  
cleaned sediment bowl  
replaced rotary screen drive belt  
replaced rotary screen belt  
cleaned cameras and changed desiccant  
adjusted tire pressures

ADDITIONAL DESCRIPTION:

\*INSTALL AND LEVEL AND ZERO CONCAVES (4)  
\*TENSION CLEAN GRAIN PADDLE CHAIN (.5)  
\*REPLACE CHOP TO DROP DOOR (WE WILL DISCUSS WITH DALE ABOUT  
A REPAIR) (6)  
\*CLEAN SEDIMENT BOWL (.5)  
\*REPLACE ROTARY SCREEN DRIVE BELT (HXE148727) AND REPLACE  
ROTARY SCREEN BELT (HXE157271) (1)  
\*CLEAN CAMERAS & CHANGE DESSICANT (.5)  
\*ADJUST TIRE PRESSURES (.5)

HXE148727	ROTARY VACUUM	1	170.60	170.60
HXE168680	ROTARY SCREEN	1	88.20	88.20
KXE10744	Desiccant	1	331.55	331.55
	PARTS			590.35
	LABOR			2275.00
16001000	SEGMENT TOTAL==>			2865.35

SEGMENT# 7 C 292 NA 04/08/25 04/09/25

ENGINE COMPARTMENT

5.50 HRS

CONTINUED ON PAGE 06

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: \_\_\_\_\_



CAMROSE:  
4717 38th St.  
Camrose, AB T4V 3W9  
Phone: 780-672-4463

KILLAM:  
5907 51st Ave  
Killam, AB T0B 2L0  
Phone: 780-385-3993

PROVOST:  
P.O. Box 299  
3403 57 Ave  
Provost, AB T0B 3S0  
Phone: 780-753-2278

WAINWRIGHT:  
1601 - 23 Street  
Wainwright, AB T9W 1L2  
Phone: 780-842-2171

Ship To: [REDACTED]

Invoice To: BRI KILLAM INTERNAL  
.  
. AB X0X 0X0

Branch KILLAM		
Date 04/29/25	Time 22:20:30 (B)	Page 06
Account No [REDACTED]	Phone No [REDACTED]	Inv No [REDACTED]
Ship Via		Purchase Order
Tax ID No		
		Salesperson 218

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016667	X9 1000 COMBINE	786E	1H0X910XEN0820102	08/25/23	
	X9 1000	507		08/23/27	1250 X

### CORRECTION:

changed vac fan drive belt  
topped up coolant  
changed radiator cap  
changed both engine air filters  
and cleaned housing  
tightened hydro hose  
changed hydraulic reservoir filter  
changed engine oil and filter  
added oil to engine gearcase  
changed fuel filters  
changed transmission breather  
could smell something burning around the turbo so i removed  
turbo collading and blew it out and put back together  
still could smell burning so i dug deeper and found a pile  
of burnt chaff so i blew it out some more blew around all  
parts of the exhaust system

### ADDITIONAL DESCRIPTION:

\*CHANGE VAC FAN DRIVE BELT (.5)  
\*BLOW OUT RAD (1)  
\*TOP UP COOLANT AND CHANGE RESERVOIR CAP (MISSING PSI  
STICKER) (.25)  
\*CHANGE BOTH ENGINE AIR FILTERS AND CLEAN HOUSING (.5)  
\*TIGHTEN HYDRO HOSE LEAKING (.5)  
\*CHANGE HYDRAULIC RESERVOIR FILTER (.5)  
\*CHANGE ENGINE OIL & FILTER (1)  
\*ADD OIL ENGINE GEARCASE - 10L JUG (.25)  
\*CHANGE FUEL FILTERS (.75)  
\*CHANGE TRANSMISSION BREATHER - RETURN FILTER IN TANK (.25)

AT310335	FILLER CAP	1	52.40	52.40
CONTINUED ON PAGE 07				

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: \_\_\_\_\_



CAMROSE:  
4717 38th St.  
Camrose, AB T4V 3W9  
Phone: 780-672-4463

KILLAM:  
5907 51st Ave  
Killam, AB T0B 2L0  
Phone: 780-385-3993

PROVOST:  
P.O. Box 299  
3403 57 Ave  
Provost, AB T0B 3S0  
Phone: 780-753-2278

WAINWRIGHT:  
1601 - 23 Street  
Wainwright, AB T9W 1L2  
Phone: 780-842-2171

Ship To:



Invoice To: BRI KILLAM INTERNAL  
.  
. AB X0X 0X0

Branch KILLAM		
Date 04/29/25	Time 22:20:30 (B)	Page 07
Account No [REDACTED]	Phone No [REDACTED]	Inv No [REDACTED]
Ship Via		Purchase Order
Tax ID No		
		Salesperson 218

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016667	X9 1000 COMBINE	786E	1H0X910XEN0820102	08/25/23	
	X9 1000	507		08/23/27	1250 X
AXE103407	Hydraulic Filte	1		126.03	126.03
	Hydraulic Filter				
AXE73797	HYDRA FILTER	1		139.28	139.28
	Hydraulic Filter				
DZ124761	Filter Element	1		136.64	136.64
DZ124786	Filter Element	1		131.27	131.27
EF4663	RECYC FEE LONG	2		1.00	2.00
HXE11090	OUTER AIR FILTE	1		386.50	386.50
HXE11091	INNER AIR FILTE	1		272.71	272.71
RE572785	OIL FILTER	1		126.76	126.76
TY22062	HY-Gard 10L	1		70.99	70.99
TY26576	10L Jug Coolant	1		52.99	52.99
TY26679	15W40 18.9L	3		137.49	412.47
	Plus-50 II Oil 15W40 CJ4/SN				
19M7864	M8 X 12MM FLANG	2		2.42	4.84
19M7866	M8 X 20MM FLANG	1		2.67	2.67
				PARTS	1917.55
				LABOR	962.50
	16001000			SEGMENT TOTAL==>	2880.05

SEGMENT# 8 C 292 NA 04/08/25 04/10/25  
GRAIN TANK .50 HRS

CORRECTION:

installed do not step on stickers

ADDITIONAL DESCRIPTION:

\*ACTIVE YIELD SENSORS - MISSING 'DO NOT STEP' STICKERS (.25)

LABOR 87.50  
16001000 SEGMENT TOTAL==> 87.50

SEGMENT# 9 C 292 NA 04/08/25 04/09/25

CONTINUED ON PAGE 08

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: \_\_\_\_\_



CAMROSE:  
4717 38th St.  
Camrose, AB T4V 3W9  
Phone: 780-672-4463

KILLAM:  
5907 51st Ave  
Killam, AB T0B 2L0  
Phone: 780-385-3993

PROVOST:  
P.O. Box 299  
3403 57 Ave  
Provost, AB T0B 3S0  
Phone: 780-753-2278

WAINWRIGHT:  
1601 - 23 Street  
Wainwright, AB T9W 1L2  
Phone: 780-842-2171

Ship To:



Invoice To: BRI KILLAM INTERNAL  
.  
. AB X0X 0X0

Branch KILLAM		
Date 04/29/25	Time 22:20:30 (B)	Page 08
Account No [REDACTED]	Phone No [REDACTED]	Inv No [REDACTED]
Ship Via		Purchase Order
Tax ID No		
		Salesperson 218

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016667	X9 1000 COMBINE	786E	1H0X910XEN0820102	08/25/23	
	X9 1000	507		08/23/27	1250 X
CAB SECTION					.25 HRS
<u>CORRECTION:</u>					
toped up washer fluid					
changed cab filters					
<u>ADDITIONAL DESCRIPTION:</u>					
*CHANGE CAB AIR FILTERS (.25)					
*TOP UP WASHER FLUID					
AXE70605	AIR FILTER	1	32.75	32.75	
TA32591	Air Filter	1	101.90	101.90	
				PARTS	134.65
				LABOR	43.75
16001000	SEGMENT TOTAL==>				178.40

SEGMENT#10 C 292 NA 04/08/25 04/09/25 5.00 HRS

BP15 HEADER SN#820245

CORRECTION:

replace 5 broken pickup fingers  
adjusted windrow hold down height  
pulled out dent in feed auger tube  
replaced one feed finger  
adjusted feed auger height and timing  
adjusted cross auger chain  
adjusted tire pressures  
adjusted rear and auger strippers

ADDITIONAL DESCRIPTION:

\*REPLACE 5 BROKEN PICK UP BELT FINGERS (.5)  
\*ADJUST HEIGHT WINDROW HOLD DOWNS (.25)  
\*FEED AUGER TUBE HAS DENT, PULL OUT (.5)  
\*ADJUST FEED AUGER HEIGHT (.5)  
\*REPLACE ONE FEED AUGER FINGER - MISSING, RETAINER &

CONTINUED ON PAGE 09

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: \_\_\_\_\_





CAMROSE:  
4717 38th St.  
Camrose, AB T4V 3W9  
Phone: 780-672-4463

KILLAM:  
5907 51st Ave  
Killam, AB T0B 2L0  
Phone: 780-385-3993

PROVOST:  
P.O. Box 299  
3403 57 Ave  
Provost, AB T0B 3S0  
Phone: 780-753-2278

WAINWRIGHT:  
1601 - 23 Street  
Wainwright, AB T9W 1L2  
Phone: 780-842-2171

Ship To:



Invoice To: BRI KILLAM INTERNAL  
.  
. AB X0X 0X0

Branch KILLAM		
Date 04/29/25	Time 22:20:30	Page [REDACTED]
Account No [REDACTED]	Phone No [REDACTED]	Inv No [REDACTED]
Ship Via		Purchase Order
Tax ID No		
		Salesperson 218

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016667	X9 1000 COMBINE	786E	1H0X910XEN0820102	08/25/23	
	X9 1000	507		08/23/27	1250 X
BEARING AS WELL (1)					
*ADJUST FEED AUGER FINGER TIMING (.5)					
*ADJUST CROSS AUGER CHAIN (.5)					
*ADJUST AUGER STRIPPERS (.5)					
*ADJUST REAR STRIPPERS (.5)					
*ADJUST TIR PRESSURES (.25)					
AH171602	BEARING	1	14.45	14.45	
H168206	CAP	1	8.82	8.82	
H169912	RETAINER	1	18.47	18.47	
H169913	SPRING LOC	1	2.56	2.56	
Spring Locking Pin					
H169914	FINGER	1	21.68	21.68	
H172459	RETAINER	1	5.33	5.33	
H86248	FINGER	5	2.95	14.75	
28316	SPRING LOC	1	4.21	4.21	
Spring Locking Pin					
PARTS					90.27
LABOR					875.00
16001000	SEGMENT TOTAL==>				965.27

SEGMENT#11 C 292 NA 04/08/25 04/28/25 2.00 HRS

RUN AND CHECK

CORRECTION:

ran up combine  
installed shields  
parked combine

ADDITIONAL DESCRIPTION:

RUN AND CHECK

16001000

LABOR 350.00  
SEGMENT TOTAL==> 350.00

CONTINUED ON PAGE 10

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: \_\_\_\_\_



**CAMROSE:**  
4717 38th St.  
Camrose, AB T4V 3W9  
Phone: 780-672-4463

**KILLAM:**  
5907 51st Ave  
Killam, AB T0B 2L0  
Phone: 780-385-3993

**PROVOST:**  
P.O. Box 299  
3403 57 Ave  
Provost, AB T0B 3S0  
Phone: 780-753-2278

**WAINWRIGHT:**  
1601 - 23 Street  
Wainwright, AB T9W 1L2  
Phone: 780-842-2171

Ship To: [REDACTED]

Invoice To: BRI KILLAM INTERNAL  
.  
. AB X0X 0X0

Branch [REDACTED]		
Date 04/29/25	Time 22:20:30 (B)	Page 10
Account No [REDACTED]	Phone No [REDACTED]	Inv No [REDACTED]
Ship Via		Purchase Order
Tax ID No		
		Salesperson 218

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016667	X9 1000 COMBINE	786E	1H0X910XEN0820102	08/25/23	
	X9 1000	507		08/23/27	1250 X

	***** WORK ORDER TOTALS *****
	INTERNAL CUSTOMER
PARTS	6328.87
LABOR	11730.00
SERV ACCESORIES	100.00
INTERNAL TOTAL	18158.87

1-877-913-3373

WWW.BRILTD.COM

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: \_\_\_\_\_