

Canada West Harvest Centre

8 Industrial Drive West
Emerald Park, SK S4L 1C6 CA

SERVICE QUOTE - DO NOT PAY

Quote: 01-8807
Date: 11/30/2024

PO: C7800434#1
CustId: WEBERPAULJ

Phone: (306) 525-2300 Fax: (306) 525-3399
Email: info@cawhc.com
Web site: cawhc.com GST#805679776 RT0001

Cust Email: weber.acres@hotmail.com
Phone: (306) 577-1204
Salesperson: JJones
User: TGuest

Bill To:

Weber Acres
P.O. Box 34
Carlyle, SK S0C 0R0 CA

Ship To:

Weber Acres

Opened: 11/30/2024
Work Order No: 01-
Pickup Date:
Unit No: 11554
Unit Serial: C7800434
Unit Desc: 740TT Lexion 2018 (#1)
Unit Meter: 1,624.0 Hours

Responsible Tech:
My Ref: Lexion 740TT
Delivery Date:
Unit Make: Class
Unit Model: 740TT
Unit Tag: N367

2025 Field Inspection

Item	Type	Description	Qty	Tax	Price	Discount	Net Price
Inspect combine							
	SL	Inspect combine at customer location. Customer Field Labour					\$0.00
Segment Total:							\$0.00
Service combine							
	SL	Perform service. Change - engine oil and filter - fuel filters - engine air filters - cab filters - add grease to autogreaser Customer Field Labour					\$0.00
CL1474800	PA	CLA - AGRIMOT PROTEC 15W-40 NA 20L	1.0000	Y	\$155.35		\$155.35
1474810	PA	CLA - AGRIMOT SDX 15W-40	3.0000	Y	\$59.73		\$179.19
7983031	PA	CLA - ENGINE OIL FILTER	1.0000	Y	\$74.82		\$74.82
7992081	PA	CLA - FUEL FILTER	2.0000	Y	\$46.88		\$93.76
7992091	PA	CLA - FILTER ELEMENT	1.0000	Y	\$87.60		\$87.60
0773672	PA	CLA - Primary Air Filter	1.0000	Y	\$312.26		\$312.26
5646982	PA	CLA - Cab Filter STANDARD	1.0000	Y	\$88.94		\$88.94
2417931	PA	CLA - AGRIGREASE EP 3 TUBE	8.0000	Y	\$9.08		\$72.64
Segment Total:							\$1,064.56
Horn							
	SL	Horn doesn't work. Replace horn. Customer Field Labour					\$0.00
0717292	PA	CLA - HORN	1.0000	Y	\$109.05		\$109.05
Segment Total:							\$109.05
Orbitrol valve							

Canada West Harvest Centre

8 Industrial Drive West
Emerald Park, SK S4L 1C6 CA

SERVICE QUOTE - DO NOT PAY

Quote: 01-8807
Date: 11/30/2024

PO: C7800434#1
CustId: WEBERPAULJ

Phone: (306) 525-2300 Fax: (306) 525-3399
Email: info@cawhc.com
Web site: cawhc.com GST#805679776 RT0001

Cust Email: weber.acres@hotmail.com
Phone: (306) 577-1204
Salesperson: JJones
User: TGuest

Bill To:

Weber Acres
P.O. Box 34
Carlyle, SK S0C 0R0 CA

Ship To:

Weber Acres

Orbitrol steering valve below cab floor is leaking. Replace all 4 o-rings between steering valve body and hydraulic lines. Remove lines and fittings and replace o-rings.					
2158390	SL	Customer Field Labour			\$0.00
	PA	CLA - O-RING	4.0000	Y	\$8.46
Segment Total:					\$33.84
Feeder chain					
Feeder chain is worn. Chain rollers dished. Excessive play between chain links. Replace chain.					
5181871	SL	Customer Field Labour			\$0.00
	PA	CLA - CONVEY.CHAIN CPL.	1.0000	Y	\$3,007.26
Segment Total:					\$3,007.26
Feeder house					
Feeder house floor plastic wear strips worn out. Replace wear strips.					
6305700	SL	Customer Field Labour			\$0.00
	PA	CLA - SLIDE RAIL	4.0000	Y	\$48.68
2349530	PA	CLA - M8 x 20 8.8 CH	12.0000	Y	\$0.95
2393870	PA	CLA - WASHER, CONTACT	16.0000	Y	\$0.18
2353621	PA	CLA - M8 x 60 8.8 CH	4.0000	Y	\$1.92
2361700	PA	CLA - M8 HEX NUT	16.0000	Y	\$0.26
Segment Total:					\$220.84
Dust extractor					
Dust extractor drive belt cracked. Replace belt.					
3257281	SL	Customer Field Labour			\$0.00
	PA	CLA - Dust Extraction Belt V/HP	1.0000	Y	\$42.24
Segment Total:					\$42.24
Feeder cylinder					
RH feeder lift cylinder leaking badly. Cylinder rod chrome peeling off in many areas. Take apart cylinder. Replace rod and reseal cylinder. OR Replace cylinder. New hydraulic cylinder 2653\$					
0427652	SL	Customer Field Labour			\$0.00
	PA	CLA - PISTON ROD	1.0000	Y	\$946.64
2186480	PA	CLA - ROD GUIDE RING	1.0000	Y	\$48.35
2168730	PA	CLA - ROD GUIDE RING	1.0000	Y	\$28.61
2176890	PA	CLA - PISTON SEAL	1.0000	Y	\$126.82
2124760	PA	CLA - O-RING	1.0000	Y	\$19.43
2158370	PA	CLA - O-RING	1.0000	Y	\$3.12

Canada West Harvest Centre

8 Industrial Drive West
Emerald Park, SK S4L 1C6 CA

SERVICE QUOTE - DO NOT PAY

Quote: 01-8807
Date: 11/30/2024

PO: C7800434#1
CustId: WEBERPAULJ

Phone: (306) 525-2300 Fax: (306) 525-3399
Email: info@cawhc.com
Web site: cawhc.com GST#805679776 RT0001

Cust Email: weber.acres@hotmail.com
Phone: (306) 577-1204
Salesperson: JJones
User: TGuest

Bill To:

Weber Acres
P.O. Box 34
Carlyle, SK S0C 0R0 CA

Ship To:

Weber Acres

2176950	PA	CLA - O-RING	1.0000	Y	\$2.83	\$2.83
2168740	PA	CLA - DOUPLE SCRAPER	1.0000	Y	\$21.77	\$21.77
Segment Total:						\$1,197.57
APS Anchors						
		5 APS anchors bent. Straighten bent anchors.				
	SL	Customer Field Labour				\$0.00
Segment Total:						\$0.00
Disawning plate						
		Second row of disawning plates middle plate missing. Remove APS grates and replace second row of disawning plates.				
	SL	Customer Field Labour				\$0.00
7574331	PA	CLA - COVER	1.0000	Y	\$330.25	\$330.25
Segment Total:						\$330.25
ITS hardware						
		ITS hardware worn. Replace ITS hardware.				
	SL	Customer Field Labour				\$0.00
2373820	PA	CLA - M10x20 Hex Bolt	6.0000	Y	\$0.95	\$5.70
2393941	PA	CLA - WASHER, CONTACT	6.0000	Y	\$1.01	\$6.06
Segment Total:						\$11.76
Unloading Chain						
		Unloading auger drive chain connecting link cotter pin broken. Replace cotter pin.				
	SL	Customer Field Labour				\$0.00
Segment Total:						\$0.00
Hyd.tank						
		Hydraulic suction hoses connected to tank sweating with oil. Reposition and retight hose clamps.				
	SL	Customer Field Labour				\$0.00
Segment Total:						\$0.00
Wheel light						
		LH rear wheel light out. Replace bulb.				
	SL	Customer Field Labour				\$0.00
0137300	PA	CLA - LAMP	1.0000	Y	\$29.68	\$29.68
Segment Total:						\$29.68
Chopper knives						
		Rotational chopper knives worn on one side. Flip chopper knives.				

Canada West Harvest Centre

8 Industrial Drive West
Emerald Park, SK S4L 1C6 CA

SERVICE QUOTE - DO NOT PAY

Quote: 01-8807
Date: 11/30/2024

PO: C7800434#1
CustId: WEBERPAULJ

Phone: (306) 525-2300 Fax: (306) 525-3399
Email: info@cawhc.com
Web site: cawhc.com GST#805679776 RT0001

Cust Email: weber.acres@hotmail.com
Phone: (306) 577-1204
Salesperson: JJones
User: TGuest

Bill To:

Weber Acres
P.O. Box 34
Carlyle, SK S0C 0R0 CA

Ship To:

Weber Acres

SL	Customer Field Labour					\$0.00
Segment Total:						\$0.00
Radial spreader						
Radial straw spreader LH upper deflector arm bearings have excessive play. Replace bearings on upper and lower arms. Replace hydraulic cylinder broken mounting bolt.						
	SL	Customer Field Labour				\$0.00
2175440	PA	CLA - ANG. BALL BEARING	2.0000	Y	\$119.21	\$238.42
2175450	PA	CLA - GRVD.BALL BEARING	2.0000	Y	\$134.62	\$269.24
2113450	PA	CLA - BOLT HEXAGONAL	1.0000	Y	\$5.44	\$5.44
2393890	PA	CLA - WASHER CONTACT M12	1.0000	Y	\$0.86	\$0.86
2333230	PA	CLA - M12 Lock Nut 10.9	1.0000	Y	\$2.38	\$2.38
Segment Total:						\$516.34
Clean fan drive						
Cleaning fan drive stage1 belt cracked. Replace belt.						
	SL	Customer Field Labour				\$0.00
6679570	PA	CLA - V-BELT Stage 1 Cleaning Fan	1.0000	Y	\$87.10	\$87.10
Segment Total:						\$87.10
Rotary screen						
Rotary screen seal is missing. Glue in new seal.						
	SL	Customer Field Labour				\$0.00
14973890	PA	CLA - RUBBER SEAL REPAIR KIT	1.0000	Y	\$132.14	\$132.14
Segment Total:						\$132.14
Screen drive						
Rotary screen drive belt tensioner seized. Unseized tensioner.						
	SL	Customer Field Labour				\$0.00
Segment Total:						\$0.00
Speeds						
Can't learn speeds. Spread variable pulleys and blow out chaff from inside of pulleys. Grease and cycle pulleys.						
	SL	Customer Field Labour				\$0.00
Segment Total:						\$0.00
Blow & Clean						
Blow all drive and driven pulleys and extra time spent on insuring the Main drive pulley is cleaned out completely Blow behind the variable speed pulleys Open tail board and blow out the spreader drive system Open radiator compartment and clean all engine and oil coolers Blow above transmission and reach in behind and below transmission area						

Canada West Harvest Centre

8 Industrial Drive West
Emerald Park, SK S4L 1C6 CA

SERVICE QUOTE - DO NOT PAY

Quote: 01-8807
Date: 11/30/2024

PO: C7800434#1
CustId: WEBERPAULJ

Phone: (306) 525-2300 Fax: (306) 525-3399
Email: info@cawhc.com
Web site: cawhc.com GST#805679776 RT0001

Cust Email: weber.acres@hotmail.com
Phone: (306) 577-1204
Salesperson: JJones
User: TGuest

Bill To:

Weber Acres
P.O. Box 34
Carlyle, SK S0C 0R0 CA

Ship To:

Weber Acres

Blow above and behind Fuel and DEF tanks
Remove all covers and blow all areas to remove any chaff and fine dust

SL Customer Field Labour

\$0.00

Segment Total: \$0.00

Belts & Chains

Adjust all belts and chains to proper operating tensions.

SL Customer Field Labour

\$0.00

Segment Total: \$0.00

Test run

Perform operational test run after all repairs are complete.

SL Customer Field Labour

\$0.00

Segment Total: \$0.00

Small things

Small things:
-TT tracks inner logs in poor shape
- Feeder house upper dust shield bent
- radial spreader fingers rubber mounts worn through will last one more season
- header engagement switch slightly loose
- filling auger worn will last one more season

SL Customer Field Labour

\$0.00

Segment Total: \$0.00

Parts: \$6,782.63

Totals

Sub Total: \$6,782.63

Total Tax: \$339.12

Invoice Total: \$7,121.75